Surveyor: OB	ASSIGNME	NT (Office)		
From (Person): Peter W	ary of	ASM	Date/Time	28092018 8-45am
Estimated Cost:	J	Bill to:		
OD / TP WS / TP RES / OD TO Inspect Vehicle No:		S	Insured:	SHID 858B
at Workshop m/s	1st Auto		Tel: 924	16 6906
of	Blk 6 Defu Lare 10	#01-554		
Policy No:		Claim No: _	38 MOO X5T	C-03=61
Sum Insured:		Excess:		
Make of Veh: (Client's Record)			D.O.A	18062018
CA / REV / REP. / REV 2	4 HRS WY		H.O.D_E	ndorsement:
Date/Time: 38093018 383	Person Contacted:	Chris	Vehicle (IN	4.OUT
Date/Time Action/Instruction	on (x) Estimate			***************************************
TBL 2135 1	J - NA/GAT 18016	859 /4		DUD: 180618
SHD 858B	- CC3/AG18011187	Kugs 2		DLA: 180618

Serveyor XXX. AXA	
	ASSIGNMENT
From: Date:	Veh No: 75(2735 U Yr Regn: Jul / 16
Estimated Cost:	Type: M.Car / M.Cyole / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or WH
To Inspect Vehicle No:	Make: Handa CBA90 c.c 184
at Workshop m/s Bike Pynamic	Colour Black A/C: Insured / Std / NI / NA
of	Sp.Reading - T/Radio: Insured / Std / NI / N.
Insured:	Eng/No:
Policy No.	C/No: LWBMC4695H1101892
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Ing@er / Jammed / Leaked / Burnt or
Make of Veh:	Modi: MiL/S/Rim / STD A/Rim or
V	Tyre Size: F: 10/70-17
(Policy Condition)	R: 140/70-17 (TRC
Remark: The veh had commenced its N/S	
repair at the time of inspection.	TOYO/YOKO OF (LA)
Bal. or Market Value:	Front Rear
Bal. or Market Value: DAC Accident Rport: Consistent? : Yes or No	D/Del /
12.10.1001011.1	1/0-1
Lot. Hopano.	10
Lum Sum: % 3 Val.: Yes or No	
CA / REV / REP. / 24 HRS	Des. of Damages (Fro / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	e: IN / OUT The U/C / Chassis frame / Body Structure affected due to collisi
Date / Time Action / Instruction	·
Estimeted repair	range \$3,800 - \$4,500 mont
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
i) : Final Report	Resurvey No. of Trip: _ Survey Fee: 100
	Transportation:
Date/Time, File Return to?	
Date/Time, File Return to?	Add Fee: Site Insp (\$) _s+RS,_si
Date/Time, File Return to?	

invalid - Menu



Service Request Details

Claim

S8M00X5T

Reference

None 🧳

Loss Date

June 18, 2018

Request Date

September 28, 2018

Due Date

October 5, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions Next Step Agree to perform service Decline Work Accept Work

Vehicle Information

Incident Vehicle Registration #

FBL2135U

Make

TPVD HONDA

Model CBF190WH

Service Address

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD No.2 ANG MO KIO STREET 63, 569111, Singapore

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

> Back to OneMotoring

Enquire Transfer Fee

		25.00
25.00	•	25.00
(S\$)	(S\$)	(\$\$)
Amount Before GST		Amount After GST
yment (if any) of a vehicle will follow th	ne vehicle to the new registe	red owner when its
nposed if road tax / lay up has expired.	Please use Enquire Road Tax	(Payable forfee(s)
-		D 11 (() ()
-		
-		
-		
-		
09 Oct 2018		
D - Motorcycle		
÷		
25 Jul 2016		
310 kg		
-		
184 cc		
MC46E5010628		
Petrol		
LWBMC4695H1101892		
CBF190WH		
HONDA		
Normal		
No Attachment		
P00 - Passenger Motorcycle/Autoc	ycle/Moped	
	No Attachment Normal HONDA CBF190WH LWBMC4695H1101892 Petrol MC46E5010628 184 cc - 310 kg 140 kg 2016 25 Jul 2016 - D - Motorcycle \$6,012.00 24 Jul 2026 24 Jan 2019 24 Jul 2019 09 Oct 2018	Normal HONDA CBF190WH LWBMC4695H1101892 Petrol MC46E5010628 184 cc - 310 kg 140 kg 2016 25 Jul 2016 - D - Motorcycle \$6,012.00 24 Jul 2026 24 Jul 2019 09 Oct 2018

You may print this page for reference.

OK Print

.> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	9687D	
Vehicle No.:	FBL2135U	
Vehicle to be Exported:	No	
Intended Deregistration Date:	09 Oct 2018	
Vehicle Make:	HONDA	
Vehicle Model:	CBF190WH	
Primary Colour:	Blue	
Manufacturing Year:	2016	
Engine No.:	MC46E5010628	
Chassis No.:	LWBMC4695H1101892	
Maximum Power Output:		
Open Market Value:	\$2,964.00	
Original Registration Date:	25 Jul 2016	
First Registration Date:	25 Jul 2016	
Transfer Count:	2	
Actual ARF Paid: Intended PARF Rebate Details	\$445.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:		
PARF Rebate Amount: Intended COE Rebate Details	\$0.00	
COE Expiry Date:	24 Jul 2026	
COE Category:	D - Motorcycle	
COE Period(Years):	10	
QP Paid:	\$6,012.00	
COE Rebate Amount:	\$4,683.00	
Total Rebate Amount:	\$4,683.00	

The information contained herein is correct as at 09 Oct 2018

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

		PRE-REPAIR II	NSPECTION REPO	RT
AXA	INSURANCE PTE	LTD	Ref: CS3/ASM18	017665/Gcbe2
SLOSTON'S	ENTON WAY #24 TOWERSINGAPO		Date: 11-10-2018	
ATT	N : PETER WANG		Code: ASM	
1.		Policy Particula	ars :- (THIRD PARTY C	LAIM)
	Insured Veh.	SHD 858B	Veh. Inspected	FBL 2135U
	Policy No.		Coverage (\$)	0.00
	Claim No.	S8M00X5T	Excess (\$)	0.00
	Assign From	PETER WANG	Assign Date	28/09/2018
2.		Vehicle P	articulars & Condition	
	Make & Model	HONDA CBF190WH	c.c	184
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	LWBMC4695H1101892	Colour	BLACK
	Odometer		Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.		Cor	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	110/70-17	MICHELIN	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70-17	IRC	4 mm
	L/H Rear Tyre			mm
1.		Desc	ription of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	FRONT PORTION.	
5.		Ger	neral Information	
	Accident Date	18/06/2018	Inspect Date / Tim	e 28/09/2018 (06:00 PM)
	Survey held at Repairer	1ST AUTO - 6 DEFU LANE	10 #01-554	
5a.			Remarks	
	B) THE REPAIR E THE REPAIRER W C) ENCLOSED PL	ON WAS CONDUCTED ON A STIMATE WAS NOT PRESEN WAS TOLD TO PREPARE THE EASE FIND DAMAGED VEHI ED REPAIR COST OF THE DA	ITED AT THE TIME OF IN: ESTIMATE. CLE PHOTOGRAPHS.	
5b.		Estim	ate Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 W	Vorking Days
		Poport Pof No. C	S3/ASM18017665/Gcbe	2

Report Ref No. CS3/ASM18017665/Gcbe2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or torf, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.