

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS FIRST CAPITAL INSURANCE LTD			Ref: CS/FCI18017669/R1sd3e2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date: 14-05-2019  Code: FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHC 1818R	Veh. Inspected	GBC 3433A	
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
	Claim No.	D18007081MFSH	Excess (\$)	0.00	
	Assign From	EILEEN LEE	Assign Date	28/09/2018	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200 1.5L MT	c.c	1461	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	VSKYBAM20U0025013	Colour	WHITE	
	Odometer	236296	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185 R14C	FALKEN	6 mm	
	L/H Front Tyre	185 R14C	FALKEN	6 mm	
	R/H Rear Tyre	185 R14C	FALKEN	6 mm	
	L/H Rear Tyre	185 R14C	FALKEN	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	25/09/2018	Inspection Date	20/11/2018	
	Survey held at SNG AH TEE MOTOR & PANEL SERVICE PTE LTD  BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.				
5a.					
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	6 Working Days		