

ASS. REC. BY:

REF:

CS/CTI18017670/A1d39

Special Instruction:

Surveyor:
Menmen

Adrian

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

28/9/18 @ 1:54pm

Estimated Cost:

Bill to:

OD / TP DWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLU 6300S

Insured:

SKF 3917Z

at Workshop m/s

Motorcarz Garage

Tel:

6841 5383

of

53 Ubi Ave 1 #01-19

Policy No:

DMPCSN1342491704

Claim No:

SNM18D04653C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/09/2018

CA / REV / REP. / REV 24 HRS / up?

H.O.D. Endorsement:

Date/Time:

2:27pm @ 28/9/18

Person Contacted:

Elma

Vehicle:

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLU 6300S - NA/INC18017566/24

DOA: 27/9/18

SKF 3917Z - NA/INC18017566/24

DOA: 27/9/18

lump sum \$4100 (Red: 44th. 5th; 52%)

REF: CTI

ASSIGNMENT

From: _____ Date: **28/1/18**
 Estimated Cost: _____
 OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SLU G300S**
 at Workshop m/s: **Motoricarz Garage**
 of **53 Ubi Ave 1 # 01-19**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR. Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS ^{hp}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLU6300S** Vr Regn: **2017 Nov**
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Prius Alpha cc 1797**Colour: **Grey** A/C Insured / Std / NI / NASp. Reading: **140923** T/Radio: Insured / Std / NI / NA

Eng No: _____

C/No: **2VW400026863**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: **205/60R16**R: **205/60R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal: **06** mm R/Bal: **06** mmL/Bal: **06** mm L/Bal: **06** mmD.O.A. D.O.I. **28/09/18**Survey held at: **Motoricarz Garage**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP China.

RECEIVED 28 OCT 2018

Date/Time, File Pass to?

0510 Typast

Date/Time, File Return to?

☐ : Preli. Report☒ : Final ReportDays Of Repair: **5**Resurvey No. of Trip: **1**

Survey Fee:

Transportation

) \$ - RS. \$

) Photos

) Other

TOTAL

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$Report Format: **TP**Lump Sum ☒ I.B.I. (\$ **41007**)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Sep 2018		28 Sep 2018 13:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GOH NAI EE, ID: S7822652H		
Main Claimant:	GOH JIA YING, ID: S7910513I		
Vehicle Reg. No.:	SLU6300S	Date of Loss:	27/09/2018 07:00 - :59
Claim Type:	TP / SNM18D04653C02	Policy/Cover Note No.:	DMPCSN1342491704 (Comprehensive)
Vehicle Reg. No. (Insured):	SKF3917Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Motoricarz Garage (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Paya Lebar - Tel: 68415383		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/10/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: motoricarz garage <motoricarzgarage@gmail.com>
Sent: Thursday, 27 September, 2018 5:42 PM
To: Claims Dept of CTI
Subject: ARRANGEMENT FOR PRE-REPAIR INSPECTION FOR SLU6300S
Attachments: PRI_SLU6300S.pdf

Your ref: SKF 3917Z

Our ref: SLU6300S

Dear Motor Claim Dept,

Kindly arrange a pre-repair inspection for the **ABOVEMENTIONED** Vehicle. Attached herewith a pre-repair inspection request and GIA Report for your perusal and attention.

--
Best Regards,

Elma | Account

Motoricarz Garage

Phone: 6844-4290 | email: motoricarzgarage@gmail.com | fax: 6841-6043

Blk 53, Paya Ubi Industrial Park, Ubi Avenue 1, #01-19 | S(408934)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18017670/Atd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 28-09-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 3917Z	Veh. Inspected	SLU 6300S
Policy No.	DMPCSN1342491704	Coverage (\$)	0.00
Claim No.	SNM18D04653C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	28/09/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/09/2018	Inspection Date	28/09/2018
Survey held at	MOTORICARZ GARAGE 53 UBI AVE 1 #01-25 PAYA UBI IND. PARK SINGAPORE 408934		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

eBao

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Membership](#)[My Insurance](#)

Policy Query

Policy No:

Date of Accident:

Include Ins (For Motor):

Certificate Number:

Search	Policy No	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Claim Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5006120110		GON RA YING	802301403H	GPC	drive CLASSIC	SL063005	SL063005	24/11/2017	23/11/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2018 11:20
Date Of Accident	27/09/2018 07:25
Exact Location Of Accident	COMMONWEALTH DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU6300S
Insured/Policyholder	
Name Of Registered Owner	GOH JIA YING
NRIC No	S8230103H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97600737
Alternative Phone No	OFFICE-97600737

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS ALPHA HYBRID 1.8S CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096120110
Cover Note Number	

Driver

Name of Driver	ERIC HEW BOO LEONG (ERIC ZHOU WULIANG)
NRIC No	S7910513I
Date Of Birth	09/04/1979
Occupation	OUTDOOR
Date Of Driving Pass	17/11/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97600717
Fax Number	
Contact Number	OFFICE-97600717
Email Address	NOEMAIL

Address	BLK 316C PUNGGOL WAY
	#02-695
Postcode	823316
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG COMMONWEALTH DR AND TURN ON MY VEHICLE INDICATOR LIGHT AS I WANTED TO MAKE A RIGHT TURN TO DROP OFF POINT. SUDDENLY VEHICLE B OVERTAKE MY VEHICLE FROM BEHIND. AS A RESULT, VEHICLE B HIT ONTO MY VEHICLE FRONT RIGHT PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKF3917Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	UTHAYASURIAN S/O SIDAMBARAM
NRIC/Passport Number	S1703416B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2

Passenger 1

NAME: :

GENDER: :

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
 - (a) I understand, acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (ii) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (iii) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (iv) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (v) the information so collected under (i) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



A-1463005

g: SKF3932

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Role of statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/ID No: _____

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S79105131**

ERIC CHEW BOO LEONG
(ERIC ZHOU WULIANG)

Birth Date: 09 Apr 1979
Issue Date: 24 Feb 2015

002388872C

SG 50

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S79105131**



ERIC CHEW BOO LEONG
(ERIC ZHOU WULIANG)
周武良

Race: CHINESE
Date of Birth: 09-04-1979
Country of Birth: SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

	EFFECTIVE DATE
Class 1: Motor cars < 3500kg, with or without trailer, 4 or fewer seats	17 Nov 2007
Class 2: Motor cars < 3500kg, with or without trailer, 5 or more seats	01 Jul 2017

S / No. 9000271356



3911092



NRIC No: **S79105131**



Date of issue: 10-07-2006

APT BLK 310C PUNGGOL WAY #02-885
SINGAPORE 823318

NRIC No: **S79105131** Issue: 07/06/2015

MOTORICARZ GARAGE

53 Ubi Avenue 1#01-19 Paya Ubi Industrial Park Singapore 408934

Tel: 6844 4290 Fax: 6841 6043 Email: motoricarzgarage@gmail.com

Kaman Koh: 9769 9299

UEN: 53188526K

Estimate

2VW430026863

TP Chim
Deviser

Vehicle: SLU6300S

Make & Model: TOYOTA PRIUS ALPHA

Signature:

No	Particular	Qty	Amount (\$)
<u>List Price</u>			
1	FRONT HEADLANP RH <i>Cashed</i>	1PC	1600.00
2	FRONT FENDER RH <i>Pistard</i>	1PC	585.00
3	FRONT FENDER RIM GANISH RH <i>Dehd</i>	1PC	168.00
4	FRONT BUMPER <i>Dehd</i>	1PC	793.00
5	FRONT BUMPER FOG LAMP RH <i>Not new</i>	1PC	322.00
6	FRONT ABSOBER <i>Best.</i>	1PC	655.00
7	NAKAL BEARING <i>Best</i>	1PC	776.00
8	STEERING RACK ASSY <i>new</i>	1PC	1,300.00
9	DRIVE SHAFT <i>new</i>	1PC	980.00
10	LOWER ARM <i>Best</i>	1PC	422.00
11	LOWER ARM BALL JOINT <i>new</i>	1PC	165.00
12	BUMPER RETAINER RH <i>new</i>	1PC	85.00
13	wiper tank <i>#185</i> Total		7,213.00
	Less 25%		(1,803.25)
	Sub-Total cost for parts		5,409.75
<u>Part Replacement - Special</u>			
<u>Nett Item</u>			
1	FRONT RIM RH <i>lot</i>	1PC	550.00
2	FRONT TYRES RH <i>not on</i>	1PC	280.00
3	FRONT BUMPER CLIP <i>new</i>	1PC	28.00
4	FRONT RIM GANISH CLIP <i>new</i>	1PC	28.00
	Sub-Total cost for parts		886.00
<u>Labour & MISC Charges</u>			
1	TOWING FOR ACCIDENT VEHICLE TO WORKSHOP		150.00
2	TO REMOVE AND REFIX UNDERCARRIAGE		450.00
3	REMOVE, REFIX, PANEL BEAT AND etc..TO ACCIDENT AREAS		800.00
4	SPRAY PAINTING TO ACCISENT AREAS		800.00
5	WHEEL ALIGNAMNT		80.00
	Sub-Total Labour		2,280.00
	Grand Total		8,575.75

total: 5184
h/s: A.11C
#

Adrian Lim
h/s 28/09/18. 05 days.



Chassis Measurement Chart

Subsidiary/Branch-Company no.

Customer:

C&Y AUTO PTE LTD
53 UBI AVE 1 #01-28 PAYA UBI INDUSTRIAL PARK
S'PORE 408934

MOTORICARZ

Vehicle ident. no.

Repair order no.

Measurement made Name

Date:

WEI KEN

28/09/2018

Reg. N.:

First registration:

Type

Mileage:Km/miles

SLU 6300 S

TOYOTA PRIUS ZVW40 (AL 2011 - 2015 (33541)

km

Complaint or reason for measurement

Tyres:make

Description

Mileage:Km/miles

		front LH	front RH	rear LH	rear RH
Pressure measured (cold) bar/psi/kPa		2.3	2.3	2.3	2.3
	external				
Tread depth (mm)	centre				
	internal				
		Before correction		After correction	
Vehicle level					
REAR AXLE	Camber +/- (°)	LH	-01.66°	-01.42° / +00.50°-00.50°	-01.66°
		RH	-01.54°	-01.42° / +00.50°-00.50°	-01.54°
	total		+00.00°	+00.17° / +00.25°-00.25°	+00.00°
	Toe +/- (°)	LH	+00.38° *	+00.09° / +00.12°-00.12°	+00.38° *
		RH	-00.38° *	+00.09° / +00.12°-00.12°	-00.38° *
	Thrust angle		+00.38°		+00.38°
FRONT AXLE	Camber +/- (°)	LH	+00.11°	-00.17° / +00.75°-00.75°	+00.12°
		RH	-02.42° *	-00.17° / +00.75°-00.75°	-02.43° *
	Caster (°)	LH		+05.92° / +00.75°-00.75°	
		RH		+05.92° / +00.75°-00.75°	
	Lh steering lock lh wheel 20°				
	Rh steering lock rh wheel 20°				
	Set Back		-00.34°		-00.34°
	total		+03.50° *	+00.17° / +00.17°-00.17°	+03.53° *
Toe +/- (°)	LH		-00.06° *	+00.09° / +00.09°-00.09°	-00.03° *
	RH		+03.56° *	+00.09° / +00.09°-00.09°	+03.56° *
	Maximum steering angle on wheel side on inside of bend (°)	LH			
		RH			

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2018		28 Sep 2018 13:54 Edit Adj Rpt	S\$4,100.00 Edit Estimates	S\$4,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	GOH NAI EE, ID: S7822652H								
Main Claimant:	GOH JIA YING, ID: S79105131								
Vehicle Reg. No.:	SLU6300S	Date of Loss:	27/09/2018 07:00 - :59 [10 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04653C02	Policy/Cover Note No.:	DMPCSN1342491704 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKF3917Z	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Motorcarz Garage (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK, 408934 Paya Lebar - Tel: 68415383								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 09/10/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN ADRIAN LING AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLU6300S (SNM18D04653C02)
[SKF3917Z]
TP
GOH JIA YING
Sep 27 2018 7:00AM
[GOH NAI EE]
Motoricarz Garage

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 16:00	Accident Statement	Load HTML	
Photos/Images			3 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
2	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
3	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
4	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
5	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
6	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
7	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
8	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
9	27/09/18 15:57	Accident Photo [Linked Accident Report Documents]	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 09:27	General View	Load JPG	☒
2	25/10/18 09:27	General View	Load JPG	☒
3	25/10/18 09:27	General View	Load JPG	☒
4	25/10/18 09:27	General View	Load JPG	☒
5	25/10/18 09:27	General View	Load JPG	☒
6	25/10/18 09:27	General View	Load JPG	☒
7	25/10/18 09:27	General View	Load JPG	☒
8	25/10/18 09:27	General View	Load JPG	☒
9	25/10/18 09:27	General View	Load JPG	☒
10	25/10/18 09:27	General View	Load JPG	☒
11	25/10/18 09:27	General View	Load JPG	☒
12	25/10/18 09:27	General View	Load JPG	☒
13	25/10/18 09:27	General View	Load JPG	☒
14	25/10/18 09:27	General View	Load JPG	☒
15	25/10/18 09:27	General View	Load JPG	☒
16	25/10/18 09:27	General View	Load JPG	☒
17	25/10/18 09:27	General View	Load JPG	☒
18	25/10/18 09:27	General View	Load JPG	☒
19	25/10/18 09:27	General View	Load JPG	☒
20	25/10/18 09:27	General View	Load JPG	☒
21	25/10/18 09:27	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
22	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
23	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
24	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
25	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
26	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
27	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
28	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
29	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
30	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
31	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
32	25/10/18 09:27	Reinspection Photo	 Load JPG	☒
33	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
34	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
35	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
36	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
37	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
38	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
39	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
40	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
41	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
42	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
43	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
44	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
45	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
46	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
47	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
48	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
49	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
50	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
51	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
52	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
53	25/10/18 09:28	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/09/18 13:53	PRS	 Load PDF	
2	28/09/18 13:53	TP GIA	 Load PDF	
3	28/09/18 13:54	OI GIA	 Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 15:56	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	27/09/18 15:57	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
3	27/09/18 15:57	Identification Card [Linked Accident Report Documents]	 Load JPG	☒
4	27/09/18 15:57	Driving Licence [Linked Accident Report Documents]	 Load JPG	☒

Linked Accident Report Documents

View

Assessment Reports			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 16:00	Accident Statement	 Load HTM	

Assessment Reports			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
Photos/Images			3 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 15:57	Accident Photo	 Load JPG	☒
2	27/09/18 15:57	Accident Photo	 Load JPG	☒
3	27/09/18 15:57	Accident Photo	 Load JPG	☒
4	27/09/18 15:57	Accident Photo	 Load JPG	☒
5	27/09/18 15:57	Accident Photo	 Load JPG	☒
6	27/09/18 15:57	Accident Photo	 Load JPG	☒
7	27/09/18 15:57	Accident Photo	 Load JPG	☒
8	27/09/18 15:57	Accident Photo	 Load JPG	☒
9	27/09/18 15:57	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	27/09/18 15:56	Accident Sketch Plan	 Load JPG	☒
2	27/09/18 15:57	Accident Sketch Plan	 Load JPG	☒
3	27/09/18 15:57	Identification Card	 Load JPG	☒
4	27/09/18 15:57	Driving Licence	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18017670/ATD3Q2

Date: 26/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1342491704
Claimant Vehicle No :	SLU6300S	Insured Vehicle No :	SKF3917Z
Date of Loss:	27/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04653C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU6300S	Engine No:	2ZR0A12992
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	ZVW400026863
Reg. Date:	24/11/2017 (Man. Year: 2017)	Odometer:	40923 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,913.00	4,084.00	2,829.00	40.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,280.00	1,100.00	1,180.00	51.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,193.00	5,184.00	4,009.00	43.61
Approved Total (Overridden) (S\$)		4,100.00		
Nett Amount (S\$)	9,193.00	4,100.00	5,093.00	55.40

INSPECTION

Date of Assignment:	28/09/2018	
Date Inspected:	28/09/2018 Inspected At:	Motoricarz Garage (HQ) 53 UBI AVENUE 1, #01-19 PAYA UBI INDUSTRIAL PARK Singapore 408934
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 26 Oct 2018)	
Parts: 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLU6300S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP RH	Cracked	1,600.00 FL	*1,600.00 FL
2	1		*FRONT FENDER RH	Distorted	585.00 FL	*585.00 FL
3	1		*FRONT FENDER RIM GARNISH RH	Deformed	168.00 FL	*168.00 FL
4	1		*FRONT BUMPER	Deformed	793.00 FL	*793.00 FL
5	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	322.00 FL	*- FL
6	1		*FRONT ABSORBER	Bent	655.00 FL	*450.00 FL
7	1		*KNUCKLE ARM	Bent	776.00 FL	*520.00 FL
8	1		*STEERING RACK ASSY	Not Necessary	1,300.00 FL	*- FL
9	1		*DRIVE SHAFT	Not Necessary	980.00 FL	*- FL
10	1		*LOWER ARM	Bent	422.00 FL	*422.00 FL
11	1		*LOWER ARM BALL JOINT	Not Necessary	165.00 FL	*- FL
12	1		*BUMPER RETAINER RH	Necessary	85.00 FL	*85.00 FL
13	1		*WIPER TANK	Deformed	185.00 FL	*185.00 FL
14	1		*FRONT RIM RH	Cut	550.00 FS	*450.00 FS
15	1		*FRONT TYRES RH	Not Necessary	280.00 FS	*- FS
16	1		*FRONT BUMPER CLIP	Necessary	28.00 FS	*28.00 FS
17	1		*FRONT RIM GANISH CLIP	Not Necessary	28.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc

Sub Total (\$\$)	8,922.00	5,286.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,009.00	1,202.00
Total Parts (\$\$)	6,913.00	4,084.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FOR ACCIDENT VEHICLE TO WORKSHOP	New	150.00	0.00
2	TO REMOVE AND REFIX UNDERCARRIAGE	New	450.00	220.00
3	REMOVE ,REFIX ,PANEL BEAT AND ETC .TO ACCIDENT AREAS	New	800.00	400.00
4	SPRAY PAINTING TO ACCIDENT AREAS	New	800.00	400.00
5	WHEEL ALIGNMENT	New	80.00	80.00
Gross Labour Cost (\$\$)			2,280.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >