

22/03/2002

ASS. REC. BY:

REF:

CS3/AIG18017673/Ccd302

Special Instruction:

Survivor:

Meimien

Guo Qiong

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

28/9/18 @ 1:51pm

Estimated Cost:

Bill to:

OD/TP-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 9111R

Insured:

SDP 33317

at Workshop m/s

Self Motor

Tel:

9859 9677 / 9126 9987

of

No. 24 Defu Lane 12

Policy No:

2100452044

Claim No:

432333645186

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/09/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

1:58pm @ 28/9/18

Person Contacted:

Jonathan

Vehicle:

IN/OUT

Date/Time

Action/Instruction

(x)

Estimate

SLW 9111R - X

SDP 33317 - X

Dismantle: 1/10/2018

(08/11/15)

REF:

ALG

8909E

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Sat Motor.

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt.: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLW9111R Yr Regn: 25 Oct 2007Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1998Colour: Red A/C: Insured / Std / NI / NASp. Reading: 207654 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FD 21203103Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 225/40R18R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 28 Oct - 18Survey held at w/s 3 pmDes. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/10

~~\$7000 - \$8000~~
Submit DAR report.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Report Format: DAR

Lump Sum / I.B.I. (\$) _____




180

20

200

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 28/9/2018 1:51:20 PM

Attachments:  [GIA REPORT - SLW9111R.PDF](#)  [PRS Letter to AIG 27092018.pdf](#)
 [2nd PRS Letter to AIG 28092018.pdf](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Satwant Singh
Pritani Singh
Khong Zi-Wei



CONVEYANCING OFFICE:
450 Lorong 6 Toa Payoh
#02-03 Harsing Centre
Singapore 319394
Tel: 6221 6114
Fax: 6266 6925
www.satwantlaw.com.sg
(Fax not for service
of documents)

An Official Member of The Lawyer Network, an international network of law firms

(Please quote our Ref. when replying)

Your Ref: To be advised
Our Ref: PD/DL/1801706 (ml) – Toa Payoh Office
(margaretlim@satwantlaw.com.sg)
28 September 2018

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#07-16 AIG Building
Singapore 079120

BY EMAIL ONLY

Attention: Motor Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING SLW9111R & SDP3331T ALONG FARRER ROAD TOWARDS QUEENSWAY ON 26/09/2018 @ 09:00

We refer to your email dated 28 September 2018 confirming your intention to conduct a pre-repair survey on our client's vehicle SLW9111R.

Please be informed that said vehicle can be inspected at:

Workshop name: Sat Motors
Address: No. 24 Defu Lane 12 Singapore 539131
Contact Person: Jessie (HP: 9859 9677), Jonathan (HP: 9126 9987)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

SATWANT & ASSOCIATES

cc client

For Surveyor: To initial after Completion

1st Inspection
Appointed surveyor
(Name & Signature)

Date & Time

2nd Inspection
Appointed surveyor
(Name & Signature)

Date & Time

3rd Inspection
Appointed surveyor
(Name & Signature)

Date & Time

NB: Any Settlement of offer is on the express condition that this settlement is in respect of our client's claim for property related damaged only and shall not preclude our client from claiming injury-related damages arising from this accident.
This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8909E
Vehicle Details	
Vehicle No.:	SLW9111R
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC TYPE-R 2.0 M
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	K20A5803195
Chassis No.:	FD21203103
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$28,681.00
Original Registration Date:	25 Oct 2007
First Registration Date:	25 Oct 2007
Transfer Count:	4
Actual ARF Paid:	\$31,550.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 Oct 2027
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$50,451.00
COE Rebate Amount:	\$45,717.00
Total Rebate Amount:	\$45,717.00

The information contained herein is correct as at 01 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/09/2018 14:32
Date Of Accident	26/09/2018 09:00
Exact Location Of Accident	ALONG FARRER ROAD TOWARDS QUEENSWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW9111R
Insured/Policyholder	
Name Of Registered Owner	TOH CHWEE IMM
NRIC No	S1468909E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96515238
Alternative Phone No	OTHERS-96515238

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC TYPE R
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA281612
Cover Note Number	

Driver

Name of Driver	NG HONG BIN
NRIC No	S8734719B
Date Of Birth	27/10/1987
Occupation	INDOOR
Date Of Driving Pass	31/08/2007
Driving Experience	11 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96515238
Fax Number	
Contact Number	
EMail Address	BEN.NG@HALAUTO.COM.SG

Address	BLK 810 YISHUN RING ROAD #12-4185
Postcode	760810
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDP3331T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHB5353T

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

NG HONG BIN

Approximate Age

Injuries Sustain

BACK & NECK PAIN

Injured person in which vehicle?

SLW9111R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN

ALONG FARRER ROAD

A: SLW9111R
B: SDP3331T
C: SHB5353T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG FARRER ROAD TOWARDS QUEENSWAY WHEN TRAFFIC IN FRONT OF ME SLOWED DOWN. WHEN VEHICLE B SDP3331T REAR-ENDED MY CAR AND I FELT A HUGE IMPACT CAUSING MY VEHICLE TO MOVE AND COLLIDED WITH THE FRONT VEHICLE C SHB5353T. I SUFFER NECK & BACK PAIN AND WILL SEEK MEDICAL ATTENTION.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

MOTOR CAR (Frt)

Front Portion

Vehicle No: SLW-9111R

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BR ✓		
1002	991887	Frt Number Plate Base	BR ✓		
1003	991889	Frt Number Plate Garnish	BR ✓		
1004	991300	Frt Bumper	CRA ✓		
1005	992341	Frt Bumper Clips	NEC ✓		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS ✓		
1008	991433	Frt Bumper Reinforcement	DD ✓		
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CRA ✓		
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille lower	CUT ✓		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	BR ✓		
1022	991328	Frt Grille Emblem	SCR ✓		
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel	BT ✓		
1026	992025	Frt Support Panel Top Garnish Cover	DL ✓		
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA ✓		
1030	991821	Frt RH Headlamp Assy	CRA ✓		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet	BT ✓		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser	DD ✓		
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

MOTORCAR (Rear)

282

Vehicle No: SLW 9111R

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	BR	✓	
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket LH	BR	✓	1
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	CUT	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	BR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DT	✓	
1171	991328	Bootlid Emblem	NEC	✓	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding / Trim	DL	✓	
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	BR	✓	
1176	992899	Bootlid Lamp RH	BR	✓	
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber	CUT	✓	
1179	990382	Bootlid Hinge LH / RH	BT	✓	2
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board	?		
1203	994328	Spare Tyre Panel	?		
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	DD	✓	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish	DL	✓	
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: 20

Assessor: ..

TGLim
3/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2018 Edit Reg		28 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LOW SIOW KHEE (LIU SHAOQI), ID: S7210244D		
Main Claimant:	-		
Vehicle Reg. No.:	SLW9111R	Date of Loss:	26/09/2018 00:00 - :59 [131 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4323336451SG	Policy/Cover Note No.:	2100452044 (Comprehensive) Coverage: 16/02/2018 - 15/02/2019
Vehicle Reg. No. (Insured):	SDP3331T	Policy No. (Claimant):	
		Excess:	
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/10/2018]		
Claimant's Solicitor:	SATWANT & ASSOCIATES - Tel: 62216114		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (01/10/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






































Claim Documents
















































***SLW9111R (4323336451SG)
[SDP3331T]**

TP

-

**Sep 26 2018 12:00AM
[LOW SIOU KHEE (LIU SHAOQI)]
Sat Motors**

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images										3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print	
1	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
2	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
3	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
4	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
5	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
6	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
7	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
8	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
9	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
10	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
11	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
12	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
13	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
14	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
15	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
16	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
17	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
18	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
19	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
20	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
21	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
22	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
23	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
24	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
25	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
26	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
27	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
28	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
29	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
30	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
31	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
32	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
33	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
34	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
35	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
36	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	
37	02/10/18 12:06	General View									Load JPG	<input checked="" type="checkbox"/>	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
39	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
40	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
41	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
42	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
43	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
44	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
45	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
46	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
47	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
48	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
49	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
50	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
51	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
52	02/10/18 12:06	General View		Load JPG	<input checked="" type="checkbox"/>
53	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
54	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
55	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
56	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
57	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
58	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
59	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
60	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
61	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
62	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
63	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
64	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
65	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
66	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
67	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
68	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
69	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
70	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
71	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
72	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
73	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
74	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
75	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
76	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
77	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
78	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
79	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
80	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
81	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
82	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
83	02/10/18 12:09	Photographs of Damaged Parts		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	01/10/18 09:47	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18017673/GCD3E2

Date: 04/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100452044

Claimant Vehicle No : SLW9111R

Insured Vehicle No : SDP3331T

Date of Loss: 26/09/2018

Nature of Claim: TP

Claim No: 4323336451SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW9111R

Make & Model: HONDA CIVIC, 2.0 TYPE-R (M)

Engine No: K20A5803195

Reg. Date: 25/10/2007 (Man. Year: 2007)

Chassis No: FD21203103

Colour: Red

Odometer: 207654 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/09/2018

Date Inspected: 28/09/2018

 Inspected At: Sat Motors (HQ)
 24 Defu Lane 12
 Singapore 539131

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Broken	0.00 F	*- F
2	1		*FRT NUMBER PLATE BASE	Broken	0.00 F	*- F
3	1		*FRT NUMBER PLATE GARNISH	Broken	0.00 F	*- F
4	1		*FRT BUMPER	Cracked	0.00 F	*- F
5	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
7	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
8	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
9	1		*FRT BUMPER GRILLE LOWER	Cut	0.00 F	*- F
10	1		*FRT GRILLE	Broken	0.00 F	*- F
11	1		*FRT GRILLE EMBLEM	Scratched	0.00 F	*- F
12	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F
13	1		*FRT SUPPORT PANEL TOP GARNISH COVER	Dislodged	0.00 F	*- F
14	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
16	1		*BONNET	Bent	0.00 F	*- F
17	1		*AIR CON CONDENSER	Dented	0.00 F	*- F
18	1		*REAR BUMPER	Broken	0.00 F	*- F
19	1		*REAR BUMPER LOWER	Broken	0.00 F	*- F
20	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
21	1		*REAR BUMPER BRACKET LH	Broken	0.00 F	*- F
22	1		*REVERSE SENSOR	Cut	0.00 F	*- F
23	1		*REAR END PANEL	Dented	0.00 F	*- F
24	1		*REAR END PANEL TOP GARNISH	Dislodged	0.00 F	*- F
25	1		*REAR RH TAILLAMP	Broken	0.00 F	*- F
26	1		*BOOTLID	Dented	0.00 F	*- F
27	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
28	1		*BOOTLID MOULDING / TRIM	Dislodged	0.00 F	*- F
29	1		*BOOTLID LAMP LH	Broken	0.00 F	*- F
30	1		*BOOTLID LAMP RH	Broken	0.00 F	*- F
31	1		*BOOTLID LOCK	Bent	0.00 F	*- F
32	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
33	2		*BOOTLID HINGE LH / RH	Bent	0.00 F	*- F
34	1		*SPARE TYRE BOARD	* Check	0.00 F	*- F
35	1		*SPARE TYRE PANEL	* Check	0.00 F	*- F
36	1		*REAR LH FENDER	Dented	0.00 F	*- F
37	1		*REAR LH FENDER INNER GARNISH	Dislodged	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)	0.00	0.00
---------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >