

ASS. REC. BY:

REF: CS3/AIG18017674/Gcd3ST

Special Instruction:

Surveyor: Quo Chong
Memmen

ASSIGNMENT (Office)

From (Person): Chin Lee Ying

of AIG

Date/Time: 28/9/18 @ 10:03am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLX 5636P

Insured: SKR1567A

at Workshop m/s: Green Star Spray

Tel: 6546 3092

of Blk 3011 Bedok north ave 4 #01-2004

Policy No: 0999994579

Claim No: 752032694486

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 22/09/18

CA / REV / REP. / REV 24 HRS 'up

H.O.D. Endorsement:

Date/Time: 10:39am @ 28/9/18

Person Contacted: Debbie

Vehicle IN OUT

Date/Time	Action/Instruction (x) Estimate
	SLX 5636P - X
	SKR1567A - X
	Dismantle: 28/9/2018

PR5
Ked

REF: AL6

2521A /
(-2028)

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s Green Star
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLX5636P Yr Regn: 08 Apr 2008
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Honda Civic Tyre-R 1998
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 142783 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: FD 21402561
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 225/45 R17
R: _____

(Policy Condition)
Remark: **The veh had commenced its repair at the time of inspection.**



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Bal. or Market Value: _____
IDAC Accident Rpt.: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 4 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. _____ D.O.I. 28-09-18
Survey held at w/s 1pm

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>4/10</u>	\$2500 - \$3500 <u>Submit DAR report.</u>

Date/Time, File Pass to? : Preli. Report
1) : Final Report
Date/Time, File Return to?
2) _____
Report Format : DAR
Lump Sum / I.B.I: (\$) _____

Days Of Repair: 4
Resurvey No. of Trip: 1
Survey Fee: _____
Transportation: _____
Add Fee: Site Insp (\$ _____)) S + RS \$
 Interview (\$ _____)) Photos
 Tech. Invs (\$ _____)) Others
 Weekend (\$ _____))
TOTAL _____

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 28/9/2018 10:03:18 AM
Attachments:  tmp2A60.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/09/2018 15:06
Date Of Accident	22/09/2018 13:10
Exact Location Of Accident	ALONG CAUSEWAY BRIDGE AFTER JB CUSTOMS TWDS S'PORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX5636P
Insured/Policyholder	
Name Of Registered Owner	JAI NARAYAN RAI
NRIC No	S1452521A
Email Address	JNRAI98@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97639245
Alternative Phone No	OFFICE-97639245

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC TYPE-R 2.0 M
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA384524
Cover Note Number	06/08/2018/06/08/2018

Driver

Name of Driver	RAHUL RAI
NRIC No	S9313325J
Date Of Birth	20/04/1993
Occupation	INDOOR
Date Of Driving Pass	18/10/2012
Driving Experience	5 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96807576
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	336 TAMPINES ST 32 04-484
Postcode	520336
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : JAI NARAYAN RAI GENDER: : MALE
Passenger 2	NAME: : SAVITRI DEVI GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer to sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR1567A
Vehicle Make/Model/Colour	CHEVROLET CRUZE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ABDUL HAMID BIN MOHAMED SALLEH
NRIC/Passport Number	S13091911
Contact Number	83716900
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: Sahlan
 NRIC/FIN No.:

SKETCH PLAN

A: SLX 5636P

B: SKR 1567A



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At about 1310 HRS I was driving along the causeway bridge towards Woodlands checkpoint from Jinar Customs. My car was stationary when vehicle SKR 1567A hit the rear of my car.

You had been advised by workshop that in the event that you wish to claim against your own policy (OD claim), there is a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence.

Reporting Only
<input type="checkbox"/> Claim OD
<input checked="" type="checkbox"/> Claim TP
Claim OD / TP at other workshop

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature:
Date & Time:

Driver's Signature:
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature:
Name:
NRC/FIN No.:



redefining

Date: 22/11/15

To: Owner of vehicle Number: SLX 503HX

The following sign is used to add to your workshop staff: [Signature]



through this

Please tick the applicable box if you had been advised by the workshop as listed below:

You had been advised by the workshop that in the case that you wish to claim against your own policy there is a fourteen (14) days clause whereby the claim must be made within the stipulated time frame from the day of occurrence.

You had been advised by the workshop on the liability and extent of the case accordingly.

You had been advised by the workshop on the claim procedure for the type of claim that you will be making due to this accident.

There will be delay to your vehicle repair due to the unavailability of spare parts locally and there is no other option except to import it from overseas.

There will be no cancellation/withdrawal of the Own Damage claim once the order of the spare parts have been placed. If you wish to cancel/withdraw the claim, you shall bear all costs, expenses &/or related charges incurred directly &/or indirectly to the procurement of the spare parts.

The estimated waiting time for the spare parts to arrive is _____ The estimated arrival time does not include the repair period.

You will be driving the vehicle out despite being advised by the workshop mechanic/personnel that the vehicle may not be road worthy.

For vehicles below Three (3) years old, your Insurance Company will use only genuine original parts to repair your vehicle.

For vehicles above Three (3) years old, your Insurance Company will be carrying out repairs using **any combination** of genuine original parts and/or original equipment manufacturer (OEM) parts.

You had been advised by the workshop of the Twelve (12) months warranty for Own Damage repairs on workmanship related to the accident.

For vehicles that are under warranty with a local distributor, you have been advised by the workshop to check with your local distributor on any effect to your warranty prior to making this Own Damage claim.

Other: Claim 3rd Party

Signed and acknowledged by:

[Signature]

Name and signature of policyholder/authorised driver

[Signature]

Name and signature of workshop personnel including company stamp



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2521A
Vehicle Details	
Vehicle No.:	SLX5636P
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC TYPE-R 2.0 M
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	K20A5822647
Chassis No.:	FD21402561
Maximum Power Output:	165.0 kW (221 bhp)
Open Market Value:	\$27,666.00
Original Registration Date:	08 Apr 2008
First Registration Date:	08 Apr 2008
Transfer Count:	4
Actual ARF Paid:	\$30,433.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Apr 2028
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$40,881.00
COE Rebate Amount:	\$38,905.00
Total Rebate Amount:	\$38,905.00

The information contained herein is correct as at 01 Oct 2018

OK

(1) Deformed (02) Shifted (03) Buckled (16) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (X)

Vehicle No: SLX 5636 P

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CRA ✓		
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	CRT ✓		
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC ✓		
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS ✓		
1149	993045	Rear Bumper Reinforcement			
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM ✓		
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish	CRA ✓		
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA ✓		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CRA ✓		
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR R ✓		
1171	991328	Bootlid Emblem	NEC ✓		
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1195	990247	Sticker			

No of Items: 5

Assessor: _____

TGim

lin

2/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Sep 2018 Edit Reg		28 Sep 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	NEO R & R PTE LTD , Co. Reg. No.: -		
Main Claimant:	JAI NARAYAN RAI , ID: S1452521A		
Vehicle Reg. No.:	SLX5636P	Date of Loss:	22/09/2018 00:00 - :59 [125 Months and 14 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7520326944SG	Policy/Cover Note No.:	0999994579
Vehicle Reg. No. (Insured):	SKR1567A	Policy No. (Claimant):	
		Excess:	
Repairer:	GREEN STAR SPRAY PAINTING (HQ) BLK 3011 BEDOK NORTH AVENUE 4 #01-2004 BEDOK INDUSTRIAL PARK E, 489977 Bedok - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/10/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (01/10/2018): No OI GIA Report (SKR1567A VS SLX5636P)
- AIG_SG (01/10/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents












***SLX5636P (7520326944SG)
[SKR1567A]**

TP

**JAI NARAYAN RAI
Sep 22 2018 12:00AM
[NEO R & R PTE LTD]**

GREEN STAR SPRAY PAINTING

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
2	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
3	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
4	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
5	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
6	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
7	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
8	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
9	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
10	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
11	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
12	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
13	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
14	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
15	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
16	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
17	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
18	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
19	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
20	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
21	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
22	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
23	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
24	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
25	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
26	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
27	02/10/18 11:49	General View	Load JPG	<input checked="" type="checkbox"/>
28	02/10/18 11:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	02/10/18 11:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	02/10/18 11:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	02/10/18 11:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
32	02/10/18 11:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
33	02/10/18 11:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
34	02/10/18 11:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	02/10/18 11:50	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	02/10/18 11:50	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18017674/GCD3S2
Date: 04/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994579
Claimant Vehicle No : SLX5636P **Insured Vehicle No :** SKR1567A
 Date of Loss: 22/09/2018 Nature of Claim: TP Claim No: 7520326944SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX5636P**
 Make & Model: HONDA CIVIC, 2.0 TYPE-R (M) Engine No: K20A5822647
 Reg. Date: 08/04/2008 (Man. Year: 2008) Chassis No: FD21402561
 Colour: White Odometer: 142783 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/09/2018
 Date Inspected: 28/09/2018 Inspected At: GREEN STAR SPRAY PAINTING (HQ)
 BLK 3011 BEDOK NORTH AVENUE 4 #01-2004
 BEDOK INDUSTRIAL PARK E
 Singapore 489977
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	1		*REAR BUMPER LOWER	Cut	0.00 F	*- F
3	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
6	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
7	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
8	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
9	1		*BOOTLID	Repair	0.00 F	*- F
10	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >