

22/03/2003

ASS. REC. BY:

REF: CS3/MSG18017686/RICd307 Special Instruction:

Surveyor:

Meimien

From (Person):

Rasul
Monica Chung

ASSIGNMENT (Office)

MSG

Date/Time:

28/9/18 @ 3:34pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGW 4814M

Insured:

YN 6698C

at Workshop m/s

Motor Intel

Tel:

88383318

of

13 kaki BK Rd 4 # 01-20

Policy No:

B28627779MKC

Claim No:

571600

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/09/2018

CA / REV / REP. / REV 24 HRS

lup

01/10/18

H.O.D. Endorsement:

Date/Time:

5:40pm @ 28/9/18

Person Contacted:

wilson

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SGW 4814M - CC6/AXA11013519/Un3b3q2 DOA: 10/7/2011

YN 6698C - NA1INC16006735/K4

DOA: 12/4/16

Dismantle: 2/10/2018

Surveyor

Ram

REF: MSIG

ASSIGNMENT

From: Date: 01/10/2018

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGW 4814M

at Workshop m/s

Motor Intel

of 13 kaki Bkt Rd 4 #01-20

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SGW 4814M Yr Regn: Jul / 07

Type: (C) M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic

C.C. 1799

Colour: WHITE

A/C: Insured / Std / NI / NA

Sp. Reading: 136994

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMF0163075218426

Gen. Cond: Good / (C) Fair / Poor / Burnt

Steering: (C) Inorder / Jammed / Leaked / Burnt or

Brake: (C) Inorder / Jammed / Leaked / Burnt or

Modi: Nil / (C) Rim / STD A/Rim or

Tyre Size: F: 215/45R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 01/10/18

Survey held at

Des. of Damages: (C) Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 4,000/- - 5,000/-

RECEIVED 09 OCT 2018

[Signature]
8/10/2018

TGim
5/10/18

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: PRG

Lump Sum / I.B.I: (\$)

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2018		28 Sep 2018 15:34 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HUPCO PTE LTD, Co. Reg. No.: 199206471G		
Main Claimant:	MUHAMMAD FAIZAL S/O MAIDEEN MEETHIN, ID: S9130427I		
Vehicle Reg. No.:	SGW4814M	Date of Loss:	26/09/2018 17:00 - :59 [134 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 571600	Policy/Cover Note No.:	B28627779MKC (Comprehensive) Coverage: 23/10/2017 - 22/10/2018
Vehicle Reg. No. (Insured):	YN6698C	Policy No. (Claimant):	
		Excess:	
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/09/2018]		
Driver/Custodian (Insured):	AW SENG CHAI (58 / Male), NRIC: S1426836G, Tel: +6598470780		
Adj Asg. Remarks:	LIAB 100%. SJE DISAGREE APPOINT LKK. PLS CONTACT WILSON / TINIE @ 8838 3318 / 6281 0087		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SGW4814M		
Vehicle Type :	P10 - Passenger Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HONDA		
Vehicle Model :	CIVIC 1.8L A		
Chassis No. :	JHMFD16307S218426		
Propellant :	Petrol		
Engine No. :	R18A12039431		
Engine Capacity :	1799 cc		
Maximum Power Output :	103.0 kW (138 bhp)		
Maximum Laden Weight :	1640 kg		
Unladen Weight :	1219 kg		
Year Of Manufacture :	2007		
Original Registration Date :	20 Jul 2007		
Lifespan Expiry Date :	-		
COE Category :	B - Car (1601cc & above)		
PQP Paid :	\$26,237.00		
COE Expiry Date :	19 Jul 2022		
Road Tax Expiry Date :	19 Jan 2019		
Inspection Due Date :	19 Jul 2019		
Intended Transfer Date :	03 Oct 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0427I
Vehicle Details	
Vehicle No.:	SGW4814M
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	White
Manufacturing Year:	2007
Engine No.:	R18A12039431
Chassis No.:	JHMF16307S218426
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$19,453.00
Original Registration Date:	20 Jul 2007
First Registration Date:	20 Jul 2007
Transfer Count:	3
Actual ARF Paid:	\$21,399.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jul 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$26,237.00
COE Rebate Amount:	\$19,903.00
Total Rebate Amount:	\$19,903.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 03 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/09/2018 15:57
Date Of Accident	26/09/2018 17:15
Exact Location Of Accident	BLK 632 BEDOK RESERVOIR ROAD CP LOT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW4814M
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	MUHAMMAD FAIZAL S/O MAIDEEN MEETHIN
NRIC No	S9130427I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91164876
Alternative Phone No	OTHERS-91164876

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC 1.8L A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094002708-01
Cover Note Number	

Driver

Name of Driver	MUHAMMAD FAIZAL S/O MAIDEEN MEETHIN
NRIC No	S9130427I
Date Of Birth	02/09/1991
Occupation	INDOOR
Date Of Driving Pass	30/06/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91164876
Fax Number	
Contact Number	OTHERS-91164876
EMail Address	NOEMAIL

Address	BLK 44 #07-407 TEBAN GARDENS ROAD
Postcode	600044
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6698C
Vehicle Make/Model/Colour	MITSUBISHI CANTER FEB71ER4SDEC (CBU)
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 27.9.2018
1157h8

Driver's Signature


(If driver is not the policyholder)

Date & Time: 27.9.2018
1157h8

IDAC KAKI BUKIT(VAC)

23 KAKI BUKIT AVE 4
Reporting Centre Personnel's Signature
Name: Singapore 415933
Tel: 67416697
NRIC/FIN No: 67492305
Fax: 67492305
Email: vackb@singnet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car park at the car Park Lot 43 at Bedok Reservoir Car Park BLK 632 after my drink, I came back to my car I saw vehicle YN6698C Moving out from his car park lot and collided on to my front car portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 27.09.2018
1157hrs

Signature of Policyholder

Driver's Signature

(If driver is not the policyholder)
Date & Time: 27.09.2018
1157hrs

Signature of Driver

IDAC KAKI BUKIT(VAC)

23 KAKI BUKIT AVE 4

Singapore 415933
Reporting Centre/Personnel's Signature
Tel: 67416697

Name: Fax: 67492305

NRIC#IN No: Email: vackb@singnet.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Sep 2018		28 Sep 2018 15:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	HUPCO PTE LTD, Co. Reg. No.: 199206471G	
Main Claimant:	MUHAMMAD FAIZAL S/O MAIDEEN MEETHIN, ID: S91304271	
Vehicle Reg. No.:	SGW4814M	Date of Loss: 26/09/2018 17:00 - :59 [134 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 571600	Policy/Cover Note No.: B28627779MKC (Comprehensive) Coverage: 23/10/2017 - 22/10/2018
Vehicle Reg. No. (Insured):	YN6698C	Policy No. (Claimant):
		Excess:
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 29/09/2018]	
Driver/Custodian (Insured):	AW SENG CHAI (58 / Male), NRIC: S1426836G, Tel: +6598470780	
Adj Asg. Remarks:	LIAB 100%. SJE DISAGREE APPOINT LKK. PLS CONTACT WILSON / TINIE @ 8838 3318 / 6281 0087	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SGW4814M (571600)**

[YN6698C]



































TP





























MUHAMMAD FAIZAL S/O MAIDEEN MEETHIN

Sep 26 2018 5:00PM

[HUPCO PTE LTD]

Motor Intel Automo Pte Ltd - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/09/18 09:32	Accident Statement From: SC - Reg. No: YN6698C, Claimant: HUPCO PTE LTD	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
2	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
3	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
4	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
5	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
6	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
7	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
8	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
9	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
10	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
11	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
12	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
13	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
14	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
15	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
16	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
17	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
18	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
19	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
20	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
21	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
22	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
23	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
24	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
25	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
26	03/10/18 12:10	General View	 Load JPG	<input checked="" type="checkbox"/>
27	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
28	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
29	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
30	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
31	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	03/10/18 12:10	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/09/18 09:32	PRI From: SC - Reg. No: YN6698C, Claimant: HUPCO PTE LTD	 Load PDF	
2	28/09/18 09:32	Third Party Accident Report From: SC - Reg. No: YN6698C, Claimant: HUPCO PTE LTD	 Load PDF	
3	28/09/18 15:26	SJE DISAGREE APPOINT LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18017686/R1CD3E2

Date: 10/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28627779MKC

Claimant Vehicle No : SGW4814M

Insured Vehicle No : YN6698C

Date of Loss: 26/09/2018

Nature of Claim: TP

Claim No: 571600

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW4814M**

Make & Model: HONDA CIVIC, 1.8 (A)

Reg. Date: 20/07/2007 (Man. Year: 2007)

Colour: White

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: R18A12039431

Chassis No: JHMF16307S218426

Odometer: 136994 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 28/09/2018

Date Inspected: 01/10/2018 Inspected At:

Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000.00 -\$5,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 10 Oct 2018)
Parts: 143	HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGW4814M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >