

NATIONAL Assessment Centre Services

[wef: Jan'05]

Date In: 29/09/2018 15:23	Job description	Date & Time Completed	Done by
Ref No: NA/INC 18017704/K	SAS e-filing		
Veh No: GBE 7433 M	E-mail (within 8hrs, AIC 2hrs)		
D.O.A: 29/09/2018 00:05	i-Motor Claim Form	MT/1013604001	29/9/2018 15:57
OD: TP: Reporting Only	i-Motor W/O (Within: OD 2hrs, TP 4hrs)		
	i-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / QW: (	Tel:	Fax:
TP Particulars:	Veh No: JPV9292	INC () / Non-INC ()
Owner / Driver: (	Tel: ()	
Policy No: ()	Period: ()	Cover Type: ()
Confirmed by: (	Date:	Time:
Insured/Driver Liability: ()	[Note-Est. Status (WO): N: 0-20%; P: 21-79%; P: 80-100%]	
Year of Registration: ()	Warranty: YES () / NO ()	
Excess: (\$)	Loading: \$1,000 () / \$2,000 ()	

General Remarks:-

() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repalrer.

() Total Loss Case : to e-mail Insurer URGENTLY.

Drive-In () / Towed-In () ; Invoice: YES () / NO () ; Towing Co: ()

Remarks:- (INC hotline: 6788 6616)	Date & Time Completed	Done by
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo [Repair Cost > \$3000] ()		

Injury :

Date/Time	Actions
01/10/18 13:25	Driver came and Amended from TP to OD, vehicle is here but no key?
31/01/18 13:40	Have Email to 'OD support' to do assessments and waiting for reply. from [unclear]

NA1806351	Invoice Preparation Checklist	Amt (\$)	Amt (\$)
		Int Bill	Add Bill
Claimant's Particulars :-	1) AR: Accident Reporting (\$30);		
Driver/Owner:	2) DA: Damage Assessment (\$100); INC (\$30)		
Contact No:	3) TP: Towing Fee \$40/\$45		
Damaged Portion:	4) FT: Follow-Through Survey \$120		
QC Checked by (Engr-In-Charge):	5) FT: Follow-Through Survey (Resurvey) \$30		
Auditors' Comments :-	For claiming against INC Only (wef 10 Jan 2005)		
at 1:	6) TR: Re-inspection \$75		
at 2/3:	7) N1: Idao DA + SMRT Survey \$160		
	8) NTUC Additional Services:-		
	ON*		
	*N5: Courtesy Car / Tpt Allowance \$5		
	*N6: Repair Co-ordination \$10		
	*N7: Post Repair Inspection \$25		
	*N8: DV / Collect Excess Coordination \$5		
	TP (N11): TP (Non INC) against INC \$20		
	9) N12: Idao Mobile 30		
	Invoice dated	Fee Charged	
	Invoice dated	Fee Charged	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/09/2018 15:23
Date Of Accident	29/09/2018 00:05
Exact Location Of Accident	JUNCTION OF EUNOS ROAD 5 AND EUNOS AVENUE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE7433M
Insured/Policyholder	
Name Of Registered Owner	BLUEFLAME ENGINEERING PTE LTD
Co Reg No	199404136C
Email Address	ADMIN@BLUEFLAME.COM.SG
Mobile Phone No	(LOCAL) +65-96259508
Alternative Phone No	OFFICE-96259508

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088033644-01
Cover Note Number	

Driver

Name of Driver	SIM TA TJEH (SHEN DAZHI)
NRIC No	S7341362A
Date Of Birth	10/11/1973
Occupation	INDOOR
Date Of Driving Pass	23/02/1994
Driving Experience	24 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96259508
Fax Number	
Contact Number	OTHERS-96259508
Email Address	SIM_TT@YAHOO.COM.SG

Address	BLK 236 PASIR RIS STREET 21 #06-03
Postcode	510236
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	JPV9292 (COMMERCIAL VEHICLE)
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PASIR RIS NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 1 PASIR RIS DRIVE 4 , POSTCODE: 519457 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-5852999 - FAX NO: 65855261
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO POLICE REPORT T/20180929/2016 (TYPE OF COLLISION IS HEAD TO SIDE)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	JPV9292
Vehicle Make/Model/Colour	TOYOTA PICKUP
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CHOO KOK LEONG
NRIC/Passport Number	741125015045
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/TIN No:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Police report

Police 7/2016

DECLARATION

I/We declare that the following particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180929/2016

1 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No: T/20180929/2016

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/09/2018 02:57	Vide Report No.: G/20180929/0011	Station Diary No.: 10
--	-------------------------------------	--------------------------

Informant's Particulars

Name of Informant: SIM TA TJEH			Address: APT BLK 236 PASIR RIS STREET 21 #06-03 SINGAPORE 510236	
ID Type / ID No.: NRIC NO / S7341362A			Contact No.: Home/Office: Mobile: 96259508	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 44	Date of Birth: 10/11/1973	Type of Informant: Driver	
Race: Chinese			Language:	Institution / School Name:
Occupation: GAS PLUMBER			Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident

General Information of the Accident				
Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: Yes	Date/Time of Accident: 29/09/2018 00:00	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 EUNOS AVENUE 3 EUNOS ROAD 5				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE7433M	Van				Seriously Damaged	0
JPV9292	Lorry				Slightly Damaged	2

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180929/2016

2 of 3

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

Report No. T/20180929/2016

CONTINUATION OF REPORT

Driver			
Name	SIM TA TJEH	ID No.	S7341362A
Related Vehicle	GBE7433M (Van)	Contact No.	96259508
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	CHOO KOK LEONG	ID No.	741125015045
Related Vehicle	JPV9292 (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 29/09/2018 at about 1200 am, I was driving my vehicle at the said location on the single lane road and approached the said junction. Suddenly, while crossing the junction, I felt an impact on the front side portion of my vehicle. After the Impact, we both alighted from our vehicle and exchanged particulars and took photographs of the damage. I then called for the police and shortly after, the traffic police came. They then took a breathalyzer test on both of us and he failed the test. I was then informed to make a police report. There is in-car camera footage. However, there is no SD card in the camera. However, I managed to save the footage into the phone. Currently, the right front side portion of my vehicle is heavily dented and the door can only be opened slightly.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20180929/2016

Police Station Of Origin:
Pasir Ris N.P.C
1 Pasir Ris Drive 4 #01-01 SINGAPORE
519457
Tel No: 1800-5852999

3 of 3

Report No. T/20180929/2016

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
G /
Sgt 1 ISAAC LIM JUN CHENG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
29/09/2018 02:57

Officer In Charge Of Case:
TP / AEIT /
SI ANG YI TING, STEPHANIE
Contact No.: 65476414

Classification Of Case:

Authentication Stamp
NP168



ASSIGNMENT 1 (ID 50)

By: 1) Nature of Accident:

- 1) Vehicle hit Vehicle:
 - a) Pedestrian ☐
 - b) Motorcycle ☐
 - c) Bicycle ☐
- 2) Vehicle hit:
 - a) Pedestrian ☐
 - b) Animal ☐
- 3) Vehicle hit Road Side Object:
 - a) Green Property ☐
 - b) Road Work Object ☐
 - c) Private Property ☐
- 4) Vehicle drop into drain ☐
- 5) Damage due to Act of God:
 - a) Fallen Object ☐
 - b) Flood ☐
 - c) Other ☐
- 6) Parked & Found Damaged:
 - a) Vandalism ☐
 - b) Hit by Moving Object ☐
- 7) Theft Case:
 - a) Stolen ☐
 - b) Damaged found when recovered ☐
- 8) Fire:
 - a) Whilst driving ☐
 - b) Parked ☐
- 9) Accident date more than 24hrs ☐

By: 2) Vehicle Information:

Vehicle: **GBE7433M** / Date: **23 Mar 2016**
 Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 / Truck / Trailer: **NV350 Panel Van 2.5**
 Make & Model: **Nissan Urvan** / 2488
 Colour: **Black** / Transmission Type: Auto / Manual
 Engine: **43884**
 C/U: **JN1MC2E26Z0005121**
 Gett. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt /
 Brake: Good / Jammed / Leaked / Burnt /
 Mod: Nil / SRim / STD ARim /
 Tyre Size: F: **195/80R15**
 R: **195/80R15**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO
 Front: **7** mm / Rear: **8** mm
 R/Bal: **7** mm / L/Bal: **8** mm
 Parallel Import: Yes ☒ No
 Towed-In: Yes ☒ No
 Repair Type: LS / LB.I
 Towing Required: Yes ☒ No
 No of Repair Days: **10**
 Vehicle in Idar: Yes ☒ No
 D.O: **3/10/2018** / Time: **9.35am**

By Assessor- 2) Comments

1) Damages not due to recent accident.

2) Damages do not seem hit onto:

a) Vehicle ☐ b) Motorcycle ☐ c) Bicycle ☐ d) Pedestrian ☐

e) Animal ☐ f) Green Object ☐ g) Road Work Object ☐

h) Private Property ☐ i) Drain ☐ j) Road Fend/Glass Vange ☐

3) Vehicle does not seem damaged as a result of:

a) Fallen Object ☐ b) Flood ☐ c) Vandalism ☐ d) Fire ☐

e) Moving Object ☐ f) Stolen ☐ g) Stolen & Recovered ☐

Time Started

Time Completed

0.500

0.500

0.500 (Total Operation Time)

Remarks to appear in Works Order & Assessment report

1) Potential Total Loss ☐

2) SRS Light on ☐

3) ABS Light on ☐

VAN / LORRY (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	BR		✓
2001	991477	Frt Bumper Clip	NEC		✓
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side Retainer	DIS		2 ✓
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement	DD		✓
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover	MIS		✓
1018	991355	Frt RH Bumper Fog Lamp Cover	CRA		✓
1019	995079	Frt LH Bumper Fog Lamp			✓
1020	995080	Frt RH Bumper Fog Lamp	CRA		✓
1021	991793	Frt Grille			✓
1022	991328	Frt Grille Emblem			✓
2006	990247	Frt Grille Sticker			✓
1023	991799	Frt Grille Chrome Moulding			✓
2007	991891	Frt Panel	SCR	R	✓
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel RH	SCR	R	✓
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	BR		✓
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel	BT		✓
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator	DD		✓
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

Vehicle No:

GBE 7433M

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			✓
2031	990106	Air Con Blower			✓
1082	990427	Brake Master Pump Assy			✓
1083	990403	Brake Booster Pump Assy			✓
2032	990431	Brake Pedal			✓
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Column Shaft			✓
1128	994485	Steering Column			✓
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			✓
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Instrument Cluster Panel	DIS		✓
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Wind Mirror Switch Panel	DIS		✓
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			8870 ✓
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt RH Door Speaker			✓
1316	995327	Frt RH Door	BT		✓
1317	991654	Frt RH Door Edge Protector	BT		2 ✓
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wire Harness			
1323	991584	Frt RH Door Lock			
1324	991595	Frt RH Door Glass Regulator	BT		✓
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Checker	BT		✓
1333	991617	Frt RH Door Inner Trim Board	CRA		✓
2037	991644	Frt Door Frt Pillar	BVC		✓
2038	991657	Frt Door Rear Pillar Inner Garnish			✓
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel RH	BT		✓
2042	994498	Frt Step Panel Top Garnish	DIS		✓
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
		Frt Floor Panel	NEC		✓
		Accelerator Pedal	BVC		✓
		Steering Wheel Column Lower Cover			✓

No of Items:

Assessor:

Claim Handling

Task Transfer Exit

Accident MT/1013604

LOA SAL SUB

Policy No.	5088033644-01	Vehicle No.	GBE7433M	GST Registration No.	
Certificate No.					
Policyholder Name	BLUEFLAME ENGINEERING PTE LTD			Policyholder NRIC	199404136C
Product Code	COMMERCIAL VEHICLE INSURAI	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	96259509	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	20	Private Hire	No

Accident Details

Report Date	29/09/2018 15:49	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Cross Junction
Date of Accident	29/09/2018	Time of Accident hh:mm	00:05	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	JUNCTION OF EUNOS ROAD 5 AND EUNOS AVENUE 3				

Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History	01/10/2018 08:47:53 Deborah Mui changed GST Status Verified from No to Yes		

Policyholder Mailing Address

Address 1	BLK 1045 #01-112	Address 2	EUNOS AVENUE 4	Address 3	SINGAPORE 409795
Address 4		Address Type	Singapore address	Post Code	409795
Unit No.		Related Policy Number	5099866211		

O1 Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	SIM TA TJEH (SHEN DAZHI)	Driver NRIC	S7341362A	Driver DOB	10/11/1973
Register Date of Driver License	23/02/1994	Driver Age	44	Driving Experience	24
Contact No.(Mobile)	96259509	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 236 #06-03	Address 2	PASIR RIS STREET 21	Address 3	SINGAPORE 510236
Address 4		Address Type	Foreign address	Post Code	510236
Unit No.	06-03				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.	GBE7433M	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Choo

Claim Type	OD-MD	Insured Name	BLUEFLAME ENGINEERING PTE	Insured NRIC	199404136C
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	67457838
Email Address		DI Vehicle Number	GBE7433M	TP Vehicle Number	JPV9292
Claim Description	GBE7433M / JPV9292 ON 29 Sept 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Not at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Received
Date Registered	29/09/2018 16:00	Claim Close Date		Date Received	03/10/2018 1
Report Taken By	ROSLI WAHAB	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	

Modification History 02/10/2018 13:56 s069588 Modify Claim Type(OD-MX-->OD-MD)

Special Claim Creation Approval

Approval	Reason
----------	--------

Remarks

damage assessment Activity Handling Attachment

Accident No.	MT/1013604	Claim No.	001
Last Doc. Received	☒ Yes ☐ No	Upload Date	03/10/2018 15:38
Path *	Category * Confidential Urgency *		
	Browse...	Clear	Please Select
	Browse...	Clear	Please Select
	Browse...	Clear	Please Select
	Browse...	Clear	Please Select
	Browse...	Clear	Please Select
	Browse...	Clear	Please Select
	Browse...	Clear	Please Select

Message Read

Attachment List

Attachment	Uploaded By/Date	Category	Urgency	Description
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:38	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:38	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:38	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:38	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:38	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:37	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3

	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:36	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:35	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:35	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:35	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:35	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:35	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:35	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:34	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:34	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:34	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:34	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:34	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:34	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SER VICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3

	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:33	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:32	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:31	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:31	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:31	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:31	Photos	Normal	Photos 2018-10-3
	NAC_PAYA_UBI_800601(NATIONAL ASSESSMENT CENTRE SERVICES) on 03 Oct 2018 15:31	Photos	Normal	Photos 2018-10-3
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29

	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:57	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:56	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:56	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:56	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:56	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:56	Photos	Normal	Photos 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:56	SAS	Normal	SAS 2018-9-29
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)) on 29 Sep 2018 15:56	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-9-29

 Video List

Uploaded By/Date	Folder Date	File Name	Source
		Display in New Window Scan and uploading	

Claim Handling

Task Transfer Exit

Accident MT/1013604

LOG SAL SUB

Policy No.	5088033644-01	Vehicle No.	GBE7433M	GST Registration No.	
Certificate No.					
Policyholder Name	BLUEFLAME ENGINEERING PTE LTD			Policyholder NRIC	199404136C
Product Code	COMMERCIAL VEHICLE INSURA	Cover Type	Comprehensive	Loading	0
Contact No.(Mobile)	96259509	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	20	Private Hire	No

Accident Details

Report Date	29/09/2018 15:49	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Cross Junction
Date of Accident	29/09/2018	Time of Accident hh:mm	00:05	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	JUNCTION OF EUNOS ROAD 5 AND EUNOS AVENUE 3				

Excess

Own damage Excess	600.00	Additional Excess		Windscreen Excess	100.00
Unnamed Driver Excess		Outside Singapore OD Excess			
Third Party Excess	0.00	Outside Singapore TP Excess			

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History	01/10/2018 08:47:53 Deborah Mui changed GST Status Verified from No to Yes		

Policyholder Mailing Address

Address 1	BLK 1045 #01-112	Address 2	EUNOS AVENUE 4	Address 3	SINGAPORE 409795
Address 4		Address Type	Singapore address	Post Code	409795
Unit No.		Related Policy Number	5099866211		

OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	SIM TA TIEH (SHEN DAZHI)	Driver NRIC	S7341362A	Driver DOB	10/11/1973
Register Date of Driver License	23/02/1994	Driver Age	44	Driving Experience	24
Contact No.(Mobile)	96259509	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 236 #06-03	Address 2	PASIR RIS STREET 21	Address 3	SINGAPORE 510236
Address 4		Address Type	Foreign address	Post Code	510236
Unit No.	06-03				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.	GBE7433M	Driver Insurer Company	NTUC

Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
-------------------------------------	------	-------------	---

Modification History

Investigation

Claim 001 OD-MD

Claim Case Officer Tan Siew Choo

Claim Type	OD-MD	Insured Name	BLUEFLAME ENGINEERING PTE	Insured NRIC	199404136C
Contact No.(Mobile)		Contact No.(Home)		Contact No.(Office)	67457838
Email Address		OI Vehicle Number	GBE7433M	TP Vehicle Number	JPV9292
Claim Description	GBE7433M / JPV9292 ON 29 Sept 2018			Name of Preferred Workshop	
Preferred Workshop Contact No.		Insured Liability	Not at Fault		
Require Finalisation	Yes	Preferred Repair Option	Preferred Workshop, Name unknown	GIA report	Received
Date Registered	29/09/2018 16:00	Claim Close Date		Date Received	03/10/2018 15:38
Report Taken By	RCSLI WAHAB	Workshop Repairer		Total Loss but Repaired	
				OD Excess Collected by Workshop	

☒ Print AK letter

Modification History 02/10/2018 13:56 s069588 Modify Claim Type(OD-MX-->OD-MD)

Special Claim Creation Approval

Approval	Reason
----------	--------

Remarks

damage assessment Activity Handling Attachment

Vehicle Info

Vehicle Make	NISSAN	Vehicle Model	NV350	Engine Capacity	1
Date of Registration	23/03/2016	Classis No.	JN1MC2E26Z0005121		
Towing Required *	☒ Yes ☐ No	Vehicle in IDAC *	☒ Yes ☐ No	Parallel Import *	☐ Yes ☒ No
Type of Tender *	Own Damage	Assessor Name *	SIMON	Survey Current Status	
IDAC/Workshop Name	NATIONAL ASSESSMENT CENTR	IDAC/Workshop Location	51 UBI AVENUE 1 #01-25 PAYA		
Windscreen Parts & Labour Cost		Total Loss *	☐ Yes ☒ No		
Market Value (\$)		Scrape Value(\$)		Economical Repair Value(\$)	
NO OF REPAIR DAYS : 10 /1X FRT BUMPER REINFORCEMENT REPLACE/1X FRT GRILLE CHROME MOULDING UNCONFIRM/1X STEERING COLUMN SHSFT COUPLING UNCONFIRM/1X ASSY UNCONFIRM/1X INSTRUMENT CLUSTER PANEL UNCONFIRM/1X WINDMIRROR SWITCH PANEL UNCONFIRM/1X FRT RH DOOR EDGE PROTECTOR REPLACE/2X FRT RH DOOR REPLACE/1X FRT RH DOOR WIRE HAMESS UNCONFIRM/1X FRT RH DOOR LOCK UNCONFIRM/1X FRT RH DOOR INNER TRIM BOARD REPLACE/1X FRT DOOR FRT PILLAR REPLACE/1/ DOOR PILLAR INNER GARNISH UNCONFIRM/1X FRT STEP PANEL RH REPLACE/1X FRT STEP PANEL TOP GARNISH REPLACE/1X FRT STEP PANEL INNER GARNISH UNCONFIRM/1X ST REPLACE/1X STEERING WHEEL COLUMNHAWER DIG COVERING UNCONFIRM/					

Remark

Remark for Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *
root					
Not Applicable	1	16002401	BUMPER CLIPS (FRONT)	1	Replace
ABS	2	16005102	BUMPER RETAINER (FRONT RIGHT)	2	Replace
ABSORBER	3	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Replace
ACCELERATOR	4	27100801	GRILLE EMBLEM (FRONT)	1	Unconfirm
ACTUATOR	5	27700102	HEAD LAMP (RIGHT)	1	Replace
ADVERTISEMENT STICKER	6	41300101	SUPPORT PANEL (FRONT)	1	Replace
AIR BAG	7	344001	RADIATOR	1	Replace
AIR BLOWER	8	23300202	DOOR (FRONT RIGHT)	1	Replace
AIR BOX	9	23301602	DOOR CHECKER (FRONT RIGHT)	1	Replace
AIR CHAMBER BOX	10	256005	FLOOR PANEL	1	Repair
AIR CLEANER	11	16000101	BUMPER (FRONT)	1	Replace
AIR COMPRESSOR	12	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Replace
AIR CON	13	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Unconfirm
AIR CON (VAN)	14	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Replace
AIR COOLER	15	27100101	GRILLE (FRONT)	1	Unconfirm
AIR DISTRIBUTOR	16	33000101	PANEL (FRONT)	1	Repair
AIR FILTER	17	21300102	CORNER PANEL (FRONT RIGHT)	1	Repair
AIR FLOW	18	112053	AIR CON EVAPORATOR	1	Unconfirm
AIR GRILLE	19	112003	AIR CON BLOWER	1	Unconfirm
AIR HORN	20	15701601	BRAKE MASTER PUMP (FRONT LEFT)	1	Unconfirm
AIR INTAKE	21	15701602	BRAKE MASTER PUMP (FRONT RIGHT)	1	Unconfirm
AIR RESONATOR BOX	22	401017	STEERING COLUMN SHAFT	1	Unconfirm
AIR THROTTLE BODY AND SENSOR	23	43600102	TYRE (FRONT RIGHT)	1	Unconfirm
ALARM	24	23306302	DOOR SPEAKER (FRONT RIGHT)	1	Unconfirm
ALTERNATOR	25	23302402	DOOR GLASS REGULATOR (FRONT RIGHT)	1	Replace
ALUMINIUM PANEL - SIDE	26	23302502	DOOR GLASS REGULATOR MOTOR (FRONT RIGHT)	1	Unconfirm
AMPLIFIER	27	23306102	DOOR RUBBER (FRONT RIGHT)	1	Replace
ANTENNA	28	103002	ACCELERATOR PEDAL	1	Unconfirm
ANTI ROLL					
APRON					
ARCH					
ARM REST					
ASH TRAY					
AUTO CLUTCH					
AUTO COOLER PIPE					
AUTO CRUISE MOTOR					
AUTO TRANSMISSION					

Save Submit



NATIONAL ASSESSMENT CENTRE SERVICES
(LKK GROUP)
51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,
Singapore 408933, TEL: 6841 0055 FAX: 6841 6315

NAC NATIONAL
ASSESSMENT
CENTRE

Vehicle Movement Form

Vehicle Check-In

Vehicle No: GBF 7435M Date In: _____ Time In: _____ with Keys: Yes / No

For Office use

Attended by: _____

Workshop Collection of Vehicle

Workshop: Hock Weh motor

Collection Date: 5/10/18 Time: 1410 hrs with Keys: Yes / No

Tow Truck No: YH 1388L Tow Man: Only Eng Beng NRIC: S7048847A

Signature: [Signature]

For office use

Attended by: Shan Hui

Approved by: _____

Workshop Return of Vehicle

Workshop: _____

Returned Date: _____ Time: _____ with Key: Yes / No

* Tow In / Drive In

Tow Man / Workshop Representative: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Owner Collection of Vehicle

Collection Date: _____ Time: _____ with Key: Yes / No

Owner: _____ NRIC: _____

Signature: _____

For office use

Attended by: _____

Approved by: _____

LKK Paya Ubi

From: Tan Siew Choo <siewchoo.tan@income.com.sg>
Sent: Friday, 5 October 2018 12:31 PM
To: NAC ; Hock Wah Motor Pte Ltd
Subject: GBE7433M, OD claim no : MT/1013604

Importance: High

Dear IDAC and Hock Wah,

Learnt that veh is in IDAC (IDAC – pls confirm), do assist with the necessary arrangement asap.

Dear Hock Wah,

OD excess of \$600/- is applicable, pls assist to liaise with Mr Sim at tel : 96259508.

Survey required and you have to arrange personally at mtsurvey@income.com.sg

FOR PAYMENT: Please forward the Invoice & Discharge Voucher within 14 days after the repair has been done/ finalized with Surveyor to my email, cc a copy to Yap Chee Ling at cheeling.yap@income.com.sg

Regards.

Tan Siew Choo
Senior Executive
Motor Insurance
T +65 6430 7882
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers



Our Ref: MT/CA/OD/051/1013604-001/TSC
05 Oct 2018
HOCK WAH MOTOR WORKSHOP PTE LTD
BLK 3011 BEDOK NORTH AVE 4 #01-2008/10/12
BEDOK INDUSTRIAL PARK E
SINGAPORE 489977

Dear Sir

CLAIM NUMBER: MT/1013604-001

REPAIR OF VEHICLE NUMBER: GBE7433M

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 05 Oct 2018

Make: NISSAN

Model: NV350

Estimated Repair Days: 9

Location: NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Tan Siew Choo at 64307882 or email us at motor@income.com.sg.

Yours sincerely

Low Choo Mee

Senior Manager

Motor Insurance

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.