

ASS. REC. BY:

REF:

CS3/ALG18017718/Gcd3eb

Special Instruction:

Surveyor: Edu Qiang

ASSIGNMENT (Office)

Meimien

From (Person): Chin lee Ying

of

ALG

Date/Time: 1/10/18 @ 11:39 am

Estimated Cost:

Bill to:

OD. TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 4278Y

Insured:

SBJ 839 X

at Workshop m/s

Lian Hler Motors

Tel:

8299 0599

of

BLK 5038, AMK Ave 3 # 01-405

Policy No:

1700052580

Claim No:

95883658198G

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/09/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

12:21 pm @ 1/10/18

Person Contacted:

James

Vehicle IN / OUT

Date/Time	Action/Instruction (x) Estimate
	SLS 4278Y - X
	SBJ 839 X - NA / CAI 15000582/d2
	Dismantle: 3/10/2018.

DOA: 10/01/15

Surveyor: XYZ

REF: ALG

C4543E

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Lian Her Motors  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: SL54278Y Yr Regn: 22 Sep 2017  
 Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Toyota C.C. 179  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp.Reading: 80810 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
 C/No: 2YX102065392

Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Good / Jammed / Leaked / Burnt or  
 Brake: Good / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R17  
 R: 215/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>01-10-18</u>

Survey held at w/s 2:20pm  
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>\$2000 - \$3000</u>
	<u>Waiting for GAO Chang to upload re-survey photos.</u>
	<u>9/10.</u>

Date/Time, File Pass to? ☐ : Preli. Report  
☐ : Final Report

Days Of Repair: 3  
 Resurvey No. of Trip: 1


Survey Fee:	<u>180</u>
Transportation	
	<u>20</u>
TOTAL	<u>200</u>

Report Format : DAR  
 Lump Sum / I.B.I. (\$) \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ )  
☐ : Interview (\$ )  
☐ : Tech. Invs (\$ )  
☐ : Weekend (\$ )

**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying  
To: assignments@lkkauto.com, admin-a@lkkauto.com  
Cc: Fong, Andy-SY  
Sent: 1/10/2018 11:39:59 AM

Attachments:  [20180928170718.pdf](#)  [20180928162447.pdf](#)  
 [20180928124028.pdf](#)

---

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947 | Fax +(65) 6835 7416  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with limited liability)

ERIC NG CHING BOON  
RAYNEY WONG KENG LEONG  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI D/O MUNIANDY  
SEGA PARAM  
TIWARY ANURADHA  
ONG BOCK KEE  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

## ✓HEAD OFFICE

133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## ✓HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX : (65) 65356802 (General)  
✓: (65) 65355905 (Litigation)  
E-mail : yvonneim@visionlawllc.com

## BRANCH

TEL : (65) 63580703  
FAX : (65) 63580448 (Conveyancing)

**WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER**

Our Ref : SLS 4278 Y (PM)  
Your Ref : SBJ 839 X

28 September 2018

**BY EMAIL ONLY**

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
[Attention : Motor Claim Department]

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SLS 4278 Y & SBJ 839 X & SGQ 3335 S ON 20 SEPTEMBER 2018 AT COMMONWEALTH SECONDARY SCHOOL AT ABOUT 0720 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your letter on even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : **LIAN HER MOTORS**  
Block 5038 Ang Mo Kio Avenue 3  
#01-405 Ang Mo Kio Industrial Park 2  
Singapore 569541  
Contact Person : **Mr. James @ 8299 0599 (Please call before going)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

JANICE HAN  
(HEAD OFFICE)

cc: SLS 4278 Y – By fax: 64816131 only

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

## CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4543E
Vehicle Details	
Vehicle No.:	SLS4278Y
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	2ZR8169729
Chassis No.:	ZYX102065392
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,624.00
Original Registration Date:	22 Sep 2017
First Registration Date:	22 Sep 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	21 Sep 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,189.00
COE Rebate Amount:	\$44,119.00
<b>Total Rebate Amount:</b>	<b>\$47,869.00</b>

The information contained herein is correct as at 02 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/09/2018 14:16
Date Of Accident	20/09/2018 07:20
Exact Location Of Accident	COMMONWEALTH SECONDARY SCHOOL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS4278Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	H.L CAR RENTAL PTE LTD
Co Reg No	201004543E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91794867
Alternative Phone No	OFFICE-91794867

### Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5083403664-02
Cover Note Number	

### Driver

Name of Driver	LEE SWEE TECK
NRIC No	S1612183E
Date Of Birth	10/08/1963
Occupation	OUTDOOR
Date Of Driving Pass	28/11/1981
Driving Experience	36 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91794867
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	206 LOYANG AVE #01-06
Postcode	509061
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	KIV, SUBMIT BY CLAIMANT WORKSHOP
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBJ839X
Vehicle Make/Model/Colour	MAZDA 3
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MUHD AIDIL BIN NOOR
NRIC/Passport Number	S8622276J
Contact Number	94234891
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	LEE SWEE TECK
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLS4278Y
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


H.I. CAR RENTAL PTE LTD

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/9/18 at Commonwealth Secondary School at approximately 7.20 am  
 My car was going straight after alighting a student.  
 My car was behind a Mazda 3 car plate number JBJ 839 X going  
 towards the exit when he suddenly stop and reverse into a parking  
 lot. I horn and try to reverse but it was too late as I do not have  
 enough time to react. This resulted in his back bumper hitting the  
 front of my car (Passenger Side).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

H.I. CAR RENTAL PTE LTD

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

# MOTOR CAR (Frt)

## Front Portion

Vehicle No: **SL S 4278Y**

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BT	✓	
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish	BR	✓	
1004	991300	Frt Bumper	CRA	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer	DIS	✓	
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	BR	✓	
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille & lower grille	BR	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover	BR	✓	
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
1023	991799	Frt Grille Chrome Moulding			
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	CRA	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: **8**

Accessories:

TGum  
31.1.10

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Sep 2018 <a href="#">Edit Reg</a>		01 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

MUHAMMAD AIDIL BIN NOOR, ID: S8622276J

Main Claimant:

-

Vehicle Reg. No.:

SLS4278Y

Claim Type:

TP / 9588365819SG

Vehicle Reg. No. (Insured):

SBJ839X

Repaire:

Lian Her Motors (HQ) Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2, 569541 Ang Mo Kio - Tel: 82990599

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 10/10/2018]

Claimant's Solicitor:

VISION LAW LLC - Tel: 65342811

Date of Loss:

20/09/2018 00:00 - :59  
[11 Months and 29 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

1700052580 (Comprehensive)

Policy No. (Claimant):

Excess:

[Created by adjuster]

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

- AIG\_SG (02/10/2018): Request To Upload TP GIA Report

**ALL ASSOCIATED TASKS**




































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)


Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLS4278Y (9588365819SG)  
[SBJ839X]  
TP  
-

Sep 20 2018 12:00AM  
[MUHAMMAD AIDIL BIN NOOR]  
Lian Her Motors

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print
1	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
2	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
3	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
4	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
5	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
6	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
7	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
8	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
9	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
10	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
11	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
12	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
13	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
14	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
15	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
16	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
17	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
18	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
19	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
20	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
21	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
22	02/10/18 12:29	General View											Load JPG	<input checked="" type="checkbox"/>
23	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
24	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
25	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
26	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
27	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
28	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
29	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
30	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
31	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
32	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
33	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
34	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
35	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
36	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
37	08/10/18 09:10	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/10/18 10:20	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18017718/GCD3E2

Date: 11/10/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700052580  
**Claimant Vehicle No :** SLS4278Y **Insured Vehicle No :** SBJ839X  
 Date of Loss: 20/09/2018 Nature of Claim: TP Claim No: 9588365819SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SLS4278Y**  
 Make & Model: KIA CERATO, 1.6 (A) Engine No: 2ZR8169729  
 Reg. Date: 22/09/2017 (Man. Year: 2017) Chassis No: ZYX102065392  
 Colour: White Odometer: 80810 km  
 Engine Capacity: 1797 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 01/10/2018  
 Date Inspected: 01/10/2018 Inspected At: Lian Her Motors (HQ)  
 Block 5038 Ang Mo Kio Avenue 3, #01-405  
 Ang Mo Kio Industrial Park 2  
 Singapore 569541  
 Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT NUMBER PLATE GARNISH	Broken	0.00 F	*- F
3	1		*FRT BUMPER	Cracked	0.00 F	*- F
4	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
5	1		*FRT BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
6	1		*FRT BUMPER SPONGE	Broken	0.00 F	*- F
7	1		*FRT BUMPER GRILLE & LOWER GRILLE	Broken	0.00 F	*- F
8	1		*FRT LH BUMPER FOG LAMP COVER	Broken	0.00 F	*- F
9	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >