

Your Ref: 18/18/18/VP02/263932

Date: 19th October 2018

Our Ref: CS1/LPC18017750/Brbs2

M/s Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
(The Motor Claims Department)

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SLE 1994G INSURED VEHICLE: JQV 7798 ACCIDENT DATE: 22/07/2018**

We thank you for your instruction on 01/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLE 1994G from M/s United Appraisal And Management Pte Ltd.
- b) Singapore Accident Statement of Vehicle SLE 1994G.
- c) Colour damaged vehicle photographs of SLE 1994G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLE 1994G
Make & Model	: Honda Vezel 1.5X CVT
Year of Registration	: 2016
Chassis Number	: RU11117610
Engine Capacity	: 1496 cc
2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.