

1592/10

INS. CASE OWNER:

CC 4/LPC1801

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age: MUHAMMAD KHARAL AMAN BIN

Driver Tel No.:

(V/L: YES / NO) MO

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

TP GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:INSRS:  
WSP:  
Tel:  
Liability:  
RMKS:

Date/Time		STAGE	DATE / PIC
8/10/18	578 15824	Non-Reporting ltr (1st):	
	578 15824	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OE:	
		After call ltr to OE:	
24/06/19	FILE RECORDED. OIRERL- ENDED TP.	Documentation Check List: Handler	Typist
	FINISHED	Notification ltr (if non-pickup)	
	TP LOW IN.	After call ltr to OE:	
		Authorisation To Act:	
		Release Voucher:	
13/08/19	TYPE REPORT FOR WANDATE APPROVAL	Final Repair Bill:	
16/08/19	REPORT DONE	Car Rental Invoice:	
	SEEK WANDATE APPROVAL TO LPC	Towing Invoice:	
	LPC APPROVED WANDATE.	LTA / GIA:	
	SEND 1ST OFFER TO TP.	Medical Bill:	
	DU TAX - IN.	PIR:	
11/10/19	TP REQUESTER RIGHT LOI. LPC IMPROVE.	Mandate/Reject Instruction:	
15/10/19	SEND 2ND OFFER	LOD	
	TP ACCEPTED OFFER.	Payment Breakdown Form:	
	ALL WORK IN ORDER. TO CLOSE.	Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time: 02/10/18	Sent By: SB	
FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost: P/P	SS 2,246.42 (3 days)	Reduction: 50 %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 17/10/19	Confirm with: CECILIA	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed)	BOLA S/N No.:	27
Repair Cost: (w/647)	SS 2,403.67		
Loss of Rental (LOR):	SS - ( days)		
Loss of Use (LOU):	SS 500.00 (\$100 x 5 days)		
Loss of Income (LOI):	SS 750.00 (\$150 x 5 days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input checked="" type="checkbox"/> LOR + LO <input type="checkbox"/> [Tick only one]		
GIA/LTA Search	SS 2.00		
Medical:	SS 342.00 (DRIVER & PAX)		
Disbursement: PACE	SS 29.75 (TAXI) (e.g. Tow/ Independent)		
Legal Cost	SS -		
Total:	SS 4,026.92	Global Sum SS: -	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 4,026.92	Name 1: COMFORTOLARO ENGINEERING PTB LTD	
Payee 2: (Strike if N.A.)	SS -	Name 2: -	
Payee 3: (Strike if N.A.)	SS -	Name 3: -	





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18017751/Gjb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 01-10-2018	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJJ 1583G	Veh. Inspected	SLG 2881G	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	01/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	27/09/2018	Inspection Date	01/10/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised  
Our ref: CC4/LPC18017751/Gjb3

Date: 02.10.2018

The Motor Claims Department  
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SLG2881G**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.10.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Braddell) and have the following to report:-

Workshop Estimate Amount	: S\$	5,402.02
Revised Estimate Amount	: S\$	2,042.15
"Check" Items Amount	: S\$	1,641.09
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

**XING GUO QIANG**  
**Licensed Appraiser**

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	4597K
Vehicle Details	
Vehicle No.:	SLG2881G
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	2ZRR949390
Chassis No.:	JTDKB3FU103534900
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$31,008.00
Original Registration Date:	27 Sep 2016
First Registration Date:	27 Sep 2016
Transfer Count:	1
Actual ARF Paid:	\$5,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Sep 2026
PARF Rebate Amount:	\$4,059.00
Intended COE Rebate Details	
COE Expiry Date:	26 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,000.00
COE Rebate Amount:	\$44,706.00
<b>Total Rebate Amount:</b>	<b>\$48,765.00</b>

The information contained herein is correct as at 02 Oct 2018

OK



ComfortDelGro Engineering

205 Braddell Road S(579701)

**ACCIDENT REPAIR ESTIMATE**

Our Ref:

Type of Claim : TPVehicle No. : SLG2881GMake & Model : TOY PRIUS HYBRID 1.8 CVTYear of Manufacture : 2016Chassis No. : JTDKB3FU103534900Ins Company : AIG VS LONPACEngine No. : 2ZRR949390Excess : -Policy No. : -Date of Accident : 27.09.2018Time of Accident : 15:00

Suggested Days of Repair : \_\_\_\_\_

In-house Vehicle Assessor**Repair Estimate**

Case Owner : \_\_\_\_\_

Signature : \_\_\_\_\_

Parts (a) Cost / List Price Items \$ 4,296.02

Contact No

Plus/Less 25% \$ 1,074.01**Frt Counter Operation**Total of Cost / List \$ 3,222.02

63837103 - Patrick Tia

(b) Nett Price Items \$ -

63837730 - Brenda Ng

Less \_\_\_\_\_

63837466 - Rohani

Total of Nett Item \_\_\_\_\_

[braddell\\_cr@sparkcarcare.com](mailto:braddell_cr@sparkcarcare.com)(c) Special Nett Items \$ 200.00**Workshop Operation**

63837656 - Ngo Toh Wee

Total Parts Cost (Appendix A) \$ 3,422.02

63837362 -

63838115 - William Wang

63838115 - Andrew Goh

[braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)Labour (Appendix B) \$ 1,980.00Total Repair Cost \$ 5,402.02

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Euro Corp.

Company : \_\_\_\_\_

Survey conducted on : 01/10/18 at \_\_\_\_\_Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 3 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_



# Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

## Spare Parts

Vehicle No : SLG2881G Case Owner : 0

Make & Model : TOY PRIUS HYBRID 1.8 C Year Manufacture : 2016

Chassis No : JTDKB3FU103534900 Engine No : 2ZRR949390

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper / <i>re</i>	1		\$ 423.90			
2	Rear bumper center guard / <i>re</i>	1		\$ 552.60			
3	Rear bumper cover / <i>sub</i>	1		\$ 14.70			
4	Rear bumper filler LH <i>X UN</i>	1		\$ 113.46			
5	Rear bumper filler RH <i>2 UN</i>	1		\$ 113.46			
6	Rear bumper reinforcement <i>2 DM</i>	1		\$ 318.90			
7	Rear bumper retainer LH <i>X UN</i>	1		\$ 111.60			
8	Rear bumper retainer RH <i>X UN</i>	1		\$ 112.70			
9	Rear bumper clips / <i>re</i>	10		\$ 25.00			
10	Reverse sensor set <i>DM</i>	1				\$ 200.00	
11	Rear end panel <i>X UN</i>	1		\$ 556.90			
12	Rear end panel top garnish <i>X UN</i>	1		\$ 121.60			
13	Taillamp upper LH <i>X NN</i>	1		\$ 433.70			
14	Taillamp lower LH <i>X UN</i>	1		\$ 481.90			
15	Taillamp upper RH <i>X NN</i>	1		\$ 433.70			
16	Taillamp lower RH <i>X UN</i>	1		\$ 481.90			
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Vehicle No.	: <b>SLG2881G</b>	Case Owner	: <b>0</b>
Make & Model	: <b>DY PRIUS HYBRID 1.8 CVT</b>	Year of Manufacture	: <b>2016</b>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



## Nivitha (LKK Auto)

---

**From:** Shu Pei (LKKAuto) <shupe@lkkauto.com>  
**Sent:** Monday, 1 October 2018 10:08 AM  
**To:** assignments  
**Subject:** FW: SLG2881G CLAIMING AGAINST SJJ1583G DOA27092018 CHECK LIABILITY & ARRANGE SURVEY  
**Attachments:** SLG2881G DOA27092018 ESTIMATE.pdf; SLG2881G DOA27092018 SAS.pdf

10.11 am @ 1/10/18  
vehicle in  
Person @ William  
sup @ Guo Qiang

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupe@lkkauto.com](mailto:shupe@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Monday, 1 October 2018 10:02 AM  
**To:** Admin A <admin-a@lkkauto.com>  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>  
**Subject:** FW: SLG2881G CLAIMING AGAINST SJJ1583G DOA27092018 CHECK LIABILITY & ARRANGE SURVEY

Our Ref : 18/18/18/VP05/020959

Dear Catherine/Nivitha,

Kindly proceed to conduct the survey and revert to them on liability.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** CDGE Braddell Private Cars Crash Repair Operation [[mailto:braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)]  
**Sent:** Friday, 28 September, 2018 5:11 PM  
**To:** GERALD POH WEE BIN  
**Cc:** CDGE Braddell Private Cars Crash Repair Counter; Patrick Chung Chan Kim; Denis Teo Chin Chye  
**Subject:** SLG2881G CLAIMING AGAINST SJJ1583G DOA27092018 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir/Madam,

Kindly assist to check liability for this case and arrange survey at CDGE braddell.  
Your insured vehicle number is SJJ1583G  
Please see attached and reply as soon as possible.

Thanks

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

[www.SPARKcarcare.com](http://www.SPARKcarcare.com)

**Shu Pei (LKKAUTO)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Wednesday, 3 October 2018 4:10 PM  
**To:** Shu Pei (LKKAUTO)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: SLG2881G CLAIMING AGAINST SJJ1583G DOA27092018 CHECK LIABILITY & ARRANGE SURVEY  
**Attachments:** 03102018151804.pdf

Dear Shu Pei,

Attached copy of insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]  
**Sent:** Tuesday, 2 October, 2018 5:36 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Admin A; Joy Irene (LKKAUTO)  
**Subject:** RE: SLG2881G CLAIMING AGAINST SJJ1583G DOA27092018 CHECK LIABILITY & ARRANGE SURVEY

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SLG 2881G at M/s Comfortdelgro Engineering Pte Ltd.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Our case handler in-charge is Joy and she can be contacted at DID: 6841 2409.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAuto)

**Sent:** Monday, 1 October 2018 10:14 AM

**To:** 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: SLG2881G CLAIMING AGAINST SJJ1583G DOA27092018 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** GERALD POH WEE BIN <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>

**Sent:** Monday, 1 October 2018 10:02 AM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** FW: SLG2881G CLAIMING AGAINST SJJ1583G DOA27092018 CHECK LIABILITY & ARRANGE SURVEY

Our Ref : 18/18/18/VP05/020959

Dear Catherine/Nivitha,

Kindly proceed to conduct the survey and revert to them on liability.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

**From:** CDGE Braddell Private Cars Crash Repair Operation [[mailto:braddell\\_operation@sparkcarcare.com](mailto:braddell_operation@sparkcarcare.com)]

**Sent:** Friday, 28 September, 2018 5:11 PM

**To:** GERALD POH WEE BIN

**Cc:** CDGE Braddell Private Cars Crash Repair Counter; Patrick Chung Chan Kim; Denis Teo Chin Chye

**Subject:** SLG2881G CLAIMING AGAINST SJJ1583G DOA27092018 CHECK LIABILITY & ARRANGE SURVEY

Dear Sir/Madam,

Kindly assist to check liability for this case and arrange survey at CDGE braddell.

Your insured vehicle number is SJJ1583G

Please see attached and reply as soon as possible.

Thanks

William Wang

Best Regards

External Business | ComfortDelGro Engineering Pte Ltd

Off: 6383 7656 (Ngo - Supervisor) / Off: 6383 8115 (William) / Off: 6383 7362 (Andrew)

Fax: 6281 5767

[www.SPARKcarcare.com](http://www.SPARKcarcare.com)



This email has been checked for viruses by AVG antivirus software.

[www.avg.com](http://www.avg.com)

CCX/LPC18019751/GLB392

Vic



ComfortDelGro Engineering

Our Ref: PTE/SLG2881G/20180927/DS-CL

03/09/2019

Lonpac Insurance Berhad  
C/O LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933  
Attn: Vic Alpeh

Without Prejudice

ComfortDelGro Engineering Pte Ltd

Corporate Office

205 Braddell Road Singapore 579701

Mainline +65 6383 6280

Facsimile +65 6280 9755

Company Registration No: 198706049W

Car Care Centres

Braddell

205 Braddell Road

Singapore 579701

Tel 6383 8110

Loyang

59 Loyang Drive

Singapore 508969

Tel 6214 6300

Pandan

45 Pandan Road

Singapore 609286

Tel 6338 8778

Sin Ming

383 Sin Ming Drive

Singapore 575717

Tel 6553 0400

Sungei Kadut

7 Sungei Kadut Way

Singapore 728791

Tel 6366 7369

Ubi

320 Ubi Road 3

Singapore 408649

Tel 6848 5721

www.SPARKcarcare.com

Dear Sirs

**ACCIDENT ON 27/09/2018 INVOLVING SLG2881G & SJJ1583G ALONG  
CTE BEFORE EXIT LENTOR**

Strictly without admission of any liability and solely for quick amicable settlement, the claimant accepts your offer of \$221.00 for his medical expenses claim.

The duly completed document is enclosed for your attention. Please arrange to let us have your payment made in favor of SIM MUHAMMAD FADHLY within the next seven (7) days.

Yours sincerely

Cecilia Lee  
CDGE Claims Department  
DID: 6214 8354 FAX: 6214 1843  
Email: ceciliale@sparkcarcare.com

Enclosures

This is a computed generated letter. No signature is required.





ComfortDelGro Engineering

Your Ref: CC4/LPC18017751/Ghb3

Our Ref: PTE/SLG2881G/20180927/DS-CL

ComfortDelGro Engineering Pte Ltd

Corporate Office

205 Braddell Road Singapore 579701

Mainline +65 6383 8280

Facsimile +65 6280 9755

Company Registration No: 199506048W

Car Care Centres

Braddell

205 Braddell Road

Singapore 579701

Tel 6383 8110

Loyang

59 Loyang Drive

Singapore 508969

Tel 6214 8300

Pandan

45 Pandan Road

Singapore 609286

Tel 6338 8778

Sin Ming

383 Sin Ming Drive

Singapore 575717

Tel 6553 0400

Sungei Kadut

7 Sungei Kadut Way

Singapore 728791

Tel 6369 7369

Ubi

320 Ubi Road 3

Singapore 408649

Tel 6848 6721

1 - OCT 2019  
 Lonpac Insurance Berhad  
 C/O LKK Auto Consultants Pte Ltd  
 51 Ubi Ave 1 #01-25  
 Paya Ubi Industrial Park  
 Singapore 408933  
 Attn: Vic Alpeh

Without Prejudice

Dear Sir

### ACCIDENT ON 27/09/2018 INVOLVING SLG2881G & SJJ1583G ALONG CTE BEFORE EXIT LENTOR

We refer to your offer dated 11/10/2019.

Strictly without admission of any liability and solely for quick amicable settlement, we accept your offer as follows:

Cost of Repair (w/gst)	\$ 2,403.67	(LCR)
Loss of Use (\$100 x 5 days)	\$ 500.00	(LCR)
Loss of Income	\$ 750.00	(HIRER)
Driver/Hirer Medical Bills	\$ 121.00	(HIRER)
Passenger Medical Bills	\$ 221.00	(PASSENGER)
Driver/Hirer Transport Expenses	\$ 29.25	(HIRER)
GIA Search Fee	\$ 2.00	(LCR)
<b>TOTAL</b>	<b>\$ 4,026.92</b>	

Please note that this settlement is strictly on a without prejudice basis and only in relation to the claim of vehicle damages and It should not be cited or relied on as precedent in any proceeding.

Please note that the contents of this letter and enclosures apply to vehicle damages only. It shall not include other claims which the driver and/or the passenger(s) may have against you and/or your insured for their damages in relation to their bodily injuries arising out of this accident, even if the medical expenses / loss of income claimed herewith formed part of settlement reached.

The duly completed documents are enclosed for your attention. Please arrange to let us have your payment made in favor of ComfortDelGro Engineering Pte Ltd within the next seven (7) days.

Thank you.

Yours sincerely

Cecilia Lee  
 CDGE Claims Department  
 DID: 6214 8354 FAX: 6214 1843  
 Email: cecilialee@sparkcarcare.com

Enclosures

A member of

COMFORTDELGRO






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18017751/Ghb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 24-10-2019	
			Code : LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJJ 1583G	Veh. Inspected	SLG 2881G	
Policy No.	Z18VP05019508	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020959	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	01/10/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FU103534900	Colour	WHITE	
Odometer	235669	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	PIRELLI	6 mm	
L/H Front Tyre	195/65 R15	PIRELLI	6 mm	
R/H Rear Tyre	195/65 R15	PIRELLI	6 mm	
L/H Rear Tyre	195/65 R15	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	27/09/2018	Inspection Date	01/10/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 2881G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	423.90	423.90
1	REAR BUMPER CENTER GUARD	DEFORMED	552.60	552.60
1	REAR BUMPER COVER	SCRATCHED	14.70	14.70
1	REAR BUMPER FILLER LH	NOT NECESSARY	113.46	-
1	REAR BUMPER FILLER RH	DAMAGED	113.46	113.46
1	REAR BUMPER REINFORCEMENT	DAMAGED	318.90	318.90
1	REAR BUMPER RETAINER LH	NOT NECESSARY	111.60	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	112.70	-
10	REAR BUMPER CLIPS	NECESSARY	25.00	25.00
1	REAR END PANEL	NOT NECESSARY	556.90	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	121.60	-
1	TAILLAMP UPPER LH	NOT NECESSARY	433.70	-
1	TAILLAMP LOWER LH	NOT NECESSARY	481.90	-
1	TAILLAMP UPPER RH	NOT NECESSARY	433.70	-
1	TAILLAMP LOWER RH	NOT NECESSARY	481.90	-
	LESS 25% DISCOUNT		-1,074.01	-362.14
			3,222.01	1,086.42
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REVERSE SENSOR (SN)	DAMAGED	200.00	200.00
			200.00	200.00
	<b><u>LABOUR</u></b>			
	LABOR CHARGES TO PANEL BEAT AND REPAIR ON REAR FLOOR PANEL ,CUTTING/WELDING AND REPLACE DAMAGED PARTS.		720.00	360.00
	TO INSTALL REVERSE SENSOR .		120.00	80.00
	TO CHECK WIRING FUNCTIONS.		40.00	20.00
	TO APPLY RUST PROOFING ON REPLACED AND REPAIRED PANELS.	NOT NECESSARY	100.00	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINT REAR BUMPER ,REAR BUMPER REINFORCEMENT ,REAR END PANEL,REAR FLOOR PANEL AND ALL AFFECTED AREAS.		1,000.00	500.00
			1,980.00	960.00
GRAND TOTAL			5,402.01	2,246.42
RECOMMENDED COST OF REPAIRS				2,246.42

Report Ref No. CC4/LPC18017751/Ghb3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.