

CS3/MSG1015137/ Nsd 3-1

ASSIGNMENT (Office)

Shiley

28/09/2018,

-menmen

Katherine Wong

MSG

OD / TP / WS / IF RES / OD RES / IVA / INV / MV / C

Impact Vehicle No

FBA 7543A

Brand

SIV 4563H

Workshop

Brother's Motor

Ref

9643 2540

at

81K 1016, Yishun Ind. Park A # 01-218

Police No

MSD / vpcp / 18-000001

Chassis

566091

Year Model

Excess

Make of Veh

Chassis Board

DOA 31/07/2018

CA / REV / REP / REV 24 HRS

cup

Date/Time

12:31pm @ 20/8/18

Person Contacted

Mr Tat

Hold Information

Vehicle IN OUT

Date/Time

Actual/Estimated (✓) Estimate

15/10/18

Submit L/S \$5,550/- @ 3 days, checked by smen.  
(\$2,650/- Red - 32%)

*[Signature]*  
15/10/2018

RECEIVED 07 NOV 2018

1251

Survivor

NA2

REF:

MS16

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball. or Market Value: 12.5K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

Repair range \$2K - \$4K

Net Value 85K

2/1/18 Submit PAB Report

Veh No: FBA 75437 Yr Regn: 3 AUG 200

Type: A. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CB400 cc 399

Colour: - BLUE A/C: Insured / Std / Nil / K

Sp. Reading: 141, 43 T/Ratio: Insured / Std / Nil / K

Eng/No: \_\_\_\_\_

CrNo: JH2N6V946M760-38

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 150 / 100 RT

R: 160 / 100 RT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or PETZELER

Front Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: mm L/Bal: mm

D.O.A. 31/7/2018 D.O.I. 20/8/18

Survey held at BROTHERS MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT O/S

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: 120

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech Invs (\$)

☐ : Weekend (\$)

) \$ + RS. 10

) Photos

) Others

TOTAL 120

Report Format: \_\_\_\_\_

Lump Sum / L.B.I: (\$)

# PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L

Blk 131 Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref : PS/012/08/18

Date : 28th August 2018

Miss Nurhayati Binte Kamarudin  
c/o Blk 1016 Yishun Industrial Park A  
#01-218  
Singapore 768758

Dear Sir,

Re : **THIRD PARTY CLAIM**

We refer to your instruction to appraise the vehicle **FBA 7543 A** on 20th August 2018.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Brother Motors** for **\$14,190.00** as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of **\$8,200.00 lump sum** corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **FOUR (4) days**. Photographs of the damaged vehicle taken by us during our inspection are enclosed.

We are reverting the matter to you for a decision.


Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

---

**PRESTIGE APPRAISER SERVICES**

  
**LOUIS S C NG CAE AMIMI**  
Dip. MTM. Automotive Engineer  
Licensed Appraiser

Encl.

# PRESTIGE APPRAISER SERVICES

## VEHICLE INSPECTION REPORT

To: Miss Nurhayati Binte Kamarudin  
c/o Bk 1016 Yishun Industrial Park A  
#01-218  
Singapore 768758

Date : 28th August 2018  
Our Ref : PS/012/08/18  
Policy No :  
Sum Insured :  
Excess : T/P Claim

Assigned By : Miss Nurhayati Binte Kamarudin  
Assignment Date : 20th August 2018  
Accident Date : 31st July 2018  
Inspection Date : 20th August 2018  
Workshop Name : Brother Motors  
Survey Conducted At : Bk 1016 Yishun Industrial Park A  
#01-218  
Singapore 768758

### PARTICULARS OF VEHICLE

Registration No	: FBA 7543 A	Mileage	: 141625km
Make/Model	: Honda CB400	Engine No	: NC23E3100145
Type Of Body	: Motorcycle	Chassis No	: JH2NC39946M200128
Year Of Manu./Regn.	: 2006	Passenger Cap.	: 1 Passenger
Colour	: Grey	Others	: -

### CONDITION OF TYRES

Front Tyre : 5mm 120/60ZR17 Metzeler  
Rear Tyre : 5mm 160/60ZR17 Metzeler

*The above represent the estimated remaining life of the tyre treads.*

### PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

### POINT OF IMPACT

The vehicle sustained an impact on the front, R/H & L/H portion.

### GENERAL DESCRIPTION OF DAMAGES

The main body frame, handle bar, fuel tank, forks, wheel rim, exhaust muffler were dented/bent.

For details of damages please refer to schedule attached.

### REMARKS :

This survey was conducted strictly without prejudice.

# PRESTIGE APPRAISER SERVICES

Vehicle No : FBA 7543 A

Our Ref :

PS/012/08/18

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
<u>LIST ITEMS</u>				
1	handle-bar	dented/bent	\$ 160.00	\$ 160.00 / BT
2	handle balancer	necessary	48.00	48.00 / SCR
2	handle grip	necessary	48.00	48.00 XNN
1	R/H mirror	fractured	90.00	90.00 / BC
1	L/H mirror	sliced	90.00	90.00 XNL (BC)ff
1	clutch lever	sliced	68.00	68.00 XSVL
1	brake lever	sliced	68.00	68.00 / SCR
1	brake pump	serviceable	250.00	- XSVL
1	throttle cable	cut	98.00	98.00 / CUT
1	brake cable	cut	85.00	85.00 XSVL
1	meter assy	cracked	950.00	950.00 X METER COVER
1	headlamp	dented/sliced	580.00	/ CRA 580.00 CRA-MHU/
1	headlamp stay	bent	120.00	/ CRA 120.00
2	front signal lamp	sliced	180.00	180.00 X RH RCL
1	front fork assy	warped	800.00	800.00 X LH N/SCL
1	under bracket	bent	280.00	280.00 X LH ST
1	steering cone w/bearing	necessary	180.00	180.00 BT LH N/SCL
1	R/H front brake caliper	serviceable	450.00	180.00 MV X
1	R/H front brake disc	warped	280.00	- XSVL
1	front mudguard	dented/sliced	240.00	280.00 XSVL
1	radiator	dented	820.00	240.00 / SCR
1	coolant	necessary	38.00	820.00 / BT
1	radiator cover	dented	160.00	38.00 / NBL
1	fuel tank	dented/distorted	960.00	160.00 / BT
1	fuel tank lock	serviceable	280.00	960.00 / DD
1	tail cover	sliced	280.00	- XSVL
1	taillamp	scratched	220.00	280.00 / SCR
1	brake pedal	bent	85.00	220.00 XNL (XCL)
1	gear pedal	bent	120.00	85.00 / SCR
1	R/H front foot rest	sliced	70.00	120.00 XNL (XCL)
1	L/H front foot rest	sliced	70.00	70.00 / SCR
1	L/H rear foot rest	sliced	70.00	70.00 XNL (XCL)
1	R/H engine protector bar	dented	180.00	70.00 XNL (XCL)
1	L/H engine protector bar	dented	180.00	180.00 / SCR
1	rear shock absorber	serviceable	680.00	180.00 XNL (XCL)
1	exhaust muffler	dented/sliced	1,200.00	-
1	front wheel rim	warped/sliced	950.00	1,200.00 / DD
1	rear wheel rim	serviceable	850.00	950.00 XSVL
			12,278.00	- XSVL
				9,768.00
		Less 10%	-	976.80
			\$ 12,278.00	\$ 8,791.20
<u>S/NETT ITEMS</u>				
1	rear number plate	dented	22.00	18.00
1	rear box	sliced	260.00	200.00
1	rear box bracket	dented	180.00	140.00
		Balance c/f	\$ 12,740.00	\$ 9,149.20

# PRESTIGE APPRAISER SERVICES

Vehicle No : FBA 7543 A

Our Ref : PS/012/08/18


Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
		Balance b/d	\$ 12,740.00	\$ 9,149.20
	<u>Labour Charges &amp; Misc</u>			
	To dismantle & replace damaged parts, panel beat where necessary.		600.00	<del>480.00</del> 300
	To putty, apply primer & spray-paint on the affected portion.		450.00	<del>350.00</del> 100
	To align main body frame.		350.00	<del>280.00</del> 150
	Transportation charges.		50.00	40.00 ✓ net
			\$ <u>14,190.00</u>	\$ <u>10,299.20</u>

3 days

**Note:** The repairer has agreed to undertake the repairs at our adjusted amount of \$8,200.00 lump sum corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be FOUR ( 4 ) days.  
Pursuant to your instruction we have not authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES



LOUIS S C NG CAE AMIMI (UK)  
Licensed Appraiser  
Dip. MTM. Automotive Engineer

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/08/2018 13:05
Date Of Accident	31/07/2018 18:30
Exact Location Of Accident	KALLANG PAYA LEBAR EXPRESSWAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBA7543A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NURHAYATI BINTE KAMARUDIN
NRIC No	S8428980I
Email Address	NURHAYATI.KAMARUDIN@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-92318124
Alternative Phone No	OTHERS-92318124

### Vehicle Particulars

Manufacturer	HONDA
Model	CB400
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5098137784
Cover Note Number	21/02/18 - 02/02/19

### Driver

Name of Driver	NURHAYATI BINTE KAMARUDIN
NRIC No	S8428980I
Date Of Birth	25/09/1984
Occupation	INDOOR
Date Of Driving Pass	24/11/2009
Driving Experience	8 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92318124
Fax Number	
Contact Number	OTHERS-92318124
Email Address	NURHAYATI.KAMARUDIN@YAHOO.COM.SG

Address	BLK 274D PUNGGOL PLACE #12-838
Postcode	824274
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	SHELTERED
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV4563H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	PAUL LIEW YONG-JIA
NRIC/Passport Number	S7497217I
Contact Number	96800198
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	NURHAYATI BINTE KAMARUDIN
Approximate Age	33
Injuries Sustain	
Injured person in which vehicle?	FBA7543A
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 274D PUNGGOL PLACE #12-838
Postcode	824274

## Sketch Plan

### SKETCH PLAN

VEHICLE NO.: FHA 7543A  
INSURER: NTUC  
DATE & TIME: 30/7/18 15:30

### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders


  
Policyholder's Signature  
Date & Time: 14/08/18

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time

  
Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
NRIC/FIN No.: \_\_\_\_\_

### Sketch Plan #2

### SKETCH PLAN



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

Insurance : MTW      Veh no - FBA7543A      DoA - 31/7/18

(18-30)

Refer Police Report.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time: 14/08/18

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

(74) pag 14/2/18  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FN No.:

( ) Claim Own Policy    ( ☒ ) Claim Third Party    ( ) Reporting Only  
( ) Claim OD/TP at other workshop ( )



**SINGAPORE  
POLICE FORCE**



T/20180801/7011

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408655  
Tel No. 65470000

1 of 3

Report No. T/20180801/7011

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made 01/08/2018 16:36	Vide Report No. G/20180731/0175	Station Diary No.
---	------------------------------------	-------------------

**Informant's Particulars**

Name of Informant: NURHAYATI BINTE KAMARUDIN			Address: APT BLK 274D PUNGGOL PLACE #12-838 SINGAPORE 824274		
ID Type / ID No.: NRIC NO / S8428980I			Contact No. Home/Office: Mobile: 92318124		
Nationality SINGAPORE CITIZEN			Email nurhayati.kamarudin@yahoo.com.sg		
Sex: Female	Age: 33	Date of Birth: 25/09/1984	Type of Informant Rider		
Race Malay			Language: English		Institution / School Name
Occupation: OPERATION TECHNICIAN			Driving Licence Information: Class: 2B,2A,3		
			Date of Expiry		

**General information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 31/07/2018 18:30	Type of Location: Tunnel
Location:  KALLANG PAYA LEBAR EXPRESSWAY				
Weather: Sheltered		Road Surface: Dry		Road Speed Limit: 80 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBA7543A	Motorcycle	HONDA	CB400	Grey		0
SLV4563H	Car	BLUECAR	BLUESG rental car	White	Slightly Damaged	1

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBA7543A	NTUC Income Insurance Co-Operative Limited	5098137784	21/02/2018	02/02/2019



**SINGAPORE  
POLICE FORCE**



T/20180801/7011

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No: T/20180801/7011

## CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	NURHAYATI BINTE KAMARUDIN	ID No.	S84289801
Related Vehicle	FBA7543A (Motorcycle)	Contact No.	92318124
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B,2A.3 Date of Expiry: NIL
Date Treatment	31/07/2018	Date Discharge	01/08/2018
No. of Days granted Medical Leave	05	Degree of Injury	Slight
<b>Driver</b>			
Name	PAUL LIEW YONG-JIA	ID No.	S74972171
Related Vehicle	SLV4563H (Car)	Contact No.	96800198
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details

Accident inside KPE tunnel towards TPE, exactly after ECP entrance into KPE & before PIE (Tuas/Changi) exit. Car switch lane from 3rd lane to 2nd lane, and subsequently 1st lane without exercising due care and proper check. Motorcyclist was on 1st lane at the point of accident. Car swipe motorcycle, motorcyclist fell on right side upon impact. No video/pictures attached.

PR3



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000



T/20180801/7011

3 of 3

Report No: T/20180801/7011

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
IRMAN BIN MOHAMAD SAID  
Contact No: 65476365

Authentication Stamp  
NP168

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required

Date/Time  
01/08/2018 16:36

Classification Of Case

Accident Photo



Accident Photo





Accident Photo



Accident Photo



Accident Photo



Accident Photo



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Paper Survey



































## CLAIM SUBFOLDER TRACKING




































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Aug 2018		17 Aug 2018 15:43 <a href="#">Edit Adj Rpt</a>	<b>\$55,550.00</b> <a href="#">Edit Estimates</a>	<b>\$55,550.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	BLUECAR EAST ASIA PTE LTD, Co. Reg. No.: 201617259H								
Main Claimant:	NURHAYATI BINTE KAMARUDIN, ID: 584289801								
Vehicle Reg. No.:	FBA7543A	Date of Loss:	31/07/2018 18:00 - :59 [143 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 566091	Policy/Cover Note No.:	MSD/VPCP/18-000001 (Comprehensive) Coverage: 01/01/2018 - 31/12/2018						
Vehicle Reg. No. (Insured):	SLV4563H	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Brothers Motor (HQ) BLK 1016 YISHUN INDUSTRIAL PARK A #01-218, 768758 Yishun - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 02/10/2018]								
Driver/Custodian (Insured):	PAUL LIEW YONG-JIA {}, NRIC: S74972171, Tel: +6596800198								
Adj Asg. Remarks:	Liability 100%, SJE disagree - assign LKK, Contact : Mr Tat at 9643 2540								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
• MSIG_SG (28/09/2018): Report Send Back Alerts - FBA7543A (TP)									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FBA7543A (566091)  
[SLV4563H]  
TP  
NURHAYATI BINTE KAMARUDIN  
Jul 31 2018 6:00PM  
[BLUECAR EAST ASIA PTE LTD]  
Brothers Motor

<a href="#">Upload Documents</a>		<a href="#">Upload Photos</a>	<a href="#">Compose New Letter</a>	<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	16/08/18 13:40	<b>Accident Statement</b> <small>From: OD - Reg. No: SLV4563H, Claimant: BLUECAR EAST ASIA PTE LTD</small>	 Load HTM		
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
2	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
3	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
14	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
15	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
16	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
17	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
18	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
19	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
20	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
21	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
22	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
23	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
24	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
25	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
26	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
27	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
28	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
29	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
30	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
31	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
32	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	
33	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
40	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
41	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
42	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
43	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
44	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
45	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
46	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
47	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
48	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
49	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
50	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
51	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
52	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
53	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
54	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
55	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
56	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
57	25/09/18 09:41	General View	 Load JPG	<input checked="" type="checkbox"/>
58	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
59	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
60	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
61	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
62	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
63	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
64	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
65	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
66	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
67	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
68	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
69	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
70	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
71	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
72	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
73	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
74	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
75	25/09/18 09:42	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/08/18 13:43	FBA7543A E-file & Police Report	 Load PDF	
2	16/08/18 13:44	PRI from Centro-Legal Law	 Load PDF	
3	17/08/18 09:20	Survey Disagree on SJE - assign LKK	 Load PDF	
4	27/09/18 19:50	Survey report & Photos	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/11/18 17:29	PRS Invoice	 Load PDF	
2	02/11/18 17:29	Colour Photo	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<div></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18015137/NSD3E2-1

Date: 05/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/18-000001

Claimant Vehicle No: FBA7543A

Insured Vehicle No: SLV4563H

Date of Loss: 31/07/2018

Nature of Claim: TP

Claim No: 566091

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBA7543A

Make &amp; Model: HONDA CB 400 F3WYB, 399cc (M)

Engine No: NC23E3100145

Reg. Date: 03/08/2006 (Man. Year: 2006)

Chassis No: JH2NC39946M200128

Colour: Grey

Odometer: 141628 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60 R17

Rear Tyre Size: 160/60 R17

Front Left Side: Metzeler 6 mm

Rear Left Side: Metzeler 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,740.00	6,155.80	6,584.20	51.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	790.00	660.00	45.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,190.00</b>	<b>6,945.80</b>	<b>7,244.20</b>	<b>51.05</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,550.00</b>		
<b>Nett Amount (S\$)</b>	<b>14,190.00</b>	<b>5,550.00</b>	<b>8,640.00</b>	<b>60.89</b>

INSPECTION

Date of Assignment: 17/08/2018

Date Inspected: 20/08/2018 Inspected At:

 Brothers Motor (HQ)  
 BLK 1016 YISHUN INDUSTRIAL PARK A  
 #01-218  
 Singapore 768758

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	(Last Synchronised: 05 Nov 2018)	
<b>Parts:</b>	N/A	HONDA CB 400 F3WYB 399cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBA7543A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	160.00 F	*160.00 FL
2	2		*HANDLE BALANCER	Scratched	48.00 F	*48.00 FL
3	2		*HANDLE GRIP	Not Necessary	48.00 F	*- FL
4	1		*R/H MIRROR	Broken	90.00 F	*90.00 FL
5	1		*L/H MIRROR (BROKEN)	Not Consistent With The Impact	90.00 F	*- FL
6	1		*CLUTCH LEVER	Serviceable	68.00 F	*- FL
7	1		*BRAKE LEVER	Scratched	68.00 F	*68.00 FL
8	1		*BRAKE PUMP	Serviceable	250.00 F	*- FL
9	1		*THROTTLE CABLE	Cut	98.00 F	*98.00 FL
10	1		*BRAKE CABLE	Serviceable	85.00 F	*- FL
11	1		*METER ASSY (METER SERVICEABLE)	MetercoverCracked	950.00 F	*475.00 FL
12	1		*HEADLAMP	Cracked	580.00 F	*580.00 FL
13	1		*HEADLAMP STAY	Cracked	120.00 F	*120.00 FL
14	1		*FRONT SIGNAL LAMP (N/S SCRATCHED) (N/S NOT CONSISTENT WITH THE IMPACT)	O/S Scratched	180.00 F	*90.00 FL
15	1		*FRONT FORK ASSY (N/S SERVICEABLE) (N/S NOT CONSISTENT WITH THE IMPACT)	O/S Bent	800.00 F	*400.00 FL
16	1		*UNDER BRACKET	Bent	280.00 F	*280.00 FL
17	1		*STEERING CONE W/BEARING	Not Necessary	180.00 F	*- FL
18	1		*R/H FRONT BRAKE CALIPER	Serviceable	450.00 F	*- FL
19	1		*FRONT MUDGUARD	Scratched	240.00 F	*240.00 FL
20	1		*RADIATOR	Dented	820.00 F	*820.00 FL
21	1		*COOLANT	Necessary	38.00 F	*38.00 FL
22	1		*RADIATOR COVER	Bent	160.00 F	*160.00 FL
23	1		*FUEL TANK	Dented	960.00 F	*960.00 FL
24	1		*FUEL TANK LOCK	Serviceable	280.00 F	*- FL
25	1		*TAIL COVER	Scratched	280.00 F	*280.00 FL
26	1		*TAILLAMP (SCRATCHED)	Not Consistent With The Impact	220.00 F	*- FL
27	1		*BRAKE PEDAL	Scratched	85.00 F	*85.00 FL
28	1		*GEAR PEDAL (SCRATCHED)	Not Consistent With The Impact	120.00 F	*- FL
29	1		*R/H FRONT FOOT REST	Scratched	70.00 F	*70.00 FL
30	1		*L/H FRONT FOOT REST (SCRATCHED)	Not Consistent With The Impact	70.00 F	*- FL
31	1		*L/H REAR FOOT REST (SCRATCHED)	Not Consistent With The Impact	70.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*L/H ENGINE PROTECTOR BAR (SCRATCHED)	Not Consistent With The Impact	180.00 F	*- FL
33	1		*REAR SHOCK ABSORBER	Serviceable	680.00 F	*- FL
34	1		*EXHAUST MUFFLER	Dented	1,200.00 F	*1,200.00 FL
35	1		*FRONT WHEEL RIM	Serviceable	950.00 F	*- FL
36	1		*REAR WHEEL RIM	Serviceable	850.00 F	*- FL
37	1		*REAR NUMBER PLATE	Dented	22.00 FS	*18.00 FS
38	1		*REAR BOX	Sliced	260.00 FS	*200.00 FS
39	1		*REAR BOX BRACKET	Dented	180.00 FS	*140.00 FS
40	1		*R/H FRONT BRAKE DISC	Serviceable	280.00 F	*- FL
41	1		*R/H ENGINE PROTECTOR BAR	Scratched	180.00 F	*180.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

<b>Sub Total (\$\$)</b>	<b>12,740.00</b>	<b>6,800.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	<b>0.00</b>	<b>644.20</b>
<b>Total Parts (\$\$)</b>	<b>12,740.00</b>	<b>6,155.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY	New	600.00	300.00
2	TO PUTTY, APPLY PRIMER & SPRAY PAINT ON THE AFFECTED PORTION	New	450.00	300.00
3	TO ALIGN MAIN BODY FRAME	New	350.00	150.00
4	TRANSPORTATION CHARGES	New	50.00	40.00
Gross Labour Cost (\$\$)			1,450.00	790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >