

INSURANCE

INS. CASE OWNER:

Joel.

CC 3/EQ1801

7801, 1/10/16

LKK:

IDAC:

Surveyor:

Edwin

DOI:

ASSIGNMENT

1/10/16

Date / Time:

1/10/16

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBF 1232E

Name of Insured:

MY ENGINEERING PTE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

20/1/15

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

USAMAHAN KNEKUNAR

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

bmupha15-0071K

NISSAN

PAYA LEBER RD

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SH 9222M



INSRS:
WSP:
Tel:
Liability:
RMKS:

COBE
M



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
8/10/16	Non-Reporting hr (1st)	
	Non-Reporting hr (2nd)	
	Non-Reporting hr (Final)	
	Notification hr (if non-pickup)	
	Call CR:	18/10/16 LKMA
	After call hr to CR:	18/10/16 LKMA (Email)
	Documentation Check List:	Handler Typist
12/3/19	Notification hr (if non-pickup)	
14/3/19	After call hr to CR:	
15/3/19	Authorization To Act:	
17/3/19	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
2/4/19	LTA / GIA:	
11/4/19	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE Date/Time:		Sent By:	
FINALIZATION Date/Time:		Confirm with:	
Repair Cost:	SS	days) Reduction:	%
FINAL SETTLEMENT Date/Time: 11/4/19 10am		Confirm with: JIM	
Final Liability:	SS 50%	(Agreed / Assessed) BOLA S/N No. : 19	
Repair Cost:	SS 1725.31	Both changing lane.	
Loss of Rental (LOR):	SS 230	4 days x \$115 (WLGST)	
Loss of Use (LOU):	SS 15	x 4 days	
Loss of Income (LOI):	SS 100	x 4 days	
LOR only	<input type="checkbox"/>	LOU only	<input type="checkbox"/>
LOR + LOU	<input type="checkbox"/>	LOR + LOI	<input type="checkbox"/>
LOI only	<input type="checkbox"/>	LOR + LOU	<input type="checkbox"/>
CLV/LTA Search	SS 7.49		
Medical:	SS		
Disbursement:	SS	(e.g. Tow/Independent)	
Legal Cost	SS		
Total:	SS 2062.80	Global Sum SS: 2065.00	
FINAL PAYMENT Date/Time:		Confirm with:	
Payee 1:	SS 2065.00	Name 1: Confem Belgio Engineering Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

(WLGST)

COPY SENT

on 16/4/19

11/4/19

Girreya: Kalvin

ASSIGNMENT

Veh No: SH 9333M Yr Reg: Apr 2016

Type: M, Car / M, Cycle / Bus / Van / Lorry / T / Prime Mover /

Truck/Trailer or

Make: Hunter 24 cc 168

Colour B/E A/C: Insured G Std / Nil / NA

Sp. Reading 245365 T/Radio: Ins ☒ / Std / NI / NA

End/Not:

C/No: KMHLP46A5U087848

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order Jammed / Leaked / Burnt or

Brake: Inoperative / Jammed / Leaked / Burnt or...

Modl: Nil / S/R'm / STD / R'm of

N/S	C/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Hon Kook*

Front		Rear
-------	--	------

R/Bal.	3	mm	R/Bal.	3	mm
--------	---	----	--------	---	----

L/Sel. 7 mm L/Sel. 7 mm

D.O.A. 29/9/18 D.O.I. 1/10/18

Survey held at: CHÉ (Louvain)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

MP Front.

The V/C / Chassis / Frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	EQ PIP
	PIP = \$3224.88 + towing fee (\$60) @ 3 days repair.
	Red = \$574 14%

☐: Prel. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$

☐ : Site Insp (\$

$$S + RS \rightarrow S_2$$

Photo:

5. Others

Report Format :

Interview (5)

Tech Invs (\$)

Weekend (\$)

TOTAL

Lump Sum / I.B.I.: (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI18017801/K1pb3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 02-10-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 1332E	Veh. Inspected	SH 9333M
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/10/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	29/09/2018	Inspection Date	01/10/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 3860764

JC NO.: 305219667

CUSTOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R)
(P)

(O)

COUNT CARD NO.

REGN NO.:

SH 9333M

MILEAGE

MAKE:

HYUNDAI

FUEL

E 1/2 F

MODEL:

I-40

DATE/TIME IN

29.09.2018 13:10

YR OF MANU

28.04.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU087848

COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 29.09.2018

NATURE: 3P 29.09.18/C

S/NO
000010

LABOR CODE
23-01

DESCRIPTION
TOWING FEE



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SH 9333M JU EQ

Vehicle No.: SH 9333M

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: <u>29/8/18</u> Time Received: <u>1310</u>		3. Vehicle Type:	
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : Contact No. : <u>85119996</u> Vehicle No. : <u>BH9333M</u> Make / Model / Colour : Email :		<input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	
		4. Type of Towing:	
		<input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up	
		5. Nature of Service:	
		<input type="checkbox"/> Jumpstart <input checked="" type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	
7. Location: <u>38 Lor 30 Geylang</u>		6. Parts Replaced/Remarks:	
9. Preferred Workshop:		8. Vehicle Tow - In Workshop:	
<input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:		<input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
10. Odometer Reading : Fuel Level : <u>F 1/4 1/2 3/4 E</u>		11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	
Job Attended			
12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input type="checkbox"/> QA <input type="checkbox"/> STD <input checked="" type="checkbox"/> TZ <input type="checkbox"/> IRS <input type="checkbox"/> OTHERS Name of Driver : <u>ADA-1</u> Vehicle No. : <u>125566J</u> Time Dispatch : <u>1312</u> Time of Arrival : <u>1340</u> Time Completed :		 # : Cracked X : Dented / : Scratched O : Missing Signature of Customer	
Cash Invoice Details (if applicable)			
13. Cash Invoice No. :			
Customer Acknowledgement			
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.			
<u>29/9/18</u> Date		<u>1340</u> Time	
14. WORKSHOP		Signature of Customer	
Name of Attending Staff/Guard		Signature of Attending Staff/Guard	
Date & Time of Arrival		CUSTOMER'S COP	



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/EQ118017801/K1pb3

Date: 02.10.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SH9333M

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 01.10.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,748.88
Revised Estimate Amount	: S\$	3,164.88
"Check" Items Amount	: S\$	17.92
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 9333M

DATE 1/10/2018 10:56

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 1,052.20
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH)			\$ 24.60
	Headlamp (LH)			\$ 1,388.00
	Front Fender (LH)			\$ 566.30
	Front Fender Shield (LH) X			\$ 175.90
	Front Fender Retainer X			\$ 24.60
	Frt Wheel Hub Cap, LH X			\$ 107.10
	SUB TOTAL			\$ 3,361.10
	LESS 20%			\$ 672.22
	DISCOUNTED TOTAL			\$ 2,688.88
	Labour Charge			300
	Panel Beating			\$ 440.00
	Spray Painting Charge			\$ 440.00 400
	Wiring			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 1,060.00
	ESTIMATE TOTAL			\$ 3,748.88
<p> <i>Kalvin 16/10/18</i> <i>1/10/18 1100L</i> <i>3 Days</i> <i>P/P</i> <i>Before Paint photo</i> </p> <div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No legal modification is allowed Supplementary Part(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> </div>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Cecilia Chong (LKK Auto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 4 April 2019 9:34 AM
To: Cecilia Chong (LKK Auto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - DM18HO02632-JG) AND SH9333M (TP : LKK REF -CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Cecilia

Please proceed to resolve this matter up to 50% liability.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the s

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]
Sent: Wednesday, April 3, 2019 4:24 PM
To: Joel Goh
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - DM18HO02632-JG) AND SH9333M (TP : LKK REF -CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Joel,

Have called OI's incharge (Ms Fanny), and they agree to settle based on 50/50 liability. Kindly give us your instruction to proceed. Thanks

Best Regards,
Cecilia Chong | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Monday, 18 March 2019 4:56 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - DM18HO02632-JG) AND SH9333M (TP : LKK REF -CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Cecilia

Please advise if insured is agreeable to settle this matter at 50-50.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Cecilia Chong (LKK Auto) [mailto:CeciliaChong@lkkauto.com]
Sent: Monday, March 18, 2019 4:55 PM
To: Joel Goh
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - DM18HO02632-JG) AND SH9333M (TP : LKK REF -CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Joel,

Yes, the TP AVF have already forward to Insured.

Best Regards,
Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]
Sent: Monday, 18 March 2019 1:58 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - DM18HO02632-JG) AND SH9333M (TP : LKK REF -CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Cecilia

Has third party's video footage been forwarded to insured?

Best Regards,

Joel Goh

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the s

From: Cecilia Chong (LKK Auto) [<mailto:CeciliaChong@lkkauto.com>]

Sent: Monday, March 18, 2019 11:44 AM

To: Joel Goh

Cc: Hsiao Tong (LKKAuto); Admin A

Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - DM18HO02632-JG) AND SH9333M (TP : LKK REF -CC3/EQI18017801/K1pb3) on 29.09.2018

Hi Joel,

I have spoke to the insured, however they do not have any video footage or other evidence to support. Kindly let us have your comments/instructions. Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh [<mailto:joel.goh@eqinsurance.com.sg>]

Sent: Friday, 15 March 2019 2:17 PM

To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - DM18HO02632-JG) AND SH9333M (TP : LKK REF -CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Cecilia

Please advise if this video footage has been shown to insured and if they have other further evidence for this accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the s

From: Cecilia Chong (LKK Auto) [<mailto:CeciliaChong@lkkauto.com>]
Sent: Thursday, March 14, 2019 12:13 PM
To: Joel Goh
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - TBA) AND SH9333M (TP : LKK REF - CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Joel,

Kindly refer to attachment for the video footage from TP.
Base on our opinion, both parties change into the same lane.
We are of the view that BOLA S19 is applicable.
Kindly let us have your comment/instructions. Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Wednesday, 3 October 2018 2:52 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Shu Pei (LKKAuto) <shupe@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - TBA) AND SH9333M (TP : LKK REF - CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Hsiao Tong

Please assist to obtain a copy of third party's video footage before any settlement.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the s

From: Joel Goh
Sent: Wednesday, October 3, 2018 2:47 PM
To: 'Shu Pei (LKKAuto)'
Cc: Admin A; Hsiao Tong (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving GBF1332E (OI : EQI - TBA) AND SH9333M (TP : LKK REF - CC3/EQI18017801/K1pb3) on 29.09.2018

Dear Shu Pei

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the s

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Tuesday, October 2, 2018 5:41 PM

To: Joel Goh

Cc: Admin A; Hsiao Tong (LKKAuto)

Subject: Direct Settlement - Accident Involving GBF1332E (OI : EQI - TBA) AND SH9333M (TP : LKK REF - CC3/EQI18017801/K1pb3) on 29.09.2018

WITHOUT PREJUDICE

Dear Joel,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SH 9333M at M/s ComfortDelGro Engineering Pte Ltd – Loyang.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Thursday, 11 April 2019 2:32 PM
To: Jim Wong See Pah
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Your ref: SH 9333M (Our Ref: CC3/EQI18017801/K1gb3) *** ACCIDENT INVOLVING GBF 1332E & SH 9333M ON 29/09/2018 ***

Without Prejudice

Dear Jim,

We agreed settlement at global sum \$2065.00 as propose by you.
Do note DV not required for this case. Thanks

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jim Wong See Pah [mailto:jimwong@cdge.com.sg]
Sent: Thursday, 11 April 2019 9:51 AM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: Re: Your ref: SH 9333M (Our Ref: CC3/EQI18017801/K1gb3) *** ACCIDENT INVOLVING GBF 1332E & SH 9333M ON 29/09/2018 ***

Without Prejudice

Dear Ms Chong

We propose of sum \$ 2065.00 for resolving our property damage claim amicably.

Thank you.

Best Regards

Jim Wong

Claims Dept / ComfortDelgro Engineering Pte Ltd

From: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>
Sent: Wednesday, 10 April 2019 5:57 PM
To: Jim Wong See Pah
Cc: Hsiao Tong (LKKAuto); Admin A

Subject: Your ref: SH 9333M (Our Ref: CC3/EQI18017801/K1gb3) *** ACCIDENT INVOLVING GBF 1332E & SH 9333M ON 29/09/2018 ***

Your Ref: **SH 9333M**

Without Prejudice

Our Ref: CC3/EQI18017801/K1gb3

Dear Sirs/Madam,

ACCIDENT INVOLVING GBF 1332E(EQI) & SH 9333M ON 29/09/2018


We refer to the above matter.

We are of the opinion that this is a case of both parties changing lane under BOLA S19. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

Brief Details.

On 29/09/2018 at 2pm at X-Junction between Paya Lebar Road and Eunos Avenue 5, while I was driving my company van on the 3rd lane of a four lane road as I wanted to drive straight towards Guillemard Road, a blue comfortdelgro taxi which was stationary at the said junction while waiting for the right turn light to turn green, suddenly changed lane into my lane when my van was going straight. He wanted to turn right even though his lane can drive straight as he was waiting at the said junction for the right turn light to turn green. However, when my van was going straight suddenly the said taxi changed lane into my lane. The said taxi's front side hit onto my van's rear right side when doing so. Both I and the taxi driver alighted from our vehicles and exchanged particulars. No ambulance and police attended to us. The taxi driver told me that he wanted to claim insurance. My company van has no in-vehicle camera but the said taxi has it. I wish to state that after the accident, I felt chest and right shoulder pain which got worst at night hence, I went to Khoo Teck Puat Hospital on 30/09/2018 for medical check up. I received 3 days medical leave. My company van sustained a dented rear right side portion near rear right tyre.

SKETCH PLAN



Strictly without admission of liability whatever, but with a view towards a resolutions of your client's claim in the above matter without resort to litigation, we are prepared to offer 50% towards your client's claim. Please confirm.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

COMFORTDELGRO ENGINEERING

Our Ref : T 0918 / SH 9333M / JW(st)

Your ref :

Date : 09-Nov-18

EQ Insurance Company Limited
5 Maxwell Road, MND Complex
#17-00 Tower Block
Singapore 069110

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Marline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 196506447V

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 9333M YOUR INSURED GBF1332E
AND OTHER ON 29.09.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No : **SH 9333M** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **GBF1332E** we are submitting these claims for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 3,450.62
2	4 days Loss of Rental @ \$ 115.00 per day	\$ 460.00
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing / Medical / Transportation Fees	\$ -
Sub Total :		\$ 3,918.11

HIRER'S CLAIM

7	4 days Loss of Income @ \$ 80.00 per day	\$ 320.00
Total Claims:		\$ 4,238.11

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs : 7 pcs.
- b) LTA search slip/s of : **GBF1332E**
- c) GIA / Police report/s of : **SH 9333M**
- d) Letter of authority from owner / hirer / operator
 - () Witness statement/s () Towing/Medical bill/receipts () Certificate of Insurance
 - (X) Photograph/s of Accident Scene (x) Downtime/Mileage record (x) Rental Rate letter

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Jim Wong

CDGE Claims Department

Tel : 6214 8374 Fax: 6214 1843 Email : jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

COMFORTDELGRO



Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Monday, 18 March 2019 4:54 PM
To: 'HYY_ENG@YAHOO.COM'
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: Our Ref: CC3/EQ18017801/K1pb3*** involving GBF 1332E & SH 9333M ON 29/09/2018
Attachments: SH9333M & GBF1332E TP VID.avi

Our Ref: CC3/EQ18017801/K1pb3

18 March 2019

HYY ENGINEERING (PTE) LTD

Dear Sir/Madam,

ACCIDENT INVOLVING GBF 1332E & SH 9333M ON 29/09/2018

We refer to the above accident where we are acting for EQ INSURANCE COMPANY LIMITED to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Kindly note that we have reviewed this matter and would like to advise that you and/or your authorized driver may not be absolved from blame for this accident.

If you have evidence/information to proof that we should not settle the third party claim, kindly let us have them in writing within the next 10 days i.e. by 28/03/2019, after we shall proceed with negotiation with Third Party claimant on the **without prejudice basis** and any settlement should not bind any claims whatsoever by you/your driver against the other party's insurer arising from this particular accident.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please note that Third Party have submitted their video footage to us. Refer to attachment for your viewing.

Please call us if you have further queries.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONGI 40 SH9333M , GBF1332E
PAYA LEBAR RD X GEYLANG EAST CENTRAL

ON 29-Sep-18 12:20

I / We

LEE YEW NYEN

(Hirer) NRIC No.: S7303368C

and/or

(Relief) NRIC No.:

Taxi Number

SH9333M

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

30-Sep-2018

Name of Hirer
Hirer NRICLEE YEW NYEN
S7303368C

Signature :



Address

688 HOUGANG STREET 61 #11-220
530688

Contact No.

85119996

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W

Page: 1

8010325

RQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD TOWER BLOCK #17-00
SINGAPORE SG 069110

CONTACT NO: 62239433

VEHICLE NO
SH 9333M

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
28.04.2016

CHASSIS CODE
KMHLB41UMGUG087848

INV. NO/DATE
91404284 29.10.2018

JOB NO.
305219667

ODOMETER READING

DATE/TIME IN
29.09.2018 13:10

Description : 3P 29.09.18/C

S/No	Part No.		Qty	Unit Price	Wdisc	Net
PART REQUISITION						
0001	04-01-0103-2322	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76
0002	04-01-0103-0781	I40V2 LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40
0003	04-01-0103-0574	I40VC PANEL-FRONT LH+	1	566.30	20.00	453.04
0004	04-01-0103-0639	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68
SUB-TOTAL				:		2,424.88

JOB NATURE

0001	23-01	TOWING FEE	60.00	60.00
0002	I	PANEL BEATING- FRT.	300.00	300.00
0003	23-502	SPRAYPAINT ON AFFECTED AREA	400.00	400.00
0004	17-01	CHECK ALL LIGHTING	20.00	20.00

WE HEREBY ACCEPT ALL FINANCIAL RESPONSIBILITIES ARISING FROM THIS TAX INVOICE. WE AGREE TO BE RESPONSIBLE FOR THE PAYMENT OF ALL TAXES AND CHARGES ARISING FROM THIS TAX INVOICE. WE AGREE TO BE RESPONSIBLE FOR THE PAYMENT OF ALL TAXES AND CHARGES ARISING FROM THIS TAX INVOICE.

WE HEREBY AGREE TO BE RESPONSIBLE FOR THE PAYMENT OF ALL TAXES AND CHARGES ARISING FROM THIS TAX INVOICE. WE AGREE TO BE RESPONSIBLE FOR THE PAYMENT OF ALL TAXES AND CHARGES ARISING FROM THIS TAX INVOICE.

WE HEREBY AGREE TO BE RESPONSIBLE FOR THE PAYMENT OF ALL TAXES AND CHARGES ARISING FROM THIS TAX INVOICE. WE AGREE TO BE RESPONSIBLE FOR THE PAYMENT OF ALL TAXES AND CHARGES ARISING FROM THIS TAX INVOICE.

WE HEREBY AGREE TO BE RESPONSIBLE FOR THE PAYMENT OF ALL TAXES AND CHARGES ARISING FROM THIS TAX INVOICE. WE AGREE TO BE RESPONSIBLE FOR THE PAYMENT OF ALL TAXES AND CHARGES ARISING FROM THIS TAX INVOICE.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHO No.
8010325	91404284	3,450.62	

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 2

8010325

RQ INSURANCE COMPANY LIMITED

5 MAXWELL ROAD TOWER BLOCK #17-00
SINGAPORE SG 069110

CONTACT NO: 62239433

VEHICLE NO
SH 9333M

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
28.04.2016

CHASSIS CODE
KMH1R411UMSU087848

INV. NO/DATE
91404284 29.10.2018

JOB NO.
305219667

(ODOMETER READING)

DATE/TIME IN
29.09.2018 13:10

S/No	Part No.		Qty	Unit Price	%Disc	Net
0005	20-00	TUFF COAT ON AFFECTED PARTS.	20.00			20.00
SUB-TOTAL:						800.00

Items total	3,224.88
Add GST @ 7.000 %	225.74
Invoice amount	3,450.62

Issued by : KATHERINETAN 29.10.2018 11:13:36
Repair type : CSO/57/57
Payment Type/Term: /Credit 30 days

BY ACCEPTING THIS INVOICE, THE CUSTOMER AGREES TO THE FOLLOWING TERMS AND CONDITIONS:
1. THE COMPANY'S LIABILITY FOR DAMAGE OR LOSS OF OTHERS' PROPERTY IS LIMITED TO THE AMOUNT OF THE INVOICE.
2. THE CUSTOMER SHALL INSPECT THEIR VEHICLE IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM WHICH THE COMPANY'S LIABILITY FOR DAMAGE OR LOSS OF OTHERS' PROPERTY IS LIMITED TO THE AMOUNT OF THE INVOICE.
3. THE CUSTOMER SHALL NOT MAKE OR HAVE MADE ANY REPAIRS OR ALTERATIONS TO THE VEHICLE WITHOUT THE WRITTEN PERMISSION OF THE COMPANY.
4. THE CUSTOMER SHALL NOT USE THE VEHICLE FOR ANY PURPOSES OTHER THAN THE PURPOSES FOR WHICH IT WAS DESIGNED.
5. THE CUSTOMER SHALL NOT USE THE VEHICLE FOR ANY PURPOSES OTHER THAN THE PURPOSES FOR WHICH IT WAS DESIGNED.
6. THE CUSTOMER SHALL NOT USE THE VEHICLE FOR ANY PURPOSES OTHER THAN THE PURPOSES FOR WHICH IT WAS DESIGNED.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010325	91404284	3,450.62	

Our Ref: CT18090829

Date: 04 October 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON	29/09/2018 @ 12:20 hrs
ALONG	PAYA LEBAR RD X GEYLANG EAST CENTRAL
INVOLVING	GBF1332E

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH9333M** (the "Taxi"). The Taxi was hired to **LEE YEW NYEN IC NO S7303368C** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$115.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **India International Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
GBF1332E	29 Sep 2018 / 12:20:00	Successful	E04	EQ INSURANCE COMPANY LTD

Previous OK



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 18/04/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBF 1332E (Insd Veh)	Your Ref. No. : DMCPHQ18-003128
	SH 9333M (TP Veh)	Our Ref. No. : CC3/EQI18017801/K1gb3q2
Date of Accident	29/9/2018	

Liability	50%	
Final Repair Cost	: \$ 1,725.31	
Loss of Income	: \$ 100.00	4 days
Rental (If any)	: \$ 230.00	4 days
Others:	: \$ 7.49	
	: \$	
	2,062.80	
Final Settlement Sum	: \$ 2,065.00	GLOBAL SUM
Remarks	:	

Payment Instruction: Payee's Breakdown		
1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$ 2,065.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQI18017801/K1gb3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 18-04-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 1332E	Veh. Inspected	SH 9333M
Policy No.	DMCPHQ18-003128	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	01/10/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU087848	Colour	BLUE
Odometer	245365	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	29/09/2018	Inspection Date	01/10/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9333M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER COVER	DEFORMED	1,052.20	1,052.20
1	FRONT BUMPER BRACKET TOP (LH)	SERVICEABLE	22.40	-
1	FRONT BUMPER BRACKET (LH)	CRACKED	24.60	24.60
1	HEADLAMP(LH)	CRACKED	1,388.00	1,388.00
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER SHIELD (LH)	SERVICEABLE	175.90	-
1	FRONT FENDER RETAINER	SERVICEABLE	24.60	-
1	FRT WHEEL HUB CAP ,LH	SERVICEABLE	107.10	-
	LESS 20% DISCOUNT		-672.22	-606.22
			2,688.88	2,424.88
	<u>LABOUR</u>			
	PANEL BEATING .		440.00	300.00
	SPRAY PAINTING CHARGE.		440.00	400.00
	WIRING .		50.00	20.00
	TUFF KOTE.		50.00	20.00
	FRT WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TOWING FEE.		60.00	60.00
			1,120.00	800.00
	GRAND TOTAL		3,808.88	3,224.88
	RECOMMENDED COST OF REPAIRS			3,224.88

Report Ref No. CC3/EQ18017801/K1gb3q2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Joanne Lee (LKK Auto)

From: Joanne Lee (LKK Auto) <report@lkkauto.com>
Sent: Thursday, 18 April 2019 3:27 PM
To: 'Joel Goh'
Subject: TP Direct Settlement - Accident Involving GBF 1332E (OI) and SH 9333M (TP) on 29/09/2018
Attachments: LKK REPORT & PHOTO.pdf; TP DS SUPPORTING DOCUMENT.pdf

Dear Sir/Madam,

Please be informed that the above-mentioned case had been settled.

Enclose herewith final report & relevant documents for your necessary action please.

Thank you.

Best Regards,

JOANNE | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933