

ASS. REC. BY: _____ REF: CS3/FCI/8017829/RICd3^{SR} Special Instruction: _____

Surveyor: Rasul ASSIGNMENT (Office)

From (Person): Sifhera of FCI Date/Time: 21/10/18 @ 2:34pm

Estimated Cost: _____ Bill to: _____

OD (IP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JSM 8536 Insured: SHA 82417

at Workshop m/s: Sincere lead Tel: 8510 9999

of 38 Woodlands Ind. Park E1 #05-13

Policy No: _____ Claim No: D18007169MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29/9/18
(Client's Record) 3/10/18 @ Afternoon

CA / REV / REP. / REV 24 HRS (up) H.O.D. Endorsement: _____

Date/Time: 3:05pm @ 21/10/18 Person Contacted: Xia Foong Vehicle: IN / OUT

Date/Time	Action/Instruction (X) Estimate
	JSM 8536 - X
	SHA 82417 - CS/FCI/8013058 / Urd 3rd DOA: 30/5/18
12-10-2018 @ 11am	Xiao Fong not yet get log card from owner.

MOTOR SURVEY ASSIGNMENT

Date	01-10-2018	Our Ref No. D18007169MFSH
Accident Date	29-09-2018	Claim Type. Third Party
Insured Vehicle	SHA8241T	Third Party Vehicle. JSM8536
Survey Location	38 WOODLANDS INDUSTRIAL PARK E1 #05-13	
Contact Person.	MANOJ KUMAR ROY	
Contact No.	65368466/ 0	Fax No. 65361963
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SINCERE LEAD	Attention. NIL
Cc : TP Solicitor	ROY & PARTNERS	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/244656)



PRI Documents



Close



PRI Header Details

Claim No	D18007169MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & ROY & PA
Workshop Name	SINCERE LEAD (Contact Person : MANOJ KUMAR ROY)	Survey Location & Contact Details	38 WOODLANDS INDUSTRIAL PARK E1 #05-13 Mobile: 0 , Phone: 65368466 , Fax: 65361963 EmailId: ROYNPARTNERS@ROYPARTNERS.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA8241T	TP Vehicle No	JSM8536
PRI Recieved Date	01-10-2018 07:15:14 PM	Surveyor Appointed Date	02-10-2018 02:33:00 PM	Surveyor Accept Date	04-10-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-10-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

ROY & PARTNERS

(Business Registration No. 53131170L)

Advocates & Solicitors

Commissioner For Oaths

Notary Public

MONOJ KUMAR ROY LLB (Hons.) S'pore

HARPAL SINGH BAJAJ LLB (Hons.) London

101 Cecil Street #11-09 Tong Eng Building, Singapore 069533

Tel : 6536 8466

Fax : 6536 1963 (Not For Service Of Documents)

Enquiries: roynpartners@roynpartners.com.sg

Your Ref : Your insured vehicle: SHA 8241T

Our Ref : MKR/403/8278/2018/as.wl;

1st October 2018

IMMEDIATE ATTENTION

MS FIRST CAPITAL INSURANCE LTD

BY FAX: 6507 3849 ONLY

30 Robinson Road

#10-01/02 Robinson Towers

Singapore 048546

(Attn: Motor Claims Department)

Dear Sirs,

CLAIMANT : LIM CHEE POH

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. JSM 8536 AND SHA 8241T
ALONG GAMBAS AVENUE ON 29.09.2018 AT ABOUT 1430 HOURS.**


We refer to the above matter.

We act for Lim Chee Poh, the owner of motor vehicle No. **JSM 8536**.

We are instructed by our client to notify you of a road traffic accident on 29th September 2018 at about 2.30 pm along Gambas Avenue involving our client's motor vehicle registration number **JSM 8536** and motor taxi registration number **SHA 8241T** driven by your insured at the material time. A copy of the Traffic police report is enclosed.

As a result of the accident, our client's motor vehicle **JSM 8536** has been damaged. Before our client proceed to repair the damaged motor vehicle, please let us know within **two (2) working days** of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor vehicle **JSM 8536** at our client's repairer workshop, M/s Sincere Lead Automotive at 38 Woodlands Industrial Park E1 #05-13 Singapore 757700, Your said surveyor may contact Mr. Raymond Chua at 9815 8858. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor vehicle without further reference to you.

Yours faithfully



MONOJ KUMAR ROY

Encl.

Cc: Clients (SINCERE LEAD AUTOMOTIVE)
(JSM 8536)

.By Email)



**SINGAPORE
POLICE FORCE**



T/20180929/7015

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20180929/7015

CONTINUATION OF REPORT

Rider			
Name	LIM CHEE POH	ID No.	880316235059
Related Vehicle	JSM8536 (Motorcycle)	Contact No.	97792877
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	02	Degree of Injury	Slight
FRIEND			
Name	LAI LIEW FOONG	ID No.	G8483551Q
Related Vehicle	NIL	Contact No.	85109999
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the stated time and date, my motorcycle was stopped at Gambas Avenue (Yishun) due to red traffic light ahead. Suddenly, I felt a great impact coming from the rear. After the collision, I fall on the ground. Then I realized a taxi bearing registration number SHA8241T had collided onto the rear of my motorcycle. I was conveyed to Khoo Teck Puat Hospital after that. I was given 2 days of medical leave. A passerby help to take a few accident scene photos & call for ambulance. That is all.



**SINGAPORE
POLICE FORCE**



T/20180929/7015

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20180929/7015

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report: Not applicable
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / TPHQ / SHAHRUL NIZAM BIN SAMARRI Contact No.: 65476904

Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Date/Time: 29/09/2018 20:05
Classification Of Case:

Authentication Stamp
NP168


**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS3/FCI18017829/R1cd3s2 Date: 25-10-2018	
		Code: FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SHA 8241T	Veh. Inspected	JSM 8536
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18007169MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	02/10/2018
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA FZ 150I (S)	c.c	0
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	PMYRG3410G0005967	Colour	MULTI
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	90/80-17	MAXXIS	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	90/80-17	MAXXIS	3 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY.			
5. General Information			
Accident Date	29/09/2018	Inspect Date / Time	04/10/2018 (12:11 PM)
Survey held at	SINCERE LEAD AUTOMOTIVE 280 WOODLANDS INDUSTRIAL PARK E5 #02-10 SINGAPORE 757322		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/FCI18017829/R1cd3s2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.