



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                |                       |                              |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|-----------------------|------------------------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD                                                                                                                  |                                                                |                       | Ref : CC4/ASM18017871/Npa3q2 |                                                                                     |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN:WINNIE                                                                       |                                                                |                       | Date : 08-07-2020            |  |
|                                                                                                                                        |                                                                |                       | Code : ASM                   |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                |                       |                              |                                                                                     |
| Insured Veh.                                                                                                                           | GBG 2387K                                                      | Veh. Inspected        | SMC 4926H                    |                                                                                     |
| Policy No.                                                                                                                             | CV1/GA367024                                                   | Coverage (\$)         | 0.00                         |                                                                                     |
| Claim No.                                                                                                                              | S8M00XJ5                                                       | Excess (\$)           | 0.00                         |                                                                                     |
| Assign From                                                                                                                            |                                                                | Assign Date           | 01/10/2018                   |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                |                       |                              |                                                                                     |
| Make & Model                                                                                                                           | TOYOTA C-HR HYBRID 1.8G                                        | c.c                   | 1797                         |                                                                                     |
| Engine No.                                                                                                                             | HIDDEN                                                         | Year of Reg.          | 2018                         |                                                                                     |
| Chassis No.                                                                                                                            | ZYX102087097                                                   | Colour                | SILVER                       |                                                                                     |
| Odometer                                                                                                                               | 17300                                                          | Steering              | IN ORDER                     |                                                                                     |
| Brakes                                                                                                                                 | IN ORDER                                                       | Modification          | STANDARD ALLOY RIM           |                                                                                     |
| General                                                                                                                                | FAIR                                                           |                       |                              |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                |                       |                              |                                                                                     |
|                                                                                                                                        | Size                                                           | Make                  | Balance                      |                                                                                     |
| R/H Front Tyre                                                                                                                         | 225/50 R18                                                     | MICHELIN              | 5 mm                         |                                                                                     |
| L/H Front Tyre                                                                                                                         | 225/50 R18                                                     | MICHELIN              | 5 mm                         |                                                                                     |
| R/H Rear Tyre                                                                                                                          | 225/50 R18                                                     | MICHELIN              | 5 mm                         |                                                                                     |
| L/H Rear Tyre                                                                                                                          | 225/50 R18                                                     | MICHELIN              | 5 mm                         |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                       |                                                                |                       |                              |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.<br>DAMAGES SEE DETAILS.                                                                 |                                                                |                       |                              |                                                                                     |
| <b>5. General Information</b>                                                                                                          |                                                                |                       |                              |                                                                                     |
| Accident Date                                                                                                                          | 28/09/2018                                                     | Inspection Date       | 23/11/2018                   |                                                                                     |
| Survey held at                                                                                                                         | HUA HONG PTE LTD<br>25D SUNGEI KADUT STREET 1 SINGAPORE 729332 |                       |                              |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                     |                                                                |                       |                              |                                                                                     |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                |                       |                              |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                |                       |                              |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                | <b>3 Working Days</b> |                              |                                                                                     |