

(08/11/13)

Surveyor: James

REF:

17875 / P17 / 7144H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 83104at Workshop m/s Volkswagenof 17, runs m/s 9Insured: AXA / up

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 119K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLC 83104 Yr Regn: 2016 / MAYType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Passat B82.0 c.c. 1984Colour: BROWNA/C: Insured / Std / NI / NASp. Reading: 33075T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW2223CZGE210485Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 235/45R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 30/09/18D.O.I. 03/10/18Survey held at TUUSDes. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

03/10/18 @ 0945 . Call owner that Rear windscreen glass is cracked due to accident. Owner said he wanted to get his thing inside the boot and placed accidentally while opening the boot lid hit the rear windscreen glass.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7144H
Vehicle Details	
Vehicle No.:	SLC8310U
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Oct 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT B8 2.0 TFSI AT SR 3G24MY
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	CHH149473
Chassis No.:	WVWZZZ3CZGE210485
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$34,373.00
Original Registration Date:	26 May 2016
First Registration Date:	26 May 2016
Transfer Count:	0
Actual ARF Paid:	\$40,123.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2026
PARF Rebate Amount:	\$30,092.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,970.00
COE Rebate Amount:	\$35,896.00
Total Rebate Amount:	\$65,988.00

The information contained herein is correct as at 03 Oct 2018

OK

119,000
 65,988
 53,012
 32k