

ASS. REC. BY:

REF:

TV /

A878/Km (P)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

I.B.I %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

12/10 File pass to Catherine

\$ 1,605.44

Veh No:

SLW 69321A

Regn: 10.15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 3

c.c. 1.496

Colour:

M. Green

A/C: Insured / Std / NI / NA

Sp. Reading

67857

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Jm6BM42ABG0321158

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

27/8/18

D.O.I.

11/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SHD6504H (III)

Accident Date : 27-09-2018

Date : 01-10-2018

Our Ref : SLW6932H / CHAN

ALAN'S UNITED AUTO PTE LTD

BLK 7 SIN MING IND. EST. SECTOR C

#01-76

SINGAPORE 575642

Not Withheld

Resurvey B4 paint

3 days

ESTIMATE COST OF REPAIR FOR MAZDA 3 1.5L SEDAN SLW6932H

1 PC	FRONT BUMPER FASCIA	<i>Bul/en</i>	\$1,083.10	✓
1 PC	FRONT O/S BUMPER FOGLAMP COVER	<i>Gr</i>	\$48.70	✓
1 PC	FRONT O/S BUMPER SIDE RETAINER	<i>SL</i>	\$19.65	X
			\$1,151.45	
		LESS 20%	\$230.29	
			\$921.16	

\$921.16

TO PUTTY AND SPRAY REPLACED PARTS

\$600.00

400L

TO REMOVE DAMAGED PARTS, PANEL BEATING, ALIGN, REFIX AND TO RENEW ABOVE PARTS

\$500.00

300L

\$2,021.16

Singapore Dollars Two Thousand Twenty One And Cents Sixteen Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Print Received Message

This mail is associated with :

***SLW6932H (MCT18090795)
[SHD6504H]**

TP

ALAN'S UNITED AUTO PTE LTD

Sep 27 2018 4:00PM

[COMFORT TRANSPORTATION PTE LTD]

Alan's United Auto Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 14/01/2019 09:42 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$978.91) - SLW6932H - Claim Handler: Sundari Nagarajan

Approved:978.91.

ALAN'S UNITED AUTO PTE LTD

Blk 7 Sin Ming Industrial Estate
#01-76
Singapore 575642

Date: 16-10-2018

INDIA INTERNATIONAL INSURANCE PTE LTD
MOTOR CLAIMS DEPT.
64 CECIL STREET
#04-00 / #05-00
IOB BUILDING
SINGAPORE 069711

Dear Sir / Madam

ACCIDENT INVOLVING MOTOR VEHICLES SLW6932H AND SHD6504H
ALONG SIN MING IND. EST. SECTOR C BLK 187 SVC RD ON 27-09-2018

I / We, the owner of Vehicle No. SLW 6932 H which was involved in the above accident.

My / Our vehicle sustained damages as a result of the above said accident and I / we are now claiming against you for the followings:-

- | | | |
|---|---|-------------------|
| 1. Costs of repair | - | \$1717.82 |
| 2. Loss-of-Use/Rental fees 4 days (per) | - | \$ 200.00 |
| 3. Police / GIA report / LTA fees | - | |
| 4. Surveyor report fees | - | |
| 5. Others | - | |
| Total: | | <u>\$ 1917.82</u> |

Please advise whether you are now prepare to settle my claims as outlined above.

I / We hereby authorise my / our repairers, M/s Alan's United Auto Pte. Ltd. and/or their representatives to negotiate/compromise settlement of my / our above claim on my / our behalf. If there is a settlement I / we further authorise you to pay whatever settlement sum to my / our repairers being the outstanding repair bill and incidentals due to them.

Your kind attention and prompt settlement is much appreciated.

Yours faithfully,



LETTER OF AUTHORITY

ACCIDENT INVOLVING SLW6932H AND SHD6504H
ALONG SIN MING IND. EST. SECTOR C BLK 1 & 7 SVC RD
ON 27-09-2018

BY THE LETTER OF AUTHORITY, I/We, ALAN'S UNITED AUTO PTE LTD
NRIC NO. 201113667 N The owner of Vehicle No. SLW6932H

Hereby irrevocably appoint Messrs **Alan's United Auto Pte. Ltd.** at Block 7, Sin Ming Industrial Estate, Sector C, #01-76, Singapore 575642, and/or their representative to process the Third Party claim on my/our behalf and to do all and/or any of the followings:-

1. To submit, negotiate/compromise and to resolve settlements of my/our above mentioned claim.
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favor of **Alan's United Auto Pte. Ltd.**
3. For any of the purpose aforesaid, to execute, sign and deliver all documents whatsoever as they deem necessary for the purpose of settling my/our said claim.

I / We hereby declare that all the processing and documents done by virtue of this letter of authority on my/our behalf by my/our repairers or any person authorized by them shall be as good valid and effectual to all intends and purposes whatsoever as if the same had been done or executed by me/us in person.

I / We further confirm that the acceptance by Messrs **Alan's United Auto Pte. Ltd.** of the settlement amount constitute the full discharge of my/our claim(s) in respect of the above accident.

Signed on the 28 (day) 09 (month) 2018 (year)



Acknowledged by Owner
(company stamp if applicable)

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT18090795
Claimant Ref: SLW 6932H

We/I, ALAN'S UNITED AUTO PTE. LTD. ("The workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 858.91 (repair cost), S\$ 100.00 (loss of use/rental), S\$ - (search fee), vehicle no. SLW 6932H that was damaged pursuant to the accident which occurred on 27/09/18 (date) at SECTOR C SIN MING IND. ESTATE (location) involving vehicle no. SHD 6504H (insured vehicle). This is pursuant to the inspection conducted on 11/10/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ALAN'S UNITED AUTO PTE LTD ("the third party claimant") of vehicle no. SLW 6932H to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLW 6932H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 958.91 to ALAN'S UNITED AUTO PTE.LTD.

Dated this 30th day of JAN 20 19

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

NRIC:

Address:

Nationality:

Occupation:

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

NRIC:

Address:

Nationality:

Occupation:



LKK AUTO CONSULTANTS PTE LTD

199607198R

51 UBI AVENUE 1 #01-25

PAYA UBI INDUSTRIAL PARK (S) 408933

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 15624

Date : 16-Oct-2018

PAGE : 1

Vehicle Insured : SHD6504H
Accident Date : 27-Sep-2018

Our Ref : 218166 (III) / CHAN

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#04-00/#05-00
IOB BUILDING
Singapore 049711

FINAL REPAIR COST FOR MAZDA 3 1.5L (A) SLW6932H
=====

1 pc Front bumper fascia	1,083.10	
1 pc Front o/s bumper foglamp cover	48.70	

	1,131.80	
Less 20% :	226.36	

		905.44
To putty and spray replaced parts		400.00
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts		300.00

		1,605.44
Add 7% GST :		112.38

Total :		S\$ 1,717.82
		=====

Singapore Dollars One Thousand Seven Hundred
and Seventeen and Cents Eighty Two Only

ALAN'S UNITED AUTO PTE. LTD.



Authorised Signature

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Oct 2018 Edit Reg		02 Oct 2018 00:00 Edit Adj Rpt	S\$1,605.44 Edit Estimates	S\$1,605.44 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	ALAN'S UNITED AUTO PTE LTD , Co. Reg. No.: 201113667N								
Vehicle Reg. No.:	SLW6932H	Date of Loss:	27/09/2018 16:00 - :59 [35 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18090795	Policy/Cover Note No.:	MCOM0015 (TP, Fire & Theft)						
Vehicle Reg. No. (Insured):	SHD6504H	Policy No. (Claimant):	Z18VC40102095						
		Excess:							
Repairer:	Alan's United Auto Pte Ltd (HQ) Bk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 11/10/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (30/01/2019): Alert - Adj Mandate Approved (S\$0.00) - SLW6932H - Claim Handler: Sundari Nagara... - III_SG (14/01/2019): Alert - Adj Mandate Approved (S\$978.91) - SLW6932H - Claim Handler: Sundari Naga... - III_SG (30/10/2018): Alert - Adj Mandate Approved (S\$0.00) - SLW6932H - Claim Handler: Sundari Nagara...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW6932H (MCT18090795)
[SHD6504H]
TP
ALAN'S UNITED AUTO PTE LTD
Sep 27 2018 4:00PM
[COMFORT TRANSPORTATION PTE LTD]
Alan's United Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	30/10/18 14:06	Video - Accident CCTV		Load MP4	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/01/19 17:17	General View		Load JPG	☒
2	11/01/19 17:17	General View		Load JPG	☒
3	11/01/19 17:17	General View		Load JPG	☒
4	11/01/19 17:17	General View		Load JPG	☒
5	11/01/19 17:17	General View		Load JPG	☒
6	11/01/19 17:17	General View		Load JPG	☒
7	11/01/19 17:17	General View		Load JPG	☒
8	11/01/19 17:17	General View		Load JPG	☒
9	11/01/19 17:17	General View		Load JPG	☒
10	11/01/19 17:17	General View		Load JPG	☒
11	11/01/19 17:17	General View		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/10/18 20:00	ACKNOWLEDGEMENT EMAIL TO III DD 02.10.2018		Load PDF	
2	02/10/18 20:00	TP ESTIMATE + TP GIA REPORT		Load PDF	
3	23/10/18 17:49	TP ESTIMATE - MARKED		Load PDF	
4	21/12/18 12:36	WORKSHOP INVOICE		Load PDF	
5	21/12/18 12:36	LOD		Load PDF	
6	14/02/19 10:03	DISCHARGE VOUCHER		Load PDF	
7	14/02/19 10:03	AUTHORISATION TO ACT FORM		Load PDF	

No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	03/10/18 09:21	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18017878/KJA3Q2

Date: 14/02/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLW6932H	Insured Vehicle No :	SHD6504H
Date of Loss:	27/09/2018	Nature of Claim:	TP
		Claim No:	MCT18090795

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW6932H	Engine No:	HIDDEN
Make & Model:	MAZDA 3, 1.5 (A)	Chassis No:	JM6BM42A8G0321158
Reg. Date:	01/10/2015 (Man. Year: 2015)	Odometer:	67657 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	921.16	905.44	15.72	1.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	700.00	400.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,021.16	1,605.44	415.72	20.57
+ GST 7.00/7.00% (S\$)	141.48	112.38	29.10	20.57
Nett Amount (S\$)	2,162.64	1,717.82	444.82	20.57
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
		(S\$) 1,917.82		
Liabe Amount (50.00%) (S\$)		958.91		

INSPECTION

Date of Assignment:	02/10/2018	
Date Inspected:	11/10/2018	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG**Manager:** Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Dec 2018)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW6932H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Buckled / Cut	1,083.10 FL	*1,083.10 FL
2	1		*FRONT O/S BUMPER FOGLAMP COVER	Cut	48.70 FL	*48.70 FL
3	1		*FRONT O/S BUMPER SIDE RETAINER	Serviceable	19.65 FL	*- FL
					Sub Total (S\$)	1,151.45
					- List Item Discount on L Items 20.00/20.00% (S\$)	230.29
					Total Parts (S\$)	921.16

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	400.00
2	TO REMOVE DAMAGED PARTS ,PANEL BEATING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	500.00	300.00
Gross Labour Cost (S\$)			1,100.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >