



Your Ref: AEMD/105/009/2018/118

Date: 19th October 2018

Our Ref: CS1/SPF18017881/Bsd3s2

M/s Automotive Engineering & MGT Division

Contract Management Section

(Singapore Police Force)

1 Mount Pleasant Road

Blk 8 Old Police Academy

Singapore 298333

(The Motor Claims Department)

Attn: Frankie Thay

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:
SLK 8543Y INSURED VEHICLE: QX 704A ACCIDENT DATE: 06/07/2018**

We thank you for your instruction on 02/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLK 8543Y from M/s Borneo Motors (S) Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLK 8543Y.
- c) Colour damaged vehicle photographs of SLK 8543Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLK 8543Y
Make & Model	: Toyota Corolla Altis, 1.6
Year of Registration	: 2017
Chassis Number	: MR053REH104559861
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 9 (Nine) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.