

22/03/2002

ASS. REC. BY:

REF:

CS/CTI18017886/Nvd301

Special Instruction:

Surveyor:  
Meimien

Naz

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time: 31/10/18 @ 10:55am

Estimated Cost:

Bill to:

OD / ☒ TP / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL948K

Insured:

GBF 308H

at Workshop m/s

Kah Motor

Tel:

65145248 / 8288 6302

of

6A Mandai Estate

Policy No:

DMCVSN3037681801

Claim No:

SNM18D04669C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/09/18

CA / REV / REP. / REV 24 HRS 1up

H.O.D. Endorsement:

Date/Time:

12:01pm @ 31/10/18

Person Contacted:

Annika

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

SLL948K - X

GBF308H - X

26/10/18

@ 12:22pm Annika will email us finalise

16/11/18

@ 2:59pm Annika will email us finalise

21/11/18

Recd email from Annika vehicle convert to OD claim

Surveyor: NAZ

REF: CTI

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLC 948K Yr Regn: 14 FEB 2017  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: HONDA CIVIC C.C. 1,597  
 Colour: WHITE A/C: Insured / Std / NI / NA  
 Sp. Reading: 22,513 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: MRHFC 56506T00.1091  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 215/55 R16  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or HANKOOK  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 8 mm R/Bal. 6 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 28/9/18 D.O.I. 3/10/18  
 Survey held at KAH MOTOC  
 Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

>>11/18 Submit preli report

RECEIVED 22 NOV 2018

Date/Time, File Pass to?

☒ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2) >>11-typist

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_) S + RS. SI  
☐ : Interview (\$ \_\_\_\_\_) Photos  
☐ : Tech. Invs (\$ \_\_\_\_\_) Others  
☐ : Weekend (\$ \_\_\_\_\_)

TOTAL

220

220

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2018		03 Oct 2018 10:55 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LAUNDRYMART PROFESSIONAL PTE LTD, Co. Reg. No.: 201303465M		
Main Claimant:	LOW JIH YNG, ID: S6844548E		
Vehicle Reg. No.:	SLL948K	Date of Loss:	28/09/2018 06:00 - :59
Claim Type:	TP / SNM18D04669C02	Policy/Cover Note No.:	DMCVSN3037681801 (Comprehensive)
Vehicle Reg. No. (Insured):	GBF308H	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/10/2018]		
Driver/Custodian (Insured):	LEE DUO RUEY (57 / Male), NRIC: S1511476B, Tel: +6596506639		
Adj Asg. Remarks:	EST \$24,117.65, CASE WITH SJE.		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

---

**From:** Anikka Lai <anikkalai@honda.com.sg>  
**Sent:** Monday, 1 October, 2018 8:38 PM  
**To:** Claims Dept of CTI; Irene Tay; Jowyn Tay  
**Subject:** SLL948K - TP CLAIMS AGAINST GBF308H DOA: 28/09/2018  
**Attachments:** 2891\_001.pdf; SAS2480235.pdf

Dear Sir / Madam,

We are representing our client (SLL948K) to proceed claim against your insured (GBF308H) for total losses due to his negligent for the accident which happened on 28/09/2018, along SLE towards BKE.

Attached pls find the claims documents for your necessary action. Kindly advise the liability of direct settlement and arrange survey at 8 Mandai Estate.

Thank you

Warmest Regards

Anikka Lai  
Kah Motor Co. Sdn Bhd  
6A Mandai Estate  
Singapore 729903  
DID : 6514 5248 HP : 8288 6302  
Email: [anikkalai@honda.com.sg](mailto:anikkalai@honda.com.sg)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	4548E
<b>Vehicle Details</b>	
Vehicle No.:	SLL948K
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.6 VTI CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	R16B21601406
Chassis No.:	MRHFC5650GT001091
Maximum Power Output:	92.0 kW (123 bhp)
Open Market Value:	\$20,818.00
Original Registration Date:	14 Feb 2017
First Registration Date:	14 Feb 2017
Transfer Count:	0
Actual ARF Paid:	\$21,146.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Feb 2027
PARF Rebate Amount:	\$15,859.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	13 Feb 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$40,942.00
<b>Total Rebate Amount:</b>	<b>\$56,801.00</b>

The information contained herein is correct as at 22 Nov 2018

OK

MM118126503 / Kah Motor Co Sdn Bhd - Ubi  
ENTRY DATE & TIME: 29/09/2018 17:08  
SUBMITTED BY: Lai Swee Kam

Att: Ms Nivitha  
fr: Anikka / Kah Motor

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report 29/09/2018 17:08  
Date Of Accident 28/09/2018 06:55  
Exact Location Of Accident SLE > BKE  
Country/State of Loss SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL948K  
Insured/Policyholder  
Name Of Registered Owner LOW JIH YNG  
NRIC No S6844548E  
Email Address JIHYNGLOW@YAHOO.COM.SG  
Mobile Phone No (LOCAL) +65-97869698  
Alternative Phone No OFFICE-97869698

## Vehicle Particulars

Manufacturer HONDA  
Model CIVIC-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

## Insurance Company

Name of Insurance Company TOKIO MARINE INSURANCE SINGAPORE LTD  
Type Of Coverage COMPREHENSIVE  
Fleet Policy NO

Policy Number

Cover Note Number

## Driver

Name of Driver LOW JIH YNG  
NRIC No S6844548E  
Date Of Birth 20/11/1968  
Occupation INDOOR  
Date Of Driving Pass 14/09/1990  
Driving Experience 28 YEARS AND 0 MONTHS  
Gender FEMALE  
Mobile Number (LOCAL) +65-97869698  
Fax Number  
Contact Number OFFICE-97869698  
Email Address JIHYNGLOW@YAHOO.COM.SG

Address -  
 Postcode -  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name WOODLANDS EAST N.P.C  
 Police Station Address ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

AS ANNEX D&E POLICE REPORT NO : T/20180928/2022

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBF308H  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category GOODS VEHICLE  
 Name of Driver ALEX  
 NRIC/Passport Number S1511476B  
 Contact Number 96508639  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

## DETAILS OF INJURED PERSON 1

Name	LOW JIH YNG
Approximate Age	
Injuries Sustain	LEFT KNEE BRUISES
Injured person in which vehicle?	SLL948K
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	



## Sketch Plan Pg. 1

Vehicle No \_\_\_\_\_

**SKETCH PLAN**

Annex D


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &amp; Time



Driver's Signature (If driver is not the policyholder) / Date &amp; Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**

Please continue to Annex E

Sketch Plan Pg. 2

<p>Vehicle No <u>SLL 948K</u></p>	<p>Annex E</p>
<p><b>Describe Circumstances of the Accident</b></p>	
<p style="text-align: center;">/c per police report no:</p> <p style="text-align: center;">T/20/86758/2002</p> <p>* I was alone onboard #</p>	
<p><b>Declaration</b></p> <p>I/We declare the foregoing particulars are true in every respect.</p>	
	
<p>Policyholder's Signature / Date &amp; Time</p>	<p>Driver's Signature (if driver is not the policyholder) / Date &amp; Time</p>
<p>Witnessed by Reporting Centre Personnel</p>	

## Sketch Plan Pg. 3



**SINGAPORE  
POLICE FORCE**



T/20180928/2022

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7879999

1 of 3

Report No. T/20180928/2022

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/09/2018 09:24		Vide Report No.: J/20180928/0058		Station Diary No.: 52	
Name of Informant: LOW JIH YNG					
Address: BLK 48 TOH TUCK ROAD #07-08 SINGAPORE 596739					
ID Type / ID No.: NRIC NO / S8844548E			Contact No.: Home/Office: Mobile: 97869698		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 49	Date of Birth: 20/11/1968	Type of Informant: Driver		
Race: Chinese			Language: Chinese	Institution / School Name:	
Occupation: DIRECTOR			Driving Licence Information: Class: 3 Date of Expiry:		

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 28/09/2018 06:55	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY SLE TWDS CTE BEFORE EXIT 10				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 75 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

GBF308H	Van				Slightly Damaged	2
SLL948K	Car	HONDA	CIVIC 1.6 VTI CVT	White	Seriously Damaged	0

SLL948K	TOKIO MARINE INSURANCE SINGAPORE LTD.	MU001470	14/02/2017	13/02/2019
---------	---------------------------------------	----------	------------	------------

## Sketch Plan Pg. 4



**SINGAPORE  
POLICE FORCE**



T/20180928/2022

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

2 of 3

Report No. T/20180928/2022

## CONTINUATION OF REPORT

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	ALEX	ID No.	S1511476B
Related Vehicle	GBF308H (Van)	Contact No.	986506639
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	LOW JIH YNG	ID No.	S6844548E
Related Vehicle	SLL948K (Car)	Contact No.	97869698
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 28/09/2018 at about 0655hrs, I was driving my vehicle bearing SLL948K along SLE towards CTE before exit 10. A van bearing GBF308H was driving in the middle lane. All of a sudden, the van malfunction and went to hit the fence at the road side and the vehicle spin and stopped at the right most lane. I was driving on the right lane saw the vehicle however I could not stop in time and hit onto the right side of the van.

Both of us came out of the vehicle to make a check. I called for Police assistance and the van passenger called for Ambulance. I make a check on my vehicle, the front of my vehicle was seriously damaged while the right side of the van has a dent in it. Traffic Police and ambulance came shortly after.

Traffic police interviewed both the driver and me. Case card was given to both of us. Ambulance conveyed the passengers who is inside the van. I do not have an In-car camera inside my vehicle. I am unsure if there is any Traffic camera at the incident location. We have a witness regards to this incident. The witness namely: Mr Tan, HP: 98553944.

## Sketch Plan Pg. 5



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7678999



T/20180928/2022

3 of 3

Report No. T/20180928/2022

## CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/  
Sgt 1 TOH CHAI TEE

Signature Of Informant:

Signature Of Interpreter:  
Not applicable

Date/Time:  
28/09/2018 09:24

Officer In Charge Of Case:  
TP / GIT /  
Staff Sgt MOHAMED SUFIAN BIN MOHAMED  
JUNID

SN 130

Contact No.: 65476247

Authentication Stamp

NP



Signature :

**Singapore Police Force**

Classification Of Case:



# SINGAPORE POLICE FORCE



T/20180928/2022

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

1 of 3

Report No. T/20180928/2022

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 28/09/2018 09:24	Vide Report No.: J/20180928/0056	Station Diary No.: 52
--	-------------------------------------	--------------------------

<b>Informant's Particulars</b>			
Name of Informant: LOW JIH YNG		Address: BLK 48 TOH TUCK ROAD #07-08 SINGAPORE 596739	
ID Type / ID No.: NRIC NO / S6844548E		Contact No.: Home/Office: Mobile: 97869698	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 49	Date of Birth: 20/11/1968	Type of Informant: Driver
Race: Chinese		Language: Chinese	Institution / School Name:
Occupation: DIRECTOR		Driving Licence Information: Class: 3 Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 28/09/2018 06:55	Type of Location: Straight Road
Location: Along Road 1 SELETAR EXPRESSWAY  SLE TWDS CTE BEFORE EXIT 10				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 75 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF308H	Van				Slightly Damaged	2
SLL948K	Car	HONDA	CIVIC 1.6 VTI CVT	White	Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLL948K	TOKIO MARINE INSURANCE SINGAPORE LTD.	MU001470	14/02/2017	13/02/2019



# SINGAPORE POLICE FORCE



T/20180928/2022

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

2 of 3

Report No. T/20180928/2022

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	ALEX	ID No.	S1511476B
Related Vehicle	GBF308H (Van)	Contact No.	966506639
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LOW JIH YNG	ID No.	S6844548E
Related Vehicle	SLL948K (Car)	Contact No.	97869698
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 28/09/2018 at about 0655hrs, I was driving my vehicle bearing SLL948K along SLE towards CTE before exit 10. A van bearing GBF308H was driving in the middle lane. All of a sudden, the van malfunction and went to hit the fence at the road side and the vehicle spin and stopped at the right most lane. I was driving on the right lane saw the vehicle however I could not stop in time and hit onto the right side of the van.

Both of us came out of the vehicle to make a check. I called for Police assistance and the van passenger called for Ambulance. I make a check on my vehicle, the front of my vehicle was seriously damaged while the right side of the van has a dent in it. Traffic Police and ambulance came shortly after.

Traffic police interviewed both the driver and me. Case card was given to both of us. Ambulance conveyed the passengers who is inside the van. I do not have an In-car camera inside my vehicle. I am unsure if there is any Traffic camera at the incident location. We have a witness regards to this incident. The witness namely: Mr Tan, HP: 98553944.





**SINGAPORE  
POLICE FORCE**



T/20180928/2022

Police Station Of Origin:  
Woodlands East N.P.C.  
3 Woodlands Drive 63 SINGAPORE 737890  
Tel No: 1800-7679999

3 of 3

Report No. T/20180928/2022

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

J /

Sgt 1 TOH CHAI TEE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt MOHAMED SUFIAN BIN MOHAMED  
JUNID

SN 130

Contact No.: 65476247

Authentication Stamp

NP168



Signature :

**Singapore Police Force**

Signature Of Informant:

Date/Time:

28/09/2018 09:24

Classification Of Case:





# KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
Registration No : SLL948K  
Chassis No : MRHFC5650GT001091  
Model : CIVIC 1.6 VTI YM2016  
Owner's Name : LOW JIH YNG  
Ins Policy No :  
Date of Accident : 28/9/2018

Document No. : SQT18004137 Page 1  
Date : 1. Oct 2018  
Customer No. : WZC008  
Svc Advisor : ANIKKA LAI SWEE KAM  
Engine No : R16B21601406  
Date | Time : 1. Oct 2018 8:16:14 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: LOW JIH YNG OWNER INSURER: TOKIO MARINE ACC DATE: 28/09/2018 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIWAN TP VEH: GBF308H						
71101-TEA-T00ZZ	FACEFR.BUMPER	1	579.90	25	434.92	30.44	465.36
71193-TEA-T01	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIPBUMPER	9	2.00	25	13.50	0.95	14.45
71102-TBA-A10	GRILLEFR.BUMPER LOWER	1	35.10	25	26.32	1.84	28.16
71103-TEA-T00	GARNISHR.FR.BUMPER SIDE	1	17.50	25	13.12	0.92	14.04
71108-TEA-T00	GARNISHL.FR.BUMPER SIDE	1	17.50	25	13.12	0.92	14.04
71130-TEA-T00	BEAM COMPFR.BUMPER	1	335.80	25	251.85	17.63	269.48
71140-TEA-T00	BEAMR.FR.BUMPER UPPER	1	25.90	25	19.42	1.36	20.78
71150-TEA-T00	BEAM COMPFR.BUMPER CENTER UPP	1	208.60	25	156.45	10.95	167.40
71190-TEA-T00	BEAML.FR.BUMPER UPPER	1	25.90	25	19.42	1.36	20.78
71201-TEA-T00	PLATER.FR.BUMPER SIDE INDUCTN	1	42.00	25	31.50	2.21	33.71
71206-TEA-T00	PLATEL.FR.BUMPER SIDE INDUCTN	1	42.70	25	32.02	2.24	34.26
71121-TEA-T01	BASE,FR.GRILLE CHROME	1	76.60	25	57.45	4.02	61.47
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE	1	83.20	25	62.40	4.37	66.77
71125-TEA-T01	MOLDINGFR.GRILLE	1	97.40	25	73.05	5.11	78.16
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE	1	83.20	25	62.40	4.37	66.77
71410-TEA-T01	BULKHEAD ASSYFR.	1	510.60	25	382.95	26.81	409.76
74127-TEA-T00	COVERFR.BULKHEAD	1	17.70	25	13.27	0.93	14.20
80100-TBA-A01	CONDENSER ASSY	1	704.40	25	528.30	36.98	565.28
80312-TEA-T11	HOSE COMPSUCTION	1	85.60	25	64.20	4.49	68.69



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: [www.honda.com.sg](http://www.honda.com.sg)

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
Registration No : SLL948K  
Chassis No : MRHFC5650GT001091  
Model : CIVIC 1.6 VTI YM2016  
Owner's Name : LOW JIH YNG  
Ins Policy No. :  
Date of Accident : 28/9/2018

Document No. : SQT18004137 Page 2  
Date : 1. Oct 2018  
Customer No. : WZC008  
Svc Advisor : ANIKKA LAI SWEE KAM  
Engine No : R16B21601406  
Date | Time : 1. Oct 2018 8:16:14 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
80315-TEA-T01	HOSE COMPDISCHARGE	1	159.80	25	119.85	8.39	128.24 ?
80321-TEA-T01	PIPE COMPAIR CONDITIONER	1	50.90	25	38.17	2.67	40.84 ?
80341-TEA-T11	PIPE COMPRECEIVER	1	26.40	25	19.80	1.39	21.19 ?
19010-5FA-Z01	RADIATOR COMP	1	1100.50	25	825.37	57.78	883.15 ?
19020-5BA-A01	FAN COMPCOOLING	1	64.40	25	48.30	3.38	51.68 ?
80525-TBA-A01	SENSOR ASSYAMBIENT	1	39.30	25	29.47	2.06	31.53 ?
91555-TBA-K01	CLIPAMBIENT SENSOR	1	5.30	25	3.97	0.28	4.25 ?
19030-5BA-A01	MOTORCOOLING FAN	1	666.50	25	499.87	34.99	534.86 ?
19015-5BA-A01	SHROUD COMP	1	117.10	25	87.82	6.15	93.97 ?
33100-TEC-Q01	HEADLIGHT ASSY,R.	1	568.70	25	426.52	29.86	456.38 ?
33150-TEC-Q01	HEADLIGHT ASSYL.	1	568.70	25	426.52	29.86	456.38 ?
17100-R1A-A00	MANIFOLD COMPINTAKE	1	463.40	25	347.55	24.33	371.88 ?
32120-RNA-000	COVER ASSYENGINE WIRE HARNESS	1	24.70	25	18.52	1.30	19.82 ?
50820-TEA-T02	MOUNTING ENGINE SIDE	1	162.10	25	121.57	8.51	130.08 ?
60100-TEA-T00ZZ	HOOD COMPENGINE	1	581.30	25	435.97	30.52	466.49 ?
60120-TEA-T00ZZ	HINGE COMPR.HOOD	1	32.00	25	24.00	1.68	25.68 ?
60170-TEA-T00ZZ	HINGE COMPL.HOOD	1	32.00	25	24.00	1.68	25.68 ?
74120-TBA-A01	LOCK ASSYHOOD	1	85.40	25	64.05	4.48	68.53 ?
74131-TEA-T01	WIRE ASSYFR.HOOD	1	18.30	25	13.72	0.96	14.68 ?
74132-TEA-T01ZA	WIRE ASSY,HOOD RR.	1	9.90	25	7.42	0.52	7.94 ?
74141-TEA-T00	INSULATORHOOD	1	74.70	25	56.02	3.92	59.94 ?
74143-TEA-T01	SEAL RUB HOOD RR	1	19.00	25	14.25	1.00	15.25 ?
74145-TBA-A00	STAYHOOD OPEN	1	9999.99	25	7499.99	525.00	8024.99 ?
74148-TBA-A00	SEALRUBBER INTAKE	1	18.70	25	14.02	0.98	15.00 ?
60261-TBA-A00ZZ	PANELL.FENDER	1	241.60	25	181.20	12.68	193.88 ?
60211-TBA-A00ZZ	PANELR.FENDER	1	241.60	25	181.20	12.68	193.88 ?
74151-TEA-T00	FENDERL.FR.INNER	1	49.60	25	37.20	2.60	39.80 ?
74101-TEA-T00	FENDERR.FR.INNER	1	49.60	25	37.20	2.60	39.80 ?
Sum Item					13874.80	971.25	14,846.05
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00

Printed on 1/10/2018 8:54:20 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



# KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

## QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
Registration No : SLL948K  
Chassis No : MRHFC5650GT001091  
Model : CIVIC 1.6 VTI YM2016  
Owner's Name : LOW JIH YNG  
Ins Policy No. :  
Date of Accident : 28/9/2018

Document No. : SQT18004137 Page 3  
Date : 1. Oct 2018  
Customer No. : WZC008  
Svc Advisor : ANIKKA LAI SWEE KAM  
Engine No : R16B21601406  
Date | Time : 1. Oct 2018 8:16:14 AM  
Surveyor Name :  
Survey Date :  
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BML001	INSPECT ALL LIGHTINGS MECHANISMS FOCUS HEADLAMP	1	160.00	120	160.00	11.20	171.20
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	400.00	?	400.00	28.00	428.00 ?
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	400.00	?	400.00	28.00	428.00 ?
BKBH01M	CUT OFF & RENEW BULKHEAD & DAMAGE PARTS	1	4500.00	2,240	4500.00	315.00	4815.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3500.00	3,150	3500.00	245.00	3745.00
Sum Labor					9060.00	634.20	9,694.20

Survey By \_\_\_\_\_  
Date & Time \_\_\_\_\_  
Excess \_\_\_\_\_  
Status \_\_\_\_\_  
Signature \_\_\_\_\_

Total Amount 22,934.80 1,605.45 24,540.25  
Total (Inclusive of GST) 24,540.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NAZ LKK  
PIP  
10 DAYS  
BEFORE PAINT PHOTOS  
DISMANTLE PARTS PHOTOS  
67418434 / 84809158  
naz@lkkauto.com

Printed on 1/10/2018 8:54:20 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 22 November 2018 2:27 PM  
**To:** 'Anikka Lai'  
**Cc:** SUR  
**Subject:** RE: SLL 948K-DOA: 28/9/2018

Dear Anikka,

Noted with thanks.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Anikka Lai <anikkalai@honda.com.sg>  
**Sent:** Wednesday, 21 November 2018 8:55 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: SLL 948K-DOA: 28/9/2018

Dear Veron,

Sorry to inform you that the claims revert to OD as China Taiping has not advise liability till date.

Thank you

Warmest Regards

Anikka Lai  
Kah Motor Co. Sdn Bhd  
6A Mandai Estate  
Singapore 729903  
DID : 6514 5248 HP : 8288 6302  
Email: [anikkalai@honda.com.sg](mailto:anikkalai@honda.com.sg)

---

**From:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Sent:** Wednesday, 21 November, 2018 2:58 PM  
**To:** Anikka Lai <anikkalai@honda.com.sg>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: SLL 948K-DOA: 28/9/2018

Dear Annika,

Kindly advise vehicle status.

**If vehicle has been repaired, please finalize with us.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)

**Sent:** Tuesday, 30 October 2018 10:31 AM

**To:** 'anikkalai@honda.com.sg' <anikkalai@honda.com.sg>

**Subject:** SLL 948K-DOA: 28/9/2018

Dear Annika,

Kindly advise vehicle status.

**If vehicle has been repaired, please finalize with us.**

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2018		03 Oct 2018 10:55 <a href="#">Edit Adj Rpt</a>	<b>S\$14,607.78</b> <a href="#">Edit Estimates</a>	<b>S\$14,607.78</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: LAUNDRYMART PROFESSIONAL PTE LTD, Co. Reg. No.: 201303465M

Main Claimant: LOW JIH YNG, ID: S6844548E

Vehicle Reg. No.: SLL948K

Date of Loss: 28/09/2018 06:00 - :59  
[19 Months and 14 Days From LTA Reg Date (Man Yr)]

Claim Type: TP / SNM18D04669C02

Policy/Cover Note No.: DMCVSN3037681801 (Comprehensive)

Vehicle Reg. No. (Insured): GBF308H

Policy No. (Claimant):

Excess: S\$0.00

Repairer: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]

Claimant's Insurer: Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111

Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 12/10/2018]

Driver/Custodian (Insured): LEE DUO RUEY (57 / Male), NRIC: S1511476B, Tel: +6596506639

Adj Asg. Remarks: EST \$24,117.65, CASE WITH SJE.

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

Claim Documents

\*SLL948K (SNM18D04669C02)  
[GBF308H]  
TP  
LOW JIH YNG  
Sep 28 2018 6:00AM  
[LAUNDRYMART PROFESSIONAL PTE LTD]  
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print			
1	29/09/18 17:32	Accident Statement	1	Load HTM				
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print			
1	29/09/18 17:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>			
2	29/09/18 17:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>			
3	29/09/18 17:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>			
4	29/09/18 17:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>			
5	29/09/18 17:32	Accident Photo [Linked Accident Report Documents]	1	Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	04/10/18 10:50	General View	1	Load JPG	<input checked="" type="checkbox"/>			
2	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
3	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
4	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
5	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
6	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
7	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
8	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
9	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
10	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
11	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
12	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
13	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
14	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
15	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
16	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
17	04/10/18 10:51	General View	1	Load JPG	<input checked="" type="checkbox"/>			
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print			
1	03/10/18 10:55	EMAIL FM KAH	1	Load PDF				
2	03/10/18 10:55	REPAIR EST	1	Load PDF				
3	03/10/18 10:55	TP GIA	1	Load PDF				
4	03/10/18 10:55	OI GIA	1	Load PDF				
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print			
1	29/09/18 17:31	Sketch Plan [Linked Accident Report Documents]	1	Load TIF				

Linked Accident Report Documents

View

View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	29/09/18 17:32	Accident Statement	Load HTM	
2	10/10/18 19:32	Addendum Sheet	Load TIF	
3	10/10/18 19:32	Accident Statement Addm. #1	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	29/09/18 17:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	29/09/18 17:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	29/09/18 17:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	29/09/18 17:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	29/09/18 17:32	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	29/09/18 17:31	Sketch Plan	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18017886/NVD3E2

Date: 30/11/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN3037681801

Claimant Vehicle  
No : SLL948KInsured Vehicle  
No : GBF308H

Date of Loss: 28/09/2018

Nature of Claim: TP

Claim  
No: SNM18D04669C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLL948K

Make &amp; Model: HONDA CIVIC, 1.5 (A)

Engine No: R16B21601406

Reg. Date: 14/02/2017 (Man. Year: 2016)

Chassis No: MRHFC5650GT001091

Colour: White

Odometer: 22513 km

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Hankook 5 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 5 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,974.80	9,097.78	4,877.02	34.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,960.00	5,510.00	3,450.00	38.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>22,934.80</b>	<b>14,607.78</b>	<b>8,327.02</b>	<b>36.31</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,605.44</b>	<b>1,022.54</b>	<b>582.90</b>	<b>36.31</b>
<b>Nett Amount (S\$)</b>	<b>24,540.24</b>	<b>15,630.32</b>	<b>8,909.92</b>	<b>36.31</b>

## INSPECTION

Date of Assignment: 03/10/2018

Date Inspected: 03/10/2018 Inspected At:

6A MANDAI ESTATE  
Repairer : Kah Motor Co Sdn Bhd (Ubi)

Estimated Period of Repair: 10.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TP CONVERT TO OD CLAIM

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$5,272.70 NETT)

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Nov 2018)
Parts:	143	HONDA CIVIC 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL948K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACEFR.BUMPER	Cracked	434.92 FS	*434.92 FS
2	1		*SPACERR.FR.BUMPER SIDE	Serviceable	7.80 FS	*- FS
3	1		*SPACERL.FR.BUMPER SIDE	Serviceable	7.80 FS	*- FS
4	9		*CLIPBUMPER	Necessary	13.50 FS	*13.50 FS
5	1		*GRILLEFR.BUMPER LOWER	Serviceable	26.32 FS	*- FS
6	1		*GARNISHR.FR.BUMPER SIDE	* Check	13.12 FS	*- FS
7	1		*GARNISHL.FR.BUMPER SIDE	* Check	13.12 FS	*- FS
8	1		*BEAM COMPFR.BUMPER	* Check	251.85 FS	*- FS
9	1		*BEAMR.FR.BUMPER UPPER	* Check	19.42 FS	*- FS
10	1		*BEAM COMPFR.BUMPER CENTER UPP	* Check	156.45 FS	*- FS
11	1		*BEAML.FR.BUMPER UPPER	* Check	19.42 FS	*- FS
12	1		*PLATER.FR.BUMPER SIDE INDUCTN	* Check	31.50 FS	*- FS
13	1		*PLATEL.FR.BUMPER SIDE INDUCTN	* Check	32.02 FS	*- FS
14	1		*BASE,FR.GRILLE CHROME	Missing	57.45 FS	*57.45 FS
15	1		*EXTENSION ASSYR.FR.GRILLE	* Check	62.40 FS	*- FS
16	1		*MOLDINGFR.GRILLE	Missing	73.05 FS	*73.05 FS
17	1		*EXTENSION ASSYL.FR.GRILLE	* Check	62.40 FS	*- FS
18	1		*BULKHEAD ASSYFR	* Check	382.95 FS	*- FS
19	1		*COVERFR.BULKHEAD	* Check	13.27 FS	*- FS
20	1		*CONDENSER ASSY	Dented	528.30 FS	*528.30 FS
21	1		*HOSE COMPSUCTION	* Check	64.20 FS	*- FS
22	1		*HOSE COMPDISCHARGE	* Check	119.85 FS	*- FS
23	1		*PIPE COMPAIR CONDITIONER	* Check	38.17 FS	*- FS
24	1		*PIPE COMPRECEIVER	* Check	19.80 FS	*- FS
25	1		*RADIATOR COMP	* Check	825.37 FS	*- FS
26	1		*FAN COMPCOOLING	* Check	48.30 FS	*- FS
27	1		*SENSOR ASSYAMBIENT	* Check	29.47 FS	*- FS
28	1		*CLIPAMBIENT SENSOR	* Check	3.97 FS	*- FS
29	1		*MOTORCOOLING FAN	* Check	499.87 FS	*- FS
30	1		*SHROUD COMP	* Check	87.82 FS	*- FS
31	1		*HEADLIGHT ASSY, R	Cracked	426.52 FS	*426.52 FS
32	1		*HEADLIGHT ASSYL.	* Check	426.52 FS	*- FS
33	1		*MANIFOLD COMPINTAKE	* Check	347.55 FS	*- FS
34	1		*COVER ASSYENGINE WIRE HARNESS	* Check	18.52 FS	*- FS
35	1		*MOUNTING ENGINE SIDE	* Check	121.57 FS	*- FS
36	1		*HOOD COMPENGINE	* Check	435.97 FS	*- FS
37	1		*HINGE COMPR.HOOD	* Check	24.00 FS	*- FS
38	1		*HINGE COMPL.HOOD	* Check	24.00 FS	*- FS
39	1		*LOCK ASSYHOOD	Jammed	64.05 FS	*64.05 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*WIRE ASSYFR.HOOD	* Check	13.72 FS	*- FS
41	1		*WIRE ASSY, HOOD RR.	* Check	7.42 FS	*- FS
42	1		*INSULATORHOOD	* Check	56.02 FS	*- FS
43	1		*SEAL RUB HOOD RR	* Check	14.25 FS	*- FS
44	1		*STAYHOOD OPEN	Dented	7,499.99 FS	*7,499.99 FS
45	1		*SEALRUBBER INTAKE	* Check	14.02 FS	*- FS
46	1		*PANELL.FENDER	Repair	181.20 FS	*- FS
47	1		*PANELR.FENDER	Repair	181.20 FS	*- FS
48	1		*FENDERL.FR.INNER	* Check	37.20 FS	*- FS
49	1		*FENDERR.FR.INNER	* Check	37.20 FS	*- FS
50	1		*SUNDRIES	* Check	100.00 FS	*- FS
Total Parts (S\$)					13,974.80	9,097.78

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	INSPECT ALL LIGHTINGS MECHANISMS FOCUS HEADLAMP	New	160.00	120.00
2	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS * Check	New	400.00	0.00
3	REMOVE & INSTALL RADIATOR WITH FITTINGS * Check	New	400.00	0.00
4	CUT OFF & RENEW BULKHEAD & DAMAGE PARTS	New	4,500.00	2,240.00
5	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	New	3,500.00	3,150.00
Gross Labour Cost (S\$)			8,960.00	5,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >