

ASS. REC. BY:

REF:

CS3/CT118017888/TICd3d2

Special Instruction:

Surveyor:

Mennen Taufich

From (Person):

Irene Fay

of

CT1

Date/Time:

21/01/18 @ 5.30pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGW 3447X

Insured:

SJE 3543K

at Workshop m/s

Lys Engineering

Tel:

9730 8695

of

No.1 Julien Samulin

Policy No:

DMPCSN 3048581800

Claim No:

SNM18D04692C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/09/18

Insp: 7800n lee st # 01-39

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9.30am @ 3/10/18

Person Contacted:

Steven

Vehicle ☒ IN ☒ OUT

Date/Time	Action/Instruction (X) Estimate
	SGW 3447X - X
	SJE 3543K - X
	Dismantle: 4/10/2018

Quintec

Tanfer

REF:


CT1

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SGW 3447X Yr Regn: Jul 07
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan Sylphy C.C. 1448
 Colour: Grey A/C Insured / Std / NI / NA
 Sp. Reading: 243239 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SN1BPA6120125119
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Front	6	mm	Rear	6	mm
R/Bal.	6	mm	R/Bal.	6	mm
L/Bal.	6	mm	L/Bal.	6	mm
D.O.A.			D.O.I.	3/20/18 & 1/7/18	

Survey held at Lys En
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction No 919. 7.5am Lee St #01-39

Estimated repair range \$4,800 - \$6,000.

12/10/2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

150

Date/Time, File Return to?

Transportation

1)

\$ + PS \$

Report Format: DAR.

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)

Photos

Others

TOTAL

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	02 Oct 2018		02 Oct 2018 17:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NORALINA BINTE HASSHIM, ID: S8733608E		
Main Claimant:	RAYMOND & DOREEN STUDIO, Co. Reg. No.: 53362536W		
Vehicle Reg. No.:	SGW3447X	Date of Loss:	28/09/2018 17:00 - :59
Claim Type:	TP / SNM18D04692C02	Policy/Cover Note No.:	DMPCSN3048551800 (Comprehensive)
Vehicle Reg. No. (Insured):	SJE3543K	Policy No. (Claimant):	5092588054-01 (CLASSIC)
		Excess:	S\$0.00
Repairer:	Lys Engineering (pioneer) (HQ) No. 1 Jalan Samulun, 629119 Pioneer - Tel: 97308695		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/10/2018]		
Driver/Custodian (Insured):	NORALINA BINTE HASSHIM (30 / Female), NRIC: S8733608E		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

[View All](#) [Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	2536W
Vehicle Details	
Vehicle No.:	SGW3447X
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.5 4AT
Primary Colour:	Grey
Manufacturing Year:	2007
Engine No.:	HR15168029A
Chassis No.:	JN1BAAG11Z0105119
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,419.00
Original Registration Date:	13 Jul 2007
First Registration Date:	13 Jul 2007
Transfer Count:	2
Actual ARF Paid:	\$18,061.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jul 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,100.00
COE Rebate Amount:	\$18,075.00
Total Rebate Amount:	\$18,075.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 12 Oct 2018

OK

MVA118126526 / VAC - Bukit Batok
ENTRY DATE & TIME: 30/09/2018 09:07
SUBMITTED BY: SUSAN SEAH SOH ENG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/09/2018 09:07
Date Of Accident	28/09/2018 17:25
Exact Location Of Accident	LOYANG AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGW3447X
Insured/Policyholder	
Name Of Registered Owner	RAYMOND & DOREEN STUDIO
Co Reg No	53362536W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97856272
Alternative Phone No	Office-97856272

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092588054-01 (CLASSIC)
Cover Note Number	

Driver

Name of Driver	CHEN WEIYUAN RAYMOND
NRIC No	S8301803H
Date Of Birth	07/01/1983
Occupation	OUTDOOR
Date Of Driving Pass	20/04/2008
Driving Experience	10 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97856272

Fax Number

Contact Number

EMail Address

Address

Postcode

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

OFFICE-97856272

NOEMAIL

579 HOUGANG AVE 4
#04-630

S530579

NO

OWNER

-
-
--
-
-**General Information of the Accident**

Type Of Accident

Weather Conditions

Road Surface

COLLISION - HEAD TO REAR

CLEAR

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

NO

NO

YES

NO

1

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

NO

NO

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

YES

NO

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

SJE3543K

TOYOTA VIOS

PRIVATE CAR

NORALINA BINTE HASSHIM

S8733608E

96964370

10/12/2018

E-FILE

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 655545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Layang Ave and traffic light turn red so I stopped the car.

When the traffic light turn green, I was about to move when the car behind (Car B) bang into my car rear badly damage. No one injure.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659515
Tel: 676 412 5111
Fax: 676 412 5112

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2018		02 Oct 2018 17:30 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: NORALINA BINTE HASSHIM , ID: S8733608E									
Main Claimant: RAYMOND & DOREEN STUDIO , Co. Reg. No.: 53362536W									
Vehicle Reg. No.: SGW3447X		Date of Loss: 28/09/2018 17:00 - :59 [134 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04692C02		Policy/Cover Note No.: DMPCSN3048551800 (Comprehensive)							
Vehicle Reg. No. (Insured): SJE3543K		Policy No. (Claimant): 5092588054-01 (CLASSIC)							
		Excess: S\$0.00							
Repairer: Lys Engineering (pioneer) (HQ) No. 1 Jalan Samulun, 629119 Pioneer - Tel: 97308695									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 11/10/2018]									
Driver/Custodian (Insured): NORALINA BINTE HASSHIM (30 / Male) , NRIC: S8733608E									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGW3447X (SNM18D04692C02)**
[SJE3543K]

TP
RAYMOND & DOREEN STUDIO
Sep 28 2018 5:00PM
[NORALINA BINTE HASSHIM]
Lys Engineering (pioneer)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	30/09/18 12:19	Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	30/09/18 09:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
2	30/09/18 09:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
3	30/09/18 09:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
4	30/09/18 09:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
5	30/09/18 09:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
6	30/09/18 09:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>
7	30/09/18 09:12	Accident Photo <small>[Linked Accident Report Documents]</small>		Load JPG	<input checked="" type="checkbox"/>

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/10/18 16:17	General View		Load PDF	
2	12/10/18 16:19	Photographs of Damaged Parts		Load PDF	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/10/18 17:29	PRS		Load PDF	
2	02/10/18 17:29	OI GIA		Load PDF	

No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	30/09/18 12:19	Sketch Plan <small>[Linked Accident Report Documents]</small>		Load TIF	
2	30/09/18 12:19	Sketch Plan #2 <small>[Linked Accident Report Documents]</small>		Load TIF	

Linked Accident Report Documents

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	30/09/18 12:19	Accident Statement		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)		Thumbnail	Print
1	30/09/18 09:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	30/09/18 09:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	30/09/18 09:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	30/09/18 09:12	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	30/09/18 09:12	Accident Photo		Load JPG	

Assessment Reports			1 per page	✓
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
				✓
6	30/09/18 09:12	Accident Photo	Load JPG	✓
7	30/09/18 09:12	Accident Photo	Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	30/09/18 12:19	Sketch Plan	Load TIF	
2	30/09/18 12:19	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>	^ v
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017888/T1CD3E2

Date: 16/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3048551800

Claimant Vehicle
No: SGW3447XInsured Vehicle
No: SJE3543K

Date of Loss: 28/09/2018

Nature of Claim: TP

Claim
No: SNM18D04692C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGW3447X

Make & Model: NISSAN SYLPHY, 1.5 (A)

Engine No: HR15168029A

Reg. Date: 13/07/2007 (Man. Year: 2007)

Chassis No: JN1BAAG11Z0105119

Colour: Grey

Odometer: 243739 km

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/10/2018

Date Inspected: 03/10/2018

Inspected At:

Lys Engineering (pioneer) (HQ)
No. 1 Jalan Samulun
Singapore 629119

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,800.00 -\$6,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Oct 2018)

Parts: 143 NISSAN SYLPHY 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGW3447X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >