

ASS. REC. BY:

REF:

C83/CT#18017889/Ucd3^{SP}

Special Instruction:

Surveyor:

Makus

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CPI

Date/Time:

21/01/18 @ 5:19pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKD 1545L

Insured:

GBE 1143 P

at Workshop m/s

Blumel Automotive

Tel:

67452088

of

1 kaki Bkt Ave 6 # 01-28

Policy No:

DMCVSN 1758091801

Claim No:

SNM18 D04701C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/09/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

9:56am @ 3/10/18

Person Contacted:

Sally

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SKD 1545L - X
	GBE 1143P - X
	Dismantle: 4/10/2018
	After repair: 8/10/2018

(08/11/13) wef

ASS. REC. BY: Marius

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKD1545at Workshop m/s 3wy

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 25

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

L7A17182

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKD1545Yr Regn: 1210

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAIMake: Volkswagen Polo cc1197Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 179111

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WUWAZZ6R2B4021046

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/40R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NexenFront 6Rear 6R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 30/9/18D.O.I. 3/10/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

no settl. @ 11am.
3500 - 4500

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: PRE

Lump Sum / I.B.I. (\$) _____

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2018		02 Oct 2018 17:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	H & T I.T. DEVELOPMENT PTE LTD, Co. Reg. No.: 200200248M		
Main Claimant:	BOH LEE GEK KAREN, ID: S7034188C		
Vehicle Reg. No.:	SKD1545L	Date of Loss:	30/09/2018 19:00 - :59
Claim Type:	TP / SNM18D04701C02	Policy/Cover Note No.:	DMCVSN1758091801 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE1143P	Policy No. (Claimant):	GA362726
		Excess:	S\$0.00
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/10/2018]		
Driver/Custodian (Insured):	NGUYEN NGOC SON (25 / Male), NRIC: G1037620R, Tel: +6596911108		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

[View All](#)[Compose Case Mail](#)

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MSG#18126838 / SME Motor Pte Ltd - Kekj Bukit
ENTRY DATE & TIME: 01/10/2018 13:23
SUBMITTED BY: Chia Pal Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2018 13:23
Date Of Accident	30/09/2018 19:30
Exact Location Of Accident	ANG MO KIO AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKD1545L
Insured/Policyholder	
Name Of Registered Owner	BOH LEE GEK KAREN
NRIC No	S7034188C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96188727
Alternative Phone No	OFFICE-96188727

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	POLO

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA362728
Cover Note Number	

Driver

Name of Driver	CHUA SAI LUAN CATHERINE
NRIC No	S0812825H
Date Of Birth	29/03/1946
Occupation	INDOOR
Date Of Driving Pass	05/11/1977
Driving Experience	40 YEARS AND 10 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91295567
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 51 PARRY TERRACE
 Postcode 547150
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PARENT
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

ON 30/09/2018 AT ABOUT 7.28PM, I WAS DRIVING ALONG ANG MO KIO AVE 1. TRAFFIC LIGHT TURNED AMBER AND I STOPPED MY CAR. SUDDENLY, VEHICLE B CAME AND HIT ONTO THE REAR OF MY CAR.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE1143P
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver NAGUYEN NGOCSON
 NRIC/Passport Number G1037630R
 Contact Number 91308481
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or Court orders.

Kanun
Policyholder's Signature

Date & Time: 11/10/18, 11:20AM

CBSh
Driver's Signature

(If driver is not the policyholder)

Date & Time: 11/10/18, 11:20AM


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/9/18 at about 7:28pm, I was driving along Ang Mo Kio Ave 1. Traffic light turned amber and I stopped my car. Suddenly Car B came and hit the rear of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Brown
Policyholder's Signature

Date & Time: 1/10/18, 11:30am

GIARMC SketchPlanForm_V3

C.B. Ch
Driver's Signature
(If driver is not the policyholder)

Date & Time: 1/10/18, 11:30am

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4188C
Vehicle Details	
Vehicle No.:	SKD1545L
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.2L AT 6R14F7
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	CBZ193071
Chassis No.:	WVWZZZ6RZBU021046
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$16,987.00
Original Registration Date:	09 Dec 2010
First Registration Date:	09 Dec 2010
Transfer Count:	2
Actual ARF Paid:	\$16,987.00 <i>2493</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Dec 2020
PARF Rebate Amount:	\$10,192.00
Intended COE Rebate Details	
COE Expiry Date:	08 Dec 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$30,587.00
COE Rebate Amount:	\$6,990.00
Total Rebate Amount:	\$17,182.00

The information contained herein is correct as at 04 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2018		02 Oct 2018 17:19 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	H & T I.T. DEVELOPMENT PTE LTD , Co. Reg. No.: 200200248M		
Main Claimant:	BOH LEE GEK KAREN , ID: S7034188C		
Vehicle Reg. No.:	SKD1545L	Date of Loss:	30/09/2018 19:00 - :59 [93 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04701C02	Policy/Cover Note No.:	DMCVSN1758091801 (Comprehensive)
Vehicle Reg. No. (Insured):	GBE1143P	Policy No. (Claimant):	GA362726
		Excess:	S\$0.00
Repairer:	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67452088		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/10/2018]		
Driver/Custodian (Insured):	NGUYEN NGOC SON (25 / Male), NRIC: G1037620R, Tel: +6596911108		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Claim Documents

*SKD1545L (SNM18D04701C02)
[GBE1143P]
TP
BOH LEE GEK KAREN
Sep 30 2018 7:00PM
[H & T I.T. DEVELOPMENT PTE LTD]
Bluwel Automotive Service Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports				1 per page	✓
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	01/10/18 13:54	Accident Statement	1	Load HTM	
Photos/Images				3 per page	✓
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	01/10/18 13:54	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
2	01/10/18 13:54	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
3	01/10/18 13:54	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
4	01/10/18 13:54	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
5	01/10/18 13:54	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
6	01/10/18 13:54	Accident Photo [Linked Accident Report Documents]	1	Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/10/18 12:44	General View	1	Load PDF	
2	10/10/18 11:08	Photographs of Damaged Parts	1	Load PDF	
3	10/10/18 11:08	Photo After Spray	1	Load PDF	
Documentation				1 per page	✓
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	02/10/18 17:18	PRS WITH TP GIA	1	Load PDF	
2	02/10/18 17:18	OI GIA	1	Load PDF	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	01/10/18 13:30	Sketch Plan [Linked Accident Report Documents]	1	Load TIF	
2	01/10/18 13:30	Sketch Plan #2 [Linked Accident Report Documents]	1	Load TIF	
3	01/10/18 13:30	Sketch Plan #3 [Linked Accident Report Documents]	1	Load TIF	
4	01/10/18 13:30	Sketch Plan #4 [Linked Accident Report Documents]	1	Load TIF	
5	01/10/18 13:30	Sketch Plan #5 [Linked Accident Report Documents]	1	Load TIF	
6	01/10/18 13:30	Sketch Plan #6 [Linked Accident Report Documents]	1	Load TIF	

Linked Accident Report Documents

Assessment Reports				1 per page	✓
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	01/10/18 13:54	Accident Statement	1	Load HTM	

Assessment Reports			1 per page ▼	✓
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
Photos/Images			3 per page ▼	✓
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	01/10/18 13:54	Accident Photo	 Load JPG	✓
2	01/10/18 13:54	Accident Photo	 Load JPG	✓
3	01/10/18 13:54	Accident Photo	 Load JPG	✓
4	01/10/18 13:54	Accident Photo	 Load JPG	✓
5	01/10/18 13:54	Accident Photo	 Load JPG	✓
6	01/10/18 13:54	Accident Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
1	01/10/18 13:30	Sketch Plan	 Load TIF	
2	01/10/18 13:30	Sketch Plan #2	 Load TIF	
3	01/10/18 13:30	Sketch Plan #3	 Load TIF	
4	01/10/18 13:30	Sketch Plan #4	 Load TIF	
5	01/10/18 13:30	Sketch Plan #5	 Load TIF	
6	01/10/18 13:30	Sketch Plan #6	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118017889/UCD3S2

Date: 17/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1758091801
Claimant Vehicle No :	SKD1545L	Insured Vehicle No :	GBE1143P
Date of Loss:	30/09/2018	Nature of Claim:	TP
		Claim No:	SNM18D04701C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKD1545L	Engine No:	CBZ193071
Make & Model:	VOLKSWAGEN POLO, 1.4 (A)	Chassis No:	WVWZZZ6RZBU021046
Reg. Date:	09/12/2010 (Man. Year: 2006)	Odometer:	179111 km
Colour:	White		
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/40ZR17	Rear Tyre Size:	215/40ZR17
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	02/10/2018	Bluwel Automotive Service Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, #01-28/37/53/55/56 Autobay@Kaki Bukit Singapore 417883
Date Inspected:	03/10/2018 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2018)
Parts:	144	VOLKSWAGEN POLO 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD1545L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >