

INS. CASE OWNER:

CC6, ALB 180 17896, Hpa5

IDAC:

Surveyor:

UMP

DOI:

ASSIGNMENT

1-10-18

Date / Time:

1-10-18

Registered in Merimen:

3-10-18

Pre-assign / CCU / FTE



Insured Vehicle No. : SFW 117K

Name of Insured :

Insured Tel No. : HP:

Excess Sec II :SS D.O.A : 1-10-18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SFW 117K

SGF 6696m

SKL 128P

INSRS:
WSP:
Tel:
Liability:
RMKS:

or

INSRS:
WSP:
Tel:
Liability:
RMKS:

Leung Pao

TP

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SGF 6696m - X ; SFW 117K - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ (days) Reduction: %

Email ☐ Call ☐

FINAL SETTLEMENT Date/Time: Confirm with

Email ☐ Call ☐

Final Liability: % (Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost: S\$

Loss of Rental (LOR): S\$ (days)

Loss of Use (LOU): S\$ (\$ x days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost S\$

Total: S\$

Global Sum S\$:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

FINAL PAYMENT Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$

Name 1:

Payee 2: (Strike if N.A.) S\$

Name 2:

Payee 3: (Strike if N.A.) S\$

Name 3:

Surveyor

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: S6F6696M Yr Regn: 2016 / MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel C.C. 1496Colour: White A/C: Insured / Std / NI / NASp.Reading: 144262 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11107262Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/60R16R: 215/60R16BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 01/10/18Survey held at Leang Auto.Des. of Damages Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

CPAIG.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

S + RS, \$ _____

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$ _____)

TOTAL