

ASS. REC. BY:

REF:

CS/GAU 8017906/NH22

Special Instruction:

Surveyor

Naz.

ASSIGNMENT (Office)

From (Person):

Channon Ng

of

GAZ

Date/Time:

03/02/18 9:18am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 5310S

Insured:

PC 6434L

at Workshop m/s

SMRT

Tel:

of

60 Woodlands Ind Park Et

Policy No:

Claim No:

CLMOMVC000003495

Sum Insured:

Excess:

Make of Veh:

D.O.A.

30092018

(Client's Record)

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 5310S - NS/INC/14017105 / Kilm3d1
	PC 6434 - X
	Part by Part \$1027.37 (Red: 3116.97; 75%)

DA: 05092014

Surveyor: NAR

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHB 5310 S Yr Regn: 11 MAR 2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: TOYOTA PRINS c.c. 1798Colour: MAROON A/C: Insured / Std / NI / NASp. Reading: 202,304 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN36U505767609

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ACHILLES (CF) FALKEN (CR)

Front Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 30/9/18 D.O.I. 3/10/18Survey held at SMART WOODLAND

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1) 23/10/2018

Date/Time, File Pass to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Survey Fee: 290

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS. SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)Report Format: TPLump Sum / I.B.I. (\$) 1027.37

TOTAL

290

RECEIVED 23 OCT 2018

GAI PIP

Catherine Chong (LKK Auto)

From: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Sent: Wednesday, 3 October, 2018 9:18 AM
To: Denise Tay (LKKAuto); SUR; assignments
Subject: New assignment - TP survey to SHB5310S - GAIC ref: CLMOMVC000003495 (PC6434L) DOA: 30/09/2018
Attachments: SHB5310S.pdf; PC6434L - OI.pdf; SHB5310S - TP.pdf
Importance: High

Dear Denise

Please survey the TP taxi today. Attached both parties' SAS to verify damages consistency.

Regards
Sharon Ng
Great American
DID: 6804 7845

From: Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ZhiYang.Phua@smrt.com.sg>
Sent: Wednesday, October 03, 2018 8:56 AM
To: Selena Tan Lee See (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <TanSelena@smrt.com.sg>; Ng, Sharon <Sharon.Ng@sg.gaig.com>; Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <BThaiyalN@smrt.com.sg>; Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Tan, Angela <Angela.Tan@sg.gaig.com>; Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ngsiuching@smrt.com.sg>; Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <limkhachiew@smrtlan.com.sg>; Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <weisiong@smrt.com.sg>; Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <kimming.chin@smrtlan.com.sg>
Subject: [External] RE: SHB5310S - Survey (Great American Insurance) - PC6434L - DOA: 30/09/2018

Hi all,

Please refer to the attach estimate.

Thanks,
zhiyang

From: Selena Tan Lee See (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)
Sent: Tuesday, 2 October, 2018 5:51 PM
To: Ng, Sharon; Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Ngian, Kelvyna; Tan, Angela; Tan, Rachel
Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR)
Subject: RE: SHB5310S - Survey (Great American Insurance) - PC6434L - DOA: 30/09/2018

Dear Sharon

There is no video available.

Aside to Zhi Yang > please send estimates to Sharon of Great American.

Thanks

Regards

Selena Tan

Claims and Insurance Agency
Direct line +65 6866 2653 | Direct fax +65 6368 7421
60 Woodlands Industrial Park E4
Singapore 757705



From: Ng, Sharon [mailto:Sharon.Ng@sg.gaig.com]

Sent: 02/10/2018 11:59

To: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Ngian, Kelvyna; Tan, Angela; Tan, Rachel

Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Selena Tan Lee See (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)

Subject: RE: SHB5310S - Survey (Great American Insurance) - PC6434L - DOA: 30/09/2018

WITHOUT PREJUDICE

Dear Shanti

We refer to your email.

Our insured has not reported the accident to-date. Please let us have the repair estimates and scene photos/video for our investigation.

Regards

Sharon Ng

Great American

From: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <BThaiyalN@smrt.com.sg>

Sent: Tuesday, October 02, 2018 9:20 AM

To: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; Ng, Sharon <Sharon.Ng@sg.gaig.com>; Tan, Angela <Angela.Tan@sg.gaig.com>; Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ngsiuching@smrt.com.sg>; Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <limkhachiew@smrtlan.com.sg>; Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <weisiong@smrt.com.sg>; Chin Kim Ming (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <kimming.chin@smrtlan.com.sg>; Selena Tan Lee See (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <TanSelena@smrt.com.sg>

Subject: [External] RE:SHB5310S - Survey (Great American Insurance)

Dear Sir / Mdm,

Kindly arrange to survey the vehicle **SHB5310S** within 48 hours according to GIA guide line, involving your insured **PC6434L**
Vehicle in **Woodlands. SMRT Depot**

Regards
Shanti
SMRT Automotive Services PTE LTD
Accident Reporting Center (Claims Dept)
6866 2671/2 | bthaiyaln@smrt.com.sg



The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Case Details

Case Reference Number : TAX/09/18/2149

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5310S

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-3966-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : Great American Insurance Company

Accident Date and Time : 30/09/2018 12:15 PM

Vehicle Age(In Months) : 30

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval			
			Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace
One Time Key In			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair
One Time Key In			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0	Check
One Time Key In			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0	Repair
One Time Key In			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace
One Time Key In			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	0	0	Check
One Time Key In			FENDER LINER PAD, FR WHEEL, LH	1	49.30	49.30	25.00	36.97	Replace	0	0	Check
One Time Key In			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0	Check
Total Spare Part Cost								2,016.69		Surveyor Total	38.92	
Lump Sum Discount (%)								0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost								2,016.69		Final Sur Total	38.92	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPAIR FRONT PORTION LH	676.00	400	
Total:		676.00	400.00	


Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REPSRAY FRONT BUMPER	378.00	200	
2	TO RESPRAY FRONT FENDER LH	378.00	200	
Total:		756.00	400.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	CHECK
2	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
3	TO WASH AND VACUUM	60.00	0	NN
4	TO REPLACE SUNDRY PARTS	100.00	0	NN
5	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	148.44	NEC
Total:		488.44	188.44	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,016.69	38.92
Total Labour Cost	676.00	400.00
Total Spray Painting	756.00	400.00
Other	488.44	188.44
Overall Total	3,937.13	1,027.36
Lump Sum Repair Option		
Lump Sum Total	0.00	1,027.36
Surveyor Approved Amount		1,027.36
No of Repair Days*	4	3
Remarks	-	PART BY PART REPAIR 3 DAYS AFTER REPAIR PHOTO
Surveyor Name		Naz
Signature		
Survey Date	03/10/2018	

Save

Clear

NAZ LKK
3/10/18 1130
P/R
AFTER REPAIR PHOTO
3 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2018 11:51
Date Of Accident	30/09/2018 20:15
Exact Location Of Accident	AIRPORT BOULEVARD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5310S
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	LAI SWEE KOW
NRIC No	S0944823C
Date Of Birth	20/01/1948
Occupation	OUTDOOR
Date Of Driving Pass	29/06/1972
Driving Experience	46 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	4
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : RONG FANG
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ALONG AIRPORT BOULEVARD AT THE RIGHT LANE WHEN THE VEHICLE PC6434L FROM BEHIND ON THE LEFT LANE AT A GREAT SPEED ABRUPTLY CUT INTO MY LANE AND COLLIDED ONTO THE LEFT FRONT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Details of Witness 1

Name	RONG FANG
Phone Number	
Email Address	

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC6434L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	VISMU CHERAN
NRIC/Passport Number	S8301129G
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

ah 1/10/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A - SHB 53105
B - PC 6434L

↑ | ↑

↓

[illegible]

I/We declare the foregoing particulars are true in every respect.

SMRT TAX SYSTEM



Long

ale 11.1.2018

Drisc

Section A - Accident Details



Registration Number	SHB5310S
Case Reference Number	TAX/09/18/2149
Registration Date	11/03/16
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	LAI SWEE KOW @ LAI SER PHENG
Type of Accident	Side Swipe
Accident Date and Time	30/09/18 8:15 PM
Accident Reported Date and Time	01/10/18 12:05 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No <input checked="" type="checkbox"/>
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24098144
Special Instruction to ARC, if any	GREAT AMERICAN
Prepared Date and Time	02/10/18 2:42 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Drisc

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$2,016.69	\$38.93
Total Other Cost	\$488.44	\$188.44
TOTAL COST	\$3,937.13	\$1,027.37
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Zhi Yang Phua	Naz
ARC / Surveyor Sign Off Date	03/10/2018 2:01 PM	03/10/2018 11:53 AM
Signature		
Remarks	444.34.	PART BY PART REPAIR 3 DAYS AFTER REPAIR PHOTO

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1810-0273	Invoice Number	
Quotation Date	12.10.2018	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION LH	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$756.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$40.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$148.44	\$148.44
Total Other Costs	\$488.44	\$188.44

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair <i>XR</i>
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Check <i>X SUC</i>
		53802-47050	FENDER FRT/LH	1.00	\$723.40	100.00	\$0.00	Replace	Repair <i>XR</i>
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace <i>NEC</i>
		53876-47030	FENDER LINER FRT/LH	0.00	\$171.70	0.00	\$0.00	Replace	Check <i>X SUC</i>
		53852-47020	FENDER LINER PAD, FR	0.00	\$49.30	0.00	\$0.00	Replace	Check <i>X SUC</i>
		81170-47500	HEAD LAMP LH	0.00	\$945.20	0.00	\$0.00	Replace	Check <i>X SUC</i>
Total					\$2,499.90		\$38.93		

4144.21

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

38.93
+ 400.00
+ 588.44

6420.34

1027.37

CONFIRMED PART BY PART REPAIR \$1,027.31 / 3 DAYS




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18017906/Ntbe2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 22-11-2018		
		Code : GAI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 6434L	Veh. Inspected	SHB 5310S	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003495	Excess (\$)	0.00	
Assign From	SHARON NG	Assign Date	03/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKN36U505767609	Colour	MAROON	
Odometer	202304	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	ACHILLES	5 mm	
L/H Front Tyre	195/65 R15	ACHILLES	5 mm	
R/H Rear Tyre	195/65 R15	FALKEN	5 mm	
L/H Rear Tyre	195/65 R15	FALKEN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS				
5. General Information				
Accident Date	30/09/2018	Inspection Date	03/10/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5310S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.93
1	BUMPER SUPPORT F/LH	SERVICEABLE	76.40	-
1	FENDER LINER FRT/LH	SERVICEABLE	171.70	-
1	FENDER LINER PAD, FR	SERVICEABLE	49.30	-
1	HEAD LAMP LH	SERVICEABLE	945.20	-
1	BUMPER FRT	TO REPAIR SEE LABOUR	482.00	-
1	FENDER FRT/LH	TO REPAIR SEE LABOUR	723.40	-
			2,499.90	38.93
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF BUMPER FRT AND FENDER FRT/LH.		676.00	400.00
	SPRAY PAINT.		756.00	400.00
	TO CHECK WIRING AND SYSTEM FUNCTION.	NOT NECESSARY	80.00	-
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	40.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.		148.44	148.44
			1,920.44	988.44
	GRAND TOTAL		4,420.34	1,027.37
RECOMMENDED COST OF REPAIRS				1,027.37

Report Ref No. CS/GAI18017906/Ntbe2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.