

ASS. REC. BY:

REF:

CS/MSG18017908/G403

Special Instruction:

Surveyor: Guo Qiang

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG

Date/Time: 2/10/18 @ 3:57 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKR 6652D

Insured:

FBM 6804R

at Workshop m/s

Chew Goon Motor

Tel:

6484 1626

of

Bik 10, AMK Ind. Park 2A #01-15/16

Policy No:

MSD/VMS/18-378376-CA

Claim No:

MSC/V/18-001116

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/08/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:26am 3/10/18

Person Contacted:

Grace

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKR6652D - NA / MSG18014991/r3 DOA: 16/8/18
	FBM 6804R - NA / MSG18014991/r3 DOA: 16/8/18
04/10/18 @ 11:30am	Bar revised to Jasmine Lok via Mehmen.
	XGA Analysed Anal fig #2232-80
	(Red #560, 20%)
	no lump sum

Surveyor

AME.

REF:

MS16

1522F

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD (TP) WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s Chew Eoon  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKR 6652D Yr Regn: 27 Feb 2015  
 Type: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mazda 6 CC: 2488  
 Colour: Grey A/C: Insured / Std / NI / NA  
 Sp. Reading: 50569 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JM 66J 1031 F 9141232  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD / A/Rim or  
 Tyre Size: F: 225/55 R17  
 R: 11  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIS / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 03-10-18  
 Survey held at w/s 1pm  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
N/S rear  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$2222.8

RECEIVED 17 DEC 2018

RECEIVED 17 DEC 2018

14/12/2018

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

11/12/12 Amara

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$)  
☐ Interview (\$)  
☐ Tech. Invs (\$)  
☐ Weekend (\$)

Survey Fee:

Transportation:

) S \* RS, SI

) Photos

) Others

TOTAL

150
10
160

Report Format :

mer-7P

Lump Sum / I.B.I. (\$

2232.80)

**Note: This document has not been finalised.**

# LKK Auto Consultants Pte Ltd

(Co.,Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 04 Oct 2018

## Preliminary Advice

Insured Vehicle No	: FBM6804R	Accident Date	: 16/08/2018
TP Vehicle No	: SKR6652D	Assignment Date	: 02/10/2018
Make	: MAZDA 6	Est. Duration of Repair	: 2.00
Date of Inspection	: 03/10/2018		
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,792.80
Revised Amount	:S\$	2,232.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,232.80

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### Remarks

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Aug 2018		02 Oct 2018 15:57 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ONG HUAT KOK, ID: S1614649H		
Main Claimant:	LIM LEE PANG, ID: S1341522F		
Vehicle Reg. No.:	SKR6652D	Date of Loss:	16/08/2018 17:00 - :59 [41 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MSC/V/18-001116	Policy/Cover Note No.:	MSD/VMS/18-378376-CA (TP, Fire & Theft) Coverage: 06/02/2018 - 05/02/2019
Vehicle Reg. No. (Insured):	FBM6804R	Policy No. (Claimant):	
		Excess:	
Repairer:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64841626		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/10/2018]		
Driver/Custodian (Insured):	ONG YU HUI (), NRIC: S9404683A, Tel: +6582283479		
Adj Asg. Remarks:	on WP. Third Party Pre-Repair Survey. TP selected Lkk to be SJE, please arrange. Liability : unclear Contact : Ms Grace @ 6484 1626		

[View All](#)   [Compose Case Mail](#)

### ASSOCIATED MAIL RECEIVED

There are no mail for this case.

### ALL ASSOCIATED TASKS View All   Search Tasks   Create New Task   Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)
**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	1522F
<b>Vehicle Details</b>	
Vehicle No.:	SKR6652D
Vehicle to be Exported:	Yes
Intended De-registration Date:	17 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR HID
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	PY20420236
Chassis No.:	JM6GJ1031F0141232
Maximum Power Output:	138.0 kW (185 bhp)
Open Market Value:	\$22,711.00
Original Registration Date:	27 Feb 2015
First Registration Date:	27 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$18,796.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2025
PARF Rebate Amount:	\$14,097.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Feb 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,751.00
COE Rebate Amount:	\$43,566.00
<b>Total Rebate Amount:</b>	<b>\$57,663.00</b>

The information contained herein is correct as at 17 Aug 2018

OK

## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1522F
Vehicle Details	
Vehicle No.:	SKR6652D
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR HID
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	PY20420236
Chassis No.:	JM6GJ1031F0141232
Maximum Power Output:	138.0 kW (185 bhp)
Open Market Value:	\$22,711.00
Original Registration Date:	27 Feb 2015
First Registration Date:	27 Feb 2015
Transfer Count:	0
Actual ARF Paid:	\$18,796.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Feb 2025
PARF Rebate Amount:	\$14,097.00
Intended COE Rebate Details	
COE Expiry Date:	26 Feb 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$66,751.00
COE Rebate Amount:	\$42,712.00
<b>Total Rebate Amount:</b>	<b>\$56,809.00</b>

The information contained herein is correct as at 04 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/08/2018 15:40
Date Of Accident	16/08/2018 17:50
Exact Location Of Accident	ALONG YISHUN AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR6652D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM LEE PANG
NRIC No	S1341522F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92712368
Alternative Phone No	OTHERS-92712368

### Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA6 4-DOOR SEDAN 2.5L SP.6EAT SR HID
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B28681758QMY
Cover Note Number	

### Driver

Name of Driver	ANG TIEN SOO
NRIC No	S0179697F
Date Of Birth	02/09/1953
Occupation	OUTDOOR
Date Of Driving Pass	14/11/1973
Driving Experience	44 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96509529
Fax Number	
Contact Number	
EMail Address	NOEMAIL



Address	BLK 99 YISHUN AVENUE 1 #12-40
Postcode	769139
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM LEE PANG GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	YISHUN SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 32 YISHUN ST 81 , POSTCODE: 768456 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8522999 - FAX NO: 68522239
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED POLICE REPORT NO: T/20180816/2156.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PASS TO TRAFFIC POLICE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBM6804R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	
Address	



Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name UNKNOWN

Approximate Age

Injuries Sustain

Injured person in which vehicle? FBM6804R

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Sketch Plan #2

### SKETCH PLAN

A: SkR6652D  
B: FBM6804R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRJC/FIN No.:

17/8/18 1. PM 30



# SINGAPORE POLICE FORCE



T/20180816/2156

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

1 of 3

Report No. T/20180816/2156

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 16/08/2018 21:12		Vide Report No.:		Station Diary No.: 101	
<b>Informant's Particulars</b>					
Name of Informant: ANG TIEN SOO			Address: 99 YISHUN AVENUE 1 #12-40 SINGAPORE 769139		
ID Type / ID No.: NRIC NO / S0179697F			Contact No.: Home/Office: Mobile: 96509529		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 64	Date of Birth: 02/09/1953	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: RETIRED			Driving Licence Information: Class: Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 16/08/2018 17:50	Type of Location: Straight Road
Location: Along Road 1 YISHUN AVENUE 1				
Along Yishun Ave 1, left most lane after exiting from the Estuary Condominium				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBM6804R	Motorcycle				Slightly Damaged	0
SKR6652D	Car				Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180816/2156

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

2 of 3

Report No. T/20180816/2156

**CONTINUATION OF REPORT**

<b>Driver</b>			
Name	Unknown Driver	ID No.	NIL
Related Vehicle	FBM6804R (Motorcycle)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	ANG TIEN SOO	ID No.	S0179697F
Related Vehicle	SKR6652D (Car)	Contact No.	96509529
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 16/08/2018 at about 1750hrs, I had exited from Estuary Condominium and was driving on the left most lane along Yishun Ave 1. When suddenly, a blue motorbike (Plate No: FBM6804R) hit the left rear side of my car (Plate No: SKR6652D). Another driver had called for the ambulance to check on myself and the other motorist. My wife was in the vehicle with me, however we were both uninjured.

Damages to my car include: A long line of scratch at the rear left side below the headlights. Motorist was injured due to the impact and was conveyed to KTPH.

TP and ambulance had attended to me and the other motorist. No MC was issued to me. I did not take down the other motorist's particulars and has only his HP number: 82283479.

I am lodging this report for insurance purposes.



**SINGAPORE  
POLICE FORCE**



T/20180816/2156

3 of 3

Report No. T/20180816/2156

Police Station Of Origin:  
Yishun South N.P.C  
32 Yishun Street 81 SINGAPORE 768456  
Tel No: 1800-8522999

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:  
F /  
Sgt 2 MUHAMMAD ALIF AFIF BIN MOHD  
AMRAN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIA /  
Staff Sgt WONG SIEU LUI  
Contact No.: 65476151

Signature Of Informant:

Date/Time:  
16/08/2018 21:12

Classification Of Case:

Authentication Stamp  
NP168



Signature:

Singapore Police Force

SN 085

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S1341522F



Name  
LIM LEE PANG  
林莉芳



Race  
CHINESE

Date of Birth 11-11-1958 Sex F

Country of Birth  
SINGAPORE



2376558



NRC No. S1341522F



Blood Group O+ Date of Issue 12-09-1994

APT BLK 99 YISHUN AVENUE 1 #12-40  
SINGAPORE 769139

S1341522F 12/09/2013 (R)



**REPUBLIC OF SINGAPORE DRIVING LICENCE**



Licence Number: **S0179697F**  
 Name: **ANG TIEN SOO**  
 Birth Date: **02 Sep 1953**  
 Issue Date: **02 Oct 2003**

000882703F

**REPUBLIC OF SINGAPORE**  
 IDENTITY CARD NO. **S0179697F**



Name: **ANG TIEN SOO**  
 洪 天 賜  
 Race: **CHINESE**  
 Date of Birth: **02-09-1953** Sex: **M**  
 Country of Birth: **SINGAPORE**

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **14 Nov 1973**

Licence No: **S0179697F**

NP 428A

3166840

NRIC No. **S0179697F**



Blood Group: **O+** Date of issue: **28-08-2000**

**APT BLK 99 YISHUN AVENUE 1 #12-40**  
**SINGAPORE 769139**  
**S0179697F 12/09/2013 (R)**



**MSIG**

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.X.1  
Individual Ownership

**MOTOR MAX PLUS**  
**Comprehensive**

Certificate No. B 28681758 QMY

Excess : SGD1,000  
Windscreen Excess : SGD100

1. Index Mark and Registration Number of Vehicle  
SKR5652D

2. Name of Policyholder  
Lim Lee Pang

3. Effective Date of the Commencement of Insurance for the purposes of the Act  
27/02/2018

4. Date of Expiry of Insurance  
26/02/2019

5. Persons or Classes of Persons entitled to drive\*

Lim Lee Pang

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use\*

Use only for social domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover use for hire or reward racing pace-making reliability trial speed-testing the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

PLEASE NOTE ALL CLAIMS RELATED REPAIR CAN BE CARRIED OUT AT ANY WORKSHOP OF YOUR CHOICE OR AT ANY MSIG AUTHORISED WORKSHOP LISTED IN THE ATTACHED.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.  
Approved Insurers

for Chief Executive Officer

# 趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5  
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047  
Tel: 6484 1626 (24Hrs) Fax: 6484 0465  
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: MSIG Insurance (S) Pte Ltd

Policy No: \_\_\_\_\_ Third Party

Date: \_\_\_\_\_ 27.09.2018

Accident Date : 16.08.2018

Specialised in Car Painting, Welding,  
Panel-Beating and Insurance Claim.

## ESTIMATE

承接汽车烧焊喷漆及  
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
1pc	Estimate Cost of Repair to "Mazda 6" Reg. No. SKR6652D Claiming Against Your Insured Veh. No. FBM6804R		
10pcs	Rear Bumper <i>cut</i>	4.00	1,325.00
1pc	Rear Bumper Clips <i>MC</i>		40.00
	Taillamp Assy LH (LED) <i>CEA</i>		751.00
	Less 20%		2,116.00
			423.20
			1,692.80
	To Bore New Bumper Sensor Hole, Transfer Back Up Sensors, Rewiring Etc		40 100.00
	Labour Charge - Panel Beating, Repairing Of Rear Fender and Parts Replacement		200 400.00
	To Respray Affected Areas (2L and Above)		300 600.00
		Total :	2,792.80
			2232.8

2 Days.

part by part.

before paint photos.

Gmo Ai op - 82880282

03/10/18.

*Signature*  
4/10/18

Auto Consultants hence notify  
the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

## TAX INVOICE NO. 23781

Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint

Singapore 568047 Email: [chewgoon@singnet.com.sg](mailto:chewgoon@singnet.com.sg)

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

**TEL: 6484 1626 (24Hrs) FAX: 6484 0465**

◀ 修理各种汽车烧焊打吗咭喷漆等 ▶

**M**

MSIG INSURANCE (S) PTE LTD

ACCIDENT DATE : 16.08.2018

Date 08.12.2018

趙源摩哆  
CHEW GOON MOTOR

сречу

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18017908/GQD3N2

Date: 19/12/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/18-378376-CA	
Claimant Vehicle No :	SKR6652D	Insured Vehicle No :	FBM6804R	
Date of Loss:	16/08/2018	Nature of Claim:	TP	Claim No: MSC/V/18-001116

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKR6652D	Engine No:	PY20420236
Make & Model:	MAZDA 6, 2.5 4-DOOR SEDAN 2.5L SP.6E (A)	Chassis No:	JM6GJ1031F0141232
Reg. Date:	27/02/2015 (Man. Year: 2014)	Odometer:	50569 km
Colour:	Grey		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,692.80	1,692.80	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	540.00	560.00	50.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,792.80</b>	<b>2,232.80</b>	<b>560.00</b>	<b>20.05</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>195.50</b>	<b>156.30</b>	<b>39.20</b>	<b>20.05</b>
<b>Nett Amount (\$\$)</b>	<b>2,988.30</b>	<b>2,389.10</b>	<b>599.20</b>	<b>20.05</b>

## INSPECTION

Date of Assignment:	02/10/2018	
Date Inspected:	03/10/2018 Inspected At:	Chew Goon Motor (AMK) Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 19 Dec 2018)  
**Parts:** 143      MAZDA 6 2.5 4-DOOR SEDAN 2.5L SP.6E (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SKR6652D)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut	1,325.00 FL	*1,325.00 FL
2	10		*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
3	1		*TAILLAMP ASSY LH (LED)	Cracked	751.00 FL	*751.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					2,116.00	2,116.00
- List Item Discount on L Items 20.00/20.00% (S\$)					423.20	423.20
Total Parts (S\$)					1,692.80	1,692.80

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO BORE NEW BUMPER SENSOR HOLE,TRANSFER BACK UP SENSORS,REWIRING ETC	New	100.00	40.00
2	LABOUR CHARGE-PANEL BEATING,REPAIRING OF REAR FENDER AND PARTS REPLACEMENT	New	400.00	200.00
3	TO RESPRAY AFFECTED AREAS (2L AND ABOVE)	New	600.00	300.00
Gross Labour Cost (S\$)			1,100.00	540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >