

UNIQUE

INS. CASE OWNER:

Stacy

CC 4 / AXA1801

7409, 2 cbh

LKK:

IDAC:

Surveyor:

Kasul

DOI:

ASSIGNMENT

12/10/18

Date / Time:

7/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YN 7728P

Name of Insured:

BANK THONG LOGISTIC PTE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

10/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

GERMAN DIN FARI YASUNITO

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

SBMODLME (7703)

Policy No.:

D1792720

Make / Model:

MITSUBISHI

Place of Accident:

INSIDE 128 710 SENG KO

OI GIA REPORT:

YES

/ NO

TP GIA REPORT:

YES

/ NO

Insured Liability:

%

Final ? Yes / No

GBG 66795



INSRS:

WSP:

Tel:

Liability:

RMKS:

Sin
Sheng

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

8/10/18
HSH

GBG 66795-X

YN 7728P-X

*sumitted claim

06-03-19 9am

CAUSED O/D (CONFIRMED ACCIDENT). O/D ITATIONS THE HE
FROM A TRUCK AND THE O/D FROM FALL THE TP. IMPROVE
TP O/DMS AGREE TO SETTLE AND AVOID FROM NO USE

STAGE	DATE / PIC
Non-Reporting Ir (1st):	
Non-Reporting Ir (2nd):	
Non-Reporting Ir (Final):	
Notification Ir (if non-pickup):	
Call OI:	7/10/18
After call Ir to OI:	
Documentation Check List: Handler Typist	
Notification Ir (if non-pickup):	<input checked="" type="checkbox"/>
After call Ir to OI:	<input checked="" type="checkbox"/>
Authorisation To Act:	<input checked="" type="checkbox"/>
Release-Voucher: DE SCUM:	<input checked="" type="checkbox"/>
Final Repair Bill:	<input checked="" type="checkbox"/>
Car Rental Invoice:	<input checked="" type="checkbox"/>
Towing Invoice:	<input checked="" type="checkbox"/>
LTA / GIA:	<input checked="" type="checkbox"/>
Medical Bill:	<input checked="" type="checkbox"/>
PIR:	<input checked="" type="checkbox"/>
Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
LOD:	<input checked="" type="checkbox"/>
Payment Breakdown Form:	<input checked="" type="checkbox"/>
Post-Repair Photos:	<input checked="" type="checkbox"/>
Others:	<input checked="" type="checkbox"/>

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MEB

Repair Cost:

SS 1,100

(3 days) Reduction:

31 %

Email ☒Call ☒

FINAL SETTLEMENT

Date/Time: 14-06-19

Confirm with: Susan

Email ☒Call ☒

Final Liability:

SS 100

(Agreed / Assessed) BOLA S/N No.:

YOL

If NO or B 28. Ass. Lia:

Repair Cost:

SS 1,171.00

O/D FROM THE TP.

Loss of Rental (LOR):

SS -

(days)

Loss of Use (LOU):

SS 300.00

(560 x 5 days)

Loss of Income (LOI):

SS -

(5 x days)

LOR only ☒ LOU only ☒LOR + LOU ☒LOR + LOU ☒

[Tick only one]

GLA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/Independent)

Legal Cost

SS -

Total:

SS 1,479.00

Global Sum SS:

FINAL PAYMENT

Date/Time: 14-06-19

Confirm with: Susan

Email ☒Call ☒

Payee 1:

SS 1,479.00

Name 1:

Sin SHENG ENGINEERING SERVICES

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS


Name 3:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: **GBH 6679S**
 at Workshop mis: **SIN S HONG**
 of _____
 Insured: **AXA / mp**
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **54k**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: **3** days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: **GBH 6679S** Yr Regn: **2017 / SGP**
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: **FIAT DOBLO CARO MAXI 1.6 c.c** 1598
 Colour: **WHIT** A/C: Insured / Std / NI / NA
 Sp.Reading: _____ T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: **ZFA 263 0000 6H 31077**
 Gen. Cond: Good / **B** / Poor / Burnt
 Steering: **Inorder** / Jammed / Leaked / Burnt or
 Brake: **Inorder** / Jammed / Leaked / Burnt or
 Modl: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **195/60R16**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **CONTINENTAL**

Front _____ Rear _____
 R/Bal. **6** mm R/Bal. **6** mm
 L/Bal. **6** mm L/Bal. **6** mm
 D.O.A. **20/06/18** D.O.I. **12/10/18**
 Survey held at **SIN S HONG**

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

2/1/17 (200-7-650 317-)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation: _____ \$ + RS. _____ \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18017909/eb3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 03-10-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7738P	Veh. Inspected	GBG 6679S	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/10/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/06/2018	Inspection Date		
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002631

Date : 12/10/2018

Vehicle Num. : GBC6679S

Make/Model : FIAT DOBLO 1.6MJTD-2017

Chassis/Eng# : ZFA26300006H31077/263A5000817:

Accident Date : 20/06/2018

Claim No. :

Reference : YN7738P

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO PANEL BEAT/REPAIR RH SIDE PANEL

TO PANEL BEAT/REPAIR RH SLIDING DOOR

SPRAY PAINTING

TO APPLY NEW LOGO

LOSS OF USE : 5 DAYS @ S 120/DAY

Labour Total S\$:

~~550.00~~ 300

~~750.00~~ 500

~~450.00~~ 300

1,750.00

Resur
Hp 900/10068
3 days
P/P
12/10/18 @ 1440
Resur after repair

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged car(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 1,750.00

SIN SHENG ENGINEERING SERVICES



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 16/10/2018

Survey Details:

Date of loss	20-Jun-18
Date of appointment	3-Oct-18
Date of survey	12-Oct-18
Location of survey	SIN SHENG ENGINEERING SERVICES

Vehicle Details:

Claim Type:	Third party
Vehicle number	GBG 6679S
Make and Model	FIAT DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE
Date of registration	25/9/2017
Excess	
Market Value	\$54,000
Parf Rebate	\$41,914
Nett Loss	\$12,086

Repair details:

Initial Estimate	\$ 1,750.00
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ -
Check items (estimate)	\$ -
Labour	\$ 1,100.00
Total	\$ 1,100.00
Lump Sum(if applicable)	\$ -

Number of days for repair	<u>3 DAYS</u>
---------------------------	---------------

6/4/2019

Claim Portal

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

Menu



MANDATE IA

Type

🔍 Question

Message

APPROVED

Reply

Your Insured's vehicle : YN7738P

Our customer's vehicle : **GBG6679S**

Date : 02/10/2018

AXA INSURANCE PTE LTD

Dear Sirs,

DATE OF ACCIDENT : 20 JUN 2018

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION/SURVEY & SEEK ATTENTION

We have been appointed by Goldbell Leasing Pte Ltd repair their vehicle no. GBG6679S

Please be informed that the said vehicle can be inspected at :

Workshop : Sin Sheng Engineering Services

Address : 3 Tech Park Crescent, Tuas Tech Park, Singapore 638129

Contact : Ms Susan / Ms Cheryl Yuan

Tel / Fax : 6863 9595 / 6863 6477

Pursuant to ePractice Direction No 2 of 2011, we hereby give you notice to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday and/or Public Holiday failing which we will commence repairs thereafter without any further notice or reference to you. Kindly acknowledge upon inspection in the acknowledgement box below. Alternatively kindly inform us in writing if you are waiving your rights to an inspection of our customer's vehicle.

NB. Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damage only and shall not preclude client's driver/passanger from claiming injury-related damage arising from this accident.

Your sincerely,

Susan

Acknowledgement

This is to confirm that I <i>LKK</i> <i>ASUL</i> \[Full Name of Surveyor]	
of <i>LKK</i> <i>ASUL</i> \[Surveyor's Company]	
have completed the pre-repair inspection on <i>12/10/18</i> \[Date if Inspection]	
at <i>1400</i> \[Time of Inspection]	
<i>[Signature]</i>	<i>Susan</i>
Signature of Appointed Surveyor	Witnessed By:
Company Stamp	Date

Waiver

We waive our rights to an inspection/survey of the above vehicle.	
Signature _____	
Name :	
Date :	



Service Request Details

Claim

S8M00LME

Reference

None

Loss Date

June 20, 2018

Request Date

October 2, 2018

Due Date

October 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

03/10/2018 @ 1028am
Susan veh not in

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBG6679S

Make

TPVD FIAT

Model

DOBLO CARGO MAXI-1.6 D MTJ AMT GLAZE (M)

Service Address

...

Primary Contact/Insured

BAN THONG LOGISTIC PTE LTD

21 TOH GUAN ROAD EAST, #09-16, TOH GUAN CENTRE, 608609, Singapore

64639598

operation@banthong.com

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



新盛机械工程服务

SIN SHENG ENGINEERING SERVICES

REGISTRATION NO : 312029/00D

No 3, Tech Park Crescent, Tuas Tech Park, Singapore 638129

Tel : 6863 9595 Fax : 6863 6477 Email : sinsheng1981@gmail.com

16-Nov-18

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1, #02-25
Paya Ubi Industrial Park
Singapore 408933

Fax: 6741 4108

Tel: 6256 3561

Our ref: SSES/L2018/0372

Your ref: CC4/ASM18017909/eb3

Attn: Ms Asher

Dear Sir,

VEHICLE: GBG6679S (DoA: 20/06/2018)

We refer to the above and append herewith our costings for your perusal: -

Final Repair Bill	:	1,177.00
Loss of Use: 5 days @ S\$ 120/day (including 2 day for PRI)	:	600.00
Survey Fee	:	N/A
Third Party Vehicle Insurance Search Fee	:	2.00
Total	:	<u><u>1,779.00</u></u>

Thank You

Yours faithfully

Susan Tan

OPERATIONS EXECUTIVE

Encl



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

06 MAR 2019

BAN THONG LOGISTIC PTE. LTD.

21 TOH GUAN ROAD EAST
#09-16 TOH GUAN CENTRE
SINGAPORE 608609

Dear Sir/ Mdm

OUR REF : CC4/ASM18017909/R1eb3

YOUR REF : YN 7738P

ACCIDENT INVOLVING YN 7738P AND GBG 6679S ALONG INSIDE 138 JOO SEN ROAD ON 22/10/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s SIN SHENG ENGINEERING SERVICES acting on behalf of the owner of GBG 6679S against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that item fallen off from your vehicle and hit onto Third Party Vehicle GBG 6679S. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to ashersng@lkkauto.com within 7 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at ashersng@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Asher
Case Handler
DID: 6841 6051
FAX: 6741 4108
Email: ashersng@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, GOLDBELL LEASING PTE LTD ("The Third Party Claimant") of
NO 59, SENOKO ROAD, SINGAPORE 758123 (address),
being the owner of GBG6679S (vehicle no.) hereby authorize
SIN SHENG ENGINEERING SERVICES ("the workshop") to act for me
with respect to my claim for repair cost and / or rental and / or loss of use ("claim") for my
vehicle bearing registration no. GBG6679S that was damaged pursuant to the accident
which occurred on 20/06/2018 along 138 Joo Seng Road
involving vehicle's GBG6679S / YN7738P ("the
accident")

I further authorize the workshop to settle my above mentioned claim in a manner they deem
fit and the workshop is further authorized to receive payment further to settlement of my
claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability in so far as the driver/owner/insurers of
the other vehicle is concerned.

Dated this 07 day of NOV (month) 2018 (year)



Signed by "the Third Party claimant"



Signed by "the workshop"



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	YN 7738P	(Insd veh)	Model: FIAT DOBLO CARGO MAXI
	GBG 6679S	(TP veh)	
Date of Accident/ Time:	20/06/2018 / 08:45		

Repair Estimate	: \$	1,872.50	
Final Repair Cost	: \$	1,177.00	
Loss of Use	: \$	300.00	5 days at \$60.00 per day
Rental (if any)	: \$	-	days at \$ per day
LTA / GIA Search Fee	: \$	2.00	
Others:	: \$	-	
	: \$	-	
Final Settlement Sum	: \$	1,479.00	

Payee Name : SIN SHENG ENGINEERING SERVICES

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A)	For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes / No BOLA Scenario No: <u>NIL</u>
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.		

Remarks:

NOTE:

1. PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
2. THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
3. AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.


We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp

Name of Representative:

Date:



MEB

Signature of Witness / Workshop stamp (if applicable)

Name of Witness:

Date:

Signature of AXA's surveyor/representative:

Name of AXA's surveyor /Representative:

Date:

SIN SHENG ENGINEERING SERVICES

3 TECH PARK CRESCENT

SINGAPORE 638129

Tel No. : 6863-9595 Fax No. : 6863-6477

E-Mail : sinsheng1981@gmail.com

Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD

59 SENOKO ROAD

SINGAPORE 758123

Attention : Motor Claim Department

Contact : 6861 0007 Fax No. : 6753 7780

Tax Invoice : T1002631

Date : 16/11/2018

Vehicle Num. : GBG6679S

Make/Model : FIAT DOBLO 1.6MJTD-2017

Chassis/Eng# : ZFA26300006H31077/263A500081731


Accident Date : 20/06/2018

Claim No. : S8M00LME MC/NPS

Reference : YN7738P

Policy No. : 29004183

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO PANEL BEAT/REPAIR RH SIDE PANEL		300.00
		TO PANEL BEAT/REPAIR RH SLIDING DOOR		
		SPRAY PAINTING		500.00
		TO APPLY NEW LOGO		300.00
		LOSS OF USE : 3 DAYS @ \$ 120/DAY		
		Labour Total S\$:		1,100.00



Total S\$: 1,100.00
GST @ 7% S\$: 77.00
Amount Due S\$: 1,177.00
=====

SIN SHENG ENGINEERING SERVICES

M9-0010014-J



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735**TAX INVOICE**

Our Ref No: GR-18-151935

Date of Request: 02/10/2018

Your Ref No: Online Purchase

Sin Sheng Engineering Services
3 Tech Park Crescent
Tuas Tech Park
Singapore 638129

Dear Sir/Madam,

GBG6679S (DoA:20/06/2018)

Owner : GBL

Enquiry Date: 02/10/2018
Enquiry By: Wang Sye Yuen
TP Vehicle No.: YN7738P
Accident Date: 20/06/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	YN 7738P (Insd veh)	Model:	FIAT DOBLO CARGO
	GBG 6679S (TP veh)		MAXI 1.6
Date of Accident:	20/06/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	1,872.50
Final Repair Cost	:	\$	1,177.00
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	5days at \$60.00 per day
LTA / GIA Search Fee	:	\$	2.00

Others:	:	\$	0.00
---------	---	----	------

	:	\$	
Final Settlement Sum	:	\$	1,479.00

Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____(%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/ No BOLA Scenario No: _____
	__NIL__
BOLA Liability: ____100____(%)	Assessed Liability (*): _____(%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks _____	

Payment Instruction: Payee's Breakdown		
1)	SIN SHENG ENGINEERING SERVICES	\$ 1,479.00

JOANNE LEE KHANG MIN
LKK Auto Consultants Pte Ltd

02/07/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18017909/R1eb3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG		Date : 02-07-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7738P	Veh. Inspected	GBG 6679S	
Policy No.	P1753720	Coverage (\$)	0.00	
Claim No.	S8M00LME	Excess (\$)	0.00	
Assign From		Assign Date	03/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO MAXI 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZFA26300006H31077	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16	CONTINENTAL	6 mm	
L/H Front Tyre	195/60 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	195/60 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	195/60 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/06/2018	Inspection Date	12/10/2018	
Survey held at	SIN SHENG ENGINEERING SERVICES 3 TECH PARK CRESCENT TUAS TECK PARK SINGAPORE 638129			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 6679S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO PANEL BEAT/REPAIR RH SIDE PANEL,TO PANEL BEAT/REPAIR RH SLIDING DOOR.		550.00	300.00
	SPRAY PAINTING.		750.00	500.00
	TO APPLY NEW LOGO .		450.00	300.00
			1,750.00	1,100.00
	GRAND TOTAL		1,750.00	1,100.00
RECOMMENDED COST OF REPAIRS				1,100.00

Report Ref No. CC4/ASM18017909/R1eb3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
 YN7738P 245D GIA REPORT.PDF	Reports & Statements	GIA Report	RATAN BHOSALE Pragati	2 October 2018
 CBG66795 TP GIA.PDF	Reports & Statements	GIA Report	RATAN BHOSALE Pragati	2 October 2018
 EMAIL RECIEVED FROM WORKSHOP WITH TP GIA REPORT.png	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	2 October 2018