

22/03/2002

ASS. REC. BY:

REF:

CS3/CT118017912/TLCD3

Special Instruction:

Survivor:

Menmen

Taufik

ASSIGNMENT (Office)

From (Person):

Catherine thia

of

CTI

Date/Time:

31/10/18 @ 10.43am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SGM 8554P

Insured:

SGJ 932A

at Workshop m/s

V-tech Auto

Tel:

6264 6211

of

No.1 soon lee st # 06-04

Policy No:

DMPCSN3045351802

Claim No:

SNM18D04712C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/09/2018

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

12:07pm @ 31/10/18

Person Contacted:

Ms. Chong

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SGM 8554P-X
	SGJ 932A-CC6/ALG12023809/M/g 2/2y DoA: 15/12/2012
	Dismantle: 5/10/2018

Surveyor Tamper

REF:

CT1


ASSIGNMENT

CoE: 2021 out

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / CD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 *repair at the time of inspection.



Bal. or Market Value: 9/7K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 15 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGM 855 4P Yr Regn: 2006 out
 Type: 60 M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Vios C.C: (497)
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 180435 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: M105 311y 4204208448
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or 65K14
 Tyre Size: F: 175 R: 175
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Fallen
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 3/6/18
 Survey held at V-Tech Soon to SL
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Range 3000/2 - 3800/2 9/10/2018

Trim
9/10/18

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: PRE

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Oct 2018		03 Oct 2018 10:43 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	CAO YIQIANG, ID: S2655165Z		
Main Claimant:	AURUM WING		
Vehicle Reg. No.:	SGM8554P	Date of Loss:	28/09/2018 22:00 - :59
Claim Type:	TP / SNM18D04712C02	Policy/Cover Note No.:	DMPCSN3045351802 (Comprehensive)
Vehicle Reg. No. (Insured):	SGJ932A	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

ONG & SHAN LLC

ADVOCATES & SOLICITORS
COMMISSIONERS FOR OATHS
NOTARIES PUBLIC

Our Counter-Signatory's Email Notifications:
Lawyer : ongshanllc@gmail.com
Secretary :

Please send all correspondences to:

- ☐ 2 Kallang Avenue #08-19 Singapore 339407
Tel: 6444 7845 | Fax: 6444 5847
- ☐ 101 Upper Cross Street #06-15B Singapore 058357
Tel: 6536 7991 | Fax: 6536 7995
- ☒ 184 Toa Payoh Central #02-364 Singapore 310184
Tel: 6224 9847 | Fax: 6254 7261

WE DO NOT ACCEPT SERVICE BY FAX

Our Ref : SRSTP.8246.18.CM

Your Ref : Your insured vehicle SGJ 932A

3rd October 2018

Cao YiQiang
c/o China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00, Springleaf Tower
Singapore 079909

BY EMAIL

**NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)
ROAD TRAFFIC ACCIDENT INVOLVING SGM 8554P & SGJ 932A ON 28.09.2018 ALONG BUKIT
BATOK ST 22 MSCP @ 2320 HRS**

We refer to the above matter and your email dated 2nd October 2018.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

- | | |
|--|---|
| 1. Dennis Yap Teck Wee (Pal's Appraiser Pte Ltd) | 2. Dixon Yeo (Treasure Appraisal Services) |
| 3. Yap Teck Lee (LCW Appraiser Pte Ltd) | 4. Mark (United Appraisal & Management Pte Ltd) |
| 5. Yap Teck Chye (MC. Coy Appraiser Pte Ltd) | 6. Andrew How (Prominent Appraiser Services) |
| 7. T.T Rajan (ST Appraisal Services) | 8. Amas Ong (Aeon Auto Consultants LLP) |
| 9. Alan Cheong (CL Appraiser Pte Ltd) | 10. Sebastian Lim (Constant Appraiser Services) |

Please be informed that the said vehicle can be inspected at:-

Name of workshop	M/s. V-Tech Auto Service
Address	No. 1 Soon Lee Street #06-04/05/06/07 Pioneer Centre Singapore 627605
Contact person	Ms. Chong
Telephone	6-2646211
Fax no	6-2646233

Please be informed that if we do not hear from you within 2 working days from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "Single Joint Expert".

We will accordingly inform you who the "Single Joint Expert" is to be facilitate your conduct of a pre-repair survey.

If you object to our list of motor surveyors, we will accordingly inform the claimant to instruct his choice of motor surveyors to conduct the pre-repair survey.

Yours faithfully,

Ong & Shan LLC

For Surveyor

Please initial here after completion of pre-repair inspection. Thank you.

Name:
Signature:

Date & Time of Pre-repair Inspection: /

ONG & SHAN

A LIMITED LIABILITY CORPORATION | COMPANY REGISTRATION NUMBER 201408968D

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0939L
Vehicle Details	
Vehicle No.:	SGM8554P
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	1NZX490494
Chassis No.:	MR053HY4204208448
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,237.00
Original Registration Date:	30 Oct 2006
First Registration Date:	30 Oct 2006
Transfer Count:	2
Actual ARF Paid:	\$13,461.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$26,054.00
COE Rebate Amount:	\$15,926.00
Total Rebate Amount:	\$15,926.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/09/2018 16:45
Date Of Accident	28/09/2018 23:20
Exact Location Of Accident	BUKIT BATOK ST 22 MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGM8554P
Insured/Policyholder	
Name Of Registered Owner	AURUM WING
Co Reg No	53200939L
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93861061
Alternative Phone No	OFFICE-93861061

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5075510507-02
Cover Note Number	

Driver

Name of Driver	ANG KOK LUEW
NRIC No	S8415716C
Date Of Birth	15/05/1988
Occupation	OUTDOOR
Date Of Driving Pass	27/11/2006
Driving Experience	11 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93861061
Fax Number	
Contact Number	OFFICE-93861061
Email Address	NOEMAIL

Address	296B BUKIT BATOK ST 22 #21-82
Postcode	S652296
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ932A
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 1652hrs

30 Sep 2018

30 SEP 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28 Sep 2018, Friday night @ 2320hrs, I was driving down the multi-storey carpark of B1K 296B Bukit Batok St2a and saw a car stopping at a distance of ~~50m~~ 5m away. I slowed down and stopped at 5m away to observe why it was blocking the junction of the split road which leads to the exit of the carpark. When both car was at stationary position, the car (S63 932A) in front suddenly reversed at high speed towards my car. I tried to hit reversed gear but the car in front had banged my car frontage before I could reversed.

DECLARATION

I/We declare the foregoing particulars are true in every respect. SEP 2018



Policyholder's Signature

Date & Time: 30 Sep 2018
1652hrs

Driver's Signature

(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)

511 Bukit Batok Street 23

Singapore 659515

Tel: 6560 3312, Fax: 6560 0722

Email: vac@idac.gov.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Oct 2018		03 Oct 2018 10:43 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CAO YIQIANG , ID: S2655165Z								
Main Claimant:	AURUM WING								
Vehicle Reg. No.:	SGM8554P	Date of Loss:	28/09/2018 22:00 - :59 [142 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04712C02	Policy/Cover Note No.:	DMPCSN3045351802 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGJ932A	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center, 627605 Pioneer - Tel: 62646211								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 12/10/2018]								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGM8554P (SNM18D04712C02)
[SGJ932A]
TP
AURUM WING
Sep 28 2018 10:00PM
[CAO YIQIANG]
V-Tech Auto Service

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	01/10/18 14:15	Accident Statement	Load HTM	

Photos/Images

3 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	01/10/18 14:14	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	01/10/18 14:14	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	01/10/18 14:14	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	01/10/18 14:14	CHASSIS NUMBER [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

No

Relabel/Reorder

LKK Auto Consultants Pte Ltd (HQ)

Thumbnail

Print

1	08/10/18 11:45	General View	Load PDF	
2	08/10/18 11:45	Photographs of Damaged Parts	Load PDF	

Documentation

1 per page

No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	01/10/18 11:23	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	01/10/18 11:24	CERTIFICATE OF INSURANCE [Linked Accident Report Documents]	Load TIF	
3	01/10/18 11:24	DRIVER'S NRIC + DRIVING LICENCE [Linked Accident Report Documents]	Load TIF	

No

Finalized On

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Thumbnail

Print

1	03/10/18 10:42	PRS	Load PDF	
2	03/10/18 10:43	OI GIA	Load PDF	

Linked Accident Report Documents

View View in Browser

Assessment Reports					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	01/10/18 14:15	Accident Statement		Load HTM		
Photos/Images					3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	01/10/18 14:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
2	01/10/18 14:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
3	01/10/18 14:14	Accident Photo		Load JPG	<input checked="" type="checkbox"/>	
4	01/10/18 14:14	CHASSIS NUMBER		Load JPG	<input checked="" type="checkbox"/>	
Documentation					1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print	
1	01/10/18 11:23	Sketch Plan		Load TIF		

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
2	01/10/18 11:24	CERTIFICATE OF INSURANCE		Load TIF	
3	01/10/18 11:24	DRIVER'S NRIC + DRIVING LICENCE		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
---------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017912/T1CD3E2

Date: 11/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3045351802		
Claimant Vehicle No :	SGM8554P	Insured Vehicle No :	SGJ932A		
Date of Loss:	28/09/2018	Nature of Claim:	TP	Claim No:	SNM18D04712C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM8554P		Engine No:	1NZX490494
Make & Model:	TOYOTA VIOS, 1.5 (A)		Chassis No:	MR053HY4204208448
Reg. Date:	30/10/2006 (Man. Year: 2006)		Odometer:	180435 km
Colour:	Black			
Engine Capacity:	1497 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R14	Rear Tyre Size:	175/65 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	03/10/2018	
Date Inspected:	03/10/2018 Inspected At:	V-Tech Auto Service (HQ) No.1 Soon Lee Street, #06-04 Pioneer Center Singapore 627605
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$3,800.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2018)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM8554P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >