

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

MS16/

CB/MSG/18017942/180312

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SK8705Xat Workshop m/s H.

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: Plc.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 5/11/2018

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SK8705X Yr Regn: 0/11/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Monte Stream C.C. 1799Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 333251 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RN 6 108 46 47

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: 225/452R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 2/10/18 D.O.I. 3/10/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	1 with 3 day LTA 670
	5 day 1k. net 1200
10/10/18	@ 15:50 p.m. revert pending estimate from repairer to Christine Wang
15/10/18	via memo
15/10/18	2/5 @ 1200 confirmed with Alan
15/10/18	Confirmed 2/5 @ 1,200/- @ 2 days with Marcus.
	C\$ 1,339.40 Red - 53%?

Date/Time, File Pass to?

15/10/18

1) typ

Date/Time, File Return to?

2) \_\_\_\_\_

☐ : Preli. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

150

10

160

Report Format :

Lump Sum / I.B.I. (\$ 1,200/- 2/5)

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 15 Oct 2018

**Preliminary Advice**

Insured Vehicle No	: FP8457H	Accident Date	: 02/10/2018
TP Vehicle No	: SJK8705X	Assignment Date	: 10/10/2018
Make	: HONDA STREAM	Est. Duration of Repair	: 2 days
Date of Inspection	: 03/10/2018		
Inspection At	: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,539.40
Revised Amount	:S\$	1,506.96
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,506.96

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## View Sent Message

This mail is associated with :

**\*SJK8705X  
[FP8457H]**

TP

FASTECH AUTO PTE LTD  
Oct 2 2018 12:00AM  
[JATI ABDILLAH BIN MAHMOOD]  
Fastech Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 10/10/2018 15:50 PM.  
**To** christina\_wong@sg.mslg-asla.com  
**CC** sur@lkkauto.com  
**Subject** SJK8705X [FP8457H] TP

Dear Christina,

Please be informed that we have inspected the vehicle SJK 8705X on 03/10/2018.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

### DOCUMENTS SUMMARY

There are no documents.

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Thursday, 4 October 2018 3:55 PM  
**To:** Christina\_Wong@sg.msg-asia.com; hasrianah@sg.msg-asia.com  
**Cc:** kklau@lkkauto.com; account@lkkauto.com; sur@lkkauto.com  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 29/08/2018 , SJK 8705X (TP VEHICLE), FP 8457H (OI VEHICLE)  
**Attachments:** TP GIA REPORT.pdf

Dear Christina/Hasrianah,

Please be informed that we had inspected the vehicle SJK 8705X M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 ,#01-46/48/50 AUTOBAY SINGAPORE 417883 on 03/10/2018

Enclosed herewith a copy of TP's GIA report. The estimated cost of repair will forward to you shortly.

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6262D
Vehicle Details	
Vehicle No.:	SJK8705X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	R18A1793916
Chassis No.:	RN61084647
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$19,026.00
Original Registration Date:	06 Nov 2008
First Registration Date:	06 Nov 2008
Transfer Count:	2
Actual ARF Paid:	\$13,418.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Nov 2018
PARF Rebate Amount:	\$6,709.00
Intended COE Rebate Details	
COE Expiry Date:	05 Nov 2018
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$2,949.00
COE Rebate Amount:	\$71.00
<b>Total Rebate Amount:</b>	<b>\$6,780.00</b>

The information contained herein is correct as at 04 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/10/2018 14:45
Date Of Accident	02/10/2018 07:30
Exact Location Of Accident	AMK AVE 1 TWDS UPPR THOMSON B4 CTE EXIT TWDS AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK8705X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FASTECH AUTO PTE LTD
Co Reg No	200006262D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98225633
Alternative Phone No	OFFICE-98225633

### Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 X (A)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	GA033678/1
Cover Note Number	

### Driver

Name of Driver	GOH CHEE BENG
NRIC No	S1462327B
Date Of Birth	16/03/1961
Occupation	OUTDOOR
Date Of Driving Pass	15/03/2001
Driving Experience	17 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98225633
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 335 SERANGOON AVENUE 3 #08-333 SPORE 550335

Postcode

Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OTHER - HIRER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? YES  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FP8457H  
Vehicle Make/Model/Colour YAMAHA RXZ  
Details Of Properties  
Vehicle Category MOTORCYCLE  
Name of Driver  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

### SKETCH PLAN

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.

(e) the information so collected under (d) above may be shared / disclosed:

- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
- (ii) for complying with requirements under any regulations, laws or court orders.



Driver's Signature \_\_\_\_\_  
(if driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: S. J. J. J. J.  
NRIC/FIN No.: S. J. J. J. J.

### Sketch Plan #2

### SKETCH PLAN

Feb. 11 - 1947

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/10/2018 at about 7:30 am at along  
AMK Ave / Tnd's upper Thonoores before CTE Exit Tnd's  
ANE: The front motorcycle repeatedly engaged rear  
brake, where the traffic was clear.

I slow down my vehicle A due to the front motorcycle.  
Suddenly I heard a loud bang from behind.  
Vehicle B signal me to stop at left side.  
Vehicle B motorist ask me call ambulance to send  
him hospital.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature \_\_\_\_\_

**Date & Time:**

Driver's Signature \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

Reporting Centre Personnel's Signature  
Name: *S. K. Singh*  
NRIC/PIN No.: *860503770*

Sketch Plan #3



2/10/2018

7:35 AM

UP 9405117



ARMK Ave 1 Towards Upper Thompsons  
Before CTE Exit Towards AYE





redefining / insurance

AXA Insurance Pte Ltd  
 1800 880 4888 (Within Singapore)  
 (65) 6880 4888 (International)  
 (65) 6880 4740  
 customer.care@axa.com.sg  
 www.axa.com.sg

account number  
 03180

## Certificate of Insurance

-Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) - Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 - Road Transport Act, 1987 (Malaysia)  
 -Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

### Policy details

Policyholder name	FASTECH AUTO PTE LTD	Certificate number	GA033678 / 1
Cover	Comprehensive	Chassis number	RN61084647
Plan name	Essential	Engine number	R18A1793916
NCD applicable	20%		
Vehicle registration number	SJK8705X		
Period of Insurance	from 06/05/2017 to 05/11/2018 (both dates inclusive)		
Finance loan company	Nil		

### Persons or classes of persons entitled to drive\*

(a) Any Named Driver as stated in the Policy:

1. GOH CHEE BENG

(b) Any person who is driving on the Policyholder's order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

### Limitation as to use\*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS	Basic Own Damage Excess	S\$D 600.00
	Windscreen Excess	S\$D 100.00

An Additional Excess is applicable as follows:

1. S\$500 for unnamed *Authorised Driver*
2. S\$500 for declared *Young and Inexperienced Driver*
3. S\$5,000 for undeclared *Young and Inexperienced Drivers*. This additional excess is reduced to S\$2,500 if You have chosen AXA Premium Workshops.

### Additional clauses & endorsements to your policy

Nil

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provision of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA Insurance Pte Ltd

Authorised signature

### Important note

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, endorsement etc.

AXA Insurance Pte Ltd (199903512M)  
 8 Shenton Way, #24-01, AXA Tower,  
 Singapore 068811  
 Customer Centre, #B1-01

KHC HOLDINGS PTE LTD  
 380A BALESTIER ROAD SINGAPORE 340706  
 TEL: 62562008 FAX: 62500707

1 of 3

FASTECH AUTO PTE LTD  
1 KAKI BUKIT AVENUE 6  
#01-46/48/50  
SINGAPORE 417883

VEHICLE NO: SLK 8705X

QTY	PARTICULAR
1 PCS	REAR BUMPER
1 PCS	REAR BUMPER SIDE RETAINER O/S
1 SET	REAR BUMPER CLIPS 30
1 PCS	TAILLAMP O/S 338.30

20%

LABOUR CHARGES:

TO CHECK WIRING  
TO DISMANTLE & REFIX REVERSE SENSOR  
TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY  
TO SPRAY RUSF PROOFING  
LABOUR FOR PANEL BEATING, CUT & REPLACING PARTS  
TO PUTTY & SPRAY PAINTING

Deepcur	\$665.40
11	\$35.50 X
11	\$50.00
320	\$408.50
	\$1,159.40

	\$50.00 30
	\$80.00 50
11	\$120.00 X
11	\$50.00 X
	\$500.00 200
	\$580.00 400
TOTAL	\$2,539.40

P-1033.7  
207  
826.96  
1506.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG18017942/USD3N2  
Date: 16/10/2018

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/MT/18-387891-CA	Claim No:	MSC/V/18-001368
Claimant Vehicle No :	SJK8705X	Insured Vehicle No :	FP8457H		
Date of Loss:	02/10/2018	Nature of Claim:	TP		

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK8705X	Engine No:	R18A1793916
Make & Model:	HONDA STREAM, 1.8 X (A)	Chassis No:	RN61084647
Reg. Date:	06/11/2008 (Man. Year: 2008)	Odometer:	333251 km
Colour:	Brown		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45ZR17	Rear Tyre Size:	225/45ZR17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,159.40	826.96	332.44	28.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	680.00	700.00	50.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,539.40	1,506.96	1,032.44	40.66
Approved Total (Overridden) (S\$)		1,200.00		
(S\$)	2,539.40	1,200.00	1,339.40	52.74
+ GST 7.00/7.00% (S\$)	177.76	84.00	93.76	52.75
Nett Amount (S\$)	2,717.16	1,284.00	1,433.16	52.74

### INSPECTION

Date of Assignment:	10/10/2018	Fastech Auto Pte Ltd (HQ)
Date Inspected:	03/10/2018 Inspected At:	1 Kaki Bukit Ave 6, #01-46/48/50
		Autobay
		Singapore 417883

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Oct 2018)  
 Parts: M1-MPV HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for SJK8705X)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	665.40 F	*665.40 FL
2	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	35.50 F	*- FL
3	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*30.00 FL
4	1		*TAILLAMP O/S	Broken	408.50 F	*338.30 FL
Sub Total (S\$)					1,159.40	1,033.70
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	206.74
Total Parts (S\$)					1,159.40	826.96

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	New	120.00	-
4	TO SPRAY RUSF PROOFING	New	50.00	-
5	LABOUR FOR PANEL BETAING,CUT & REPLACING PARTS	New	500.00	200.00
6	TO PUTTY & SPRAY PAINTING	New	580.00	400.00
Gross Labour Cost (S\$)			1,380.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >