

ASS. REC. BY:

REF:

CS/CTI18017948/Gcd3

Special Instruction:

Surveyor:

Meimien

ASSIGNMENT (Office)

From (Person):

Irene fuy

of

CTI

Date/Time: 3/10/18 @ 4:52pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLT 5744G

Insured:

GBH 2026Y

at Workshop m/s

TTS Eurocars

Tel:

6757 2622

of

383 Sin Ming Drive

Policy No:

DMCVSN1808171800

Claim No:

SNM18D04728C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 1/10/18

5/10/18 After 1:30pm

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

5:12pm @ 3/10/18

Person Contacted:

Mr. Ng

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLT 5744G - X

GBH 2026Y - X

kavi@FTS.com.sg

3/12 @ 4:41pm - sent estimate to TTS Eurocars to Kavi.

Yah.

REF: CTL

FIN 9758T

ASSIGNMENT

From: Date: 05.10.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLT 57446
at Workshop m/s: TTS Eurocars
of: 383 Sin ming Dr

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

after 1pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLT5744 G Yr Regn: 01 Nov 2017

Type: M / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Merd E220D C.C. 1950

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 6470 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 238 3142 F00 9533

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / STD A/Rim or 245/E.R.

Tyre Size: F: R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 05-10-18

Survey held at w/s 4pm

Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/4 Finalized \$ 4483.45 with shabir.
(Red. 10,003.65, 69%)

RECEIVED 10 APR 2019

Date/Time. File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

\$ + RE. SI

Photos

Others

TOTAL

Date/Time. File Return to?

1)

Report Format: TP

Lump Sum / I.E: \$ 4,483.45

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2018		03 Oct 2018 16:52 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ALY ENERGY SINGAPORE PTE LTD, Co. Reg. No.: 200810919G		
Main Claimant:	ZAMANI GARAKANI HADI		
Vehicle Reg. No.:	SLT5744G	Date of Loss:	01/10/2018 10:00 - :59
Claim Type:	TP / SNM18D04728C02	Policy/Cover Note No.:	DMCVSN1808171800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH2026Y	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	TTS Eurocars Pte Ltd (Sin Ming) 383 Sin Ming Drive, TTS Centre, 575717 Sin Ming - Tel: 6757 2622 / 6842 2222		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/10/2018]		
Adj Asg. Remarks:	EST \$14,217.20, ASSIGN XING QUO QIANG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	9758T
Vehicle Details	
Vehicle No.:	SLT5744G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E220D AMG AUTO
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	65492080119575
Chassis No.:	WDD2383142F009533
Maximum Power Output:	143.0 kW (191 bhp)
Open Market Value:	\$58,944.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$68,100.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2027
PARF Rebate Amount:	\$51,075.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$49,000.00
COE Rebate Amount:	\$43,569.00
Total Rebate Amount:	\$94,644.00

The information contained herein is correct as at 10 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2018 15:53
Date Of Accident	01/10/2018 10:00
Exact Location Of Accident	PECK SEAH STREET OFF-STREET CAR PARK (P0117)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT5744G
Insured/Policyholder	
Name Of Registered Owner	ZAMANI GARAKANI HADI
Passport No/FIN	F1749758T
Email Address	HADIZAMANI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97235488
Alternative Phone No	OFFICE-97235488

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E220D AMG AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP306450
Cover Note Number	

Driver

Name of Driver	ZAMANI GARAKANI HADI
Passport No/FIN	F1749758T
Date Of Birth	29/08/1985
Occupation	INDOOR
Date Of Driving Pass	08/09/2011
Driving Experience	7 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97235488
Fax Number	
Contact Number	OFFICE-97235488
Email Address	HADIZAMANI@GMAIL.COM

Address	4 ARDMORE PARK ROAD #03-01
Postcode	259960
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

refer to police report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH2026Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan Pg. 2

Describe Circumstances of the Accident

refer to police report


Declaration

I/We declare the foregoing particulars are true in every respect.

X 

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

GO FOR GREEN

SENEBOGEN

Xu YunHong

G7115957X

HP: 8783 8199

8716 8558

Hello box:

I am sorry. My Lorry
Collision. you car.

My company:

ALY ENERGY

Lorry No: GBH2026Y.

SENEBOGEN
Mechanical & Electrical

Singapore Branch: 20
8075 Shenglin, Singapore

TEL: +65 6421 2200
FAX: +65 6421 2202

EMAIL: info@senegen.com.sg
WWW: www.senegen.com.sg



CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form X1

CERTIFICATE NUMBER : MP306450

Type of Coverage : Comprehensive Own Damage Excess : SGD600.00

Sum Insured : Market Value Windscreen Excess : SGD100.00

- | | |
|--|-----------------------|
| 1. Index Mark and Registration Number of Vehicle | SLT5744G |
| Chassis Number of Vehicle | WDD2383142F009533 |
| 2. Name of Policyholder | ZAMANI, GARAKANI HADI |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 01 Nov 2017 |
| 4. Date of Expiry of Insurance | 31 Oct 2018 |
| 5. Persons or Classes of Persons entitled to drive* | |
| 01. ZAMANI, GARAKANI HADI | 02. N/A |
| 03. N/A | 04. N/A |
| 05. N/A | 06. N/A |

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business or profession. The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Please note that the Own Damage Excess will be halved if claims related repairs are done at HL Assurance Approved Workshops listed in the attached.

This Certificate is not transferable to a new owner of the Motor Vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to HL Assurance Pte. Ltd. Within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

Hire Purchase Company : N/A

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

HL ASSURANCE PTE. LTD.

Authorized Signature

Issue on: 01 Nov 2017

Driving License Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **F1749758T**

Name: **ZAMANI GARAKANI HADI**

Birth Date: 29 Aug 1985

Issue Date: 30 Oct 2017

Valid Till: 29/10/2022

002738512E



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

	EFFECTIVE DATE
Class 3 Motor cars with unladen weight \leq 3000kg with \leq 7 passengers, exclusive of driver; and other motor vehicles with unladen weight \leq 2500kg	08 Sep 2011

NP 428A



PERSONALISED EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer
THIS PERSON IS A PERSONALISED EMPLOYMENT PASS HOLDER



Name
ZAMANI GARAKANI HADI

Occupation
-

FIN
F1749758T

Date of Application
10-09-2016

Date of Issue
30-11-2016

Date of Expiry
30-11-2019





L7454600

VISIT PASS
Immigration Regulations

Name
ZAMANI GARAKANI HADI



Date of Birth Sex Nationality
29-08-1985 **M** **IRANIAN**

FIN Date of Issue Date of Expiry
F1749758T **30-11-2016** **30-11-2019**

MULTIPLE JOURNEY VISA ISSUED

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



Police report Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181001/7002

1 of 3

Report No. T/20181001/7002

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/10/2018 12:43		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: ZAMANI GARAKANI HADI			Address: APT BLK 4 ARDMORE PARK #03-01 HERITAGE APARTMENTS SINGAPORE 259960		
ID Type / ID No.: FIN NO / F1749758T			Contact No.: Home/Office: Mobile: 97235488		
Nationality: IRANIAN			Email: hadizamani@gmail.com		
Sex: Male	Age: 33	Date of Birth: 29/08/1985	Type of Informant: Vehicle Owner		
Race: Persian			Language: English		Institution / School Name:
Occupation: Trade broker (including oil and bunker trader)			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/10/2018 10:30	Type of Location: Car Park
Location: PECK SEAH STREET				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBH2026Y	Lorry				No Damage	0
SLT5744G	Car	MERCEDES BENZ	E220D	White	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------

Police report Pg. 2



**SINGAPORE
POLICE FORCE**



T/20181001/7002

2 of 3

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No.: T/20181001/7002

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLT5744G	HL ASSURANCE PTE. LTD	MP306450	31/10/2017	31/10/2018

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Xu Yun Hong		ID No.	G7115957X
Related Vehicle	GBH2026Y (Lorry)		Contact No.	87838199
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Vehicle Owner				
Name	ZAMANI GARAKANI HADI		ID No.	F1749758T
Related Vehicle	NIL		Contact No.	97235488
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	Slight

Brief Details.

My car was parked in the public open space carpark between Peck Seah street and Wallich Street. I parked my car at the lot around 9:30 am and returned to my car at around 10:55 am. I saw that someone had hit my front left side of car, breaking my headlights and damaging my bumper and hood. There was a note left on my windshield saying that the a Lorry from ALY ENERGY has hit my car. The driver had provided me with his car-plate and phone number.

I contacted the driver's company and they have agreed to cover my damages visa their car insurance.



SINGAPORE
POLICE FORCE



T/20181001/7002

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3
Report No. T/20181001/7002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
SITIMARSITA BINTE BOHARI
Contact No.: 65476219


Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
01/10/2018 12:43

Classification Of Case:

149	CC3/AIG18013680/K1EB3Q2	E220	2.0 (A)	TP	7970285506SG	SHD6675Y	19/07/18
150	CC3/AIG18002890/K1MB3Q2	E220	2.0 (A)	TP	9646612815SG	SHA7449T	08/02/18
151	CC4/AXA18015082/R1PB3Q2	E220	2.0 (A)	TP	C0474230	SH7593S	14/08/18
152	CS/CTI18006663/KTD3N2	E220	2.0 (A)	TP	SNM18D01830C02	SLP6650H	24/03/18
153	CC4/AIG18009627/APB3Q2	E220	2.1 CDI (A)	TP	1618263729SG	SGH56P	18/05/18
154	CS/TMI18021676/K1SBN2	E220	2.1 CDI (A)	TP	M1806117	SHD6755A	29/11/18
155	CC3/TMI18022613/K1VBS2	E220	2.1 D CDI (W211) (A)	TP	M1806440	SHC8208E	15/12/18
156	CC4/FWD18016999/K1EA3Q2	E220	2.1 D CDI BLUEEFFICIENCY (A)	TP	1201800011691	SHD8838G	16/09/18
157	CS/MSG18001672/K1QD3N2	E220	2.1 D CDI BLUEEFFICIENCY (A)	TP	547701	SHB6383A	26/01/18
158	CC4/AXA18009162/K1PA3Q2	E220	2.1 D CDI BLUEEFFICIENCY (A)	TP	C0473741	SHC3103G	17/05/18
159	CC3/TMI18005233/R1TBE2	E220	2.1 D CDI BLUEEFFICIENCY (A)	TP	M1801452	SHB6350U	17/03/18
160	CS/CTI18021619/DTD3N2	E220	2.1 D CDI BLUEEFFICIENCY (A)	TP	SNM18D05527C02	SHC890L	23/11/18
161	CC4/FWD18006030/K1EA3Q2	E220 BLUETEC	2.1 D (A)	TP	1201800004041	X SHD6772A	01/04/18
162	CC3/AIG18005868/K1JA3Q2	E220 BLUETEC	2.1 D (A)	TP	2303106898SG	X SHC8211U	25/03/18
163	CC3/LCR18001252/K1PA3Q2	E220 BLUETEC	2.1 D (A)	TP	2360491750SG	X SHD6625S	19/01/18
164	CC3/AIG18005863/K1JA3Q2	E220 BLUETEC	2.1 D (A)	TP	4637596164SG	✓ SHC8081C	27/03/18
165	CC3/LCR18002446/M1JA3Q2	E220 BLUETEC	2.1 D (A)	TP	6960442144SG	X SHC8041T	05/02/18
166	CC3/AIG18004628/K1UA3Q2	E220 BLUETEC	2.1 D (A)	TP	7828229736SG	X SHC8220T	07/03/18
167	CC3/AIG18009733/K1AA3Q2	E220 BLUETEC	2.1 D (A)	TP	8159079239SG	X SHC8044K	25/05/18
168	CC4/AXA18003092/K1JB3Q2	E220 BLUETEC	2.1 D (A)	TP	C0470553	X SHA7681M	12/02/18
169	CC4/AXA18014231/K1PA3Q2	E220 BLUETEC	2.1 D (A)	TP	C0474173	✓ SHD6653K	31/07/18
170	CS/TMI18000833/K1QBN2	E220 BLUETEC	2.1 D (A)	TP	M1800253	✓ SHC8223K	11/01/18
171	CS/MSG18000921/KQBE2	E220D SE	2.0 (A)	TP	545768	SLU3636T	12/01/18
172	CC6/AIG18000936/AEA3Q2	E230	2.5 (A)	TP	4145226057SG	SLK943D	13/01/18
173	CS3/MSG18018282/NTBE2-1	E230	2.5 (A)	TP	MSC/V/18-001348	SJB2130R	06/10/18
174	CC4/FWD18005082/M1EB3Q2	E250	1.8 (A)	TP	1201800003342	SKP6869G	15/03/18
175	CC4/FWD18019625/T1EB3Q2	E250	1.8 (A)	TP	1201800013922	SKG5275Z	26/10/18
176	CS3/MSG18020859/BCD3S2	E250	1.8 (A)	TP	575981	E4008B	13/11/18
177	CC4/LCR18001060/AWB3S2	E250	1.8 (A)	TP	9228122769SG	SKK9077G	13/01/18
178	CS/EQI18007364/KVBE2	E250	1.8 (A)	OD	DM18HO00927	SDQ8178G	07/04/18
179	CC6/III18001703/UYS3Q2	E250	1.8 (A)	TP	MCT18010850	SKH1760K	28/01/18
180	CC4/III18009250/R1PA3Q2	E250	1.8 (A)	TP	MCT18050439	SKC3374E	17/05/18
181	CS/CTI18002298/GRD3E2	E250	1.8 (A)	OD	SNM18D00412C01	SKD9284L	21/01/18
182	CS/CTI18012047/T1RD3N2	E250	1.8 (A)	TP	SNM18D03255C02	SKA6714Z	28/06/18



17495

Contact :

[Handwritten signature]

Authorised Signature



To	China Taiping Insurance	DATE	2/10/2018
Attn	Motor Claims Officer		
CC	1950	VEH NO	SLT5744G
YEAR	2017	C/NO NO	WDD2383142F009533
MODEL	MERCEDES BENZ E220D AMG AUTO	PAGE	1 OF 1

S/NO	PARTS		QTY	PRICE
1	Front Bumper / OE		1	\$ 1890.5 2,831.00
2	Front Bumper Retainer (LH) X {new}		1	\$ 88.00
3	Front Bumper Retainer (RH) X		1	\$ 88.00
4	Front Bonnet X Repair		1	\$ 3,353.00
5	Front Headlamp Unit (LH) / OEA		1	\$ 2380 4,858.00
6				4270.5
7				10% : 3843.
8				
9				
		SUB-TOTAL	\$	11,218.00
		DISCOUNT 5%	\$	560.90
		SUB-TOTAL	\$	10,657.10

2 Days.
put by put.
before parent photos.
Gus Qup
05/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____



TTS EUROCARS pte ltd
A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre, S'pore 575717
Tel : 67572622 Fax : 67411626

QUOTATION

VEH NO SLT5744G

PAGE 2 OF 2

<u>LABOUR</u>			
1	TO CUT, WELD, REPLACED ACCIDENT DAMAGE PARTS, ALIGNMENT AND CHECK ALSO TO KNOCKOUT & STRAIGHTEN - ACCIDENT DENTED PORTION SO AS TO REMOVE & REPLACE ACCIDENT AND REPLACED DAMAGED PARTS.	1	\$ 1,560.00
2	TO PUTTY, SAND DOWN & SPRAY PAINT ACCIDENT AFFECTED PORTION FACILITATE FOR THE REPAIR	1	\$ 700.00
3	TO REMOVE AND REFIT PARKING SENSOR ASSY.	1	\$ 250.00
4	TO CHECK WIRING AND LIGHTING OPERATION.	1	\$ 120.00
LABOUR-TOTAL			\$ 2,630.00
GRAND TOTAL			\$ 13,287.10
GST 7%			\$ 930.10
GRAND TOTAL			\$ 14,217.20

REMARK THIS QUOTE IS ONLY AN ESTIMATE FOR REPAIR, SHOULD ANY ADDITIONAL PARTS OR
LABOUR INCURRED, WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.

220

250

40

30

40

14,487.10

Total: 4483.45

Attn: kavi



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre. S'pore 575717

Tel: 67572622 Fax: 67411626

OWN DAMAGE CLAIM

SUPPLEMENTARY

TO	CHINA TAIPING INSURANCE	DATE	10.12.2018
ATTN	CLAIMS OFFICER, MOTOR CLAIMS DEPT	PAGE	1
MODEL	MERCEDES BENZ E220D AMG AUTO	VEH NO	SLT5744G
YEAR	2017	C/N0	
E/NO.		D.O.A	01.10.2018

OWN DAMAGE CLAIM

S/NO		Qty	Price
	<u>PARTS /LABOUR</u>		
1	ECU PROGRAMMING	1	S 600.00
2	LABOUR CHARGE FOR BLANCING AND REALIGNMENET OF TYRE	1	S 600.00
		SUB-TOTAL :	S 1,200.00
	Gmo Riap - 8288 0282		
	Lpk		
		SUB-TOTAL	#VALUE!
2			
3			
4		1	
	SUB-TOTAL		
	LESS EXCESS		
	SUB-TOTAL		#VALUE!
	GST 7%		#VALUE!
	TOTAL		#VALUE!

100
X NV

Gmo Riap - 8288 0282
Lpk
10/12/18

REMAR THIS QUOTE IS ONLY AN ESTIMATE FOR REPAIR, SHOULD ANY ADDITIONAL PARTS OR LABOUR INCURRED WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118017948/GCD3N2

Date: 11/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1808171800
Claimant Vehicle No :	SLT5744G	Insured Vehicle No :	GBH2026Y
Date of Loss:	01/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04728C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT5744G	Engine No:	65492080119575
Make & Model:	MERCEDES-BENZ E220D SE, 2.0 (A)	Chassis No:	WDD2383142F009533
Reg. Date:	01/11/2017 (Man. Year: 2017)	Odometer:	6470 km
Colour:	White		
Engine Capacity:	1950 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R19	Rear Tyre Size:	245/40R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,657.10	3,843.45	6,813.65	63.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,830.00	640.00	3,190.00	83.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,487.10	4,483.45	10,003.65	69.05
+ GST 7.00/7.00% (S\$)	1,014.10	313.84	700.26	69.05
Nett Amount (S\$)	15,501.20	4,797.29	10,703.91	69.05

INSPECTION

Date of Assignment:	03/10/2018	
Date Inspected:	05/10/2018	Inspected At:
		TTS Eurocars Pte Ltd (Sin Ming)
		383 Sin Ming Drive, TTS Centre
		Singapore 575717
Estimated Period of Repair:	3.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Apr 2019)
Parts: 143	MERCEDES-BENZ E220D SE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLT5744G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,831.00 FL	*1,890.50 FL
2	1		*FRONT BUMPER RETAINER (LH)	Not Necessary	88.00 FL	*- FL
3	1		*FRONT BUMPER RETAINER (RH)	Not Necessary	88.00 FL	*- FL
4	1		*FRONT BONNET	Repair	3,353.00 FL	*- FL
5	1		*FRONT HEADLAMP UNIT (LH)	Cracked	4,858.00 FL	*2,380.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)					11,218.00	4,270.50
- List Item Discount on L Items 5.00/10.00% (\$\$)					560.90	427.05
Total Parts (\$\$)					10,657.10	3,843.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CUT,WELD,REPLACED ACCIDENT DAMAGE PARTS,ALIGNMENT AND CHECK ALSO TO KNOCKOUT & STRAIGHTEN-ACCIDENT DENTED PORTION SO AS TO REMOVE & REPLACE ACCIDENT AND REPLACED DAMAGED PARTS	New	1,560.00	220.00
2	TO PUTTY,SAND DOWN & SPRAY PAINT ACCIDENT AFFECTED PORTION FACILITATE FOR THE REPAIR	New	700.00	250.00
3	TO REMOVE AND REFIT PARKING SENSOR ASSY	New	250.00	40.00
4	TO CHECK WIRING AND LIGHTING OPERATION	New	120.00	30.00
5	ECU PROGRAMMING	New	600.00	100.00
6	LABOUR CHARGE FOR BALANCING AND REALIGNMENT OF TYRE	New	600.00	0.00
Gross Labour Cost (\$\$)			3,830.00	640.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >