

22/03/2001

ASS. REC. BY:

REF: CS3/CI180/7949/R1cd3/2

Special instruction:

Surveyor:
Mennen

Rasul

ASSIGNMENT (Office)

From (Person):

Irene fay

of

CT1

Date/Time:

3/10/18 @ 4.17pm

~~Estimated Cost:~~

Bill to:

$$OD(\overline{TP})WS/TP\text{ RES} / OD\text{ RES} / EVA / INV / MV \nabla CS$$

To Inspect Vehicle No:

FU 4143M

Insured:

814 3366x

at Workshop m/s

Chek Kong Motor

Tel:

6769 7367

of

Blk 1, 387B Woodlands Rd Yew Tee Ind. Est

Policy No:

DMCVSN 1801881800

Claim No:

SNM18b 04691C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/04/2018

4/10/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time

5.18pm 3/10/18

Person Contacted:

chen

Vehicle ~~IN~~ OUT

Date/Time

Action/Instruction	(X) Estimate

FU 4143 M-X


8143366x-x.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FU 4143M
 at Workshop m/s CHEK KONG MOTOR
 of BLK I, 387 B WOODLANDS RD
 Insured: CTI
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: FU 4143M Yr Regn: 2002 / Jan
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: YAMAHA RX2 C.C. 133
 Colour: MULTI A/C: Insured / Std / NI / NA
 Sp.Reading: 37481 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZMC 263279
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 70/80-18
 R: ---
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FKR
 Front Rear
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 28/09/18 D.O.I. 09/10/18
 Survey held at CHEK KONG
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range: <u>2800/2 - 3500/2</u>
	Repair days <u>4</u>
	RECEIVED 09 OCT 2018
	<u>9/10/2018</u>
	TGrim
	<u>9/10/18</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: -

Survey Fee:

Transportation: _____ S + RS. _____ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Report Format : PRE

Lump Sum / I.B.I. (\$) _____

190
190

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2018		03 Oct 2018 16:17 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SOH YONG KEE, ID: S7324656C		
Main Claimant:	RYAN NASRULLAH BIN RUSLI, ID: T0005852H		
Vehicle Reg. No.:	FU4143M	Date of Loss:	28/09/2018 17:00 - :59
Claim Type:	TP / SNM18D04691C02	Policy/Cover Note No.:	DMCVSN1801881800 (Comprehensive)
Vehicle Reg. No. (Insured):	SJU3366X	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Chek Kong Motor Pte Ltd (HQ) BLK 1 387B WOODLANDS ROAD, YEW TEE INDUSTIRL ESTATE, 677948 Woodlands - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**GOH JP & WONG LLC****advocates & solicitors
commissioner for oaths**

GOH TECK WEE

WONG LEE BOY

WONG FUNG KWAI

SOON WEI SONG

133 New Bridge Road #16-09 Chinatown Point Singapore 059413
Tel: 6538 5868 Fax: 6538 4898 (Not for service of Court documents) Email: mail@gohjpwong.com
Goh JP & Wong LLC is a law corporation with limited liability. GST/UEN: 201406078M

YOUR REF:

OUR REF:

GTW.ACC.10T160.18.wk

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE NO

DATE:

3rd October 2018

Soh Yong Kee
Block 159 Tampines Street 12
#10-83 Singapore 521159

Dear Sirs

NOTIFICATION OF ACCIDENT**SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FU 4143M & SJU 3366X ON 28.9.2018 ALONG PIE**

We act for Ryan Nasrullah Bin Rusli in the above matter.

We are instructed to notify you of the above accident on 28th September 2018 at about 17.40 hrs along PIE involving our client's motorcycle FU 4143M and motorcar SJU 3366X driven by you at the material time. A copy of the traffic police report filed is enclosed.

As a result of the accident, our client's motorcycle FU 4143M has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair inspection of the vehicle or whether you or your insurer waive the pre-repair inspection. If we do not receive any reply from you within the stipulated timeline our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Goh Teck Wee

Enc.

Cc **China Taiping Insurance (Singapore) Pte Ltd**
Fax No. 6224 7175
Attention: Motor Claims Department

Cc **Chek Kong Motor Pte Ltd**
Fax No. 6769 7367
Please do not proceed with repairs until further notice.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9108D
Vehicle Details	
Vehicle No.:	FU4143M
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Oct 2018
Vehicle Make:	YAMAHA
Vehicle Model:	RXZ
Primary Colour:	Red
Manufacturing Year:	2001
Engine No.:	3BS263279
Chassis No.:	ZMC263279
Maximum Power Output:	-
Open Market Value:	\$2,735.00
Original Registration Date:	17 Jan 2002
First Registration Date:	17 Jan 2002
Transfer Count:	6
Actual ARF Paid:	\$411.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2022
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$1,909.00
COE Rebate Amount:	\$675.00
Total Rebate Amount:	\$675.00
Message	
Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.	
This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.	
This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.	
For more information, please visit http://www.nea.gov.sg/mtc incentive or contact NEA at 1800-2255-632.	

The information contained herein is correct as at 08 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/10/2018 14:01
Date Of Accident	28/09/2018 17:40
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FU4143M
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	RUSLI BIN SHAHDAN
NRIC No	S1729108D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-87481593
Alternative Phone No	OFFICE-87481593

Vehicle Particulars

Manufacturer	YAMAHA
Model	RXZ

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5093993273
Cover Note Number	

Driver

Name of Driver	RYAN NASRULLAH BIN RUSLI
NRIC No	T0005852H
Date Of Birth	18/02/2000
Occupation	INDOOR
Date Of Driving Pass	18/09/2018
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87481593
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 504 JELAPANG RD #04-356

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured CHILDREN

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by ambulance? YES

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : ---

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] BT PANJANG NPC

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER ATTACHED ACCIDENT REPORT FROM THE DRIVER. POLICE REPORT NO. T/20180929/2068

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJU3366X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	RIDER
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FU4143M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

DETAILS OF INJURED PERSON 2

Name	PILLION
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FU4143M
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

1/10/2018



Driver's Signature
(If driver is not the policyholder)
Date & Time:

01/10/18

 (NAC) RUKIT BATOK (NAC)

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

& Time: 1/15/2018

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

11/10/2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20180929/2068

1 of 3

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

Report No. T/20180929/2068

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/09/2018 13:54	Vide Report No.:	Station Diary No.: 93
--	------------------	--------------------------

Informant's Particulars

Name of Informant: RYAN NASRULLAH BIN RUSLI			Address: APT BLK 504 JELAPANG ROAD #04-356 SINGAPORE 670504		
ID Type / ID No.: NRIC NO / T0005852H			Contact No.: Home/Office: Mobile: 87481593		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 18	Date of Birth: 18/02/2000	Type of Informant: Rider		
Race: Malay			Language:		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

General Information				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 28/09/2018 17:40	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY Along PIE towards Changi, Flyover after Thompson road				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FU4143M	Motorcycle				Seriously Damaged	1
SJU3366X	Car				Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE POLICE FORCE



T/20180929/2068

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

2 of 3

Report No. T/20180929/2068

CONTINUATION OF REPORT

Pillion			
Name	MOHAMMAD NUR KAMARUL BIN ROSLAN	ID No.	T0002329E
Related Vehicle	FU4143M (Motorcycle)	Contact No.	94523701
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	28/09/2018	Date Discharge	28/09/2018
No. of Days granted Medical Leave	03	Degree of Injury	NIL
Rider			
Name	RYAN NASRULLAH BIN RUSLI	ID No.	T0005852H
Related Vehicle	FU4143M (Motorcycle)	Contact No.	87481593
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	28/09/2018	Date Discharge	28/09/2018
No. of Days granted Medical Leave	03	Degree of Injury	Slight
Driver			
Name	SOH YONG KEE	ID No.	S7324656C
Related Vehicle	SJU3366X (Car)	Contact No.	83384282
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 28th September 2018 at about 1741hrs, I was riding my bike (FU4143M) along PIE towards Changi, just after Thompson flyover. I was riding along lane 2. All of a sudden, there were a few vehicles slowing down to which I did so too. Suddenly, a vehicle (SJU3366X) from behind had collided onto me and my pillion, causing us to fall down from the bike. We then got up and exchange particulars. Police and Ambulance attended to our scene. My Pillion and I were both injured and given 3 days MC from TTSH. There is no CCTV available.



**SINGAPORE
POLICE FORCE**



T/20180929/2068

3 of 3

Report No. T/20180929/2068

Police Station Of Origin:
Bukit Panjang N.P.C
1 Segar Road #01-05 SINGAPORE 677738
Tel No: 1800-8929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 AUSTIN TAN RI QUAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt YAN MINGSHENG DANIEL

SN 117

Contact No. 65476252

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

29/09/2018 13:54

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Oct 2018		03 Oct 2018 16:17 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SOH YONG KEE , ID: S7324656C									
Main Claimant: RYAN NASRULLAH BIN RUSLI , ID: T0005852H									
Vehicle Reg. No.: FU4143M		Date of Loss: 28/09/2018 17:00 - :59 [200 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D04691C02		Policy/Cover Note No.: DMCVSN1801881800 (Comprehensive)							
Vehicle Reg. No. (Insured): SJU3366X		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Chek Kong Motor Pte Ltd (HQ) BLK 1 387B WOODLANDS ROAD, YEW TEE INDUSTIRL ESTATE, 677948 Woodlands - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/10/2018]									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									











Claim Documents




*FU4143M (SNM18D04691C02)
[SJU3366X]
TP
RYAN NASRULLAH BIN RUSLI
Sep 28 2018 5:00PM
[SOH YONG KEE]
Chek Kong Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	01/10/18 17:46	Accident Statement	Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	01/10/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
2	01/10/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
3	01/10/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
4	01/10/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
5	01/10/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
6	01/10/18 17:25	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
7	01/10/18 17:40	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
8	01/10/18 17:40	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
9	01/10/18 17:40	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
10	01/10/18 17:40	Accident Photo [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	08/10/18 11:16	General View	Load PDF		
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print	
1	03/10/18 16:17	PRS	Load PDF		
2	03/10/18 16:17	OI GIA	Load PDF		
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	01/10/18 17:26	Sketch Plan [Linked Accident Report Documents]	Load TIF		
2	01/10/18 17:27	CI,IC,DL [Linked Accident Report Documents]	Load TIF		
3	01/10/18 17:27	POLICE REPORT [Linked Accident Report Documents]	Load TIF		

Linked Accident Report Documents

			View View in Browser		
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	
1	01/10/18 17:46	Accident Statement	Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	01/10/18 17:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	01/10/18 17:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	01/10/18 17:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	01/10/18 17:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	01/10/18 17:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	01/10/18 17:25	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	01/10/18 17:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	01/10/18 17:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	01/10/18 17:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	01/10/18 17:40	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer)	Thumbnail	Print
1	01/10/18 17:26	Sketch Plan	 Load TIF	
2	01/10/18 17:27	CI,IC,DL	 Load TIF	
3	01/10/18 17:27	POLICE REPORT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18017949/R1CD3E2

Date: 11/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1801881800

Claimant Vehicle
No : FU4143MInsured Vehicle
No : SJU3366X

Date of Loss: 28/09/2018

Nature of Claim: TP

Claim
No: SNM18D04691C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FU4143M**

Make & Model: YAMAHA RXZ, 133cc (M)

Reg. Date: 17/01/2002 (Man. Year: 2001)

Colour: Multi-colour

Engine Capacity: 133 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 3BS263279

Chassis No: ZMC263279

Odometer: 37487 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/80-18	Rear Tyre Size:	70/80-18
Front Left Side:	FKR 3 mm	Rear Left Side:	FKR 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/10/2018

Date Inspected: 04/10/2018 Inspected At:

Chek Kong Motor Pte Ltd (HQ)
BLK 1 387B WOODLANDS ROAD, YEW
TEE INDUSTIRL ESTATE
Singapore 677948

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 - \$3,500.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 10 Oct 2018)

Parts: N/A YAMAHA RXZ 133cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FU4143M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >