· Surveyor :	0.0		SSIGNN	IENT (Office)			
From (Perso		1 Kill of		Crawfird	Da	te/Time: 03 102	.018 9599m
Estimated (				Bill to:			ower and reason and three-sa
	/STTP RES / OD /ehicle No:		NV/MV/ SKZ 3f		Insured:	Unknown	Vehidle
at Worksho	m/s	Eurosports			Tel:		19799 9596
of		14 Leng Ke	ue Rd	#01-03		(9799 9593)	
Policy No:		J		Claim No:			(
Sum Insure	1			Excess:			
Make of Ve (Client's Rec				Litotio,	D.	O.A	
CA / REV	/ REP. / REV	24 HRS 16/Pi		19.10.2018 0	llam ou	une Wuiting H.O.D. Endorsemsal:	
Who are week	MINTOLS UTE	oun Person	Contacted:	mr. Lee	Vehi	cle_IN (OUT)	
Date/Time:							
Date/Time:	· -	ion ( /)	L. C. Land	SW.			
Date/Time:	Action/Instruct		Estimat	le on tel	A0 (I)	20.0	
Date/Time Date/Time	Action/Instruct	. Le cousea	, he as	k call buck	on 08-10	3100	
Date/Time Date/Time 04\0.008\(0.008\)	Action/Instruct	. Le cuista	huas In Lee	k call buck	) NO	TO GIA RU	port,
Date/Time Date/Time	Action/Instruct	. Le cuista	huas In Lee	k Call back Crepour PA to 1	) NO	TO GIA RU	port via enai/
Date/Time Date/Time 04\0.008\(0.008\)	Action/Instruct 11)5um - Mr Confined @ 15:00	with m	huas In Lee evised	k call buck	Mr. Soh	(report)	via enail

Correction Rapid

4 4 4	3.2.5	1767	NI	200	V 10 10	
23000	3 6 4 4	1. 16.	1 V B.	32.1	N 1	
2.000		-	47.75	24	11.00	

From	Date 19/10/2018	Veh No.	SKZ 3A	Vr Regn: 20	16 Juney
Estimated Cost.		Type: (1.Car	/ M.Cycle / Bus / Van /	Lorry / Taxi / Prime N	Nover!
OD (TP) WS / T	P RES / OD RES / EVA / INV / MV	Truck	/ Trailer or		
To Inspect Vehic	le No: 3 KZ 3 A	. Make:	Lam Borchi	NI HURACON CO	Szof
at Workshop m/s	Eurosports	Colour	branks	A/C: Insured	d/Std/NI/NA
of	24 Leng Kee Rd # 0803	Sp.Reading	016000	T/Radio: Insure	d/Std/NI/NA
Insured.		Eng/No:			
Policy No.		C/No:	24 WEC12F	The state of the s	.7
Claims No.		Gen. Cond: 0	Good Fail   Poor   Bur	mt	
Sum Insured:	Excess:	Steering: (no	rder / Jammed / Leake	d/Burnt or	
(Client's Recon	llam@owner waiting		rder / Jammed / Leake		
Wilder St. Comp.		Tyre Size:		1302220	
(Policy Condition	000)	Tyre oize.	R: 7	190 21000	
	h had commenced its N/S O/S	BS / DUN / F	XNOVA / GY / FS / LIZ	A / MIC / OHTSU / M	EX SUMI.
repair	at the time of inspection.	TOYO/YO		A) IIII 0   0   1   0   0	produin.
Bal, or Market Va	alue 798K	Front		Rear	321
IDAC Accident R		R/Bal.	<b>6.</b> mm	R/Bal.	6 mm
GIA / PR Seen	Consistent? ; Yes or No	L/Bal.	6 mm	L/Bal.	G mm
Est. Repairs:	days Res.: Yes or No	D.O.A.		D.O.I. (5)	lolly
Lum Sum;	% 3 Val.: Yes or No	Survey held	et Ewlos		/
CA / REV /	REP. / 24 HRS 1402	Des. of Dam	ages: Frt / Rear / O/S	SINISIUICIROC SAU	oftop or
Date:	Vehicle: IN / OUT Person Contacted:	The U/C	/ Chassis frame / Bo		d due to collision
Date / Time	Action / Instruction		-	by disaster and and	a data ta samatan
	RECEIVED 17 J	AN 2019			
	-	ă.			
					20 > 15=30
Date/Time, File Pass	101. Tolk Report	Days Of Rep	pair: 4	/	170+300-47
17/01/1	+ : Final Report	Resurvey N	o. of Trip:	Survey Fee	420
Date/Time, File Retu				Transportation:	50
2)	Add Fee	Townson of the Party of the Par		)S+RS,St	
		Parameter State St	/lew (\$	) Photos	21
Report Forma	710011	Property and Prope	Invs (\$	) Others	80
Lump Sum / I	.B.f. (5	L] Wee	rend (\$	)	
				TOTAL	621

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Venicle Owner Particulars	Company
Owner ID Type:	Company
Owner ID:	2526E
Vehicle Details	SKZ3A
Vehicle No.:	
Vehicle to be Exported:	No
ntended Deregistration Date:	01 Nov 2018
Vehicle Make:	LAMBORGHINI
Vehicle Model:	HURACAN LP610-4
Primary Colour:	Orange
Manufacturing Year:	2015
Engine No.:	CSJ005199
Chassis No.:	ZHWEC1ZF2GLA04127
Maximum Power Output:	449.0 kW (602 bhp)
Open Market Value:	\$246,900.00
Original Registration Date:	16 Jul 2016
First Registration Date:	16 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$416,420.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jul 2026
PARF Rebate Amount:	\$312,315.00
Interided COE Rebate Details	dans the second
COE Expiry Date:	15 Jul 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$43,922.00
Total Rebate Amount:	\$356,237.00

The information contained herein is correct as at 01 Nov 2018

OK

### Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Wednesday, 14 November 2018 4:12 PM

To: soonkiat.soh@crawford.com.sg

Cc: Admin-D (LKKAuto); assignments; SUR

Subject: RE: Motor surveyor

Dear Mr Soh.

Refer to our conversation earlier, we have checked with the repairer, the vehicle still under repair and awaiting spare parts arrival by air flight.

The repair cost is not concluded yet. Expected time of arrival is about 1 months.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: soonkiat.soh@crawford.com.sg [mailto:soonkiat.soh@crawford.com.sg]

Sent: Tuesday, 13 November 2018 10:22 AM

To: ShirleyHiew@lkkauto.com

Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; assignments <assignments@lkkauto.com>; SUR

<sur@lkkauto.com>

Subject: RE: Motor surveyor

Hi Shirley

Is the repair concluded?

Any issue pertaining to the repair and look forward to your conclude report.

Kindly contact me should you have any queries.

Soh Soon Kiat • LLB MBA Dip. SCI (General) • Manager • Singapore

Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXXA Tower, 068811, Singapore

Direct: +65 6632 8638 • Mobile: +65 9634 0429 • Office: +65 6632 8600 • Fax: +65 6632 8040 • Email: soonkiat.soh@crawford.com.sg • Web Site: www.crawfordandcompany.com



## Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Tuesday, 23 October 2018 3:00 PM

To:

soonkiat.soh@crawford.com.sg

Cc:

assignments; SUR; Admin-D (LKKAuto)

Subject:

RE: Motor surveyor

Attachments:

SKZ 3A - Preli Advise.pdf

Dear Mr. Soh.

As spoken, enclosed preliminary revised of vehicle SKZ 3A.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Tuesday, 23 October 2018 9:37 AM

To: 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>

Cc: 'assignments' <assignments@lkkauto.com>; 'soonkiat.soh@crawford.com.sg' <soonkiat.soh@crawford.com.sg>;

'SUR' <sur@lkkauto.com> Subject: RE: Motor surveyor

Dear Mr. Soh.

According to the repairer, the said vehicle has not commence to repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Monday, 22 October 2018 7:18 PM

To: soonkiat.soh@crawford.com.sg; SUR <sur@lkkauto.com>

Cc: assignments < assignments@lkkauto.com>

Subject: RE: Motor surveyor

Dear Mr Soh,

Please be informed that survey done on 19.10.2018, we will revert to you shortly.

#### Dear Shirley,

#### Kindly assist. Our Ref: CS/CWF18017982/R1sb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: soonkiat.soh@crawford.com.sg [mailto:soonkiat.soh@crawford.com.sg]

Sent: Monday, 22 October, 2018 8:50 AM To: Admin-D <admin-d@lkkauto.com>

Subject: Fw: Motor surveyor

Hi Catherine

How is the survey at Eurosport?

Kindly contact me for a discussion.

Soh Soon Kiat • LLB MBA Dip. SCI (General) • Manager • Singapore

Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXXA Tower, 068811, Singapore

Direct: +65 6632 8638 • Mobile: +65 9634 0429 • Office: +65 6632 8600 • Fax: +65 6632 8040 • Email: soonkiat.soh@crawford.com.sg • Web Site: www.crawfordandcompany.com



---- Forwarded by Soon Kiat Soh/SG/Crawco-AP on 22/10/2018 08:51 AM -----

From: Soon Kiat Soh/SG/Crawco-AP

To: "Catherine Chong \(LKK Auto\)" <admin-d@lkkauto.com>@CRAWCO-AP

Date 17/10/2018 09:14 AM Subject: RE: Motor surveyor

#### Catherine

Kindly let me know the date and time of the survey at Eurosport.

Soh Soon Kiat \* LLB MBA Dip. SCI (General) \* Manager \* Singapore

Crawford & Company International Pte Ltd \* 8 Shenton Way, #03-01 AXXA Tower, 068811, Singapore

Direct: +65 6632 8638 \* Mobile: +65 9634 0429 \* Office: +65 6632 8600 \* Fax: +65 6632 8040 \* Email: soonkiat.soh@crawford.com.sg \* Web Site: www.crawfordandcompany.com



From. To: Cc:

Subject:

"Catherine Chong \(LKK Auto\)" <a href="mailto:admin-d@lkkauto.com">admin-d@lkkauto.com">admin-d@lkkauto.com</a>

<soonkiat soh@crawford.com.sg>, <assignments@lkkauto.com>

Cc: 'SUR Date: 03

'SUR' <<u>sur@lkkauto.com</u>> 03/10/2018 11:12 AM RE: Motor surveyor

Dear Sir / Madam,

Thank you for the assignment.

Kindly assist provide us the contact number for the person in-charge at Eurokars Auto Pte Ltd.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: soonkiat.soh@crawford.com.sg [mailto:soonkiat.soh@crawford.com.sg]

Sent: Wednesday, 3 October, 2018 9:59 AM

To: assignments@lkkauto.com Subject: Motor surveyor

Hi Serene Fong

We refer to our telephone conversation on the matter.

We look forward to your appointment of motor surveyor familiar with such type vehicle for survey and assessment of the repair quantum.

Please do not hesitate to contact me should you have any queries and kindly maintain confidentiality of the assignment.

Soh Soon Kiat • LLB MBA Dip. SCI (General) • Manager • Singapore

Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXXA Tower, 068811, Singapore

Direct: +65 6632 8638 • Mobile: +65 9634 0429 • Office: +65 6632 8600 • Fax: +65 6632 8040 • Email: soonkiat.soh@crawford.com.sg • Web Site: www.crawfordandcompany.com



Please think of the environment before printing out this message.

This message and any files transmitted with it may contain confidential, proprietary or legally privileged information and is intended solely for the use of the individual or entity to whom it is addressed. No confidentiality or privilege is waived or lost by any mistransmission. If you have received this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not review or in any way use or publish the content to any party. Crawford reserves the right to monitor communications through its network.

Please think of the environment before printing out this message.

## Catherine Chong (LKK Auto)

From:

soonkiat.soh@crawford.com.sq

Sent:

Wednesday, 3 October, 2018 9:59 AM

To:

assignments@lkkauto.com

Subject:

Motor surveyor

Attachments:

02102018135038-0001.pdf

Hi Serene Fong

We refer to our telephone conversation on the matter.

We look forward to your appointment of motor surveyor familiar with such type vehicle for survey and assessment of the repair quantum.

Please do not hesitate to contact me should you have any queries and kindly maintain confidentiality of the assignment.

Soh Soon Kiat • LLB MBA Dip. SCI (General) • Manager • Singapore

Crawford & Company International Pte Ltd • 8 Shenton Way, #03-01 AXXA Tower, 068811, Singapore Direct: +65 6632 8638 • Mobile: +65 9634 0429 • Office: +65 6632 8600 • Fax: +65 6632 8040 • Email:

soonkiat.soh@crawford.com.sg • Web Site: www.crawfordandcompany.com



Please think of the environment before printing out this message.

This message and any files transmitted with it may contain confidential, proprietary or legally privileged information and is intended solely for the use of the individual or entity to whom it is addressed. No confidentiality or privilege is waived or lost by any mistransmission. If you have received this message in error, please immediately delete it and all copies of it from your system, destroy any hard copies of it and notify the sender. You must not review or in any way use or publish the content to any party. Crawford reserves the right to monitor communications through its network.

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: NIL

Date: 23 October 2018

Our Ref: CS/CWF18017982/R1sb

The Motor Claims Department Crawford & Company International Pl

Dear Sir/Madam,


## INITIAL INSPECTION REPORT OF VEHICLE NO. SKZ 3A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 19/10/2018 at the premises of M/s Eurosports Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$</u>	33,306.00	
Revised Estimate Amount	: S\$	27,906.00	
"Check" Items Amount	: <u>SS</u>	3,000.00	
Market Value	: <u>S\$</u>		2
LTA Reimbursement Value	: <u>S\$</u>		
Nett Value	: <u>S</u> \$		

## Description of Damage:

The vehicle sustained damages at the n/s front portion.



#### Comments/ Present Status:

Damages Consistent. Repair days: 4 Days

Yours faithfully, Mohammed Rasul Automotive Assessor

# **EUROSPORTS AUTO PTE LTD**

24 Leng Kee Road. #01-03, Singapore 159096 TEL: (65) 6565 5995 FAX: (65) 6567 5515



Repair Quotation

08-10-18

## Lamborghini Huracan - SKZ 3A

<u>Parts</u>			Qty	Pri	ce
1	4T0807103C	FRONT BUMPER CM Broken	1	\$	7,500
2	4T0898085	AERODYNAMIC KIT HURACAN ( Broken	1	\$	15,456
3		Bumper Brackets and Clips Nec		\$	650
Labor				1	600
1	To dismantle and	ReFit all Parts		\$ '	3,500
2	To do Respray Pa	aint on Front Bumper and Spoiler Kit		\$15	2,000
3		1.00 Per Day x 15 Days (Exclude)		\$	7, 3,000
4	Front Bumper Sto		1	n #\$	1,200
		Sub-Total		\$	33,306
		GST		\$	2,331
		TOTAL		\$	35,637
					20306

1 This is only an estimate, should any additional work be found necessary in the course of work, extra material and labour, cost will be charged accordingly for which you will be informed prior to action taken.

2 All materials prices quoted are subject to change without notification (

- 3 All repairs are subject to spare parts availability
- 4 Quotation valid for one month from date of issue.

Lamborghini Singapore Workshop Contact:

Ising Lee Service Advisor the Repairer of the following:

To resurvey defourance spray painting

To the law desired and set of the spray painting

- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed.
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Pasul Hp 900 100 68

4 days

P/P

19/10/18 @ 1120

Resur by part



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	and the second of the second of the second of the second	
CRA	WFORD & COMP	ANY INTERNATIONAL PL	Ref : CS/CWF18017	982/R1sbs2
	SHENTON WAY 01 AXA TOWERSI	NGAPORE 068811	Date: 18-01-2019 Code: CWF	
1.		Policy Particular	s :- THIRD PARTY CLAI	M
	Insured Veh.	UNKNOWN VEHICLE	Veh. Inspected	SKZ 3A
	Policy No.		Coverage (\$)	0.00
	Claim No.	1089965/SSK	Excess (\$)	0.00
	Assign From	SOH SOON KIAT	Assign Date	03/10/2018
2.		Vehicle Par	ticulars & Condition	
	Make & Model	LAMBORGHINI HURACAN	c.c	5204
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	ZHWEC1ZF2GLA04127	Colour	ORANGE
	Odometer	016000	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Condi	tions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	245/30ZR20	PIRELLI	6 mm
	L/H Front Tyre	245/30ZR20	PIRELLI	6 mm
	R/H Rear Tyre	245/30ZR20	PIRELLI	6 mm
	L/H Rear Tyre	245/30ZR20	PIRELLI	6 mm
4.		Descrip	tion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE NA ETAILS.	S FRONT PORTION.	
5.		Gener	al Information	
	Accident Date		Inspection Date	19/10/2018
	Survey held at	24 LENG KEE RD #01-03		
	Repairer	EUROSPORTS AUTO PTE LT	D	
5a.			Remarks	
	B)THE INSPECTION	HAS NOT SEND IN FOR REPAIR ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS, I	ITHOUT PREJUDICE" BAS	
5b.		Estimate	e Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	4 Working Day	'S



#### LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 3A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CRACKED	7,500.00	7,500.00
1	AERODYNAMIC KIT HURACAN	CRACKED	15,456.00	15,456.00
1	BUMPER BRACKETS AND CLIPS	NECESSARY	650.00	650.00
1	FRONT BUMPER STONE FILM	NECESSARY	1,200.00	1,200.00
			24,806.00	24,806.00
	LABOUR			
	TO DISMANTLE AND REFIT ALL PARTS.		3,500.00	1,600.00
	TO DO RESPRAY PAINT ON FRONT BUMPER AND SPOILER KIT.		2,000.00	1,500.00
			5,500.00	3,100.00
	GRAND TOTAL		30,306.00	27,906.00
480	DECOMMENDED COST OF DEDAIDS			27 000 00

27,906.00

Report Ref No. CS/CWF18017982/R1sbs2

MOHAMMED RASUL BIN MOHD YUNUS

**Automotive Assessor** 

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatscever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.