

22/03/2002

ASS. REC. BY:

REF: CS/CTI18018013/ Gsd301

Special Instruction:

Surveyor:

Meimien

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Catherine Chia

of

CTI

Date/Time:

4/10/18 @ 2:00pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FY 8255B

Insured:

GBH 2532C

at Workshop m/s

Pain Euro Bikes

Tel:

6299 4929

of

21 Moonstone Lane # 01-01

Policy No:

DMCV SN 180858/800

Claim No:

SNM18D04585C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/09/18

CA / REV / REP. / REV 24 HRS

up

5/10/18

H.O.D. Endorsement:

Date/Time:

3:10pm @ 4/10/18

Person Contacted:

Kin Wah

Vehicle:

IN OUT

Date/Time

Action/Instruction

(✓)

Estimate

FY 8255B -X

GBH 2532C -X

REF: **CTI**

9682B

ASSIGNMENT

From: **5/10/18**

Date: **5/10/18**

Estimated Cost: **TP / WS / TP RES / OD RES / EVA / INV / MV**

To Inspect Vehicle No: **FY 8255B**

at Workshop m/s: **Pan Euro Bilco**

of: **21 Moonstone Lane**

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$1600**

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: **2** days Res.: Yes or No

Lum Sum: **20** % 3 Val: Yes or No

CA / REV / REP. / 24 HRS **1wp**

Date: Person Contacted: Vehicle: IN / OUT

Veh No: **FY 8255B** Yr Regn: **17 Jan 2005**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Honda Phantom** C.C. **197**

Colour: **Black** A/C: Insured / Std / NI / NA

Sp. Reading: **4955** T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **TA 200 500 2957**

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Order** / Jammed / Leaked / Burnt or

Brake: **Order** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: **90/90-17 (Golden Bay)**

R: **130/90-15 (City Demon)**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 5 mm	R/Bal. 5 mm
L/Bal. mm	L/Bal. mm
D.O.A.	D.O.I. 05-10-18

Survey held at **w/s** **5:30pm**

Des. of Damages: Frt / Rear / **Order** / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/10/18	Finalised \$1000 with Kin Wah Confirmed L/S \$1,000/- @ 2 days with XGQ (\$ 2,712.90 Red - 73%)

RECEIVED 12 OCT 2018

[Signature]
12/10/2018

Date/Time. File Pass to? **12/10/18**

1) **Typist**

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) **1,000/- L/S**

☐ : Preli. Report

☒ : Final Report

Days Of Repair: **2**

Resurvey No. of Trip: **/**

Add Fee:

☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

) S + RS \$

) Photos

) Others

Survey Fee: **220**

TRANSPORTATION:

TOTAL **220**

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2018		04 Oct 2018 14:20 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BUDGETCARS PTE LTD, Co. Reg. No.: 201618239Z		
Main Claimant:	KUN WAI KIT(JIAN WEIJIE)		
Vehicle Reg. No.:	FY8255B	Date of Loss:	19/09/2018 14:00 - :59
Claim Type:	TP / SNM18D04585C02	Policy/Cover Note No.:	DMCVSN1808581800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH2532C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Pan Euro Bikes Pte Ltd (HQ) 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/10/2018]		
Adj Asg. Remarks:	EST \$3712.90, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9682B
Vehicle Details	
Vehicle No.:	FY8255B
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	PHANTOM 200M
Primary Colour:	Black
Manufacturing Year:	2004
Engine No.:	TA200E5002957
Chassis No.:	TA2005002957
Maximum Power Output:	-
Open Market Value:	\$3,320.00
Original Registration Date:	17 Jan 2005
First Registration Date:	17 Jan 2005
Transfer Count:	2
Actual ARF Paid:	\$498.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2020
COE Category:	D - Motorcycle
COE Period(Years):	5
PQP Paid:	\$2,185.00
COE Rebate Amount:	\$553.00
Total Rebate Amount:	\$553.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 10 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/09/2018 17:57
Date Of Accident	19/09/2018 14:00
Exact Location Of Accident	ZION ROAD TOWARDS TIONG BAHRU ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FY8255B
Insured/Policyholder	
Name Of Registered Owner	KUN WAI KIT (JIAN WEIJIE)
NRIC No	S8339682B
Email Address	WAIKIT.KUN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82888249
Alternative Phone No	OTHERS-82888249

Vehicle Particulars

Manufacturer	HONDA
Model	PHANTOM 200M-197CC (M)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5062295975-04
Cover Note Number	17/01/2018 - 16/01/2019

Driver

Name of Driver	KUN WAI KIT (JIAN WEIJIE)
NRIC No	S8339682B
Date Of Birth	23/12/1983
Occupation	INDOOR
Date Of Driving Pass	08/02/2007
Driving Experience	11 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82888249
Fax Number	
Contact Number	OTHERS-82888249
Email Address	WAIKIT.KUN@GMAIL.COM

Address	BLK 747B BEDOK RESERVOIR CRESCENT #02-19
Postcode	472747
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLCIE REPORT - T/20180920/2130

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH2532C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LOW MOH BOON JOSEPH
NRIC/Passport Number	S9340004F
Contact Number	97774357
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	KUN WAI KIT
Approximate Age	35
Injuries Sustain	RIGHT LEG
Injured person in which vehicle?	FY8255B
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	BLK 747B BEDOK RESERVOIR CRESCENT #02-19
Postcode	472747

Sketch Plan Pg. 1

NTRA Income Motor Services Centre

Vehicle No.

Report Date: 9/29/2016 Shift Time: 3:54 PM

Report No: M1

DOA

Make/Model

Reporting Type

End Time

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) All Insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, law or court orders.


9/29/2016 17:49
Policyholder's Signature
Date & Time


9/29/2016 17:49
Driver's Signature (If driver is not the policyholder)
Date & Time


9/29/2016 17:49
Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - I 20180920/2130

DECLARATION

I/We declare the foregoing particulars are true in every respect.



9/20/2018 17:49

Policyholder's Signature
Date & Time:

9/20/2018 17:49

Driver's Signature (If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: Eric Woo Jun Kiat
NRIC/ Fin No: S992753



**SINGAPORE
POLICE FORCE**



T/20180920/2130

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 4

Report No. T/20180920/2130

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/09/2018 17:04	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

Informant's Particulars

Name of Informant: KUN WAI KIT			Address: APT BLK 747B BEDOK RESERVOIR CRESCENT #02-19 BELVIA SINGAPORE 472747		
ID Type / ID No.: NRIC NO / S8339682B			Contact No.: Home/Office: Mobile: 82888249		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 34	Date of Birth: 23/12/1983	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: DANCE STUDIO MANAGER			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/09/2018 14:00	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 ZION ROAD TIONG BAHRU ROAD ZION ROAD TOWARDS TIONG BAHRU ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FY8255B	Motorcycle	HONDA	PHANTOM 200M	Black		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FY8255B	NTUC Income Insurance Co-Operative Limited	5062295975-04	17/01/2018	16/01/2019



**SINGAPORE
POLICE FORCE**



T/20180920/2130

2 of 4

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

Report No. T/20180920/2130

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	KUN WAI KIT	ID No.	38339682B
Related Vehicle	FY8255B (Motorcycle)	Contact No.	82888249
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	19/09/2018	Date Discharge	19/09/2018
No. of Days granted Medical Leave	07	Degree of Injury	Serious
Driver			
Name	LOW MOH BOON, JOSEPH	ID No.	S9340004F
Related Vehicle	NIL	Contact No.	97774357
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE 19/09/2018 AT AROUND 1400HRS ALONG ZION ROAD TOWARDS TIONG BAHRU ROAD,

I WAS TRAVELLING ALONG ZION ROAD TOWARDS TIONG BAHRU ROAD, THE TRAFFIC FLOW WAS MODERATE AND THE ROAD SURFACE WAS DRY. I WAS RIDING ALONG ZION ROAD TURNING TOWARDS TIONG BAHRU ROAD AT THE JUNCTION. I IN THE FAR RIGHT LANE TRAVELLING TOGETHER WITH A VAN BESIDE THE REAR RIGHT OF MY VEHICLE, AS I WAS ABOUT TO COMPLETE THE TURN SUDDENLY THE VAN CHANGE DIRECTION AND HIT ONTO MY CENTER RIGHT SIDE. WHICH CAUSE ME TO LOSE CONTROL AND HIT THE CURB SIDE AND THEN COLLIDED ONTO THE TRAFFIC LIGHT AND THE BARRIER BEFORE HITTING THE GROUND. I WAS INJURED AND IN SHOCK, THE DRIVER PARKED HIS VEHICLE AND ATTENDED TO MY SIDE AND CHECKED IF I WAS ALRIGHT. HE APOLOGISED TO ME, I CALLED FOR THE AMBULANCE AND ABOUT ROUGHLY 10MINS BEFORE THEY ARRIVED TO THE SCENE. I WAS LATER ON CONVEYED TO THE HOSPITAL.

THAT'S ALL



SINGAPORE
POLICE FORCE



T/20180920/2130

Police Station Of Origin;
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 4

Report No. T/20180920/2130

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180920/2130

4 of 4

Report No. T/20180920/2130

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:
TP /
KEE CHUAN JIA MARCUS

Signature Of Informant:


Signature Of Interpreter:
Not applicable

Date/Time:
20/09/2018 17:04

Officer In Charge Of Case:
TP / GIT /
Staff Sgt SUFIYAN BIN KHAIRI
Contact No.: 65476390

Classification Of Case:

Authentication Stamp
NP168



PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg

Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT
CHINA TAIPING INS (S) PTE LTD

DATE: 02.10.2018

ESTIMATED COST OF REPAIRS TO HONDA PHANTOM 200

ENGINE NO : CHASSIS NO :
VEHICLE NO : FY 8255B ACCIDENT ON : 19.09.2018
INSURED : KUN WAI KIT

1 PC	RH MIRROR / Cut	\$	75.00	
1 PC	FRONT BRAKE MASTER PUMP ASSY X NN	\$	165.00	X
1 PC	RH FRONT SIGNAL, CHROME / Cut	\$	38.00	
1 SET	RH FRONT FORK ASSY / BT	\$	480.00	
1 PC	HEADLAMP RIM / Cut	\$	48.00	
1 PC	FRONT GARNISH, STEERING STEM, CHROME / CFA.	\$	55.00	
1 PC	FRONT MUDGUARD, BLACK / Cut	\$	85.00	
1 PC	PETROL TANK, BLACK / PD	\$	640.00	
1 PC	RH SPARK PLUG COVER PANEL, CHROME / Cut.	\$	42.00	
1 PC	BRAKE PEDAL / BT	\$	28.00	
1 PC	RH FRONT FOOTREST LOWER COVER, CHROME X NN	\$	12.00	X
1 PC	EXHAUST PLATE, CHROME / Cut	\$	54.00	
1 PC	EXHAUST ASSY / BT	\$	780.00	
1 PC	RH REAR SIGNAL ASSY / CFA	\$	38.00	
TOTAL		\$	2,540.00	2363
LESS 10%		\$	254.00	
SUB TOTAL		\$	2,286.00	2126.7
NETT ITEMS:				
1 PC	BRAKE FLUID X NN	\$	12.00	X
1 PC	BRAKE LEVER / Cut	\$	18.00	
1 PC	FRONT NO. PLATE / Cut	\$	12.00	
1 SET	CRASHBAR, CHROME / BT	\$	250.00	
1 SET	REAR BOX RACK, MONOKEY X NN	\$	160.00	X
1 PC	REAR TOP BOX, E52 BLACK / Cut	\$	350.00	
1 PC	REAR NO. PLATE / BT	\$	12.00	
TOWING		\$60 x 2	\$	120.00
LABOUR CHARGE			\$	250.00
TOTAL		\$	3,470.00	80 150. 872
ADD 7% GST		\$	242.90	
GRAND TOTAL		\$	3,712.90	
REMARKS:				
Kindly send a surveyor down for a 3rd Party claim against your insured GBH 2532C.				

REMARKS:

Kindly send a surveyor down for a 3rd Party claim against your insured GBH 2532C.

Thank You.

Kin Wah: 9731-7133

2 Days -
Imp am Repair
After repair photos.
Gua Qiaf
05/10/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2998.7
2998.7

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Oct 2018		04 Oct 2018 14:20 Edit Adj Rpt	S\$1,000.00 Edit Estimates	S\$1,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	BUDGETCARS PTE LTD , Co. Reg. No.: 201618239Z		
Main Claimant:	KUN WAI KIT(JIAN WEIJIE)		
Vehicle Reg. No.:	FY8255B	Date of Loss:	19/09/2018 14:00 - :59 [164 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D04585C02	Policy/Cover Note No.:	DMCVSN1808581800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH2532C	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Pan Euro Bikes Pte Ltd (HQ) 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Catherine Thia]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 15/10/2018]		
Adj Asg. Remarks:	EST \$3712.90, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FY8255B (SNM18D04585C02)**
[GBH2532C]

TP









































KUN WAI KIT(JIAN WEIJIE)

Sep 19 2018 2:00PM

[BUDGETCARS PTE LTD]
















Pan Euro Bikes Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Video				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	22/09/18 15:44	Video - Accident [Linked Accident Report Documents]		Load MP4	
2	22/09/18 15:44	Video - Accident [Linked Accident Report Documents]		Load MP4	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	22/09/18 15:44	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
1	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	22/09/18 14:11	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
2	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
3	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
4	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
5	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
6	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
7	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
8	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
9	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
10	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
11	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
12	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
13	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>
14	10/10/18 16:22	General View		Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
15	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
16	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
17	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
18	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
19	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
20	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
21	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
22	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
23	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
24	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
25	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
26	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
27	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
28	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
29	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
30	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
31	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/10/18 16:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/10/18 12:47	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
43	12/10/18 12:47	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/10/18 14:20	EMAIL FM PAN EURO	 Load PDF	
2	04/10/18 14:20	REPAIR EST	 Load PDF	
3	04/10/18 14:20	TP GIA	 Load PDF	
4	04/10/18 14:20	OI GIA	 Load PDF	
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	22/09/18 14:09	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	22/09/18 14:09	Accident Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	22/09/18 14:10	Identification Card [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	22/09/18 14:10	Driving License [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	22/09/18 14:11	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	22/09/18 14:11	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
7	22/09/18 14:11	POLICE REPORT [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	22/09/18 15:44	Video - Accident	 Load MP4	<input type="checkbox"/>
2	22/09/18 15:44	Video - Accident	 Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	22/09/18 15:44	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	22/09/18 14:11	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	22/09/18 14:09	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	22/09/18 14:09	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	22/09/18 14:10	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
4	22/09/18 14:10	Driving License	 Load JPG	<input checked="" type="checkbox"/>
5	22/09/18 14:11	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>
6	22/09/18 14:11	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>
7	22/09/18 14:11	POLICE REPORT	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18018013/GSD3E2

Date: 22/10/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1808581800

Claimant Vehicle
No: FY8255BInsured Vehicle
No: GBH2532C

Date of Loss: 19/09/2018

Nature of Claim: TP

Claim
No: SNM18D04585C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FY8255B	Engine No:	TA200E5002957
Make & Model:	HONDA PHANTOM 200M, 197cc (M)	Chassis No:	TA2005002957
Reg. Date:	17/01/2005 (Man. Year: 2004)	Odometer:	4955 km
Colour:	Black		
Engine Capacity:	197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/90-17	Rear Tyre Size:	130/90-15
Front Left Side:	Golden Boy 5 mm	Rear Left Side:	CITY DEMON 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,100.00	2,768.70	331.30	10.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	370.00	230.00	140.00	37.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,470.00	2,998.70	471.30	13.58
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	3,470.00	1,000.00	2,470.00	71.18
+ GST 7.00/7.00% (S\$)	242.90	70.00	172.90	71.18
Nett Amount (S\$)	3,712.90	1,070.00	2,642.90	71.18

INSPECTION

Date of Assignment: 04/10/2018

Date Inspected: 05/10/2018 Inspected At:

Pan Euro Bikes Pte Ltd (HQ)
21 Moonstone Lane #01-01 Poh Leng
Building
Singapore 328462

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Oct 2018)	
Parts:	N/A	HONDA PHANTOM 200M 197cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FY8255B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH MIRROR	Cut	75.00 FL	*75.00 FL
2	1		*FRONT BRAKE MASTER PUMP ASSY	Not Necessary	165.00 FL	*- FL
3	1		*RH FRONT SIGNAL, CHROME	Cut	38.00 FL	*38.00 FL
4	1		*RH FRONT FORK ASSY	Bent	480.00 FL	*480.00 FL
5	1		*HEADLAMP RIM	Cut	48.00 FL	*48.00 FL
6	1		*FRONT GARNISH, STEERING STEM, CHROME	Cracked	55.00 FL	*55.00 FL
7	1		*FRONT MUDGUARD, BLACK	Cut	85.00 FL	*85.00 FL
8	1		*PETROL TANK, BLACK	Dented	640.00 FL	*640.00 FL
9	1		*RH SPARK PLUG COVER PANEL, CHROME	Cut	42.00 FL	*42.00 FL
10	1		*BRAKE PEDAL	Bent	28.00 FL	*28.00 FL
11	1		*RH FRONT FOOTREST LOWER COVER, CHROME	Not Necessary	12.00 FL	*- FL
12	1		*EXHAUST PLATE, CHROME	Cut	54.00 FL	*54.00 FL
13	1		*EXHAUST ASSY	Bent	780.00 FL	*780.00 FL
14	1		*RH REAR SIGNAL ASSY	Cracked	38.00 FL	*38.00 FL
15	1		*BRAKE FLUID	Not Necessary	12.00 FS	*- FS
16	1		*BRAKE LEVER	Cut	18.00 FS	*18.00 FS
17	1		*FRONT NO. PLATE	Cut	12.00 FS	*12.00 FS
18	1		*SET CRASHBAR, CHROME	Bent	250.00 FS	*250.00 FS
19	1		*SET REAR BOX RACK, MONOKEY	Not Necessary	160.00 FS	*- FS
20	1		*REAR TOP BOX, E52 BLACK	Cut	350.00 FS	*350.00 FS
21	1		*REAR NO. PLATE	Bent	12.00 FS	*12.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,354.00	3,005.00
- List Item Discount on L Items 10.00/10.00% (S\$)	254.00	236.30
Total Parts (S\$)	3,100.00	2,768.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING	New	120.00	80.00
2	LABOUR CHARGE	New	250.00	150.00
Gross Labour Cost (\$\$)			370.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >