Surveyor :		ASSI	GNMENT (Office)	290		
From (Person):	Joel Nah	of	TIL	D	ste/Time: 4101180	0 1120am
Estimated Cost:	Andread and the second and the secon		Bill to:			
OD TP WS	TP RES / OD RES /	EVA/INV/			0110	
	cle No:				SHA 41:	
at Workshop m/	°E(ductor	Brotherhood		9011339	
of	25 kaki	BK- RO	d 4 # 03-70	1		
Policy No:			Claim No:			
Sum Insured:			Excess:			
Make of Veh: (Client's Record)				D.	F0108 A.O	12018
	REP. / REV 24 HRS				H.O.D. Endorsement:	
Date/Time: 1	205pmOallolle	Person Cont	acted: Mr-Willi	Q Vel	ich IN/OUT	
Date/Time	Action/Instruction (×) Est	imate		-	
	FP 2075R-	γ				
	SHA AIJ2H-	Nel INV 13	1023700/Klab	n)	DOA: 13/13	112
B 100						-117
	CIDCIMEDEL IS DULY	NECK IN FOUR	ner Hospital, not 39222657C	Liter do	all idner	

ASSIGNMENT

From Date: 51018	Veh No. FP2075R YrRegn. 4.97
Estimated Cost.	Type: M.Car M.Gycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP)WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No. FP 2075R	Make: Honde RVF400RS co 399
at Workshop m/s EQUCTOR Brotherhood	Colour 3(ec & A/C: Insured / Std / N/ / NA
25 kaki 3kt Rd 4 # 03-79	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: NC351101194
Ctaims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Instired Excess:	Steering: horder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
Make of Veh: Willie @ 90113391	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size F: 120/60 n 1 +
(Policy Condition)	R: 160/60 AD
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO OF DIA 6/0
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No.	R/Bal. 7 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. mm L/Bal. mm
Est, Repairs: days Res.: Yes or No	D.O.A. 30/7/cf D.O.I. 5/10/cf
Lum Sum: . % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS (W) 11A 1336	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	The J Chassis frame / Body Structure affected due to collision.
Date/Time Action/Instruction ToTALLOSS GRUND 31- Bol fyrs. 6 mls. 5336+3	3-2027 25w++000 = 8836
RECEIVED 1 3 NOV	2018
RECEIVED 13 No.	LOTO
Date/Time. File Pass to? : Preli. Report	Days Of Repair:
: Final Report	Resurvey No. of Trip: - Survey Fee:
Date/Time, File Return to?	Transportation
2) Add Fee	
	Interview (\$) Photos
Report Format: PRS.	Tech Invs (\$) Others
Lump 8um / I.B.I: (\$	Weakend (\$ -)
	TOTAL

Nivitha (LKK Auto)

From:

Motor Claim - III <motorclaim@iii.com.sg>

Sent:

Thursday, 4 October 2018 11:20 AM

To:

Catherine Chong (LKK Auto); 'sur@lkkauto.com'

Cc:

Subject:

'babyma 2605'; Rajpal Singh; Mekavathanan Sarangapani; Sundari Nagarajan - III RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FP2075R (Accident involving

FP2075R and SHA4173H on 30.07.2018)

Attachments:

sha4173h_20181003160443.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle FP2075R and let us have your report urgently.

This claim will be handled by Ms SUNDARI

*Kindly upload this survey request email to merimen.

Thank You.

Joel Nah

Motor Claims Department India International Insurance Pte Ltd

64 Cecil Street #04-02 IOB Building Singapore 049711 Tel: 6347 6100 Ext 206 Fax: 6224 4174

From: Rajpal Singh [mailto:rajpal@kertarlaw.com.sg]

Sent: Thursday, 4 October, 2018 11:16 AM

To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'babyma 2605' <babyma 2605@gmail.com>

Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. FP2075R (Accident involving FP2075R and SHA4173H on

30.07.2018)

Dear Sirs,

WE refer to your email dated 3rd October 2018.

Please note that we propose to use LKK Auto Consultants Pte Ltd as the surveyor and also as the single joint expert.

We would propose that the survey take place at: 25 Kaki Bukit Road 4, Synergy@KB, #03-79, Singapore 417800.

Kindly contact Mr. Willie at 90113391 to make the necessary arrangements for the survey.

Thank you.

Regards,

Rajpal Singh.

From: kertar@kertarlaw.com.sg [mailto:kertar@kertarlaw.com.sg]

Sent: Wednesday, 3 October 2018 5:21 PM
To: 'Rajpal Singh' <rajpal@kertarlaw.com.sg>

Subject: FW: PRE-REPAIR INSPECTION FOR VEHICLE NO. FP2075R (Accident involving FP2075R and SHA4173H on

30.07.2018)

From: Motor Claim - III < motorclaim@iii.com.sg > Sent: Wednesday, October 3, 2018 4:14 PM

To: kertar@kertarlaw.com.sg

Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. FP2075R (Accident involving FP2075R and SHA4173H on

30.07.2018)

Dear Sir / Mdm,

We acknowledge receipt of your letter.

We proprose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- · Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd. Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd.

Registration No. 198703792-K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	SECURISE LEGISLATION	
Owner ID Type:	Singapore NRIC	
Owner ID:	2657C	
Vehicle Details		
Vehicle No.:	FP2075R	
Vehicle to be Exported:	No	
Intended Deregistration Date:	16 Oct 2018	
Vehicle Make:	HONDA	
Vehicle Model:	RVF400RS	
Primary Colour:	White	
Secondary Colour:	Red	
Manufacturing Year:	1996	
Engine No.:	NC13E1601195	
Chassis No.:	NC351101194	
Maximum Power Output:	NC351101194	
Open Market Value:	\$7,750.00	
Original Registration Date:	14 Apr 1997	
First Registration Date:	14 Apr 1997	
Transfer Count:	12 12	
Actual ARF Paid:		
Intended PARF Rebate Details	\$1,163.00	
PARF Eligibility:	No	
PARF Eligibility Expiry Date:		
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details	***************************************	
COE Expiry Date:	31 Mar 2027	
COE Category:	D - Motorcycle	
COE Period(Years):	10	
PQP Paid:	\$6,256.00	
COE Rebate Amount:	\$5,336.00	
Total Rebate Amount: Message	\$5,336.00	
At the state of th		

Please note that the National Environment Agency (NEA) is offering an incentive for the owner of this motorcycle to deregister the motorcycle on or before 5 April 2023.

This motorcycle is currently eligible for an incentive of \$3,500 from NEA. If the COE is renewed from now till its deregistration on or before 5 April 2023, the incentive will be reduced to \$2,000. The last registered owner of this motorcycle will receive the incentive from NEA.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

For more information, please visit http://www.nea.gov.sg/mtcincentive or contact NEA at 1800-2255-632.

The information contained herein is correct as at 16 Oct 2018


OK

Model	Honda CB400 Super 4 Ver S (/listing/usedbike/model/honda-cb400-super-4-ver-s/)
Engine Capacity	399cc
Classification	2A
Registration Date	11/06/1996
COE Expiry Date	31/08/2021 (2 years 9 months left)
Mileage	(*)
No. of owners	
Type of Vehicle	Street Bikes (/listing/usedbikes/listing/?bike_type=7)

DETAILS

Visit us at Aljunied Motor Works. Well maintained condition. Seldom use, Trade in welcome / Loan available

SIMILAR BIKES





Honda CB400 Super 4 Ver S



Honda CB400 Super 4 Ver S

(/listing/usedbike/honda-honda-cb400-super-4-ver- (/listing/usedbike/honda-honda-cb400-super-4-vers/8975/)

s/1156/)



Honda CB400 Super 4 Ver S

11/9/2018	Used Honda CB400 Super 4 Spec 3 for Sale in Singapore - Price, Reviews & Contact Seller - SGBikemart	
Brand	Honda (/listing/usedbike/brand/honda/)	
Model	Honda CB400 Super 4 Spec 3	
Model	(/listing/usedbike/model/honda-cb400-super-4-sp	ec-3/)
Engine Capacity	399cc	
Classification	2A	
Registration Dat	11/08/2007	
COE Expiry Date	31/03/2027 (8 years 4 months left)	
Mileage	98000km	
No. of owners	2	

Street Bikes (/listing/usedbikes/listing/?bike_type=7)

DETAILS -

Type of Vehicle

Looking for a simple and reliable Vtec3, this is the one! Stock yellow paintwork Spec 3 with Boon siew sticker still on tank. No accident, no respray. Coe till Mar 2027. Weekend bike as mostly drive. Solid engine verified by Mech. 10 mth free Rd tax till next year Aug 2019. Price is firm and non-nego. Whatapps for viewing. Full cash deal.

Accessories

CB400 Radiator mesh. Seat Cover. New Signal lights(will give to new owner ,Not install) New Sprocket(Not Install)

SIMILAR BIKES

VIEW ALL (/LISTING/USEDBIKES/LISTING/)






Bike model	
Туре	
Type Any	•
Price From	
Any	•
Price To	
Any	•
Class	
Any	•

Q SEARCH V

Q SEARCH

■ VIEW ALL (/LISTING/USEDBIKES/LISTING/)



REPORT ERROR > (/LISTING/LISTING/ERROR/USEDBIKE/10038/) + ADD TO SHORTLIST Like 0 Share | Shar

Honda CB400 Super 4 Spec 3

Listing Type Paid Ad

11/9/2018	Used Honda CB400 Super 4 Ver S for Sale in Singapore - Price, Reviews & Contact Seller - SGBikemart
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400 Super 4 Ver S
Wodel	(/listing/usedbike/model/honda-cb400-super-4-ver-s/)
Engine Capacity	399cc
Classification	2A
Registration Date	o5/12/1997
COE Expiry Date	04/12/2022 (4 years left)
Mileage	72079km
No. of owners	3
Type of Vehicle	Street Bikes (/listing/usedbikes/listing/?bike_type=7)

DETAILS

Welcome trade in. Loan available. Ambra Enterprises is located at Block 5034 Ang Mo Kio Industrial Park 2 #01-327.

Accessories

GPR exhaust with cert.

SIMILAR BIKES

VIEW ALL (/LISTING/USEDBIKES/LISTING/)





Honda CB400 Super 4 Ver S

s/8975/)

(/listing/usedbike/honda-honda-cb400-super-4-ver- (/listing/usedbike/honda-honda-cb400-super-4-vers/1156/)

1/9/2018	Used Honda CB400 Super 4 Ver S for Sale in Singapore - Price, Reviews & Contact Seller - SGBikemart
Brand	Honda (/listing/usedbike/brand/honda/)
Model	Honda CB400 Super 4 Ver S (/listing/usedbike/model/honda-cb400-super-4-ver-s/)
Engine Capacity	399cc
Classification	2A
Registration Date	05/12/1997
COE Expiry Date	04/12/2022 (4 years left)
Mileage	72079km
No. of owners	3
Type of Vehicle	Street Bikes (/listing/usedbikes/listing/?bike_type=7)

DETAILS

Welcome trade in. Loan available. Ambra Enterprises is located at Block 5034 Ang Mo Kio Industrial Park 2 #01-327.

Accessories

GPR exhaust with cert.

SIMILAR BIKES

VIEW ALL (/LISTING/USEDBIKES/LISTING/)





Honda CB400 Super 4 Ver S

s/8975/)

(/listing/usedbike/honda-honda-cb400-super-4-ver- (/listing/usedbike/honda-honda-cb400-super-4-vers/1156/)

Bike model Honda RVF400 Type Any Price From Any Price To Any Class Any MORE SEARCH OPTIONS > Q SEARCH ■ VIEW ALL (/LISTING/USEDBIKES/LISTING/)

Q SEARCH V

Honda RVF400RS (/listing/usedbike/honda-honda-rvf400/200/)



(/listing/usedbike/honda-honda-rvf400/200/)

Reg: 01/08/1996 Type: Sport Bikes

399cc

COE Till 2024. Unique brand new Repsol CBR 1000 fairing with Moto GP graphics. Only one RVF with this paintwork, Well maintained condition. Neither use in track race or touring. Only ride to s...

Posted on : -

* PAID AD * DIRECT SELLER

■ COMPARE DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-RVF400/200/)

Honda RVF400RT (/listing/usedbike/honda-honda-rvf400rt/6459/)



(/listing/usedbike/honda-honda-rvf400rt/6459/)

Reg: 27/03/2001 Type: Sport Bikes

399cc 55600km

New tyre and battery to go along. Body work and fork done last year, Got receipt as proof. For more detail pls Contact View/Detail. Posted on : -

★ PAID AD ★ DIRECT SELLER

■ COMPARE DETAILS > (/LISTING/USEDBIKE/HONDA-HONDA-RVF400RT/6459/)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Authled	Status	
Main	16 Nov 2018 10:11 Edit Reg		04 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View R			Pending for Report Cancel Case	
	Main	Re	ference	Cla	im Details		Document	s	Show All
CLAIM SU	BFOLDER DE	TAILS		THE RESERVE AND ADDRESS.		[Create	d by adjuster]		decided any state
Insured:	-, Co. Re					Create	d by adjuster]		
Main Claimant:	-	***************************************							
Vehicle Reg No.:	FP2075	R			ate of Loss:		18 00:00 - :59 hths and 16 Days	From ITA Rea	Date (Man Ve)
Claim Type	TP				olicy/Cover	1		TOTAL ETA REG	Date (Mail 11)
Vehicle Reg No. (Insured):	SHA41731	4			olicy No. Claimant):				
Repairer:	Equator P	rotherhead (UO	AF LOCAL CO.		xcess:				
Handling Insurer:							i Bukit - Tel: 63846 ndari Nagarajan		
Adjuster:							HUA] [Final I		
ASSOCIAT	ED MAIL RE						900		
There are n	o mail for this	case.					V	iew All Cor	npose Case Mai
ALL ASSO	CIATED TAS	ks⊡				View All	Search Tasks	Create New Ta	ask Complete
Due Date	Priority	Type Task (Group Subje	ect Handler	Assign		Completed On	Created	

Claim Documents

*FP2075R [SHA4173H] TP -Jul 30 2018 12:00AM [-] Equator Brotherhood

		pad Photos Compose New Letter	View View	ew in Brow	vser 🔻
Pho	tos/Images		3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			m
1	10/10/18 11:56	General View		umbnail	Print
			■ Lo	oad PDF	
	umentation		1 per page		•
No	Finalized On	India International Insurance Pte Ltd (HQ)	The	umbnail	Drint
1	05/10/18 08:50	Singapore Accident Statement		ad PDF	Frinc

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	Keset Save Frint
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/III18018019/UCD3S2

Date:

16/11/2018

REFERENCE

Handling Insurer: Claimant Vehicle India International Insurance Pte Ltd

Policy No:

Insured Vehicle No:

SHA4173H

Date of Loss:

FP2075R 30/07/2018

Nature of Claim:

TP

Claim No:

N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

No:

FP2075R

Make & Model:

HONDA RVF400RT, 399cc (M) 14/04/1997 (Man. Year: 1996)

Engine No: Chassis No: NC13E1601195

Reg. Date: Colour:

Black

Odometer:

NC351101194 0 km

Engine Capacity:

399 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Fair

Steering (Serviceable): Yes Engine Modification:

Inspected At:

Yes No

Footbrake (Serviceable): Pre-accident Condition:

Yes

CONDITION OF TYRES

Handbrake (Serviceable):

Front Tyre Size:

120/60R17

0 mm

Rear Tyre Size:

160/60R17

Front Left Side: Front Right Side:

COST OF CLAIMS

Miscellaneous Items

Paintwork Labour

Parts

Labour

Towing

DIABLO 7 mm

Rear Left Side: Rear Right Side: DIABLO 7 mm

0 mm

The above values represent the remaining tyre treads depth

Repairer's Adjuster's Difference Diff % 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.00

0.00 0.00 0.00 Nett Amount (S\$) 0.00 0.00 0.00

INSPECTION

Date of Assignment:

04/10/2018

Date Inspected:

05/10/2018

Equator Brotherhood (HQ)

25 kaki bukit rd 4 #03-79 synergy @ kb

Singapore 417800

Estimated Period of Repair:

0.0 days

Adjuster: MARCUS CHUA

Manager:

CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

(Last Synchronised: 16 Nov 2018) Part Source:

HONDA RVF400RT 399cc (M) (Model not available in database) Parts: N/A

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FP2075R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >