

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO : SHA 5853X

MAKE :

MODEL : TOYOTA PRIUS

2/10/2018 16:51

Fauzy

| PARTS DESCRIPTION           | QTY | UNIT PRICE | AMOUNT    |
|-----------------------------|-----|------------|-----------|
| REAR BUMPER UNDER COVER     |     |            | \$ 552.60 |
| <i>Rear Bumper x repair</i> |     |            |           |
| SUB TOTAL                   |     |            | \$ 552.60 |
| LESS 20%                    |     |            | \$ 110.52 |
| DISCOUNTED TOTAL            |     |            | \$ 442.08 |
| LABOUR CHARGE               |     |            |           |
| Panel Beating               |     |            | \$ 220.00 |
| <i>Spray Painting</i>       |     |            | \$ 220.00 |
| TOTAL LABOUR                |     |            | \$ 220.00 |
| ESTIMATE TOTAL              |     |            | \$ 662.08 |

Kalk (LKK)

3/10/18 1030h.

2 Days

P/P

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.