

10/4/2018

Repairer Estimates

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

45 Pandan Road
Singapore 609286

Tel: 6338 8778 Email: denisteo@cdge.com.sg

INSURER: **EQ Insurance Company Ltd (HQ)****PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)
 Policy No: DMPPHQ18-001013
 Vehicle Reg. No.: SKT9575M
 Driver Age/Info: / MALE
 TP Injury Involved? NO
 Insured/Claimant: BJORN CHUA KANG WEI
 Driver: BJORN CHUA KANG WEI

Ref. No:
 Date of Loss: 01/10/2018
 Driveable?
 Party At Fault: UNKNOWN
 Third Party Involved? YES
 Contact No: +6590475274

Make/Model: AUDI A6, 2.8 FSI MU (A)
 Vehicle Colour: METALLIC BLACK
 Engine No: CHV004290
 Odometer: 128292 KM

Vehicle Reg. Date: 20/01/2012
 Chassis No: WAUZZZ4GXB027685

Paint Type:
 Total Loss? NO
 Est. Duration of Repair (day) 8

Tanjin 97495749
Ex: waived
Approve
5/10/18 4pm
5 days

Remarks: VEHICLE IN WORKSHOP

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (PANDAN)

*sur@hkan10.com**Resing before paint***COST OF CLAIMS**

	Amount
Parts	6,689.55
Miscellaneous Items	0.00
Labour	2,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	9,099.55
+ GST 7.00% (\$)	636.97
Nett Amount (\$)	9,736.52

This claim is handled by: WONG CHEE WEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2018)
 Parts: 143 AUDI A6 2.8 FSI MU (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SKT9575M/04/10/2018 12:30
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

parts cost \$3949

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FR BUMPER ✓	0.00	0.00	de 730.00 F
2	10		*FR BUMPER CLIPS ✓	0.00	0.00	un 15.00 F
3	1		*L / F RETAINER ✓	0.00	0.00	un 14.00 F
4	1		*R / F RETAINER ✓	0.00	0.00	un 14.00 F
5	1		*R / F UPPER BRACKET	0.00	0.00	? 25.00 F
6	1		*L / F UPPER BRACKET ✓	0.00	0.00	de 25.00 F
7	1		*FRONT GRILLE	0.00	0.00	? 380.00 F
8	1		*R / F GARNISH W/CHROME MOULDING - FOG LAMP	0.00	0.00	X 45.00 F
9	1		*L / F GARNISH W/CHROME MOULDING - FOG AMP ✓	0.00	0.00	mis 45.00 F
10	1		*LEFT FOG LAMP	0.00	0.00	cul 250.00 F
11	1		*TOW COVER	0.00	0.00	X 44.00 F
12	1		*L / F HEAD LAMP WATER JET ✓	0.00	0.00	? 73.00 F
13	1		*L / F HEAD LAMP WATER JET TOP COVER ✓	0.00	0.00	de 17.00 F
14	1		*L / F BRACKET SUPPORT ✓	0.00	0.00	? 13.00 F
15	1		*L / F FENDER ✓	0.00	0.00	bt 380.00 F
16	1		*L / F FENDER LINER ✓	0.00	0.00	de 80.00 F
17	10		*L / F FENDER LINER CLIPS ✓	0.00	0.00	un 15.00 F
18	1		*L / F FENDER - EMBLEM - V6T ✓	0.00	0.00	un 48.00 F
19	1		*L / F UNDER LIP - FR BUMPER ✓	0.00	0.00	X 75.00 F
20	1		*BONNET ✓	0.00	0.00	bt 1,400.00 F
21	1		*INSULATOR	0.00	0.00	X 45.00 F
22	1		*INSULATOR CLIPS	0.00	0.00	X 2.00 F
23	1		*LOCK - BONNET	0.00	0.00	? 98.00 F
24	1		*L / HINGE - BONNET	0.00	0.00	R 48.00 F
25	1		*R / HINGE - BONNET	0.00	0.00	R 48.00 F
26	1		*LEFT HEAD LAMP ✓	0.00	0.00	cul 840.00 F
27	1		*L / F DOOR	0.00	0.00	X 390.00 F

F=Franchise part.

Sub Total (\$\$) 5,817.00
 + Margin on L,N Items 15.00% (\$\$) 872.55
 Total Parts (\$\$) 6,689.55

ComfortDelGro Engineering Pte Ltd/SKT9575M/04/10/2018 12:30. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE / REPLACE / STRAIGHTEN / RE ALIGN :FR BUMPER,L/F FENDER,L/F DOOR,BONNET	New	500 1,000.00
2	TO PUTTY / RE SPRAY PAINT :FR BUMPER,L/F FENDER,L/F DOOR,BONNET	New	650 1,000.00
3	TO CHECK WIRE	New	30 60.00
4	TO RE SETTING ELECTRICAL SYSTEM	New	150 350.00
Gross Labour Cost (S\$)			2,410.00

ComfortDelGro Engineering Pte Ltd/SKT9575M/04/10/2018 12:30. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Oct 2018)
 Parts: 143 AUDI A6 2.8 FSI MU (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SKT9575M/12/10/2018 14:24
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*L / OUT SENSOR FR BUMPER ✓	0.00	0.00	75.00 F
2	1		*UNDER FR COVER ✓	0.00	0.00	*55.00 F
3	1		*FR SUPPORT TOP GARNISH ✓	0.00	0.00	35.00 F
Franchise part.						
Sub Total (S\$)						165.00
+ Margin on L,N Items 15.00% (S\$)						24.75
Total Parts (S\$)						189.75

ComfortDelGro Engineering Pte Ltd/SKT9575M/12/10/2018 14:24. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKT9575M P/O: 4500799069

ORDER BY: NETTY

SEND TIME

Tax Invoice No: SIN1553273

Date: 08/10/2018

Area Code: 3A DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	H/LAMP AUDI A6 12>LH 26	1	840.00	840.00 ✓
2	bumper audi a6c7 frt 1	1	730.00	730.00 ✓
3	CLIP SET BUMPER FRT AUDI A6/S6/A7 2	1	15.00	15.00 ✓
4	bumper bkt audi a6c7 f/lh 3	1	14.00	14.00 ✓
5	bumper reinf bkt audi a6c7 f/lh	1	70.00	70.00 ✓
6	bumper bkt audi a6c7 f/rh 4	1	14.00	14.00 ✓
7	bumper grille audi a6c7 f/lh	1	45.00	45.00 X
8	fender audi a6c7 f/lh 15	1	380.00	380.00 ✓
9	fender shield audi a6c7 f/lh rc 16	1	80.00	80.00 ✓
10	BONNET AUDI A6 12> 20	1	1,400.00	1,400.00 ✓
11	CLIP AUDI REAR FENDER SHIELD 17	1	15.00	15.00 ✓

COMFORTDELGRO ENGINEERING PTE LTD
Items issued to external business without discrepancies
and without exceptions. 9/10/18
Issued by: 12.20 by: 12.20
Customer's Signature / Company Stamp
Products sold are not returnable.
Sign/Date
Page: 1 of 2
FOR KIAN HUA OFFICIAL USE:
PAID / AMOUNT
TIME:
Crash Repair

WEE - 08/10/2018 5:06:01 PM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKT9575M P/O:4500799069
ORDER BY: JETTY
SEND TIME

Tax Invoice No: SIN1553273

Date: 08/10/2018

Area Code: 3A DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
	Products received and checked to be in good condition			
			Sub-Total:	SGD 3,603.00
			G.S.T(7%):	252.21
			Total :	SGD 3,855.21

WWW.KIANHUAMOTOR.COM

9/10/18
12.20

5001054887

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 2 of 2

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:
TIME:

WEE - 08/10/2018 5:06:01 PM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKT9575M PO: 4500799069
ORDER BY DON HP: 93584174

Tax Invoice No: SIN1553313

Date: 10/10/2018

Area Code: 3A DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	FENDER BKT A6/RS6 11> LH metal 14	1	13.00	13.00
2	FENDER BKT A6C7 14-> F/LH METAL 6	1	25.00	25.00

Products received and checked to be in good condition

Sub-Total: SGD 38.00
G.S.T(7%): 2.66
Total: SGD 40.66

COMFORTDELGRO ENGINEERING PTE LTD	
Items issued to external services without defects. Exceptions:	
Issued by: 11/25	Received by:
Name	Name
Sign/Date	Sign/Date
Crash Repair	

Customer's Signature / Company Stamp

Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 10/10/18 9:36:14 AM

Authorised Signature

WWW.KIANHUAMOTOR.COM



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fa 63551800
Email: Sales@KianhuaMotor.Com
Co. Reg No. / GST Reg No.: J106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKT9575M P/O:4500799069
ORDER BY NETTY
SEND TMR

Tax Invoice No: SIN1553274
Date: 08/10/2018
Area Code: 3A DELIVER
Credit Terms: 30Days
Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	WIPER SPRAY COVER AUDI A6C7 F/LH 13	1	17.00	17.00
Products received and checked to be in good condition			Sub-Total:	SGD 17.00
			G.S.T(7%):	1.19
			Total :	SGD 18.19

COMFORTDELGRO	ENGINEERING PTE LTD
Items issued to external customers	without discrepancies
9/10/18	12.20
Name	
Sign/Date	
SCM, CPD	

Customer's Signature / Company Stamp
Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:	
TIME:	

TGL - 08/10/2018 4:57:53 PM

Authorised Signature

WWW.KIANHUAMOTOR.COM



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKT9575M P/O:4500799077
ORDER BY: JETTY
SEND TMR

Tax Invoice No: SIN1553275

Date: 08/10/2018

Area Code: 3A DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	LOGO AUDI A4 V6T 18	1	48.00	48.00
Products received and checked to be in good condition			Sub-Total:	SGD 48.00
			G.S.T(7%):	3.36
			Total :	SGD 51.36

COMFORTDELGRO ENGINEERING PTE LTD	
Item: 18	External: 18
and defects Excepted	
Issued by: 12.20	Received by:
Name	Name
Sign/Date	Sign/Date
Customer's Signature / Company Stamp	Crash Repair

Products sold are not returnable.

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 08/10/18 5:16:44 PM

Authorised Signature



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKT9575M P/O: 4500799364
ORDER BY: NETTY

Tax Invoice No: SIN1553387

Date: 12/10/2018

Area Code: 3A DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	PANEL/FULL A6C7 TOP COVER - S-3	1	35.00	35.00
2	REVERSE SENSOR AUDI - S-1	1	75.00	75.00

Products received and checked to be in good condition

Sub-Total: SGD 110.00

G.S.T(7%): 7.70

Total: SGD 117.70

COMFORTDELGRO ENGINEERING PTE LTD	
Items issued to external customers must be repaired and defects corrected.	
Issued by:	Received by:
Name: <i>[Signature]</i>	Name: <i>[Signature]</i>
Sign/Date: <i>[Signature]</i> 12/10/18	Sign/Date: <i>[Signature]</i> 10/10/18
SCM. CP: 13.20	

Customer's Signature / Company Stamp

Products sold are not returnable.

500055499

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 12/10/2018 10:35:26 AM

Authorised Signature

WWW.KIANHUAMOTOR.COM



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 3A
45 PANDAN ROAD
SINGAPORE 609286

SKT9575M P/O:4500799364
ORDER BY: NETTY/DON

Tax Invoice No: SIN1553394

Date: 12/10/2018

Area Code: 3A DELIVER

Credit Terms: 30Days

Kian Hua Sales: WEE

No.	Description	Qty	Unit Price	Amount
1	fender shield audi a6c7 f/lh frt -19	1	75.00	75.00
2	H/LAMP NOZZLE AUDI A6 LH -12	1	73.00	73.00
3	BUMPER UNDERCOVER AUDI A6C7 FRT 8-2	1	55.00	55.00
4	bumper grille audi a6c7 f/lh	1	45.00	45.00

Products received and checked to be in good condition Sub-Total: SGD 248.00
G.S.T(7%): 17.36
Total: SGD 265.36

COMFORTDELGRO ENGINEERING PTE LTD	
Items issued to external business without discrepancies and defects. Exceptions to be stated above.	
Issued by:	Received by:
Name	Name
Sign/Date	Sign/Date
SCM, CPD	Crash Repair
Customer's Signature / Company Stamp	

Products sold are not returnable.

50060538 Lf1

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 12/10/18 12:31:54 PM

Authorised Signature

WWW.KIANHUAMOTOR.COM



KIAN HUA

KIAN HUA MOTOR CO. PTE LTD
7 Jalan Lembah Kallang Singapore 339563
Tel: 62933850 Fax: 63551800
Email: Sales@Kianhuamotor.Com
Co. Reg No. / GST Reg No: 200106569G

Customer's Copy

Customer: COMFORTDELGRO ENGINEERING PTE LTD

Address: 205 BRADDELL RD, WEST WING 4TH LEVEL
SINGAPORE 579701
ATTN : SHEILA -FINANCE AP

Tax Credit Note No: SCR1419830

Date: 10/10/2018

Area Code: SELF

Credit Terms: 30Days

Kian Hua Sales: WEE

Related Inv No: SIN1553273

Related Inv Date: 08/10/2018

WRONG SUPPLY REF SIN1553273

No.	Description	Qty	Unit Price	Amount
1	bumper grille audi a6c7 f/lh	1	45.00	45.00
2	bumper reinf bkt audi a6c7 f/lh	1	70.00	70.00

Products received and checked to be in good condition

Sub-Total: SGD 115.00

G.S.T(7%): 8.05

Total: SGD 123.05

Verified By	<i>Sheila Kelly</i>
GL A/C Code	
Business Area	
Cool Center	
Approved for payment	
Posted By	

Customer's Signature / Company Stamp

Page: 1 of 1

FOR KIAN HUA OFFICIAL USE:

PAID / AMOUNT:

TIME:

WEE - 18/10/2018 10:30:36 AM

Authorised Signature

C. R.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2018	04 Oct 2018	05 Oct 2018	S\$5,871.35	S\$5,871.35		Pending for Survey Report
	Sendback Est	12:30 S\$9,099.55	08:54 Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	12 Oct 2018 14:14	12 Oct 2018 14:24 S\$189.75	12 Oct 2018 14:24			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	BJORN CHUA KANG WEI , ID: S8508746J, Tel: +6590475274		
Vehicle Reg. No.:	SKT9575M	Date of Loss:	01/10/2018 00:00 - :59 [80 Months and 11 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / DM18HO02651	Policy/Cover Note No.:	DMPPHQ18-001013 (Comprehensive) Coverage: 10/02/2018 - 09/02/2019
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Pandan) 45 Pandan Road, 609286 Eunos - Tel: 6338 8778		
Handling Insurer:	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Joel Goh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 16/10/2018]		
Driver/Custodian:	BJORN CHUA KANG WEI (/ Male), NRIC: S8508746J, Tel: +6590475274		
Adj Asg. Remarks:	EXCESS WAIVED		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- EQI_HQ (25/10/2018): Alert - Adj Mandate Approved (S\$6786.75) - SKT9575M - Claim Handler: Joel Goh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKT9575M (DM18HO02651)
 OD
 Oct 1 2018 12:00AM
 [BJORN CHUA KANG WEI]
 ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

[View](#)
[View in Browser ▼](#)

Assessment Reports

1 per page ▼ ☒

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)		Thumbnail	Print
1	04/10/18 12:30	Repairer Estimates		Load HTM	
2	12/10/18 14:24	Repairer Estimates Suppl. #1		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/10/18 13:24	Adjuster Immediate Advice		Load HTM	
2	10/10/18 13:31	Adjuster Immediate Advice		Load HTM	
3	19/10/18 10:38	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/10/18 13:46	Odometer Reading		Load JPG	☒
2	10/10/18 13:46	Chassis Number		Load JPG	☒
3	10/10/18 13:46	General View		Load JPG	☒
4	10/10/18 13:46	General View		Load JPG	☒
5	10/10/18 13:46	General View		Load JPG	☒
6	10/10/18 13:46	General View		Load JPG	☒
7	10/10/18 13:46	General View		Load JPG	☒
8	10/10/18 13:46	General View		Load JPG	☒
9	10/10/18 13:46	General View		Load JPG	☒
10	10/10/18 13:46	General View		Load JPG	☒
11	10/10/18 13:46	General View		Load JPG	☒
12	10/10/18 13:46	General View		Load JPG	☒
13	10/10/18 13:46	General View		Load JPG	☒
14	10/10/18 13:46	General View		Load JPG	☒
15	10/10/18 13:46	General View		Load JPG	☒
16	10/10/18 13:46	General View		Load JPG	☒
17	10/10/18 13:46	General View		Load JPG	☒
18	10/10/18 13:46	General View		Load JPG	☒
19	10/10/18 13:46	General View		Load JPG	☒
20	10/10/18 13:46	General View		Load JPG	☒
21	10/10/18 13:46	General View		Load JPG	☒
22	10/10/18 13:46	General View		Load JPG	☒
23	10/10/18 13:46	General View		Load JPG	☒
24	10/10/18 13:46	General View		Load JPG	☒
25	10/10/18 13:46	General View		Load JPG	☒
26	10/10/18 13:46	General View		Load JPG	☒
27	10/10/18 13:46	General View		Load JPG	☒
28	10/10/18 13:46	General View		Load JPG	☒
29	10/10/18 13:46	General View		Load JPG	☒

Assessment Reports			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
30	10/10/18 13:46	General View	 Load JPG	✓
31	10/10/18 13:46	General View	 Load JPG	✓
32	10/10/18 13:46	General View	 Load JPG	✓
33	10/10/18 13:46	General View	 Load JPG	✓
34	10/10/18 13:46	General View	 Load JPG	✓
35	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
36	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
37	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
38	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
39	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
40	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
41	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
42	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
43	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
44	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
45	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
46	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
47	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
48	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
49	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
50	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
51	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
52	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
53	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
54	02/11/18 16:10	Dismantled Parts	 Load JPG	✓
55	05/11/18 11:09	Reinspection Photo	 Load JPG	✓
56	05/11/18 11:09	Reinspection Photo	 Load JPG	✓
57	05/11/18 11:09	Reinspection Photo	 Load JPG	✓
58	05/11/18 11:09	Reinspection Photo	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Pandan)	Thumbnail	Print
1	04/10/18 12:33	Singapore Accident Statement	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/10/18 13:45	ESTIMATE.pdf	 Load PDF	
2	28/11/18 15:13	SUPPLEMENTARY	 Load PDF	
3	28/11/18 15:13	PARTS INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQ18018076/T1SD3S2
Date: 28/11/2018

REFERENCE

Insured/Claimant: BJORN CHUA KANG WEI Policy No: DMPPHQ18-001013
Date of Loss: 01/10/2018 Nature of Claim: OD Claim No: DM18HO02651

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKT9575M**
Make & Model: AUDI A6, 2.8 FSI MU (A) Engine No: CHV004290
Reg. Date: 20/01/2012 (Man. Year: 2011) Chassis No: WAUZZZ4GXB027685
Colour: Black Odometer: 128292 km
Engine Capacity: 2773 cc
Market Value/New Car Price: S\$67,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18 Rear Tyre Size: 245/45R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,879.30	4,541.35	2,337.95	33.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,410.00	1,330.00	1,080.00	44.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,289.30	5,871.35	3,417.95	36.79
+ GST 7.00/7.00% (S\$)	650.25	410.99	239.26	36.80
Nett Amount (S\$)	9,939.55	6,282.34	3,657.21	36.79

INSPECTION

Date of Assignment: 05/10/2018 Present Location: ComfortDelGro Engineering Pte Ltd (Pandan)
Date Inspected: 05/10/2018 Inspected At: ComfortDelGro Engineering Pte Ltd (Pandan)
45 Pandan Road
Singapore 609286
Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2018)
Parts:	143	AUDI A6 2.8 FSI MU (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT9575M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FR BUMPER (WCP)	Deformed	750.00 F	*730.00 F
2	10		*FR BUMPER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
3	1		*L / F RETAINER (WCP)	Necessary	14.00 F	*14.00 F
4	1		*R / F RETAINER (WCP)	Necessary	14.00 F	*14.00 F
5	1		*R / F UPPER BRACKET (WCP)	Not Necessary	70.00 F	*- F
6	1		*L / F UPPER BRACKET (WCP)	Deformed	70.00 F	*25.00 F
7	1		*FRONT GRILLE (WCP)	Not Necessary	390.00 F	*- F
8	1		*R / F GARNISH W/CHROME MOULDING - FOG LAMP (WCP)	Not Necessary	45.00 F	*- F
9	1		*L / F GARNISH W/CHROME MOULDING - FOG AMP (WCP)	Missing	45.00 F	*45.00 F
10	1		*LEFT FOG LAMP (WCP)	Not Necessary	250.00 F	*- F
11	1		*TOW COVER (WCP)	Not Necessary	14.00 F	*- F
12	1		*L / F HEAD LAMP WATER JET (WCP)	Distorted	90.00 F	*73.00 F
13	1		*L / F HEAD LAMP WATER JET TOP COVER (WCP)	Deformed	30.00 F	*17.00 F
14	1		*L / F BRACKET SUPPORT (WCP)	Deformed	14.00 F	*13.00 F
15	1		*L / F FENDER (WCP)	Bent	380.00 F	*380.00 F
16	1		*L / F FENDER LINER (WCP)	Deformed	80.00 F	*80.00 F
17	10		*L / F FENDER LINER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
18	1		*L / F FENDER - EMBLEM - V6T (WCP)	Necessary	48.00 F	*48.00 F
19	1		*L / F UNDER LIP - FR BUMPER (WCP)	Deformed	75.00 F	*75.00 F
20	1		*BONNET (WCP)	Bent	1,400.00 F	*1,400.00 F
21	1		*INSULATOR (WCP)	Not Necessary	115.00 F	*- F
22	1		*INSULATOR CLIPS (WCP)	Not Necessary	2.00 F	*- F
23	1		*LOCK - BONNET (WCP)	Not Necessary	65.00 F	*- F
24	1		*L / HINGE - BONNET (WCP)	Repair	48.00 F	*- F
25	1		*R / HINGE - BONNET (WCP)	Repair	48.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*LEFT HEAD LAMP (WCP)	Cut	840.00 F	*840.00 F
27	1		*L / F DOOR (WCP)	Not Necessary	890.00 F	*- F
Supplementary #1						
28	1		*L / OUT SENSOR FR BUMPER (WCP)	Distorted	35.00 F	*75.00 F
29	1		*UNDER FR COVER (WCP)	Deformed	55.00 F	*55.00 F
30	1		*FR SUPPORT TOP GARNISH (WCP)	Deformed	75.00 F	*35.00 F

F=Franchise part.

Sub Total (S\$)	5,982.00	3,949.00
+ Margin on L,N Items 15.00/15.00% (S\$)	897.30	592.35
Total Parts (S\$)	6,879.30	4,541.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE / REPLACE / STRAIGHTEN / RE ALIGN :FR BUMPER,L/F FENDER,L/F DOOR ,BONNET	New	1,000.00	500.00
2	TO PUTTY / RE SPRAY PAINT :FR BUMPER,L/F FENDER,L/F DOOR,BONNET	New	1,000.00	650.00
3	TO CHECK WIRE	New	60.00	30.00
4	TO RE SETTING ELECTRICAL SYSTEM	New	350.00	150.00
Gross Labour Cost (S\$)			2,410.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >