

22/03/2003

ASS. REC. BY:

REF: CS/CT118018078/Gcd3

Special Instruction:

Surveyor:

Guo Qiang

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

4/10/18 @ 4:33pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLN 3024X

Insured:

GBC 5078D

at Workshop m/s

Car Times Autolution

Tel:

6471 5111

of

160 Sin Ming Drive # 02-04

Policy No:

DMCVSN3025961801

Claim No:

SNM18D04751C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

2/10/18

CA./REV/REP./REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9am @ 5/10/18

Person Contacted:

Angie

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 3024X-X
	GBC 5078D-NBA/INC17004063/Y
	DOA: 25/2/17

Surveyor

Xhe

REF: CTI

4756H

ASSIGNMENT

From

Date:

5/10/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLN 3024X

at Workshop m/s

Car times Autolution

of

160 Sin Ming Drive # 02-04

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1 up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLN3024X

Yr Regn:

28 Apr 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

C.C:

1496

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

18085

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GK81006541

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

N

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

05-10-18

Survey held at

w/s

5pm

Des. of Damages: Ftz / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Finalized \$ 2865.6 with Yuki (Red 3891.40, 57%)

RECEIVED 19 JUN 2019

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) \$ - RS \$



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format:

TP

Lump Sum / I.B. 2865.60

220

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Oct 2018		04 Oct 2018 16:33 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HONG-LE FLORAL & TRADING , Co. Reg. No.: 52825184L		
Main Claimant:	CHIA PEI SHAN(XIE PEISHAN) , ID: S8004756H		
Vehicle Reg. No.:	SLN3024X	Date of Loss:	02/10/2018 19:00 - :59
Claim Type:	TP / SNM18D04751C02	Policy/Cover Note No.:	DMCVSN3025961801 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC5078D	Policy No. (Claimant):	S118V03199/VPC/R01
		Excess:	S\$0.00
Repairer:	Car Times Autolution Pte Ltd (HQ) 160 Sin Ming Drive #02-04, AutoCity, 575722 Sin Ming - Tel: 6471 5111		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/10/2018]		
Driver/Custodian (Insured):	KOH SOON KIM (72 / Male), NRIC: S0255282E, Tel: +6597161234		
Adj Asg. Remarks:	NO EST, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4756H
Vehicle Details	
Vehicle No.:	SLN3024X
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B3537683
Chassis No.:	GK81006541
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,402.00
Original Registration Date:	28 Apr 2017
First Registration Date:	28 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$8,402.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2027
PARF Rebate Amount:	\$6,301.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$44,445.00
Total Rebate Amount:	\$50,746.00

The information contained herein is correct as at 10 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/10/2018 12:12
Date Of Accident	02/10/2018 19:05
Exact Location Of Accident	GANTRY OF BLK.229 JURONG EAST ST.21(NEXT TO SPC)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN3024X
Insured/Policyholder	
Name Of Registered Owner	CHIA PEI SHAN(XIE PEISHAN)
NRIC No	S8004756H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96552269
Alternative Phone No	OFFICE-96552269

Vehicle Particulars

Manufacturer	HONDA
Model	SHUTTLE-1.5 G CVT ABS (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SI18V03199/VPC/R01
Cover Note Number	

Driver

Name of Driver	JEVAN ARIFIN KWAN
NRIC No	S8376025G
Date Of Birth	10/08/1983
Occupation	INDOOR
Date Of Driving Pass	24/04/2010
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96552269
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 5 JURONG EAST ST.32 #07-02
SINGAPORE 609479.

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own Vehicle -
-

Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : CHIA PEI SHAN
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: VIDEO RECORD IS TOO BIG

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBC5078D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver KOH SOON KIM

NRIC/Passport Number S0255282E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form; and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected (under (d) above) may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law-enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name
NRIC/IN No.:

SKETCH PLAN

Swire East
Ave



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/10/18 @ 19.05 hours, I was stationary at the gateway of the carpark, the veh. B (GBC 5078D) suddenly reverse without checking and hit onto my front portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

CARTIMES

autolution

PG.1....

Vehicle No:SLN 3024 Y

MODEL:HONDA SHUTTLE

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>			
1	Front RHS headlamp <i>X - CRA</i>	2235.00	1650
1	Front bonnet <i>X - BT</i>	895.00	642
2	Front bonnet hinges <i>X NN</i>	90.00	
1	Front bumper <i>X repair</i>	1200.00	
2	Front bumper side retainers <i>X NN</i>	40.00	
1	Front reinforcement bar <i>X</i>	235.00	
1	Front bonnet insulator <i>X NN</i>	145.00	
1	Front bonnet lock <i>X</i>	125.00	
1	Front grille <i>X</i>	315.00	
1	Front grille chrome <i>- CRA</i>	285.00	
1	Front bumper top garnish <i>X</i>	85.00	
1	Front tow cover <i>X</i>	45.00	
1	Front RHS foglamp cover lower <i>X NN</i>	65.00	
1	Front RHS foglamp cover upper <i>X</i>	75.00	
		5835.00	0.00
		20% 1167.00	20%
		4668.00	
<u>SPECIAL NETT ITEMS</u>			
1 SETS	Front bonnet insulator clips <i>- MC</i>	40.00	10
1	Front bumper clips <i>- MC</i>	60.00	20
1	Front bumper top garnish clips <i>X NN</i>	30.00	X
1	Front number plate w/holder <i>X</i>	45.00	X
	SPECIAL NETT	175.00	
	TOTAL PARTS	4843.00	

2577

2%: 2061.6

30

CARTIMES

autolution

PG.2

Vehicle No.SLN 3024 X

MODEL:HONDA SHUTTLE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEY OF ADJUSTME
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	900.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	700.00	400
3	To remove and refix wiring and check all electrical components at damaged areas for proper functions	120.00	X 30
4	To provide anti-rust treatment on affected areas	150.00	X NN
	Labour Total :	1870.00	730
	TOTAL (PARTS & LABOUR):	6713.00	

3 Days.

part by mt.

before paint photos.

Leo Qian - 82880282

05/10/18

6757.00

2865.6

[Signature]
11/10/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUPPLEMENTARY PARTS

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	<u>LIST ITEM</u>		
1	Front RHS headlamp bracket	<i>100A</i> \$55.00	
	SUPPLEMENTARY PARTS total.	\$55.00	

20% 44

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118018078/GCD3N2

Date: 20/06/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3025961801
Claimant Vehicle No :	SLN3024X	Insured Vehicle No :	GBC5078D
Date of Loss:	02/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D04751C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN3024X	Engine No:	L15B3537683
Make & Model:	HONDA SHUTTLE, 1.5 G CVT ABS (A)	Chassis No:	GK81006541
Reg. Date:	28/04/2017 (Man. Year: 2016)	Odometer:	18085 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,887.00	2,135.60	2,751.40	56.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,870.00	730.00	1,140.00	60.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,757.00	2,865.60	3,891.40	57.59

INSPECTION

Date of Assignment:	04/10/2018	
Date Inspected:	05/10/2018	Inspected At: Car Times Autolution Pte Ltd (HQ) 160 Sin Ming Drive #02-04, AutoCity Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Jun 2019)	
Parts:	N/A	HONDA SHUTTLE 1.5 G CVT ABS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3024X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RHS HEADLAMP	Cracked	2,235.00 FL	*1,650.00 FL
2	1		*FRONT BONNET	Bent	895.00 FL	*642.00 FL
3	2		*FRONT BONNET HINGES	Not Necessary	90.00 FL	*- FL
4	1		*FRONT BUMPER	Repair	1,200.00 FL	*- FL
5	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	40.00 FL	*- FL
6	1		*FRONT REINFORCEMENT BAR	Not Necessary	235.00 FL	*- FL
7	1		*FRONT BONNET INSULATOR	Not Necessary	145.00 FL	*- FL
8	1		*FRONT BONNET LOCK	Not Necessary	125.00 FL	*- FL
9	1		*FRONT GRILLE	Not Necessary	315.00 FL	*- FL
10	1		*FRONT GRILLE CHROME	Cracked	285.00 FL	*285.00 FL
11	1		*FRONT BUMPER TOP GARNISH	Not Necessary	85.00 FL	*- FL
12	1		*FRONT TOW COVER	Not Necessary	45.00 FL	*- FL
13	1		*FRONT RHS FOGLAMP COVER LOWER	Not Necessary	65.00 FL	*- FL
14	1		*FRONT RHS FOGLAMP COVER UPPER	Not Necessary	75.00 FL	*- FL
15	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*20.00 FS
16	1		*FRONT BUMPER TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
17	1		*FRONT NUMBER PLATE W/HOLDER	Not Necessary	45.00 FS	*- FS
18	1		*SETS FRONT BONNET INSULATOR CLIPS	Necessary	40.00 FS	*10.00 FS
19	1		*FRONT RHS HEADLAMP BRACKET	Cracked	55.00 FL	*55.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,065.00	2,662.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,178.00	526.40
Total Parts (S\$)	4,887.00	2,135.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS	New	900.00	300.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	700.00	400.00
3	TO REMOVE AND REFIX WIRING AND CHECK ALL ELECTRICAL COMPONENTS AT DAMAGED AREAS FOR PROPER FUNCTIONS	New	120.00	30.00
4	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREAS	New	150.00	0.00
Gross Labour Cost (\$\$)			1,870.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >