

22/03/2002

ASS. REC. BY:

REF: CS/EQT18018081/Avd3d Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): Joel Goh of EQT Date/Time: 5/10/18 @ 9.44am

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: Q10 9749 Insured: SKT9575Mat Workshop m/s MS Car Auto Tel: 9725 4442of 8 Keki Bkt Ave 4 # 01-07Policy No: _____ Claim No: DM18HC002651-JG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01/10/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 10am @ 5/10/18 Person Contacted: Desmond H.O.D. Endorsement: _____Vehicle: IN/OUT

Date/Time	Action/Instruction (x) Estimate
	<u>Q10 9749 - x</u>
	<u>SKT9575M - CS/EQT18018076/Tlsd3</u> DOA: <u>1/10/18</u>
<u>3/6/19</u>	<u>@ 2:13pm Desmond will prepare the est.</u>
<u>8/7/19</u>	<u>@ 1:52pm Adrian spoken to Desmond, they have submitted independent report</u>

REF: EQ1

ASSIGNMENT

From: Date: 5/10/18

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Q1Q 9749

at Workshop m/s MS CAR AUTO
of 8kaki Bkt Ave 4 # 01-07

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: Q1Q 9749 Yr Regn: 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha C.C. 250

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: - T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: PMYSG 4010J 0000 187

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S(Rim) / STD A/Rim or

Tyre Size: F: 180/70 R15

R: 140/70 R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 05/10/18 @ 0451pm

Survey held at MS CAR AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP EQ.

Repair Range: 2K-3K. 04 Days.

08/07/19 St. S.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 8/7- typist

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format: PRS

Lump Sum / I.B.I. (\$)

TOTAL

Nivitha (LKK Auto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Friday, 5 October 2018 9:49 AM
To: Weng Kit
Cc: 'Jerone'; assignments@lkkauto.com
Subject: RE: Our Ref: QTQ 9749 (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING QTQ 9749 & SKT9575M (EQ) ALONG WEST COAST HIGHWAY ON 1 OCTOBER 2018
Attachments: 20181004174808959.pdf

Without Prejudice

Dear Weng Kit

We do not agree with your surveyors and will appoint LKK to conduct PRS.

Dear LKK

Please assist on this PRS.

Best Regards,

Joel Goh

Executive | Claims




EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190

www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Weng Kit [mailto:wengkit@chiaarul.com]

Sent: Friday, October 5, 2018 9:41 AM

To: Joel Goh

Cc: 'Jerone'

Subject: RE: Our Ref: QTQ 9749 (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING QTQ 9749 & SKT9575M (EQ) ALONG WEST COAST HIGHWAY ON 1 OCTOBER 2018

Dear Joel,

We refer to your email below.

Our client is not agreeable to your list of motor surveyors.

We are instructed by our client to propose the list of their surveyor as the mutual surveyor / single joint expert for your consideration as follows:

Mr. Patrick	Carlink Consultancy
Mr. Dave	Sincere Appraisal

Best Regards,

Mr Weng Kit
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted, lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

From: Joel Goh [mailto:joel.goh@eqinsurance.com.sg]

Sent: Friday, October 5, 2018 8:58 AM

To: Weng Kit

Cc: 'Jerone'

Subject: RE: Our Ref: QTQ 9749 (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING QTQ 9749 & SKT9575M (EQ) ALONG WEST COAST HIGHWAY ON 1 OCTOBER 2018

Without Prejudice

Save As To Costs

Dear Weng Kit,

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108
7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee

9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070
11) Infiniti Appraisal Service Tel: 96684818 / 90099001 Fax: 64587432	

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Weng Kit [mailto:wengkit@chiaarul.com]

Sent: Thursday, October 4, 2018 5:51 PM

To: EQI PRS

Cc: 'Jerone'

Subject: Our Ref: QTQ 9749 (wk) PRE-REPAIR SURVEY NOTICE ACCIDENT INVOLVING QTQ 9749 & SKT 9575M ALONG WEST COAST HIGHWAY ON 1 OCTOBER 2018

Dear Sirs,

We refer to the above matter.

Attached is a copy of our pre-repair survey notice dated 4 October 2018 for your attention.

Best Regards,

Mr Weng Kit
M/s Chia S Arul LLC
151 Chin Swee Road
#03-09 Manhattan House
Singapore 169876
Tel: (65) 6733 4647 Fax: (65) 6733 8183

This e-mail is from M/s Chia S Arul LLC, a firm of Advocates and Solicitors in Singapore, and is intended solely for the named addressee. It contains confidential and /or legally privileged information. If the e-mail has reached you in error, please delete the e-mail immediately and inform us of the error. You may contact us at info@chiaarul.com. Internet communications cannot be guaranteed to be secured or error-free as information could be intercepted, corrupted,

lost, arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the context of this message which arise as a result of Internet transmission.

CHIA S ARUL LLC
ADVOCATES & SOLICITORS
UEN 201330709H

ARULCHELVAN S

Our Ref : QTQ 9749 (wk)

Your Ref : To be advised

4 October 2018

EQ Insurance Company Limited

BY EMAIL

Dear Sirs,

RE: PROPERTY DAMAGE CLAIM
CLAIMANT : TEOH TEN WEI
ACCIDENT INVOLVING QTQ 9749 & SKT 9575M ALONG WEST COAST
HIGHWAY ON 1 OCTOBER 2018
PRE-REPAIR SURVEY NOTICE

1. We act for Teoh Ten Wei, the owner of motor vehicle no. QTQ 9749 which was involved in the aforesaid accident.
2. We hereby in compliance with the Pre-Action Protocol for Non-Injury Motor Accident Claims, Appendix C of the State Courts Practice Directions Amendment No. 1 of 2016 ("the NIMA Protocol") give you **NOTICE** that we are claiming against your insured motor vehicle no. SKT 9575M for damages, costs and disbursements as a result of your insured driver's negligence.
3. Please let us know if you wish to conduct a pre-repair survey on our client's motor vehicle at:

Workshop	MS Car Auto Pte Ltd
Address	8 Kaki Bukit Avenue 4 #01 - 07 Premier @ Kaki Bukit Singapore 415875
Contact Person	Mr. Desmond (9725 4442)

4. Pursuant to paragraph 2.3 of the NIMA Protocol, in the event we do not receive your response within next two (2) working days (excluding any Saturday, Sunday or public holiday), our client will instruct the workshop to commence appraisal and repairs to the damaged motor vehicle without further reference to you.
5. Please advise the appointed surveyor to endorse on page 2 of this letter after the completion of each inspection.

Yours faithfully,

MR ARULCHELVAN S
cc: Client (By Email)

151 CHIN SWEE ROAD • #03-09
MANHATTAN HOUSE • SINGAPORE 169876
TEL : (65) 6733 4647 • FAX : (65) 6733 8183 (not for Service of Court documents)
EMAIL : info@chiaarul.com

M/s Chia S Arul LLC
Page 2

Our Ref : QTQ 9749 (wk)

Your Ref : To be advised

PRE-REPAIR SURVEY (1)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

PRE-REPAIR SURVEY (2)
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

POST-REPAIR SURVEY
WORKSHOP:

SURVEYOR:

Name:
Date/Time:

Name of Surveyor:
Contact Number:
Date/Time:

Enquire Vehicle & Owner Information (Vehicle No. SKT9575M As At 01 Oct 2018 / 18:00:00)**Law Firm Search Details****Search Reason:** Insurance claim in relation to traffic accident**Law Firm Case No.:** MS**Current Owner Details****Owner ID Type:** Singapore NRIC**Owner ID:** S8508746J**Owner Name:** CHUA KANG WEI BJORN (CAI KANGWEI)**Registered Address Type:** HDB / HUDC**Registered Block/House No.:** 42**Registered Street Name:** PASIR PANJANG HILL**Registered Unit No.:** # 02 - 05**Registered Building Name:** -**Registered Postal Code:** 118894**Current Vehicle Details****Vehicle No.:** SKT9575M**Make Description/Model:** AUDI / A6 2.8 FSI MU**Insurance Company Name:** EQ INSURANCE COMPANY LTD

Veron Chen (LKKAUTO)

From: MS Car Auto <mscarautopl@gmail.com>
Sent: Monday, 8 July 2019 1:59 PM
To: SUR
Subject: QTQ 9749 Card
Attachments: CCF08019_0002.pdf

Warmest Regards,
Desmond Ng

MS Car Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-07
Premier @ Kaki Bukit
Singapore 415875
Telephone: 6385-1838
Fax : 6386-1838

SEKUTUPAN PERALATAN
JALAN PENGANGKUTAN JALAN

DSSCF0JY

No Pendaftaran	Q109749
N.S. ID	880919105125
Nama Pemunya/ Pendaftaran	YEON IEN MEI
Alamat	NO 1027 JALAN SERAI UTAMA 3/3 TAMAN SERAI UTAMA 81400 SERAI JOHOR
Nr. Chassis No. Enjin	PHYSG4010J0000187 / 63H4E-0012292
Dagang/ Nama Dagang	YABHIA / XMAX
Kepunyaan Enjin	250
Dagang Dagang	PETROL
Status Asas	PEMASANGAN TEMPATAN
Kelas Kegunaan	MOTOSIKAL
Jenis Dagang/ Jenis Dagang	MOTOSIKAL / 2018
Tarikh Pendaftaran	03/04/2018
P.D. M/S. G. K/BIN	
Syarat Pendaftaran 1	
Syarat Pendaftaran 2	
Syarat Pendaftaran 3	

PROPOSAL FORM
NOTICE: AICPA / CFP® / CPA / CFP® / CPA[illegible]

PLANTING FORM 17-5A



SINGAPORE POLICE FORCE



T/20181002/2039

1 of 3

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20181002/2039

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/10/2018 11:45	Vide Report No.:	Station Diary No.: 66
--	------------------	--------------------------

Informant's Particulars

Name of Informant: TEOH TEN WEI	Address: C/O Tanjong Pagar Terminal Rd J PSA Tanjang Pagar Terminal SINGAPORE		
ID Type / ID No.: FIN NO / G8132681P	Contact No.:	Mobile: 98189453	
Nationality: MALAYSIAN	Home/Office:	Email:	
Sex: Male	Age: 30	Date of Birth: 19/08/1988	Type of Informant: Rider
Race: Chinese	Language:		Institution / School Name:
Occupation: Lorry driver	Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 01/10/2018 18:00	Type of Location: Straight Road
Location: Along Road 1 WEST COAST HIGHWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QTQ9749	Motorcycle	YAMAHA		White	Slightly Damaged	0
SKT9575M	Car	AUDI		Black	Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20181002/2039

CONTINUATION OF REPORT

Rider			
Name	TEOH TEN WEI	ID No.	G8132681P
Related Vehicle	QTQ9749 (Motorcycle)	Contact No.	98189453
Hospital/Clinic	SHENTON FAMILY MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	01/10/2018	Date Discharge	01/10/2018
No. of Days granted Medical Leave	14	Degree of Injury	Slight
Driver			
Name	CHUA KANG WEI BJORN (CAI KANGWEI)	ID No.	S8508746J
Related Vehicle	SKT9575M (Car)	Contact No.	90475274
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 1/10/18 at around 6pm, I was riding (QTQ9749, White, Yamaha) along West Coast Highway. As the traffic was heavy, I weaved between the cars and continued my way straight. While riding, a car (SKT9575M, Audi, Black) from the other side of the road had wanted to U-turn into my lane. However, he did not notice me and had knocked my motorcycle. The front of the car had hit the right side of my motorcycle. I lost control and fell to the left.

I suffered pain on my right wrist, which became swollen and bruised, and was given 14 day of MC (MC no: DUX65414, Shenton Family medical clinic Duxton) from 1/10/18 to 14/10/18. My motorcycle suffered scratches on the front, the right fairing of my motorcycle became slightly detached and its front wind shield came out of its original position. I estimate the total cost of damage to be around SGD\$2500 to SGD\$3000. The car had suffered a large dent at its front left but its driver and passenger was not injured.



**SINGAPORE
POLICE FORCE**



T/20181002/2039

3 of 3

Police Station Of Origin:
Geylang N.P.C
132 Paya Lebar Road SINGAPORE 409014
Tel No: 1800-8486999

Report No. T/20181002/2039

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 2 NG KA WAI

W/SGT JI E

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI 2 SITIMARSITA BINTE BOHARI

Contact No.: 65476219

Signature Of Informant:

Date/Time:

02/10/2018 11:45

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
EQ INSURANCE COMPANY LTD		Ref: CS3/EQI18018081/Avd3e2		
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date: 08-07-2019		
Code: EQI				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKT 9575M	Veh. Inspected	QTQ 9749	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM18HO02651-JG	Excess (\$)	0.00	
Assign From	JOEL GOH	Assign Date	05/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA	c.c	250	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	PMYSG4010J0000187	Colour	WHITE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	180/70 R15	DUNLOP	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R14	DUNLOP	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.				
5. General Information				
Accident Date	01/10/2018	Inspect Date / Time	05/10/2018 (04:51 PM)	
Survey held at	MS CAR AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/EQI18018081/Avd3e2

Inspected By



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.