

22/07/2002

ASS. REC. BY:

REF:

CS/EG718018160 Mrber

Special Instruction:

Supervisor:

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGT

Date/Time:

08/10/2018 2:05pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 7657U

Insured:

GBB 9573U

at Workshop m/s

Liu's Brother

Tel:

6741 1730

of

Blk 1 Kaki Bukit Ave 6 #01-01

Policy No:

Claim No:

GBB 9573U / SL/p1

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/03/2018

CA / REV / REP. / REV 24 HRS w/p

09/10/2018

H.O.D. Endorsement:

Date/Time:

08/10/2018 2:43pm

Person Contacted:

Susan

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

GBC 7657U - X

GBB 9573U - X

12/10/18

Sent pending est email inform insurance

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 8 October, 2018 2:05 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GBB9573U / TP : GBC7657U/LKK / DOA : 09/03/2015
Attachments: GBC7657U - SAS.pdf; GBC7657U - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **LIU'S BROTHER AUTO**,

ADDRESS : NO 1 KAKI BUKIT AVENUE 6
#01-01 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883

PERSON TO CONTACT : SUSAN @ 6741 1730

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Please advise the consistency of damages to third party vehicle. Obtain estimate from workshop and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached is TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li (Ms)
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

www.ergo.com.sg



ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

Date: 08.10.2018
 Our Reference: GBB 9573U/SL/pl
 Your Reference: GBC 7657U
 To: LIU'S BROTHER AUTO

Sent via Fax
 or
 Email

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBC 7657U
 Insured's Vehicle: GBB 9573U
 Date Of Accident: 03.03.2015

We acknowledge receipt of your request for PRS on: 08.10.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- Your request for inspection does not have your client's GIA report, kindly forward a copy.
- We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- Our Insured's driver has not reported the accident to us todote.
- Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:
 Assignment Date: _____
 Assignment Time: _____

Workshop use only:
Assessor attended workshop on:
 Date: _____
 Time _____
 Inspector: _____

Remarks:

Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

 Workshop Acknowledgement & Stamp.
 Note: Our Inspection is on a without admission to liability basis.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-154449

Date of Request: 05/10/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP
1 Kaki Bukit Ave 6 #01-01
Auto Bay@Kaki Bukit
Singapore 417883

Dear Sir/Madam,

Enquiry Date 05/10/2018
Enquiry By Susan Low Siew Yian
TP Vehicle No. GBB9573U
Accident Date 03/03/2015

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBB9573U	ERGO Insurance Pte. Ltd.	24/03/2014-23/03/2015	6829 9199

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2015 20:22
Date Of Accident	03/03/2015 16:00
Exact Location Of Accident	33 upper cross multi storey carpark
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC7657U
Insured/Policyholder	
Name Of Registered Owner	STVE PTE LTD
Co Reg No	198703585C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-62262751

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Reporting Only
Vehicle Category	Commercial Vehicle

Insurance Company

Name of Insurance Company	First Capital Insurance Ltd
Type Of Coverage	Third Party
Fleet Policy	Yes
Policy Number	D-12O39930MFCV
Cover Note Number	N.A

Driver

Name of Driver	LEE WENG CHEONG
NRIC No	S2160142Z
Date Of Birth	12/07/1941
Occupation	Outdoor
Date Of Driving Pass	01/09/1966
Driving Experience	48 Years And 6 Months
Gender	Male
Mobile Number	(Local) +65-98219587
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	N.A
	N.A
Postcode	N.A
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Other - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	Collision- Head to Rear (TP Hit Insured)
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

I was already indicate the signal to reverse when suddenly vehicle GBB9573U from the rear trying to overtake and hit the side of my vehicle GBC7657U. The driver of GBB9573U keep saying that my vehicle doesn't have the right to park at the lot which i intend to park and cause the delay as result the driver decide to overtake my vehicle GBC7657U. I wish to indicate that my vehicle was a season parking holder that the mscp. No injuries and thats all

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB9573U
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the centers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available a/afterward.

Consent under the Personal Data Protection Act (PDPA)

- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all driver(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or;
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are collected by any of the Insurers and/or GIA or their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY
MARS OFFICER
SHAMEER DIN
S7812538A


[Signature]
9/1/15

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was already indicate the signal to reverse when suddenly vehicle GBB9573U from the rear trying to overtake and hit the side of my vehicle GBC7657U. The driver of GBB9573U keep saying that my vehicle doesn't have the right to park at the lot which i intend to park and cause the delay as result the driver decide to overtake my vehicle GBC7657U. I wish to indicate that my vehicle was a season parking holder that the mscp. No injuries and thats all

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Reporting only

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY MARS OFFICER - SHAMEER,
S7812538A

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

9 March, 2015 10:18 am

Date/Time:

9 March, 2015 10:18 am

Date: 08.10.2018
 Our Reference: GBB 9573U/SL/pl
 Your Reference: GBC 7657U
 To: LIU'S BROTHER AUTO

Sent via Fax
 or
 Email liusbro@ymail.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBC 7657U
 Insured's Vehicle: GBB 9573U
 Date Of Accident: 03.03.2015

We acknowledge receipt of your request for PRS on: 08.10.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

*

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
 Your request for inspection does not have your client's GIA report, kindly forward a copy.
 We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
 Our Insured's driver has not reported the accident to us todate.
 Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:	<u>Pei Li</u>	6829 9194	claims@ergo.com.sg
Signature:			FAX : 6829 9247

Assessor use only:

Assignment Date: _____
 Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
 Time: _____
 Inspector: _____

Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	1196N
Vehicle Details	
Vehicle No.:	GBC7657U
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL
Primary Colour:	White
Manufacturing Year:	2013
Engine No.:	1KD2310791
Chassis No.:	JTFAT35Y00K202442
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	19 Sep 2013
First Registration Date:	19 Sep 2013
Transfer Count:	1
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	18 Sep 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$71,001.00
COE Rebate Amount:	\$35,066.00
Total Rebate Amount:	\$35,066.00

The information contained herein is correct as at 10 Oct 2018

OK



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBC7657U150313

Estimate

Customer

Name: ERGO Insurance Pte Ltd

Address Motor Claims Department

5 Temasek Boulevard #04-01

Suntec Tower Five Singapore 038985

Date: 08-10-18

Vehicle No: GBC7657U

Model/Make: Toyota Dyna

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Tailgate	\$ 1,698.00	
2	Tailgate Side Lock	\$ 394.00	
3	Corner Rubber	\$ 141.00	
4	Tailgate "Toyota" Sticker	\$ 175.00	
5	"70 Km/h" Sticker	\$ 12.00	SN 10SN
6	"6 PAX" Sticker	\$ 12.00	SN 10SN
Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc		\$ 600.00	300
To putty & spray painting & including touch up paint on accident affected		\$ 600.00	300

Total Parts & Labour of estimate for damaged vehicle

\$ 3,632.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- Carer must be resurveyed before a spray painting
- To replace damaged parts during resurvey
- Purchases are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

not authorized
Lok
9/10/18
4/5
Take photo After repair
3 day

4/5 \$ 700
3 day

P-316
252
P 237
S-N+20
labour+600
\$ 700



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18018160/Urbe2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 07-11-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBB 9573U	Veh. Inspected	GBC 7657U
Policy No.		Coverage (\$)	0.00
Claim No.	GBB9573U/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	08/10/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTFAT35Y00K202442	Colour	WHITE
Odometer	87254	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/75 R15	YOKOHAMA	5 mm
L/H Front Tyre	195/75 R15	YOKOHAMA	5 mm
R/H Rear Tyre	195/75 R15 (D)	YOKOHAMA	5/5 mm
L/H Rear Tyre	195/75 R15 (D)	YOKOHAMA	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/03/2015	Inspection Date	09/10/2018
Survey held at	LIU'S BROTHER AUTO WORK SHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 7657U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,698.00	-
1	REAR TAILGATE SIDE LOCK	TO REPAIR SEE LABOUR	394.00	-
1	REAR CORNER RUBBER	TORN	141.00	141.00
1	REAR TAILGATE "TOYOTA" STICKER	NECESSARY	175.00	175.00
	LESS 25% DISCOUNT		-	-79.00
			2,408.00	237.00
SPECIAL NETT ITEMS				
1	REAR "70KM/H" STICKER (SN)	NECESSARY	12.00	10.00
1	REAR "6 PAX" STICKER (SN)	NECESSARY	12.00	10.00
			24.00	20.00
LABOUR				
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS. INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND REAR TAILGATE SIDE LOCK.		600.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED.		600.00	300.00
			1,200.00	600.00
GRAND TOTAL			3,632.00	857.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				700.00

Report Ref No. CS/EGI18018160/Urbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.