

22/03/2002

ASS. REC. BY:

REF: 093

/ALH18018175/R1cbzz

Special Instruction:

Surveyor

Maimen.

ASSIGNMENT (Office)

From (Person):

Chin Lee Yung

of

AL7

Date/Time:

08/10/2018 11:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 1231L

Insured:

YN 6608M

at Workshop m/s

Kuan Her

Tel:

8299 0599

of

Blk 5038 AMK Ind Park 2 #01-405

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

03-10-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS WPI

09-10-2018

H.O.D. Endorsement:

Date/Time:

08-10-2018 11:34am

Person Contacted:

James

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLQ 1231L - X
	YN 6608M - X
	Dismantle: 10/10/2018.

REF: ALG

9761W

ASSIGNMENT

From: Date: 9/10/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 1231L

at Workshop m/s Lian Her Motor

of BLK 5038 Amk Ind. Park 2 #01-405

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLQ 1231L Yr Regn: 2017 Jun

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel HYBRID 1.5 c.c. 1496

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 116183 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RA 312 30 388

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 03/10/18 D.O.I. 09/10/18

Survey held at Lian Her Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/10 Submit DAR report.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6.

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS SI

) Photos

) Others

TOTAL

Report Format: DAR

Lump Sum / I.B.I: (\$)

180

20

200

-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE YN6608M AND SLQ1231L ON 03/10/2018

From: Chin, Lee-Ying
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: Monday, 8 October, 2018 10:58:27 AM
Attachments:  20181004170146.pdf  20181005164004.pdf  20181005174413.pdf

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON
RAYNEY WONG KENG LEONG
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALLI D/O MUNIANDY
SEGA PARAM
TIWARY ANURADHA
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

✓ **HEAD OFFICE**

133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch: 490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

✓ **HEAD OFFICE**

TEL : (65) 65342811 (Hunting)
FAX : (65) 65356802 (General)
✓ (65) 65355905 (Litigation)
E-mail : yvonnelim@visionlawllc.com

BRANCH

TEL : (65) 63580703
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref : SLQ 1231 L (PM)
Your Ref : YN 6608 M

05 October 2018

BY EMAIL ONLY

AIG ASIA PACIFIC INSURANCE PTE. LTD.
78 Shenton Way
#07-16 AIG Building
Singapore 079120
[Attention : Motor Claim Department]

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SLQ 1231 L & YN 6608 M ON 03 OCTOBER 2018 ALONG
MARINA LINK TOWARDS ECP AT ABOUT 1035 HOURS
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email on even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : **LIAN HER MOTORS**
Block 5038 Ang Mo Kio Avenue 3
#01-405 Ang Mo Kio Industrial Park 2
Singapore 569541
Contact Person : **Mr. James @ 8299 0599 (Please call before going)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

JANICE HAN
(HEAD OFFICE)

cc: SLQ 1231 L – By fax: 64816131 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature)

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	9761N
Vehicle Details	
Vehicle No.:	SLQ1231L
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL HYBRID 1.5X AUTO
Primary Colour:	Gold
Manufacturing Year:	2016
Engine No.:	LEB5930399
Chassis No.:	RU31230388
Maximum Power Output:	112.0 kW (150 bhp)
Open Market Value:	\$27,002.00
Original Registration Date:	28 Jun 2017
First Registration Date:	28 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,110.00
COE Rebate Amount:	\$43,637.00
Total Rebate Amount:	\$47,387.00

The information contained herein is correct as at 12 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/10/2018 16:08
Date Of Accident	03/10/2018 10:35
Exact Location Of Accident	MARINA LINK TWDS ECP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ1231L
Insured/Policyholder	
Name Of Registered Owner	L H CAR RENTAL PTE LTD
Co Reg No	200009761N
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96518951
Alternative Phone No	OFFICE-96518951

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5083404689-02
Cover Note Number	

Driver

Name of Driver	LIM KHENG FOOK
NRIC No	S1338451G
Date Of Birth	06/04/1958
Occupation	OUTDOOR
Date Of Driving Pass	09/06/1978
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96518951
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 165B PUNGGOL CTRL #06-159
Postcode	822165
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN - CIRCUMSTANCES OF THE ACCIDENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN6608M
Vehicle Make/Model/Colour	LORRY
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LIM KHENG FOOK
------	----------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLQ1231L

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

L.H CAR RENTAL PTE LTD

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

A = SLQ1231L
B = YH 6608M

SKETCH PLAN

MARINA LINK



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At approximately 1035am I, Mr Lim Kheng, took NRIC NO: S133845, driver of A (Vehicle SLQ1231L) was driving along MARINA LINK at the extreme left lane (Lane 1) towards MCK/EC.P. Suddenly the vehicle B (Lorry YH 6608M) cut into my lane from lane 3 and come into contact with vehicle A, causing the whole right side of vehicle A dented from front to back including the right side mirror.

He moved the lorry forward, parked and came down to apologise. Same time we exchange our particulars

DECLARATION

I/We declare the foregoing particulars are true in every respect.

L.H CAR RENTAL PTE LTD

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

(01) Bent (02) Dented (03) Distorted (04) Cracked (05) Cut (06) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary (12) Missing
(13) Torn (14) Unconfirmed (15) Not Working

ACTION (AC)

(1) Replace (✓) (2) Repair (X) (3) Check (?)
(4) Not Consistent (NC)

Aug 2005

[illegible]

Vehicle No: SLA 1231L

[illegible]

Assessor:

TGL m lui

12/10/18

Original Com.

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2018 Edit Reg		08 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LLMS LOGISTICS PTE LTD, Co. Reg. No.: -								
Main Claimant:	-								
Vehicle Reg. No.:	SLQ1231L	Date of Loss:	03/10/2018 00:00 - :59 [15 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 7401352504SG	Policy/Cover Note No.:	0999994402 (Comprehensive)						
Vehicle Reg. No. (Insured):	YN6608M	Policy No. (Claimant):							
		Excess:							
Repairer:	Lian Her Motors (HQ) Block 5038 Ang Mo Kio Avenue 3, #01-405 Ang Mo Kio Industrial Park 2, 569541 Ang Mo Kio - Tel: 82990599								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijie.Wui@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 17/10/2018]								
Claimant's Solicitor:	VISION LAW LLC - Tel: 65342811								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (09/10/2018): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									






































Claim Documents








































***SLQ1231L (7401352504SG)
[YN6608M]**

TP

-

**Oct 3 2018 12:00AM
[LLMS LOGISTICS PTE LTD]
Lian Her Motors**

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images											3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)									Thumbnail	Print		
1	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
2	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
3	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
4	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
5	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
6	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
7	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
8	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
9	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
10	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
11	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
12	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
13	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
14	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
15	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
16	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
17	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
18	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
19	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
20	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
21	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
22	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
23	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
24	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
25	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
26	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
27	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
28	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
29	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
30	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
31	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
32	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
33	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
34	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
35	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
36	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		
37	12/10/18 14:40	General View									 Load JPG	<input checked="" type="checkbox"/>		

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
41	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
42	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
43	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
44	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
45	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
46	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
47	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
48	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
49	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
50	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
51	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
52	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
53	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
54	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
55	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
56	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
57	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
58	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
59	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
60	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
61	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
62	12/10/18 14:40	General View	 Load JPG	<input checked="" type="checkbox"/>
63	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	12/10/18 14:41	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/10/18 09:29	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18018175/R1CBE2

Date: 17/10/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994402

Claimant Vehicle No : SLQ1231L

Insured Vehicle No : YN6608M

Date of Loss: 03/10/2018

Nature of Claim: TP

Claim No: 7401352504SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ1231L

Make & Model: HONDA VEZEL HYBRID, 1.5 Z (A)

Engine No: LEB5930399

Reg. Date: 28/06/2017 (Man. Year: 2016)

Chassis No: RU31230388

Colour: Brown

Odometer: 116183 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/10/2018

Date Inspected: 09/10/2018 Inspected At:

Lian Her Motors (HQ)
Block 5038 Ang Mo Kio Avenue 3, #01-405
Ang Mo Kio Industrial Park 2
Singapore 569541

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Dented	0.00 F	*- F
2	1		*FRT RH DOOR WING MIRROR	Cracked	0.00 F	*- F
3	1		*FRT RH FENDER	Repair	0.00 F	*- F
4	1		*REAR RH DOOR	Dented	0.00 F	*- F
5	1		*REAR RH FENDER	Dented	0.00 F	*- F
6	1		*HYBRID EMBLEM	Necessary	0.00 F	*- F
7	1		*REAR RIGHT WHEEL ARCH	Cut	0.00 F	*- F
8	1		*RIGHT ROCKER PANEL	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >