

22/03/2003

ASS. REC. BY:

REF: CS3/FWD18018180/Act22

Special Instruction:

Survivor:

Adrian

ASSIGNMENT (Office)

From (Person):

Aurora Li

of

FWD

Date/Time:

08/10/2018 1036am

Estimated Cost:

Bill to:

OD / IB / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 2576Z

Insured:

SLK 91800

at Workshop m/s

Sheng Li Lai

Tel:

of

2 Kaki Bukit Ave 2 # 01-36

Policy No:

Claim No:

PNCV2018 - 00000375

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/10/2018

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

08/10/2018 11:46am

Person Contacted:

Mr. LOW

Vehicle IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SLE 2576Z - NA / INC 18018180 / KL
	SLK 91800 - X
	Dismantle: 11/10/2018.

DA: 06/10/2018

REF:

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLE2576Z Yr Regn: 2016 / JulyType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: White A/C: Insured / Std / NI / NASp. Reading: 55224 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: Ru1120069Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R16R: 215/55R16BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. \_\_\_\_\_ D.O.I. 08/10/18Survey held at Sheng Li LaiDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP FWD PRS.

— Estimated repair range \$4,500 — \$6,500

*[Signature]*  
12/10/2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: PRQ

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)8050130

**Catherine Chong (LKK Auto)**

---

**From:** clara.li@fwd.com  
**Sent:** Monday, 8 October, 2018 10:38 AM  
**To:** assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com  
**Cc:** motorclaims.sg@fwd.com; lionel.tan@fwd.com  
**Subject:** FW: FWD Insured SLK9180D [EAL.2018.5972.MK.ya - SLE2576Z] (Our Ref: PNCV2018-00000375)  
**Attachments:** 181008-GIA of SLE2576Z.PDF

Hi LKK team,

Please refer to the email below and liaise with TP repairer for survey arrangement.

Attached is the TP GIA report.

Please create the case in Merimen.


Thank you.

Kind Regards

Clara Li  
Senior Executive, Claims

FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722  
E clara.li@fwd.com  
W fwd.com.sg



---

**From:** Clara Li Zirong - SGUser  
**Sent:** Monday, 8 October, 2018 10:36 AM  
**To:** 'yvonne@ealc.com.sg'

**Cc:** Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

**Subject:** FW: FWD Insured SLK9180D [EAL.2018.5972.MK.ya - SLE2576Z] (Our Ref: PNCV2018-00000375)

**WITHOUT PREJUDICE**

Dear Yvonne,

We will be appointing, M/s LKK AUTO CONSULTANTS PTE LTD, to conduct the pre-repair survey (PRS) on your client's vehicle, SLE2576Z. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

*\*Please note that contents of this email should not be construed as any admission of liability on the part of our insured and/ or insurers. We hereby maintain full reservation of rights and all defences available to us.*

*\*Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to [motorclaims.sg@fwd.com](mailto:motorclaims.sg@fwd.com). Thank you.*

Kind Regards

Clara Li

Senior Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E [clara.li@fwd.com](mailto:clara.li@fwd.com)

W [fwd.com.sg](http://fwd.com.sg)



---

**From:** Yvonne [<mailto:yvonne@ealc.com.sg>]

**Sent:** Monday, 8 October, 2018 10:30 AM

**To:** Clara Li Zirong - SGUser

**Cc:** Motor Claims SG - SG Common; Lionel Tan Tian Pei - SGUser

**Subject:** PRI: FWD Insured SLK9180D [EAL.2018.5972.MK.ya - SLE2576Z]

Our ref : 2018.5972.MK.ya - **SLE2576Z**

Your ref : **SLK9180D**

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

FWD Singapore Pte Ltd  
6 Temasek Boulevard #18-01  
Suntec Tower Four Singapore 038986  
Attn: Motor Claims Department  
**2 DAYS' PRE-REPAIR NOTICE**

Surveyor from M/s FWD Singapore Pte Ltd Vehicle <b>SLE2576Z</b> inspected as follows by Name:		
Before repair	Parts removed	After repair
_____ Signature	_____ Signature	_____ Signature
_____ Date/ Time:	_____ Date/ Time:	_____ Date/ Time:

Dear Sir/Madam,

**NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE**

**CLAIMANT: TAN KOK HAN ANDY (CHEN GUOHAN ANDY)**

**ACCIDENT INVOLVING SLE2576Z & SLK9180D ON 06 OCTOBER 2018 ALONG JOO CHIAT TERRACE TOWARDS MANGIS ROAD AT ABOUT 1310 HOURS**

We refer to the above matter wherein we are instructed to act for **TAN KOK HAN ANDY (CHEN GUOHAN ANDY)**, the owner of vehicle no. **SLE2576Z**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **SLE2576Z** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Sheng Li Lai  
No. 2 Kaki Bukit Ave 2,  
#01-36 Autohub Kaki Bukit,  
Singapore 417921.  
Tel: 91119222 (Mr Low)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,  
Yvonne Ang

East Asia Law Corporation  
No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413  
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	2993H

**Vehicle Details**

Vehicle No.:	SLE2576Z
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	L15B4400169
Chassis No.:	RU11200169
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,139.00
Original Registration Date:	14 Jul 2016
First Registration Date:	14 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$10,195.00

**Intended PARF Rebate Details**

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jul 2026
PARF Rebate Amount:	\$7,646.00

**Intended COE Rebate Details**

COE Expiry Date:	13 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$40,561.00
<b>Total Rebate Amount:</b>	<b>\$48,207.00</b>

The information contained herein is correct as at 11 Oct 2018

OK

workshop

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/10/2018 14:32
Date Of Accident	06/10/2018 13:10
Exact Location Of Accident	JOO CHIAT TERRACE TWDS MANGIS ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLE2576Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN KOK HAN, ANDY (CHEN GUOHAN, ANDY)
NRIC No	S8102993H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83220107
Alternative Phone No	OTHERS-83220107
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	VEZEL 1.5X CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082237371-02
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN KOK HAN, ANDY (CHEN GUOHAN, ANDY)
NRIC No	S8102993H
Date Of Birth	29/01/1981
Occupation	INDOOR
Date Of Driving Pass	25/03/2008
Driving Experience	10 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83220107
Fax Number	
Contact Number	OTHERS-83220107
Email Address	NOEMAIL

Address	27 PASIR RIS GROVE #08-50
Postcode	518073
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : NIL GENDER: : FEMALE
Passenger 2	NAME: : NIL GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK9180D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KANAGARATNAM SRITHARAN
NRIC/Passport Number	S7167388Z
Contact Number	98444141
Address	
Postcode	



Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


## SKETCH PLAN


### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

6/10/2018

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the above mentioned date & time, I was travelling on Joo Chiat Terrace turning Right into Mangis Road. When I signalled & was turning right, Suddenly, I felt an impact on my right. After alighting, I realised Vehicle B has hit onto my vehicle right portion. I wish to mention it was a one-way road & Vehicle B has travelled on the wrong direction road & caused this accident to happen.

## DECLARATION


I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

 6/10/2018

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8102993H



Name

TAN KOK HAN, ANDY  
(CHEN GUOHAN, ANDY)

陈国汉

Race

CHINESE

Date of birth

29-01-1981

Sex

M

Country of birth


SINGAPORE

S8102993H



4886061

NRIC No. S8102993H



Date of issue

24-02-2011

27 PASIR RIS GROVE #08-50  
SINGAPORE 518073

NRIC No: S8102993H

Date: 13/03/2018

REPUBLIC OF SINGAPORE DRIVING LICENCE


S8102993H



TAN KOK HAN, ANDY  
(CHEN GUOHAN, ANDY)

Birth Date 29 Jan 1981

Issue Date 25 Mar 2008




001584716K

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars < 3000kg with < 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg 25 Mar 2008



Licence No: S8102993H

NP 428A

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.

Date of Accident

06/10/2018 13:10

Vehicle No. (For Motor)

SLE2576Z

Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	5082237371-02		TAN KOK HAN, ANDY (CHEN GUOHAN, ANDY)	S8102993H	GPC	drive CLASSIC	SLE2576Z	SLE2576Z	14/07/2018	13/07/2019

## Policy Information

Policy No.	5082237371-02	Policyholder Name	TAN KOK HAN, ANDY (CHEN GU	Policyholder NRIC	S8102993H
Certificate No.					
Address	27 PASIR RIS GROVE #08-50 COCO PALMS SINGAPORE 518073				
Product Name	PRIVATE CAR INSURANCE	Plan		Group Policy Flag	N
Policy issue Date	19/06/2018	Effective Date	14/07/2018 00:00	Expiry Date	13/07/2019 23:59
Third Party Excess	0	Own damage Excess	600	Windscreen Excess	100
Additional Excess	0	OS Premium	0		
Outside Singapore OD Excess	600	Outside Singapore TP Excess	0		
Agent	VINCAR PTE LTD	Agent Tel.	64741119	GST Flag	Y
Co-insurance Flag	No				
Open Policy Info					
Certificate Info					

### Policyholder Mailing Address

Address 1	27 PASIR RIS GROVE	Address 2	#08-50 COCO PALMS	Address 3	SINGAPORE 518073
Address 4		Address Type	Singapore address	Post Code	518073
Unit No.		Related Policy Number	5082237371-02		

### Insured Object: SLE2576Z

### Endorsements

Sequence	Date of Endorsement	Endorsement Type	Endorsement Status	Endorsement Content
<div>Continue</div> <div>Cancel</div>				

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2018 <a href="#">Edit Reg</a>		08 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	KANAGARATNAM SRITHARAN, ID: S7167388Z		
Main Claimant:	TAN KOK HAN, ANDY (CHEN GUOHAN, ANDY), ID: S8102993H		
Vehicle Reg. No.:	SLE2576Z	Date of Loss:	06/10/2018 13:00 - :59 [26 Months and 22 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1201800012852	Policy/Cover Note No.:	PNCV2018-00000375 (Comprehensive)
Vehicle Reg. No. (Insured):	SLK9180D	Policy No. (Claimant):	
		Excess:	
Repairer:	Sheng Li Lai (KAKI BUKIT) NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB KAKI BUKIT, 417921 Kaki Bukit - Tel: 91119222		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/10/2018]		

**ASSOCIATED MAIL RECEIVED** View All Compose Case Mail

There are no mail for this case.

**ALL ASSOCIATED TASKS** View All Search Tasks Create New Task Complete






















Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLE2576Z (1201800012852)  
[SLK9180D]  
TP  
TAN KOK HAN, ANDY (CHEN GUOHAN, ANDY)  
Oct 6 2018 1:00PM  
[KANAGARATNAM SRITHARAN]  
Sheng Li Lai

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)								Thumbnail	Print			
1	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
2	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
3	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
4	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
5	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
6	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
7	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
8	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
9	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
10	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
11	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
12	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
13	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
14	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
15	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
16	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
17	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
18	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
19	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
20	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
21	12/10/18 15:48	General View								Load JPG	<input checked="" type="checkbox"/>			
22	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
23	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
24	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
25	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
26	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
27	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
28	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
29	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
30	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
31	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
32	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
33	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
34	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
35	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
36	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			
37	12/10/18 15:48	Photographs of Damaged Parts								Load JPG	<input checked="" type="checkbox"/>			



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	12/10/18 15:48	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18018180/ACBE2

Date: 19/10/2018

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNCV2018-00000375  
**Claimant Vehicle No :** SLE2576Z **Insured Vehicle No :** SLK9180D  
 Date of Loss: 06/10/2018 Nature of Claim: TP Claim No: 1201800012852

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE2576Z**  
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4400169  
 Reg. Date: 14/07/2016 (Man. Year: 2016) Chassis No: RU11200169  
 Colour: White Odometer: 55224 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16  
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 08/10/2018  
 Date Inspected: 08/10/2018 Inspected At: Sheng Li Lai (KAKI BUKIT)  
 NO. 2 KAKI BUKIT AVE 2, # 01-36  
 AUTOHUB KAKI BUKIT  
 Singapore 417921

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 - \$6,500.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Oct 2018)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE2576Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >