

ASS. REC. BY:

REF:

CS/FCU18018208/Agbn2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

TWS May Chua

of

FCU

Date/Time:

08102018 8:40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SU 3426 H

Insured:

SHA 2640P

at Workshop m/s

Reliable Carz

Tel:

81669797

of

8 Kaki Bukit Ave 4 #05-00

Policy No:

Claim No:

D1800 7293MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04102018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpc

H.O.D. Endorsement:

Date/Time:

08102018 1137am

Person Contacted:

Jason

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SU 3426 H - xLA/INC18017914/24

DFA: 04102018

SHA 2640P - 093/7CT140 22670/Ribbel

DFA: 29112014

11/10/18 @ 7:38pm Informed May Chua, we are pending estimate from repairer.

16/11/18 @ 5:16pm revised to May Chua by email

US \$2100, 4 days (Red \$6240.73, 75%)

REF: FCL

ASSIGNMENT

From: Date: 10-10-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLU 3426H

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLU 3426H.

Yr Regn:

2017, NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

c.c

1496

Colour:

Silver.

A/C:

Insured / Std / NI / NA

Sp. Reading

86633.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

G77112094

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

185/60R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Newton.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

10/10/18.

Survey held at

Reliable.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Tp 1st Cap.

RECEIVED 19 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 19/11/18

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + RS.) SI

) Photos

) Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Report Format :

78

Lump Sum / I.B.I. (\$

2100

160

50

50

26

286



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007293MFSH

Date: 16 November 2018

Our Ref: CS/FCI18018208/Aqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 3426H

Please be informed that we had conducted the inspection of the abovementioned vehicle on 10/10/2018 at the premises of M/s RELIABLE CARZ, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,340.73</u>
Revised Estimate Amount	: S\$ <u>2,100.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the front o/s portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	04-10-2018	Our Ref No. D18007293MFSH
Accident Date	04-10-2018	Claim Type. Third Party
Insured Vehicle	SHA2640P	Third Party Vehicle. SLU3426H
Survey Location	8 KAKI BUKIT AVENUE 4#05-50	
Contact Person.	JASON LEE	
Contact No.	0/ 81669797	Fax No. 65073849
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	RELIABLE CARZ PTE LTD	Attention. NIL
Cc : TP Solicitor	CROSSBORDERS LLC	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 16 November 2018 5:16 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007293MFSH/1
Attachments: CSFCI18018208Aqb.pdf

Dear May,

Enclosed herewith preliminary advice of SLU 3426H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 11 October 2018 2:38 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007293MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SLU 3426H on 10/10/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 8 October 2018 11:38 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007293MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 11 October 2018 2:38 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18007293MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SLU 3426H on 10/10/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 8 October 2018 11:38 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18007293MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Monday, 8 October, 2018 8:40 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18007293MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7441723Z



Name

AHMAD BIN SUBDI

Race

JAVANESE

Date of birth

29-12-1974

Sex

M

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE




Licence Number S7441723Z

Name

AHMAD BIN SUBDI

Valid Until 29 Dec 1974

Issue Date 22 Oct 2012



0021150658

3704120



NRIC No. S7441723Z



Date of issue

20-04-2005

APT BLK 435 YISHUN AVENUE 6 #04-2103
SINGAPORE 760435


S7441723Z

27/06/2013

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

EFFECTIVE DATE

Class 2B	Motorcycles <= 200 cc	03 Sep 1992
Class 2A	Motorcycles between 201 cc and 400 cc	29 Nov 1994
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg	20 Jul 2001



Licence No: S7441723Z

NP 428A

RELIABLE CARZ PTE LTD

8 Kaki Bukit Avenue 4 #05-50 Premier @ Kaki Bukit Singapore 415875

Contact No.: +65 8166 9797

Fax No.: +65 6385 1751

Vehicle No.: SLU 3426 H

Model: HONDA SHUTTLE

REF: RC3117

GP71121094

QTY DESCRIPTION

List Items:

- | | | |
|---|--------------------------|-----------|
| 1 | Front fender RH | Rep |
| 1 | Front fender liner RH | new |
| 1 | Front bumper assy | Distorted |
| 1 | Front bumper retainer RH | |
| 1 | Front fender emblem | ra |
| 1 | Head lamp RH (LED) | cut |
| 1 | Front shock absorber RH | 2 |
| 1 | Front lower arm RH | free all |
| 1 | Front wheel bearing RH | |
| 1 | Front wheel cap | cut |

AMOUNT (\$S)

685.60	+
193.40	*
1740.00	1106
25.20	✓
92.40	✓
3212.40	780
585.45	*
417.42	*
208.14	*
228.40	-
7388.41	
Less 20 %	(1477.68)
Subtotal	5910.73

Special Nett Items:

- | | | |
|---|-------------------------|------|
| 1 | Front fender clip (set) | free |
| 1 | Front bumper clip (set) | |
| 1 | Front tyre | new |

50.00	30
50.00	30
250.00	*
Subtotal	350.00

Labour Charges:

- | | | |
|---|--------|-----|
| To computerise four wheels alignment | 180.00 | 80 |
| To check wiring system | 60.00 | 30 |
| To remove and refix front undercarriage | 350.00 | * |
| To remove and refix tyre | 40.00 | * |
| To remove and repair above parts | 650.00 | 300 |
| To spray painting on affected areas | 800.00 | 400 |

Subtotal	2080.00
----------	---------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$S

8,340.73

Total: 2655.60
A/S: 2.1K. 4/5 10/10/18
Addition him
04 Days..



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18018208/Aqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 2640P	Veh. Inspected	SLU 3426H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18007293MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	08/10/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GP71121094	Colour	SILVER	
Odometer	86633	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	NEUTON	6 mm	
L/H Front Tyre	185/60 R15	NEUTON	6 mm	
R/H Rear Tyre	185/60 R15	NEUTON	6 mm	
L/H Rear Tyre	185/60 R15	NEUTON	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/10/2018	Inspection Date	10/10/2018	
Survey held at	RELIABLE CARZ PTE LTD 8 KAKI BUKIT AVE 4 #05-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 3426H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	685.60	-
1	FRONT FENDER LINER RH	NOT NECESSARY	193.40	-
1	FRONT BUMPER ASSY	DISTORTED	1,740.00	1,106.00
1	FRONT BUMPER RETAINER RH	NECESSARY	25.20	25.20
1	FRONT FENDER EMBLEM	NECESSARY	92.40	92.40
1	HEAD LAMP RH (LED)	CUT	3,212.40	780.00
1	FRONT SHOCK ABSORBER RH	NOT NECESSARY	585.45	-
1	FRONT LOWER ARM RH	NOT NECESSARY	417.42	-
1	FRONT WHEEL BERAING RH	NOT NECESSARY	208.14	-
1	FRONT WHEEL CAP	CUT	228.40	228.40
	LESS 20% DISCOUNT		-1,477.68	-446.40
			5,910.73	1,785.60
SPECIAL NETT ITEMS				
1	SET FRONT FENDER CLIP (SN)	NECESSARY	50.00	30.00
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	FRONT TYRE (SN)	NOT NECESSARY	250.00	-
			350.00	60.00
LABOUR				
	TO COMPUTERISE FOUR WHEELS ALIGNMENT.		180.00	80.00
	TO CHECK WIRING SYSTEM.		60.00	30.00
	TO REMOVE AND REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	350.00	-
	TO REMOVE AND REFIX TYRE.	NOT NECESSARY	40.00	-
	TO REMOVE AND REPAIR ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		650.00	300.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		800.00	400.00
			2,080.00	810.00
GRAND TOTAL			8,340.73	2,655.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00

Report Ref No. CS/FC118018208/Aqbn2



Report Ref No. CS/FCI18018208/Aqbn2

A handwritten signature in black ink, appearing to read 'A. Ling'.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.