

ASS. REC. BY:

REF:

003/CT43018215/Dec2

Special Instruction:

Surveyor

Mullmen

By/on

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTL

Date/Time:

05/10/18 5:20pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

G8D 7933S

Insured:

SDM95K

at Workshop m/s

TR B Motor

Tel:

6458 0296

of

Blk 160 Sin Ming DM #08-03

Policy No:

DMP/CSN3061651800

Claim No:

SNM18D04-778C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04.10.2018

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

05/10/2018 10:32am

Person Contacted:

Judy

Vehicle IN / OUT

Date/Time

Action/Instruction ( X ) Estimate

G8D 7933S - X

SDM 95K - X

Dismantle: 9/10/2018

REF:

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBD 7933S

Yr Regn:

2015 / Apr 1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

C.C

2982

Colour:

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

149311

T/Radio:

Insured / Std / NI / NA

Eng/No:

1KD2458924

C/No:

KDY2318017772

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

165 R13C (dunlop)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Yokohama.

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

04/10/2018

D.O.I.

09/10/2018

Survey held at

TYB Motor Sin Ming

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Cure Taping SDM 95K

3.5K 4.5K

Repair range 4K to 5K with 5 days of repair

No of the repair photo

RECEIVED 17 DEC 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

150

Transportation

) S + RS, SI

) Photos

) Others

TOTAL

150

Report Format :

PRE

Lump Sum / I.B.I. (\$) )

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2018		05 Oct 2018 17:20 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	LIEW YIK WEE (LIU YIWEI), ID: S7201597E								
Main Claimant:	FORTUNA M&E SERVICES PTE LTD, Co. Reg. No.: 200920864D								
Vehicle Reg. No.:	GBD7933S	Date of Loss:	04/10/2018 11:00 - :59						
Claim Type:	TP / SNM18D04778C02	Policy/Cover Note No.:	DMPCSN3061651800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDM95K	Policy No. (Claimant):	M496851						
		Excess:	S\$0.00						
Repairer:	T & B Motor Repairs Services Pte Ltd (HQ) Blk 20, #01-28, Sin Ming Road, 575678 Sin Ming - Tel: 64546958/64580296								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/10/2018]								
Driver/Custodian (Insured):	LIEW YIK WEE (LIU YIWEI) (46 / Male), NRIC: S7201597E								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	0864D
<b>Vehicle Details</b>	
Vehicle No.:	GBD7933S
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Dec 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2458924
Chassis No.:	KDY2318017772
Maximum Power Output:	-
Open Market Value:	\$29,217.00
Original Registration Date:	30 Apr 2015
First Registration Date:	30 Apr 2015
Transfer Count:	0
Actual ARF Paid:	\$1,461.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	29 Apr 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$49,560.00
COE Rebate Amount:	\$31,553.00
<b>Total Rebate Amount:</b>	<b>\$31,553.00</b>

The information contained herein is correct as at 17 Dec 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report 05/10/2018 10:29  
 Date Of Accident 04/10/2018 11:30  
 Exact Location Of Accident NAPIER ROAD TOWARD GRANGE ROAD  
 Country/State of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number GBD7933S  
**Insured/Policyholder**  
 Name Of Registered Owner FORTUNA M&E SERVICES PTE LTD  
 Co Reg No 200920864D  
 Email Address NOEMAIL  
 Mobile Phone No (LOCAL) +65-93857606  
 Alternative Phone No Office-64577888

### Vehicle Particulars

Manufacturer TOYOTA  
 Model DYNA 1.5T-3.0 (A)  
 Exact Purpose for which vehicle was being used at time of accident WORK  
 Are you claiming under your own insurance policy for repair to your vehicle? NO  
 If No, Please state action to be taken THIRD PARTY  
 Vehicle Category COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company INDIA INTERNATIONAL INSURANCE PTE LTD  
 Type Of Coverage COMPREHENSIVE  
 Fleet Policy NO  
 Policy Number M496851  
 Cover Note Number

### Driver

Name of Driver LEE WAI LOON  
 NRIC No G7917845X  
 Date Of Birth 09/09/1985  
 Occupation OUTDOOR  
 Date Of Driving Pass 07/02/2009  
 Driving Experience 9 YEARS AND 7 MONTHS  
 Gender MALE  
 Mobile Number (LOCAL) +65-93857606

## \* Fax Number

Contact Number	
EEmail Address	NOEMAIL
Address	10 ADMIRALTY STREET #03-25 NORTHLINK BUILDING
Postcode	757695
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	YES
Number of Passengers (Including Driver)	1

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REF TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SDM95K
Vehicle Make/Model/Colour	BMW
Details Of Properties	FRONT PORTION
Vehicle Category	PRIVATE CAR
Name of Driver	LIEW YIK WEE
NRIC/Passport Number	S7201597E
Contact Number	
Address	
Postcode	
Insurance Company Name	

12/17/2018

E-FILE

• Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

**FORTUNA M&E SERVICES PTE LTD**  
No.10 Admiralty St #03-25 Northlink Building

Singapore 757695

Reg No. 200920864D

Tel: 64577888 Fax: 64597728

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SR4366018

## Sketch Plan #2



## ...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Oct 2018		05 Oct 2018 17:20 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	LIEW YIK WEE (LIU YIWEI), ID: S7201597E								
Main Claimant:	FORTUNA M&E SERVICES PTE LTD, Co. Reg. No.: 200920864D								
Vehicle Reg. No.:	GBD7933S	Date of Loss:	04/10/2018 11:00 - :59 [41 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D04778C02	Policy/Cover Note No.:	DMPCSN3061651800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SDM95K	Policy No. (Claimant):	M496851						
		Excess:	\$0.00						
Repairer:	T & B Motor Repairs Services Pte Ltd (HQ) Blk 20, #01-28, Sin Ming Road, 575678 Sin Ming - Tel: 64546958/64580296								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 16/10/2018]								
Driver/Custodian (Insured):	LIEW YIK WEE (LIU YIWEI) (46 / Male), NRIC: S7201597E								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*GBD7933S (SNM18D04778C02)  
[SDM95K]  
TP  
FORTUNA M&E SERVICES PTE LTD  
Oct 4 2018 11:00AM  
[LIEW YIK WEE (LIU YIWEI)]  
T & B Motor Repairs Services Pte Ltd


<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	T & B Motor Repairs Services Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 11:07	<b>Accident Statement</b>	Load HTM	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	T & B Motor Repairs Services Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 10:47	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	05/10/18 10:47	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	05/10/18 10:47	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	05/10/18 10:47	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	05/10/18 10:47	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
6	05/10/18 10:47	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
7	05/10/18 10:47	<b>Accident Photo</b> [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/12/18 15:07	<b>Rear View Right</b>	Load JPG	<input checked="" type="checkbox"/>
2	14/12/18 15:07	<b>Rear View Left</b>	Load JPG	<input checked="" type="checkbox"/>
3	14/12/18 15:07	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	14/12/18 15:07	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	14/12/18 15:07	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	14/12/18 15:07	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	14/12/18 15:07	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	14/12/18 15:07	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	14/12/18 15:07	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	14/12/18 15:08	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	T & B Motor Repairs Services Pte Ltd (HQ)	Thumbnail	Print
24	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/12/18 15:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/12/18 15:08	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
40	14/12/18 15:08	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
41	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	T & B Motor Repairs Services Pte Ltd (HQ)	Thumbnail	Print
74	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	14/12/18 15:08	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/10/18 17:19	PRS	 Load PDF	
2	05/10/18 17:19	OI GIA	 Load PDF	
No	Finalized On	T & B Motor Repairs Services Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 11:05	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	05/10/18 11:05	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>







## Linked Accident Report Documents

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	T & B Motor Repairs Services Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 11:07	Accident Statement	 Load HTM	<input checked="" type="checkbox"/>



Photos/Images

3 per page ☒

No	Finalized On	T & B Motor Repairs Services Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	05/10/18 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	05/10/18 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	05/10/18 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	05/10/18 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	05/10/18 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	05/10/18 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page ☒

No	Finalized On	T & B Motor Repairs Services Pte Ltd (HQ)	Thumbnail	Print
1	05/10/18 11:05	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	05/10/18 11:05	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CT118018215/DCBE2

Date: 18/12/2018

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3061651800

Claimant Vehicle  
No: GBD7933SInsured Vehicle  
No: SDM95K

Date of Loss: 04/10/2018

Nature of Claim: TP

Claim  
No: SNM18D04778C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD7933S**

Make &amp; Model: TOYOTA DYNA 1.5T, 3.0 (A)

Engine No: 1KD2458924

Reg. Date: 30/04/2015 (Man. Year: 2014)

Chassis No: KDY2318017772

Colour: Silver

Odometer: 149311 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 165 R13C (D)

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5/5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 05/10/2018

Date Inspected: 09/10/2018 Inspected At:

160 SIN MING DRIVE #08-03  
Repairer : T & B Motor Repairs Services  
Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: BRYAN TANI

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 -\$4,500.00

## REPAIR DETAILS

### Reference

**Part Source:** (Last Synchronised: 18 Dec 2018)

**Parts:** N/A TOYOTA DYNA 1.5T 3.0 (A) (Model not available in database)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for GBD7933S)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >