



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref : CC4/ASM18018222/Ggb3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: SAW THENG	Date : 01-11-2019 Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 6333D	Veh. Inspected	SLA 2651K
Policy No.	GA310130/1	Coverage (\$)	0.00
Claim No.	S8M00Y69	Excess (\$)	0.00
Assign From	SAW THENG	Assign Date	05/10/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VELLFIRE	c.c	2494
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTNGF3DH108004201	Colour	BLACK
Odometer	60176	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	CONTINENTAL	6 mm
L/H Front Tyre	235/50 R18	CONTINENTAL	6 mm
R/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm
L/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm

4. Description of Damages

	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--	--

5. General Information

Accident Date	29/09/2018	Inspection Date	05/10/2018
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.		

5a. Remarks

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

5b. Estimate Days of Repair

	ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
--	-------------------------------------	-----------------------