anwier	5.3	A	SSIGNM	ENT (OF	lice)			
From (Pensor	10. F. W. Phys. P.	m of		cmo		1	Oste/Time	VI-102018
Estimated Co				Bill to:			NOON IN THE INCH	
OD / TO Inspect V	/S / TP RES / OD R	es/eva/i	BAMAB	CS		Insured:	Sin)IA8Z
at Workshop		Cache	* 1	sile		Tel:		
of		No. 1 Ka		Ave 6	# D	TOUGHT .	0141	10.0
Policy No.				Claim		Anera . O	01613 /A	GC.
Sum Insured				Exce			1.11	****
Make of Veh	K						0.0.A 13	PIOLOGIC
(Clicat's Recor CA / REV	/ REP. / REV 24	HRS Wh		160420	18		Western D	
CA / REV	/ REP. / REV 24 13042018 1413pr	HRS ' W)ρι π — Региоп	Contacted;		iktor 18		H.O.D. Fasle	tsensent:
CA / REV	/ REP. / REV 24	п Регион	Contacted:	\			H.O.D. Fodo	tsensent:
CA / REV	/ REP. / REV 24 130420(8 443pr Action/Instruction	n Person		\			H.O.D. Fodo	tsensent:
CA / REV	Action/Instruction OF 304257	п р _{егия)}		\			H.O.D. Fodo	tsensent:
CA / REV Date/Line Unite/Time	/ REP. / REV 24 130420(8 443pr Action/Instruction	п р _{егия)}		\			H.O.D. Fodo	tsensent:
CA / REV Date/Line Unite/Time	Action/Instruction OF 304257	п р _{егия)}		\			H.O.D. Fodo	tsensent:
CA / REV Date/Line Unite/Time	Action/Instruction OF 304257	п р _{егия)}		\			H.O.D. Fodo	tsensent:

RECEIVED 1 2 DOT 2018

140-160 = 290

Repair days 7

TGUM

10/10/18

great State 112 1

Nivitha (LKK Auto)

From:

Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>

Sent:

Tuesday, 9 October 2018 11:28 AM

To:

'sur@lkkauto.com'; 'assignments' (assignments@lkkauto.com)

Subject:

ACC INL SGB2478Z/ SJP8844B ON 12.04.2018; OUR REF: CMTD1801613; YOUR REF:

AC1804904

Attachments:

0492_001.pdf; SAS2390364.PDF; SAS2390560.pdf; survey report.pdf

Dear LKK

We refer to the above matter.

We herewith enclosed GIA reports, the repair bill the photographs and the survey report for your attention.

Please prepare the paper resurvey of SJP8844B.

Please forward the report with the market value status within 5 days.

Thank you.

Best Regards

Agnes Chan

Claims Divison

D: 6329 5327 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @





For Travel, Personal Accident & Home Insurance | 2 For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy.

From: Chan, Shu Hui Agnes [mailto:agnes.chan@sompo.com.sg]

Sent: Tuesday, 9 October, 2018 11:22 AM

To: Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>

Subject: Attached Image

Cadre Automobile

No. 1 Kaki Bukit Ave 5 #02-49 Autobay@Kaki Bukit Singapore 417883 Tel: 67477618 Fax: 67426238

Name

: Kiong Ah Im

Date

: 13-Apr-18

Address

: Blk 706 Clementi West Street 2

#04-367

Singapore 120706

FINAL REPAIR BILL FOR Jaguar XJL NO. SJP 8844 B

Lump Sum Repair Cost

\$ 16,300.00

Singapore Dollars: Sixteen Thousand Three Hundred Only



No. 1 Kaki Bukit Ave 6 *01-28 AutoBay @ Kaki Bukit Singapore 417883 Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Invoice No 18014-04/MY

Billing Name & Address

Date

20 Sep 2018

Kiong Ah Im Blk 706 Clementi West Street 2 #04-367 Singapore 120706

Vehicle No : SJP 8844 B

Model: Jaguar XJL

Item	Descriptions	Amount S\$
1	Date of inspection: 13 Apr 2018 A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs	
3	Transportation Charges	
4	2nd Inspection & Final Inspection Total	\$ 1060.00
	SDLS : ONE THOUSAND AND SIXTY ONLY	

Notes:

- 1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
- 2. All cheque should have our "Invoice No." written on the reverse side of the cheque
- 3. For further enquiries on this invoice, please feel free to contact us

Official Stamp



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay & Kaki Bukit Singapore 417833 Tel: 6748 6653 Fax: 67471017 Registration No: 200722252D

Report Reference: TP / 18014-04/MY / 2018

Date of Report : 20 Sep 2018

Klong Ah Im Blk 706 Clementi West Street 2 #04-367 Singapore 120706

THIRD PARTY SURVEY ACCIDENT HAPPENED ON 12 Apr 2018

Workshop Address :

Cadre Automobile

No.1 Kaki Bukit Ave 6

#02-49 AutoBay @ Kaki Bukit

Singapore 417883

As per your instruction dated 13 Apr 2018 with regard to the above matter. We have carried out a physical inspection on the said vehicle SJP 8844 B . We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SJP 8844 B Engine No : 0468916306DT

Model Jaguar XJL Mileage : 164152 Year / Capacity : 2010/2993 Colour : Maroon

Year / Capacity : 2010/2993 Colour : Maroon Chassis No : SAJAC2223ANV07924

2. TYRES CONDITION

		Size	Made	Balance		Rim
FRONT O/S	35	245/45 ZR19	Kinfores	4.00	mm	Sport
REAR O/S	1	275/40 ZR19	Dunlop	4.00	mm	Sport
FRONT N/S	3	245/45 ZR19	Kinfores	4.00	mm	Sport
REAR N/S	4	275/40 ZR19	Dunlop	4.00	mm	Sport



No. 1 Kaki Bukit Ave 6 +01-28 AutoBay 3 Kaki Bukit Singapore 41788 Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

Estimated normal period of repair : 10 working days to complete.

Enclosed number of photograph : 160 copies.

- In accordance to your instruction, we have <u>Not Authorised</u> repair to the vehicle and the survey
 was done on a <u>"Without Prejudice"</u> basis. We hope that this report will be of assistance to you in
 dealing with the matter.
- Should you discover any discrepancy in the report, please kindly notify us <u>within 2 weeks</u>, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No:

SJP 8844 B

Report No:

TP/ 18014-04/MY / 2018

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	List Items Boot lid Boot lid lock Boot lid rubber boot lid release button Boot lid lock catch Rear bumper Rear bumper reinforcement Rear bumper bracket Rear bumper side guide Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp Rear taillamp bracket Rear end panel Rear end panel Rear spare tyre board Rear spare tyre panel Rear o/s exhaust silencer	Damage Damage Necessary Damage Damage Damage Damage Necessary Damage	*****	2873.00 190.00 253.00 150.00 160.00 2552.00 746.00 80.00 180.00 240.00 508.00 942.00 80.00, 1825.00 385.00	************	2873.00 190.00 150.00 150.00 2552.00 746.00 8 80.00 180.00 508.00 942.00 80.00 1825.
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Boot lid lock Boot lid rubber boot lid release button Boot lid lock catch Rear bumper Rear bumper reinforcement Rear bumper bracket Rear bumper side guide Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp Rear end panel Rear end panel Rear spare tyre board Rear spare tyre panel	Damage Necessary Damage Damage Damage Damage Necessary Damage Damage Damage Damage Damage Damage Damage Necessary Damage Damage Damage	****	190.00 253.00 150.00 160.00 2552.00 746.00 80.00 180.00 240.00 508.00 942.00 80.00, 1825.00 385.00 485.00	*************	190.00 8 253.00 N 150.00 6 160.00 8 2552.00 746.00 8 80.00 8 180.00 8 240.00 8 942.00 8 942.00 8 80.00 N 1825.00 N 485.00 N
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	boot lid release button Boot lid lock catch Rear bumper Rear bumper reinforcement Rear bumper bracket Rear bumper side guide Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Necessary Damage Damage Damage Necessary Damage Damage Damage Damage Damage Damage Necessary Damage Damage Damage Damage	***	253.00 150.00 160.00 2552.00 746.00 80.00 180.00 240.00 508.00 942.00 80.00, 1825.00 385.00 485.00	************	253.00 N 150.00 S 160.00 S 2552.00 S 746.00 S 80.00 S 180.00 S 240.00 S 508.00 S 942.00 S 80.00 N 1825.00 N 485.00 N
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Boot lid lock catch Rear bumper Rear bumper reinforcement Rear bumper bracket Rear bumper side guide Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Damage Damage Damage Damage Necessary Damage	****	150.00 160.00 2552.00 746.00 80.00 180.00 240.00 508.00 942.00 80.00, 1825.00 385.00 485.00	***********	150.00 6 160.00 8 2552.00 7 746.00 8 80.00 8 180.00 6 240.00 6 508.00 8 942.00 6 80.00 N 1825.00 N 485.00 N
1 1 1 1 1 1 1 1 1 1	Rear bumper Rear bumper reinforcement Rear bumper bracket Rear bumper side guide Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Damage Damage Necessary Damage Damage Damage Damage Necessary Damage Damage Damage Damage Damage	****	160.00 2552.00 746.00 80.00 180.00 240.00 508.00 942.00 80.00, 1825.00 385.00 485.00	**********	160.00 8 2552:00 8 80.00 8 80.00 8 240.00 8 508.00 8 942.00 8 80.00 N 1825.00 N 485.00 N
1 1 1 1 1 1 1 1 1 1	Rear bumper reinforcement Rear bumper bracket Rear bumper side guide Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Damage Damage Necessary Damage Damage Damage Damage Necessary Damage Damage Damage Damage	* * * * * * * * *	2552.00 746.00 80.00 180.00 240.00 508.00 942.00 80.00, 1825.00 385.00 485.00	**********	2552.00 P 746.00 8 80.00 B 180.00 S 240.00 B 942.00 B 942.00 B 80.00 N 1825.00 N 485.00 N
1 1 1 1	Rear bumper bracket Rear bumper side guide Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Damage Necessary Damage Damage Damage Damage Necessary Damage Damage Damage Damage	5555555	746.00 80.00 180.00 240.00 508.00 942.00 80.00, 1825.00 385.00 485.00	*******	746.00 8 80.00 8 180.00 9 240.00 6 508.00 8 942.00 6 80.00 N 1825.00 N 485.00 N
1 1 1 1	Rear bumper side guide Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Necessary Damage Damage Damage Necessary Damage Damage Damage Damage Damage	5 5 5 5 5	80.00 180.00 240.00 508.00 942.00 80.00 1825.00 385.00 485.00	******	80.00 B 180.00 S 240.00 S 508.00 B 942.00 C 80.00 N 1825.00 N 485.00 N
1 1 1 1	Rear bumper reverse sensor Rear bumper chrome moulding Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Damage Damage Damage Damage Necessary Damage Damage Damage Damage	\$ \$ \$ \$ \$ \$	180.00 240.00 508.00 942.00 80.00 1825.00 385.00 485.00	*****	180.00 5 240.00 6 508.00 8 942.00 6 80.00 N 1825.00 N 485.00 N
1 1 1 1 1 1 1 1 1 1	Rear bumper chrome moulding Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Damage Damage Damage Necessary Damage Damage Damage	\$	240.00 508.00 942.00 80.00, 1825.00 385.00 485.00	****	240.00 8 508.00 8 942.00 0 80.00 N 1825.00 N 485.00 N
1	Rear taillamp Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Damage Damage Necessary Damage Damage Damage	\$	508.00 942.00 80.00, 1825.00 385.00 485.00	***	508.00 8 942.00 0 80.00 N 1825.00 N 385.00 N 485.00 N
1 F 1 F 1 F 1 F 1 F	Rear taillamp bracket Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Necessary Damage Damage Damage	\$	942.00 80.00, 1825.00 385.00 485.00	5 5 5 5 5	942.00 C 80.00 N 1825.00 D 385.00 N 485.00 N
1 F 1 F 1 F 1 F	Rear end panel Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Necessary Damage Damage Damage	\$	80.00, 1825.00 385.00 485.00	\$ \$ \$	80.00 N 1825.00 D 385.00 N 485.00 N
1 F 1 F 1 F 1 F	Rear end panel garnish Rear spare tyre board Rear spare tyre panel	Damage Damage Damage Damage	\$ \$	1825.00 385.00 485.00	\$	1825.00 D 385.00 N 485.00 N
1 F 1 F 1 F	Rear spare tyre board Rear spare tyre panel	Damage Damage Damage	\$	485.00	\$	385.00 N 485.00 N
1 F 1 F 1 F	Rear spare tyre panel	Damage	\$	485.00	\$	485.00 N
1 F			\$	4 470 00		
1 F	Rear o/s exhaust silencer	Danne	-	1470.00	\$	1470.00
		Damage	\$	1068.00	\$	1068.00 N
1 F	Rear o/s exhaust silencer mounting	Damage	\$	97.00	\$	97.00
	Rear o/s exhaust heat shield	Damage	\$	210.00	\$	210.00
	Boot lid logo	Necessary	\$	60.00	\$	60.00 N
	Boot lid 'XJL' emblem	Necessary	\$	97.00	\$	97.00 N
	Rear number plate lamp	Damage	\$	60.00	\$	60.00 BA
	Rear reverse camera	Damage	\$	750.00	\$	750.00 N
1 5	Rear shock absorber air pump	Damage	\$	1910.00	\$	1910.00 N
	Rear wire harness	Damage	\$	1553.00	\$	1553.00 R
	Battery tray	Damage	\$	50.00	\$	50.00 A
	Boot inner garnish	Intact	\$	302.00	\$	
	Boot hinges	Intact	\$	360.00	\$	
В	Boot lifter motor	Intact	\$	988.00	\$	
			\$	20624.00	\$	18974.00
	Discount	10.0%	\$	2062.40	\$	1897.40
			\$	18561.60	\$	17076.60
S	Special Nett Items					
R	Rear number plate	Damage	\$	50.00	\$	50.00 8€
	600		\$	50.00	\$	50.00

Vehicle No:

SJP 8844 B

Report No:

TP/ 18014-04/MY / 2018

LABOUR COST

S/No	Job Descriptions	 orkshop's stimation		ur Revised stimation
	Spare Parts Total c/f	\$ 18611.60	\$	17126.60
1	To disconnect and reconnect, check electrical wiring, harness wires, sockets, replace damaged parts.	\$ 250.00	\$ 8	30. ∞ 120.00
2	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 60.00	\$	40.00
3	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$	50.60 +3 100.00
4	To remove and refit rear bumper sensor.	\$ 220.00	\$	140.00
5	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 150.00	\$	50.00 +2 100.00
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and wield body panels. To re-adjust to the original position using power tools.	\$ 1800.00	\$	900:00 111 1500:00
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1600.00	\$	1250.00
	Total	\$ 22841.60	\$	20376.60

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 16300.00

SDLS: SIXTEEN THOUSAND THREE HUNDRED ONLY

Qualified Appraiser

Page 4

Repair days 7

TGLim lin 10/10/18

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Pald:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebete Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Pald:

COE Rebate Amount:

Total Rebate Amount:

The information contained herein is correct as at 03 Oct 2018

Singapore NRIC

5658B

SJP88448

Yes

03 Oct 2018

JAGUAR

XJ 3.0L DIESEL LWB PL A/T ABS D/AB HID

Red

2010

0468916306DT

SAJAC2223ANV07924

202.0 kW (270 bhp)

\$80,897.00

20 Oct 2010

20 Oct 2010

1

\$80,897.00

Vec

19 Oct 2020

\$48,538.00

19 Oct 2020

B - Car (1601cc & above)

10

\$38,000,00

\$7,763.00

\$56,301.00

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCID	-		
ACCID	ENIS	SIAIE	300E N 1

Date Of Report

13/04/2018 12:57

Date Of Accident

12/04/2018 20:15

Exact Location Of Accident

ALONG UPPER SERANGOON ROAD

Country/State of Loss

SINGAPORE

	DETAILS OF	OWN VEHICLE

Vehicle Registration Number

SJP8844B

Insured/Policyholder

Name Of Registered Owner

KIONG AH IM

NRIC No

S2755658B

Email Address

EVEKIONG_33@YAHOO.COM.SG

Mobile Phone No

(LOCAL) +65-97925434

Alternative Phone No

OTHERS-97925434

Vehicle Particulars

Manufacturer

JAGUAR

Model

XJ 3.0 DIESEL

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

AIG ASIA PACIFIC INSURANCE PTE, LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

2100411413-03

Cover Note Number

Driver

 Name of Driver
 KIONG AH IM

 NRIC No
 \$2755658B

 Date Of Birth
 21/11/1967

 Occupation
 OUTDOOR

 Date Of Driving Pass
 28/01/2008

Driving Experience 10 YEARS AND 2 MONTHS

Gender

FEMALE

Mobile Number

(LOCAL) +65-97925434

Fax Number

Contact Number

OTHERS-97925434

EMail Address

EVEKIONG 33@YAHOO.COM.SG

Address

BLK 706 CLEMENTI WEST STREET 2

#04-367

Postcode

120706

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

POH

GENDER:

MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGB2478Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GiA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Driver's Signature

(If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature Poh Kwee Choo S6840583A Name

NRIC/FIN No.:

CARLS CALLED HAVE

.

CHART MODEL AND IS

SKETCH PLAN				
1		Post car	A - SJP 8844P B- SGB 247	782
DESCRIBE CIRCUMSTANCES	OF THE ACCIDENT			
The incident has along upper Seri and boot.	ington Road +	Floors at 8 owards Pung etricle Say	17pm, I was traveling gol. the traffic light tor. 8 24782 borg and my	ne 1 car
PECLARATION /We declare the foregoing particular	lars are true in every reso	ect.		
cl/	M			
olicyholise Signature late & Time: 1 3 APR 2013	Oriver's Senature (If driver is not the po Date & Time:	olicyholder)	Reporting Centre Personnel's Signature Name: NRIC/FIN No. Poh Kwee Choo	*

NRIC/FIN No. Poh Kwee Choo S8840583



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Kiong Ah im

. .

Period of Insurance

: 29 Apr 2018 To 19 Apr 2019 : 0468916306DT Engine No.

Chassis No. : SAJAC2223ANV07924 Vehicle No.

S IPRR44R

Policy No.

: 2100411413-03

Endorsement No.

Issued Date

: 11 Apr 2018

ABOUT THE COVER

Make/Model

JAGUAR XJ 3.0 DIESEL

Engine Capacity/Tonnage 2,993.00 CC Driver Restriction

NA.

Sum Insured : Market Value Off Peak Car : No

First Year of Registration : 2010 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive"

ii) The Paticylolae tii Any other person who is driving on the Policyholae's order or with his her permission this Paticy will independ on Palicyholae or any authorised driver only if heighe meets the specified age condition.

You have to pay an additional sum of \$2,000 as "Young emiliar inequalmented Driver Except" ("YIDR") if You are or Your Authorized Driver pleasant or ulmanwell or under the age of 22 endow has been a year's diving expenses.

Age Condition

: All Age Condition

Limitation as to use"

The only for social. Connects and phonous purposes and the the Policynollius's business. The Policy does not cover use for the or businest divining business. Owney took, facing processing valuables visit as questionable, the purpose or purpose of the day purpose in processing with facing Trade.

Loss of Use 1500cc - 1600cc Optional

* Constitution remainsed inspersions for Section 9 of the Mater Valvades (Third-Party Holes and Companishing Act (Cap. 165) and Section 65 of the Read Transport Act, 1967 (Makester, are had to be included under those bearings

EXCESS

Section 1 Fire - 50 Client Damage - S1400 Tivet - 50 Flood Cover - 50

Named Driver and Excess (where replaced)

mong Aniem - S1400 (Own Diamage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres AC Authorities in the proves of the claims extend reports
Any account reports on the Valvatic result for before out to prove of the Authorities. All news of the first registration of the Valvatic result for before out to prove of the Authorities of Sengagors. This finds the control of Authorities of Sengagors. This finds the Cole Authorities of Sengagors. This finds the Sengagors of the Cole Authorities of Sengagors. This finds the Sengagors of the Cole Authorities of Sengagors. The Cole Authorities of Sengagors of the Cole Authorities of Sengagors. The Cole Authorities of Sengagors of the Cole Authorities of Sengagors. The Cole Authorities of Sengagors of the Cole Authorities of Sengagors of the Cole Authorities of Sengagors. The Cole Authorities of Sengagors of the Cole Authorities of Sengagors. The Cole Authorities of Sengagors of the Cole Authorities of Sengagors. The Cole Authorities of Sengagors of the Cole Authorities of Sengagors. The Cole Authorities of Sengagors of the Cole Authorities of Sengagors. The Cole Authorities of Sengagors of Sengagors of Sengagors of the Cole Authorities of Sengagors of

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

Wite hereby perify that the pulling to which this Cardinate of Josephine related is leased in accordance with the juneause of the Motor Vehicles (Their Party Rises and Compression). Act (Cap. 188), Part N of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Thrit Party Rises) Rules, 1989 (Malaysia).

9503617801

CHU YONG KHIM

3 TAMPINES GRANDE 805-48 AIA TAMPINES

SINGAPORE \$28799 SP-IDYGON

Underwritten by AJG Asia Pacific Insurance Pie. Ltd.

AIG Asia Pacific Insurance Pts. Ltd. AUTHORISED REPRESENTATIVE

DRIVER'S NRIC & DRIVING LICENCE Pg. 1












Accident Photo



Accident Photo



CHASSIS NUMBER



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the ladgement of this report to the insurers, you hereby consaforesaid.	sent to the archiving of this report at the centre and to copies of the report being made available
	ACCIDENT STATEMENT
Date Of Report	13/04/2018 11:02
Date Of Accident	12/04/2018 20:05
Exact Location Of Accident	UPPER SERANGOON ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SGB2478Z
Insured/Policyholder	
Name Of Registered Owner	POH THYE MING (MO TAIMING)
NRIC No	S7103468B
Email Address	D3R3KTM@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96889548
Alternative Phone No	OFFICE-96889548
Vehicle Particulars	
Manufacturer	SAAB
Model	9-3-2.0 LPT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01017204
Cover Note Number	
Driver	
Name of Driver	POH THYE MING (MO TAIMING)
NRIC No	S7103468B
Date Of Birth	03/02/1971
Occupation	INDOOR

Occupation INDOOR Date Of Driving Pass 16/09/1995

Driving Experience 22 YEARS AND 6 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-96889548

Fax Number

Contact Number OFFICE-96889548

EMail Address D3R3KTM@GMAIL.COM

BLK 201D COMPASSVALE DRIVE Address

#11-569

Postcode 544201

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

2

Details of Police Action

Was the accident reported to the police?

Number of Passengers (Including Driver)

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

The vehicle signaled to turn right from 1st or 2nd lane from the right. Assumed that it was to signal early to turn right at the next junction of Upper Serangoon Road and Tampines Road. It stopped suddenly at the junction of upper Serangoon Road and Hougang St 21 to turn on the same lane as I was on which is a straight going lane. I stopped hard on brakes but could not stop in time

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJP8844B

Vehicle Make/Model/Colour JAGUAR (BLACK)

Details Of Properties

Vehicle Category

Name of Driver KIONG AH IM NRIC/Passport Number F7053184N

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

2

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and occurate as possible. Any will all misropresentation or withholding of material. facts may allow insurance companies to repudiate policy fiability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the just of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archaing of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use. disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured micle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law ferms, the Monotory Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s). of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (if) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me. which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the Purposes"1
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permeted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purpos
- (d) my Personal information will also be collected and used to compile claims history for the purpose of feaud detection, involtigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (ii) to all incurrers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Date & Time: 158541 30/16

11:07 cm

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Sign

Name: Jessy Soc

NRIC/RN No.: G2631072W

Accident Sketch Plan

SKETCH PLAN Vehicle A \$65 34782 Vehicle B: \$37 8844 8



Junction of Upper Strangton Rd E Hougang 20 20

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Date of Accident. 12/04/2018	Time of Accident 20:05 pm
The car signalled to turn	right from let or 2nd lane
from the right Assumed	that it was to signal early
to turn right at the The	enetion of Serringson road and
	suddenly at the junction of
	and helpang et 21 to turn
	as I am in, which is a
	Stepped how balles hard but
	t and not stop in time.
	The state of the s

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Fillipholiter's Signature Date & Time: 15 (Cur.) DOVS

H:04cm

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: Jessy Soc NRICZEN No : 02021072W

Costificate of Insurance

DICTUR VEHICLES (THRE) FARTY HISKS AND COMPERNATIONS ALT ICHAPTENSISS. MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) BULES, 1940. ROAD THANSPORT ACT 1987 (MALAYSIA) NICITOR VEHICLES (TRIPD PARTY RISKS) BULES, 1955 (MALXYSIA)

Contract Printing No.

20 P

DITHITPUNINTENA

Descript.

POSITIVE MISS.

Mater Car (Resilience) No. 55324797

Desputering Edulation-DOLD

PARTY COMMUNICATION TO DECOMPRISE OF CHILD

Proce Tracey (Inn.)

ON DECEMBER 2018 1 1 51

Marriage Datalog (Section 6: Never wave 2010) or our

Cornel"

1300 - Septem 1

Waves up to 651 (c) if a more in tipper is done at Excelling Womening for the first pure.

100 policy year!

Vincentary Manager

MA

Whateonia Escape

25 DCDD Washed Please of Extending Vermille

Countries Days

Far Fitting Statebury

Support to CST what over approprie

Personal Chieses of Forson entitles to show

The Intend

Services period who is overly be the present a set of set in automatic

to the point of the board of the expense.

- I are noticed in the advised's larvely for a past of over one cost term, driving the Matrix Car storing the risk of the research and perto the fact out been want pays proche ha dealth of his insurant and
- to the little metric and but have place an experience to the Many Car product the feet and continue promises has will be with the body of the bound.

Properties from the present priving is permitted in inconstruction with the consumption of these by regulations in severing fidure. Cut of not because of a Court of Low or by require of any enactive of or requisition as that broad finance over the Moster Car. In registered order the Road Traffic Act (Chapter 278) and its registered order the Road Traffic Act (Chapter 278) and its registered order the Road Traffic Act (Chapter 278) and its registered order the Road Traffic Act (Chapter 278) and its registered order the Road Traffic Act (Chapter 278) and its registered order the Road Traffic Act (Chapter 278) and its registered order the Road Traffic Act (Chapter 278) and its registered order the Road Traffic Act (Chapter 278) and its registered order the Road Traffic Act (Chapter 278) and its registered order to the acceptance of the Act (Chapter 278) and its registered order to the A

Lise only for social identises, and premiure purpose and for the triguest's business. This Policy does not cover use for the in resent. dot up place making, report testing, introdity than the corrupt of poods other than samples in connection with any trade or bispense of use for any suspection in connection such the Moon Trade.

Employe (In Wines are Alexent Reporting

tiny a condition procedure to satisfy that the insured easis call as the Company's Account Receiving Center with the following Center with the follo "uut 1" his paulieri in by the nest working day thereof

All accorded records to the Moste Cast must be carried subtractional Workshops, otherwise the claim is not payable under the Postsy. For Ellow Drive Havinge Place addition impairs to the Matrix Car can be derived out at any workship other titlen Eleva Drive Workships.

For the July of Accused Tokus Sing Contain and Extensions, Windows Co., please and our separate in more compactor by or call our Environce ricking with SIDE \$525.


The COPPE COPPE CONTROL OF THE COPPE CONTROL OF THE

Some Number Singspore Ple Link

Stellage

DOWN THE REAL PROPERTY AND ADDRESS OF THE PARTY AND

The factor which is the first of the control of the control of the control of the post of the control of the factor of the control of the con



2 8 2 8






POH THYE MING



CHMESE MOTEUR 03-02-1971 M MOTEUR BINGAPONE






























Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE GENERAL INSURANCE ASSOCIATION (BRAINES Quay #18-00 Singapore 048580 Tel (65) 8224 0010 Fex (65) 6224 0030 Operating Hours : Monday to Friday, 09:00 – 17:00 UEN: \$665500206 / 48T Reg. Na.: M400017785

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS: Original Report No : MAAS18049025 Vehicle Registration No: SGB2478Z Name(at shownin NRIC): POH THYE MING (MO TAIMING) NRIC/FIN/Passport No : S7103468B (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate Address BLK 201D COMPASSVALE DRIVE #11-569 Singapore (544201) Contact (Tel) : 96889548 Mobile No.: Email Address D3R3KTM@GMAIL.COM 12/04/2018 Date of Accident Time of Accident: 20:05 Place of Accident : UPPER SERANGOON ROAD Insurance Company: SOMPO INSURANCE SINGAPORE PTE, LTD. (B) ADDITIONALINFORMATION / AMENDMENTS: I have made a report on the above mentioned accident and would like to include additional information or make the following amendments: Relationship of the Driver with the insured should be "OWNER". 10 Ang Ma Kilo Industrial Park 2A 703-11 AMK Autgrain

Policyholder / Driver's Signature Date: 13 04 2018

Reporting Centre Personnel's Signature Name: 300 Jie Ti

Singepone 55/1047

NRIC/FINNO .: 4203 1072 W

Date: |8|04|20|8



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	APO INSURANCE				
50 F		SINGAPORE PL	Ref : CS3/SMO1800	6889/Grd3e2-1	
	RAFFLES PLACE -01/06 GAPORE LAND TO	OWERSINGAPORE 048623	Date : 22-10-2018 Code : SMO		
1.		Policy Particulars	:- THIRD PARTY CLA	M	
	Insured Veh.	SGB 2478Z	Veh. Inspected	SJP 8844B	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD1801613/AGC	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	09/10/2018	
2.		Vehicle Part	iculars & Condition		
	Make & Model	JAGUAR XJ	c.c	2993	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	SAJAC2223ANV07924	Colour	MAROON	
	Odometer	164152	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.		Condit	ions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	275/40Z R19	DUNLOP	6 mm	
	L/H Front Tyre	275/40Z R19	DUNLOP	6 mm	
	R/H Rear Tyre	275/40Z R19	DUNLOP	6 mm	
	L/H Rear Tyre	275/40Z R19	DUNLOP	6 mm	
1.		Descript	ion of Damages		
	THE VEHICLE SU	STAINED DAMAGES AT THE RE	EAR PORTION.		
5.	I DAME TO CALL D		al Information		
	Accident Date	12/04/2018	Inspection Date	16/04/2018	
	Survey held at	CADRE AUTOMOBILE			
	1 KAKI BUKIT AVE 6 #02-49 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.			Remarks		

Estimate Days of Repair

7 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 8844B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	DENTED	2,873.00	2,873.00
1	BOOT LID LOCK	BENT	190.00	190.00
1	BOOT LID RUBBER	NOT NECESSARY	253.00	
1	BOOT LID RELEASE BUTTON	CUT	150.00	150.00
1	BOOT LID LOCK CATCH	BENT	160.00	160.00
1	REAR BUMPER	DENTED	2,552.00	2,552.00
1	REAR BUMPER REINFORCEMENT	BENT	746.00	746.00
1	REAR BUMPER BRACKET	BROKEN	80.00	80.00
1	REAR BUMPER SIDE GUIDE	BENT	180.00	180.00
1	REAR BUMPER REVERSE SENSOR	CUT	240.00	240.00
1	REAR BUMPER CHROME MOULDING	BROKEN	508.00	508.00
1	REAR TAILLAMP LH	CRACKED	942.00	942.00
1	REAR TAILLAMP BRACKET	NOT NECESSARY	80.00	
1	REAR END PANEL	DENTED	1,825.00	1,825.00
1	REAR END PANEL GARNISH	NOT NECESSARY	385.00	
1	REAR SPARE TYRE BOARD	NOT NECESSARY	485.00	
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	1,470.00	
1	REAR O/S EXHAUST SILENCER	NOT NECESSARY	1,068.00	
1	REAR O/S EXHAUST SILENCER MOUNTING	DENTED	97.00	97.00
1	REAR O/S EXHAUST HEAT SHIELD	TO REPAIR SEE LABOUR	210.00	
1	BOOT LID LOGO	NECESSARY	60.00	60.00
1	BOOT LID 'XJL' EMBLEM	NECESSARY	97.00	97.00
1	REAR NUMBER PLATE LAMP	BROKEN	60.00	60.00
1	REAR REVERSE CAMERA	NOT NECESSARY	750.00	3
1	REAR SHOCK ABSORBER AIR PUMP	NOT NECESSARY	1,910.00	
1	REAR WIRE HARNESS	TO REPAIR SEE LABOUR	1,553.00	
1	BATTERY TRAY	NOT NECESSARY	50.00	
1	BOOT INNER GARNISH	INTACT	302.00	
2	BOOT HINGES	INTACT	360.00	9
1	BOOT LIFTER MOTOR	INTACT	988.00	9



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-2,062.40	-1,076.00
	17 1 0 0 0 1 1 2 1 0 0 0 0 0 0 0 0 0 0 0 0		18,561.60	9,684.00
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	BROKEN	50.00	50.00
			50.00	50.00
	LABOUR			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING, HARNESS WIRES, SOCKETS, REPLACE DAMAGED PARTS.		250.00	80.00
	TO REMOVE AND REFIT REAR ELECTRICAL WIRING REPLACED DAMAGED LAMPS AND TEST FOR PROPER FUNCTIONING.		60.00	40.00
	TO REMOVE AND REFIT INNER TRIMS, INNER GARNISHES, TO FACILITATE THE REPAIRS.		150.00	80.00
	TO REMOVE AND REFIT REAR BUMPER SENSOR.		220.00	80.00
	TO REMOVE AND REFIT, STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REPLACE REAR EXHAUST SILENCER AND MOUNTINGS.		150.00	70.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WIELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS. INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE PANEL, REAR O/S EXHAUST HEAT SHIELD AND REAR WIRE HARNESS.		1,800.00	1,200.00
	TO SPRAY PAINT ON THE REPLACED AND REPAIRED PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		1,600.00	
			4,230.00	2,450.00
	GRAND TOTAL		22,841.60	12,184.00

RECOMMENDED COST OF LUMP SUM REPAIRS	9,750.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS3/SMO18006889/Grd3e2-1

XING GUO QIANG

ADRIAN LING WAI PING

M.MATAI, AMSAE-A

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Automotive Assessor

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or test, is accepted to any thirst party who may reply on the Report wholly or in part. Any thirst party acting or replying on this Report, in whole or in part, does so at his or her own risk.