

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM18018225/Aba3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH			Date: 27-07-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHD 9725S	Veh. Inspected	SKD 595Z	
	Policy No.	VPX/P1680520	Coverage (\$)	0.00	
	Claim No.	S8M00XX6	Excess (\$)	0.00	
	Assign From	CYNTHIA LOH	Assign Date	09/10/2018	
2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN GOLF	c.c	1390	
	Engine No.	HIDDEN	Year of Reg.	2011	
	Chassis No.	WVWZZZ1KZCW082518	Colour	BLUE	
	Odometer	131805	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
	L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
	R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
	L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	03/10/2018	Inspection Date	10/10/2018	
	Survey held at	PEOPLE'S VEHICLE RECOVER			
	BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				