

<<

Service Request Details

Claim

S8M00XX6

Reference

CC4/ASM18018225/Aba3s2 

Loss Date

October 3, 2018

Report Date

Oct 3, 2018 1:43:26 PM

Request Date

October 4, 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle

SKD595Z

Registration #

Make

TPVD VOLKSWAGEN

Model

NEW GOLF-1.4 TSI (A)

Service Address

, , ,

Primary Contact/Insured

TRANS-CAB SERVICES PTE LTD
No.2 ANG MO KIO STREET 63, 569111,
Singapore

Claim Handler

LOH Cynthia
6568804843
cynthia.loh@axa.com.sg

Additional Instructions

NON REPORTED

1

Messages	Invoices	History	Documents	Assessment	Metrics	Notes
Document Type		Document SubType				
+ Upload Documents						
NAME	TYPE	SUB-TYPE	AUTHOR	DATE	UPLOADED	
 Accident Statement	Reports & Statement		Merimen			
 LKKInvoice1[1].pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2020		
 LKKInspection[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2020		
 LKKAdjustment1a[1].pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2020		
 EMAIL.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2020		
 LKKPhoto.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2020		

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKKPhoto.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	July 27, 2020
 TP GIA.PDF	Reports & Statement	GIA Report	LOH Cynthia	July 16, 2020
 TO LKK.tif	Letters and Correspondence	Investigator / Adjustor	LOH Cynthia	May 6, 2020
 GIA REPORT OF SHD9725S (INSD).PDF	Letters and Correspondence	Others	KADRI Mateen	October 22, 2018
 EMAIL.msg	Letters and Correspondence	Others	KADRI Mateen	October 22, 2018
 PRI EMAIL RECIEVED FROM WORKSHOP WITH TP GIA REPORT.msg	Letters and Correspondence	Workshop	RATAN BHOSALE Pragati	October 3, 2018