

ASS. REC. BY:

REF: CS/msh18018228 / Uber2

Special Instruction:

Survivor:
Merimen

ASSIGNMENT (Office)

From (Person): Jasmine Lk of SLG of Date/Time: 08.10.2018 354 pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLJ 8238J Insured: SLG 461Z

at Workshop m/s Premium Carz Tel:

of Blk 1 Kaki Bukit Ave 6 #01-90

Policy No: 2A0017210MX Claim No: 572413

Sum Insured: Excess:

Make of Veh: D.O.A. 04.10.2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 09.10.2018 12pm Person Contacted: Ann Ting Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLJ 8238J - x
	SLG 461Z - x
10/10/18	Sand preli revised via merimen

Subsidiary No/Cons

REF:

MS14/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLJ8238J
 at Workshop m/s Premium
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLJ8238J Yr Regn: 1216
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mit Attrage C.C. 1193
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 30602 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MMBSTA13AHH003732
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 185/55-215-
 R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Bal. or Market Value: 54
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 13 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS LRA 43169
 Date: _____ Person Contacted: Sys. 2nd. Day 6/10
 Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. 4/10/18 D.O.I. 9/10/18
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or
Rear & Pyl.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
ful portion report? not 10/8/18
sender 987 days 7/10
L/S & 9250

3/10/18 confirmed L/S & 9250 with Aunting (Ref 9096.440, 509)

RECEIVED 01 NOV 2018

Date/Time, File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 13

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return to?

2) 11 - typist

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Transportation: _____

_____\$ + RS_ \$

) Photos

) Other

)

TOTAL

Report Format: Merimen
 Lump Sum / I.B.I: (\$) 9250/2

200
10
210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2018		08 Oct 2018 15:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	DAI JIANYANG , ID: S7663267G, Tel: +6581617080								
Main Claimant:	HENDI RUSLI , ID: S8582428G								
Vehicle Reg. No.:	SLJ8238J	Date of Loss:	04/10/2018 21:00 - :59 [21 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 572413	Policy/Cover Note No.:	29001721QMX (Comprehensive) Coverage: 19/09/2018 - 18/09/2019						
Vehicle Reg. No. (Insured):	SLG461Z	Policy No. (Claimant):							
		Excess:	S\$500.00						
Repairer:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/10/2018]								
Driver/Custodian (Insured):	DAI JIANYANG (42 / Male), NRIC: S7663267G, Tel: +6581617080								
Adj Asg. Remarks:	LIABILITY NOT CLEAR (NON REPORTING) Please appoint MR ADRIAN LING from LKK AUTO CONSULTANTS to conduct the survey . Kindly contact MS CANDICE YEE @ 6636 9100 to arrange for survey.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 10 Oct 2018

Preliminary Advice

Insured Vehicle No	: SLG461Z	Accident Date	: 04/10/2018
TP Vehicle No	: SLJ8238J	Assignment Date	: 08/10/2018
Make	: MITSUBISHI ATTRAGE	Est. Duration of Repair	: 13.00
Date of Inspection	: 09/10/2018		
Inspection At	: PREMIUM CARZ SERVICES PTE LTD (HQ) 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY@KAKI SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,162.80
Revised Amount	:S\$	11,821.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,821.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2428G
Vehicle Details	
Vehicle No.:	SLJ8238J
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Oct 2018
Vehicle Make:	MINI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	3A92UDP0942
Chassis No.:	MMBSTA13AHH003732
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,834.00
Original Registration Date:	28 Dec 2016
First Registration Date:	28 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00 2500
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Dec 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	27 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$39,419.00
Total Rebate Amount:	\$43,169.00

The information contained herein is correct as at 10 Oct 2018

OK

FIRST AUTOWORKS

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933 Tel: 68441985 Fax: 68445185

TAX INVOICE

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way
#07-16, Singapore 079120

GST Ref. No: M2-0111811-!

Vehicle No: SKT2081S
Chassis No : KL1TA48FJFB104028
Engine No: A14XER143400482

Invoice No:

Invoice Date:

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.	Description	Price (SGD)
1	1	BONNET	1,100.00
2	1	FRT BUMPER	980.00
3	1	FRT BUMPER LOGO	157.30
4	1	FRT BUMPER SIDE RETAINER RH	87.50
5	1	FRT BUMPER TOW COVER	60.00
6	1	RH HEADLAMP	866.70
7	1	FRT GRILLE TOP	350.00

Supplementary Items

8	1	FRT RADIATOR GRILLE TOP	420.00
---	---	-------------------------	--------

Rear

9	1	REAR BUMPER ASSY	587.00
10	1	LETTERING SONIC	52.00
11	1	LETTERING "CHEVROLET"	54.00
12	1	TAIL GATE	1200.00
13	1	REAR EMBLEM	78.00

Total: 5992.50
Less 10%: 599.25
Parts Total : 5393.25

Labour

Frnt

No.	Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate & align repair / replacement parts	1,100.00
2	Carry out spray painting on affect area frt portion (frt bumper)	850.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00

Rear

4	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	1,100.00
---	---	----------

- Apple Event '18: iPhones XS, XS Max, XR, Newstead to wind up!
- Liverpool Football Club - 2018/19 season

Mitsubishi Attrage Price Range ▼ Depreciation ▼ 2016 ▼ Vehicle Type ▼

Home » Used Cars » Wheels Singapore Pte Ltd » Mitsubishi Attrage 1.2A

Resources

- [Car Buying](#)
- [Car Selling](#)
- [Car Ownership](#)
- [Car Aftermarket](#)
- [On The Move](#)
- [Lifestyle](#)

Car Tyres



Mitsubishi Attrage 1.2A

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

[Add to Shortlist](#) [Add to Compare](#) [Add a Note](#) [Report Error](#) [More Actions](#)

Car Details

Price	\$51,899	
Depreciation	\$6,010 /yr	?
	View models with similar depreciation	
Reg Date	28-Dec-2016	
	(8yrs 2mths 17days COE left)	
Manufactured	2016	?
Mileage	30,000 km (16.8k /yr)	
Transmission	Auto	
Engine Cap	1,193 cc	
Road Tax	\$506 /yr	?
Power	57.0 kW (76 bhp)	
	View specs of the Mitsubishi Attrage (2014)	
Curb Weight	940 kg	?
Features	Fuel Efficient 1.2L DOHC 12 Valves MIVEC Engine, INVECS-III CVT Automatic Transmission, ABS, EPS, 6 SRS Airbags, Keyless Entry/Start/Stop.	
Accessories	Sports Rims, Leather Seats, Factory Audio System With Steering Controls/Aux/USB Port, Reverse Sensors/Camera, Solar Film, Retractable Side Mirrors.	
Description	Well Maintained By Car Owner. 2nd Car In The Family, Comes With Free Servicing By C&C And 10 Yrs Engine Warranty. Trade In And Loan Available. Consignment Unit. Please Call To Make Viewing Appointment.	
COE	\$48,000	?
OMV	\$13,834	?
ARF	\$5,000	?



Seller Infor

Company

Address

[Compare](#)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/10/2018 15:54
Date Of Accident	04/10/2018 21:50
Exact Location Of Accident	ALONG CTE TOWARDS SLE NEAR BY BRADDELL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLJ8238J
Insured/Policyholder	
Name Of Registered Owner	HENDI RUSLI
NRIC No	S8582428G
Email Address	HENDI_R@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90223795
Alternative Phone No	OFFICE-90223795

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE 1.2 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10792438
Cover Note Number	

Driver

Name of Driver	HENDI RUSLI
NRIC No	S8582428G
Date Of Birth	15/09/1985
Occupation	INDOOR
Date Of Driving Pass	05/08/2009
Driving Experience	9 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90223795
Fax Number	
Contact Number	OFFICE-90223795
Email Address	HENDI_R@HOTMAIL.COM

Address APT BLK 136 YISHUN RING ROAD #21-122 SINGAPORE 760136 .
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : GLENDA MARCO
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS DRIVING ALONG CTE TOWARDS SLE. VEHICLE C IN FRONT OF ME MADE A SUDDEN BRAKE. I MANAGED TO BRAKE IN TIME BUT VEHICLE B BEHIND OF ME COLLIDED ONTO REAR OF MY VEHICLE. I HAVE 2 DAYS OF MC. 3 VEHICLE INVOLVED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO ULOADED INTO FILEZILLA
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG461Z
 Vehicle Make/Model/Colour TOYOTA/HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver DAI JIANSHENG
 NRIC/Passport Number S7562609F
 Contact Number 81617080
 Address
 Postcode
 Insurance Company Name

Address APT BLK 136 YISHUN RING ROAD #21-122 SINGAPORE 760136
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : GLENDA MARCO
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I was driving along CTE towards SLE (nearby Bradell exit). Vehicle C in front of me suddenly made a sudden break. I managed to stop safely on time. Unfortunately, vehicle B behind me collided onto rear of my vehicle which caused my vehicle to surge a few meters forward and hit vehicle C in front. A total of 3 vehicles were involved in this accident. I was also given a 2 days of MC from Khoo Teck Puat Hospital A&E Department.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: VIDEO ULOADED INTO FILEZILLA
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLG461Z
 Vehicle Make/Model/Colour TOYOTA/HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver DAI JIANSHENG
 NRIC/Passport Number S7562609F
 Contact Number 81817080
 Address
 Postcode

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number: SHA7740B
Vehicle Make/Model/Colour: HYUNDAI/I40 1.7L CRDI AT ABS AIRBAG 4DR
Details Of Properties
Vehicle Category: PRIVATE CAR
Name of Driver: CHAY CHEE YEONG
NRIC/Passport Number: S1529970C
Contact Number: 96485073
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name: HENDI RUSLI
Approximate Age
Injuries Sustain
Injured person in which vehicle?: SLJ8238J
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

Sketch Plan




1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Activated Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Jun

**VERIFIED BY AJAX MARS
REPORTING OFFICER
Jun Keat**

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time Witnessed by Reporting Centre Personnel

Sketch Plan



Accident Sketch Plan

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG CTE TOWARDS SLE. VEHICLE C IN FRONT OF ME MADE A SUDDEN BRAKE. I MANAGED TO BRAKE IN TIME BUT VEHICLE B BEHIND OF ME COLLIDED ONTO REAR OF MY VEHICLE. I HAVE 2 DAYS OF MC. 3 VEHICLE INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

5 October 2018 at 12:46 PM

Date/Time:

5 October 2018 at 12:46 PM



Co. Reg. No.: 201416720C
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417888
 Tel : 6636 9100 Fax : 6636 9113

Date : 06/10/2018

TO: MSIG Insurance (Singapore) Pte Ltd
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/during/after painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Our Customer : Hendi Rusli
 Vehicle No : SLJ8238J
 Model : Mitsubishi Attrage 1.2CVT
 Manufacture Year : 2016
 Date of Accident : 04/10/2018
 Total Estimate Repair Days : 20
 Total Pages : 3

Attn : Motor Claims Department
 Fax : 6225 7402

1/5 \$ 9250

not allowed
 LKR
 to be pd. before
 13 day.
 9/10/18
 P/P
 [Signature]
 10/10/18

Re: Repair Estimate For Third Party Claim against SLG461Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts (Nett)				
1	Front bumper 696	1	\$733.00	\$733.00	DS/ae ✓
2	Front bumper side retainer RH	1	\$20.00	\$20.00	ae ✓
3	Front bumper side retainer LH	1	\$20.00	\$20.00	ae ✓
4	Front bumper lower grille	1	\$172.00	\$172.00	Twi ✓
5	Front grille 548	1	\$577.00	\$577.00	ae ✓
6	Front grille "Mitsubishi" logo	1	\$52.00	\$52.00	scr ✓
7	Rear bumper 740	1	\$778.00	\$778.00	D.S ✓
8	Rear bumper side retainer RH	1	\$33.00	\$33.00	ae ✓
9	Rear bumper side retainer LH	1	\$33.00	\$33.00	ae ✓
10	Rear bumper inner corner RH guard	1	\$49.00	\$49.00	ae ✓
11	Rear bumper inner corner LH guard	1	\$49.00	\$49.00	ae ✓
12	Rear bumper reflector RH	1	\$27.00	\$27.00	12X
13	Rear bumper reflector LH	1	\$27.00	\$27.00	12X
14	Tail lamp RH	1	\$303.00	\$303.00	SD ✓
15	Tail lamp LH	1	\$303.00	\$303.00	ae ✓
16	Tail lamp panel RH	1	\$152.00	\$152.00	ae ✓
17	Tail lamp panel LH	1	\$138.00	\$138.00	ae ✓
18	Boot lid 798	1	\$910.00	\$910.00	scr ✓
19	Boot lid lock 65	1	\$227.00	\$227.00	Twi ✓
20	Boot lid lower catch	1	\$27.00	\$27.00	12X
21	Boot lid weatherstrip 148	1	\$162.00	\$162.00	Twi ✓
22	Boot lid "Mitsubishi" logo 38	1	\$45.00	\$45.00	ae ✓
23	Boot lid "Attrage" logo	1	\$27.00	\$27.00	ae ✓
24	Boot lid "MIVEC Technology" logo	1	\$55.00	\$55.00	ae ✓
25	Boot lid chrome 243	1	\$349.00	\$349.00	scr/cro ✓
26	Boot lid hinges	2	\$211.00	\$422.00	12X
27	Rear number plate lamp	2	\$52.00	\$104.00	12X
28	Rear end panel 421	1	\$442.00	\$442.00	scr/cro ✓
29	Rear end panel garnish	1	\$72.00	\$72.00	Twi ✓
30	Spare tyre panel 780	1	\$996.00	\$996.00	scr/cro/ae ✓
31	Spare tyre board	1	\$185.00	\$185.00	Twi ✓
32	Spare tyre carpet	1	\$275.00	\$275.00	12X
33	Rear fender RH 756	1	\$795.00	\$795.00	scr/cro/ae ✓

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
34	Rear fender LH	1	\$795.00	\$795.00	2x
35	Rear fender trimboard RH	1	\$173.00	\$173.00	20 on ✓
36	Rear fender trimboard LH	1	\$173.00	\$173.00	11x
37	Rear wheelhouse panel RH	1	\$275.00	\$275.00	2x
38	Rear wheelhouse panel LH	1	repair	repair	2x
39	Exhaust silencer chrome	1	\$99.00	\$99.00	PD 60
40	Exhaust silencer	1	\$628.00	\$628.00	2x
41	Rear windscreen moulding	1		40 \$0.00	me ✓
Total				\$10,702.00	
Less 10%				\$1,070.20	7231-
Sub Total 1				\$9,631.80	
A.	Spare Parts (S/Nett)				
1	Front bumper clip	10	\$5.00	\$50.00	me ✓
2	Front bumper lower lid	1	\$385.00	\$385.00	2x
3	"Samurai" sticker	1	\$40.00	\$40.00	11x
4	Front number plate	1	\$35.00	\$35.00	34 20
5	Front number plate casing	1	\$35.00	\$35.00	34 20
6	Rear number plate	1	\$35.00	\$35.00	34 20
7	Rear number plate casing	1	\$35.00	\$35.00	34 20
8	Reverse sensor (set)	1	\$250.00	\$250.00	shld 200
9	"Cycle & Carriage" logo	1	\$98.00	\$98.00	me 35
10	Boot lid spoiler	1	\$350.00	\$350.00	71x
11	Rear windscreen sealant	1	\$80.00	\$80.00	me 40
12	Rear bumper clip	10	\$5.00	\$50.00	me ✓
13	Rear end panel garnish clip	8	\$5.00	\$40.00	11x
14	Spare tyre	1	\$250.00	\$250.00	11x
15	Spare tyre tools	1		\$0.00	71x
16	Spare tyre board top cover	1	\$300.00	\$300.00	71 150
17	Rear fender trimboard clip	10	\$5.00	\$50.00	11x
18	Rear fender wheel arch RH	1	\$120.00	\$120.00	71x
19	Reverse camera	1	\$388.00	\$388.00	71x
Sub Total 2				\$2,591.00	
Total for Parts				\$12,222.80	\$605
B.	Labour				
1	To check wiring.			\$120.00	30
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$2,800.00	2 200
3	Spray painting all affected parts & areas.			\$2,000.00	1 700
4	To spray anti-rust undercoat.			\$150.00	1 20
5	To remove and refit rear windscreen glass.			\$120.00	1 20
6	To remove and replace rear exhaust silencer.			\$200.00	60
7	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00	80
8	To remove and install rear wheelhouse.			\$300.00	11x
Total Labour				\$5,940.00	
Total Repair Cost				\$18,162.80	4310

P-7438
102
6691.50

11606.50
202
9285.

18,346.40
19382.40



Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No



Co. Reg. No.: 201416720C
 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
 Tel : 6636 9100 Fax : 6636 9113

Date : 9/10/2018

TO: MSIG Insurance (Singapore) Pte Ltd
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

Our Customer : Hendi Rusli
 Vehicle No : SLJ8238J
 Model : Mitsubishi Attrage 1.2CVT
 Manufacture Year : 2016
 Date of Accident : 04/10/2018
 Total Estimate Repair Days : 20
 Total Pages : 1

Attn : Motor Claims Department
 Fax : 6225 7402

Re: Supplementary Repair Estimate For Third Party Claim against SLG461Z

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts (Nett)				
1	Rear chassis RH	1	repair	repair	R x
2	Rear air vent cover	1	\$49.00	\$49.00	De/Twi ✓
3	Front bumper reinforcement	1	\$155.00	\$155.00	Best ✓
	Total			\$204.00	
	Less 10%			\$20.40	
	Total Supplementary Repair Cost			\$183.60	

Yours faithfully,

 Aun Teng
 f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2018		08 Oct 2018 15:54 Edit Adj Rpt	S\$9,250.00 Edit Estimates	S\$9,250.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	DAI JIANYANG, ID: S7663267G, Tel: +6581617080								
Main Claimant:	HENDI RUSLI, ID: S8582428G								
Vehicle Reg. No.:	SLJ8238J	Date of Loss: 04/10/2018 21:00 - :59 [21 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / 572413	Policy/Cover Note No.: 29001721QMX (Comprehensive) Coverage: 19/09/2018 - 18/09/2019							
Vehicle Reg. No. (Insured):	SLG461Z	Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer:	Premium Carz Services Pte Ltd (HQ) 1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki, 417883 Kaki Bukit - Tel: 66369100								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jowyn Tay Mei Ling - 6643 1307]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/11/2018]								
Driver/Custodian (Insured):	DAI JIANYANG (42 / Male), NRIC: S7663267G, Tel: +6581617080								
Adj Asg. Remarks:	LIABILITY NOT CLEAR (NON REPORTING) Please appoint MR ADRIAN LING from LKK AUTO CONSULTANTS to conduct the survey . Kindly contact MS CANDICE YEE @ 6636 9100 to arrange for survey.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ8238J (572413)**
[SLG461Z]
TP
HENDI RUSLI
Oct 4 2018 9:00PM
[DAI JIANYANG]
Premium Carz Services Pte Ltd

<input type="button" value="Upload Documents"/> <input type="button" value="Upload Photos"/> <input type="button" value="Compose New Letter"/>			View <input type="button" value="View in Browser"/>
Letters/Correspondences			1 per page <input type="button" value="✓"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail Print
1	08/10/18 14:44	Non Reporting Letter to OI	Load HTM
Assessment Reports			1 per page <input type="button" value="✓"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	10/10/18 10:19	Adjuster Immediate Advice	Load HTM
Photos/Images			3 per page <input type="button" value="✓"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
2	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
3	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
4	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
5	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
6	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
7	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
8	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
9	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
10	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
11	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
12	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
13	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
14	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
15	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
16	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
17	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
18	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
19	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
20	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
21	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
22	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
23	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
24	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
25	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
26	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
27	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
28	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
29	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>
30	10/10/18 10:21	General View	Load JPG <input type="button" value="✓"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	10/10/18 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
32	10/10/18 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
33	10/10/18 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
34	10/10/18 10:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
36	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
37	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
38	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
39	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
40	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
41	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
42	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
43	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
44	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
45	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
46	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
47	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
48	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
49	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
50	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
51	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
52	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
53	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
54	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
55	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
56	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
57	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
58	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
59	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
60	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
61	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
62	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
63	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
64	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
65	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
66	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
67	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
68	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
69	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
70	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
71	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
72	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
73	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
74	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
75	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
76	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
77	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
78	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
79	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>
80	10/10/18 10:22	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
81	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
82	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
83	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
84	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
85	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
86	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
87	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
88	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
89	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
90	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
91	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
92	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
93	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
94	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
95	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
96	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
97	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
98	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
99	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
100	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
101	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
102	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
103	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
104	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
105	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
106	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
107	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
108	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
109	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
110	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
111	10/10/18 10:22	General View		Load JPG <input checked="" type="checkbox"/>
112	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
113	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
114	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
115	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
116	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
117	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
118	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
119	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
120	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
121	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
122	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
123	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
124	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
125	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
126	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
127	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
128	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
129	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
130	01/11/18 09:03	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
131	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
132	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
133	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
134	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
135	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
136	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
137	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
138	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
139	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
140	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
141	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
142	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
143	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
144	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
145	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
146	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
147	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
148	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
149	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
150	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
151	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
152	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
153	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
154	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
155	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
156	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
157	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
158	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
159	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
160	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
161	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
162	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
163	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
164	01/11/18 09:03	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
165	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
166	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
167	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
168	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
169	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
170	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
171	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
172	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
173	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
174	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
175	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
176	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
177	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
178	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
179	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
180	01/11/18 09:03	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ)		
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	08/10/18 14:54	TPD SLJ8238J GIA REPORT	Load PDF	
2	08/10/18 14:54	TPD SLJ8238J - PRI	Load PDF	
3	08/10/18 14:54	Reply email from TP Workshop & appoint MR ADRIAN LING from LKK AUTO	Load PDF	
No	Relabel/Reorder		Thumbnail	Print
1	05/11/18 11:16	Supplementary	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18018228/UVBE2

Date: 05/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29001721QMX

Claimant Vehicle No : SLJ8238J

Insured Vehicle No : SLG461Z

Date of Loss: 04/10/2018

Nature of Claim: TP

Claim No: 572413

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ8238J**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A)

Engine No: 3A92UDP0942

Reg. Date: 28/12/2016 (Man. Year: 2016)

Chassis No: MMBSTA13AHH003732

Colour: White

Odometer: 30602 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 185/55 R15

Rear Tyre Size: 185/55 R15

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,442.40	7,296.50	5,145.90	41.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,940.00	4,310.00	1,630.00	27.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,382.40	11,606.50	6,775.90	36.86
Approved Total (Overridden) (S\$)		9,250.00		
Nett Amount (S\$)	18,382.40	9,250.00	9,132.40	49.68

INSPECTION

Date of Assignment: 08/10/2018

Date Inspected: 09/10/2018 Inspected At:

Premium Carz Services Pte Ltd (HQ)
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki
Singapore 417883

Estimated Period of Repair: 13.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 05 Nov 2018)	
Parts:	N/A	MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ8238J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	733.00 FL	*696.00 FL
2	1		*FRONT BUMPER SIDE RETAINER RH	Bent	20.00 FL	*20.00 FL
3	1		*FRONT BUMPER SIDE RETAINER LH	Bent	20.00 FL	*20.00 FL
4	1		*FRONT BUMPER LOWER GRILLE	Twisted	172.00 FL	*172.00 FL
5	1		*FRONT GRILLE	Cracked	577.00 FL	*548.00 FL
6	1		*FRONT GRILLE MITSUBISHI LOGO	Scratched	52.00 FL	*52.00 FL
7	1		*REAR BUMPER	Distorted	778.00 FL	*740.00 FL
8	1		*REAR BUMPER SIDE RETAINER RH	Bent	33.00 FL	*33.00 FL
9	1		*REAR BUMPER SIDE RETAINER LH	Bent	33.00 FL	*33.00 FL
10	1		*REAR BUMPER INNER CORNER RH GUARD	Deformed	49.00 FL	*49.00 FL
11	1		*REAR BUMPER INNER CORNER LH GUARD	Deformed	49.00 FL	*49.00 FL
12	1		*REAR BUMPER REFLECTOR RH	Not Necessary	27.00 FL	*- FL
13	1		*REAR BUMPER REFLECTOR LH	Not Necessary	27.00 FL	*- FL
14	1		*TAIL LAMP RH	Broken	303.00 FL	*303.00 FL
15	1		*TAIL LAMP LH	Cracked	303.00 FL	*303.00 FL
16	1		*TAIL LAMP PANEL RH	Bent	152.00 FL	*152.00 FL
17	1		*TAIL LAMP PANEL LH	Repair	138.00 FL	*- FL
18	1		*BOOT LID	Buckled	910.00 FL	*798.00 FL
19	1		*BOOT LID LOCK	Twisted	227.00 FL	*65.00 FL
20	1		*BOOT LID LOWER CATCH	Not Necessary	27.00 FL	*- FL
21	1		*BOOT LID WEATHERSTRIP	Twisted	162.00 FL	*148.00 FL
22	1		*BOOT LID MITSUBISHI LOGO	Necessary	45.00 FL	*38.00 FL
23	1		*BOOT LID ATTRAGE LOGO	Necessary	27.00 FL	*27.00 FL
24	1		*BOOT LID MIVEC TECHNOLOGY LOGO	Necessary	55.00 FL	*55.00 FL
25	1		*BOOT LID CHROME	Scratched / Cracked	349.00 FL	*243.00 FL
26	2		*BOOT LID HINGES	Not Necessary	422.00 FL	*- FL
27	2		*REAR NUMBER PLATE LAMP	Not Necessary	104.00 FL	*- FL
28	1		*REAR END PANEL	Badly Dented	442.00 FL	*421.00 FL
29	1		*REAR END PANEL GARNISH	Twisted	72.00 FL	*72.00 FL
30	1		*SPARE TYRE PANEL	Crumpled / Buckled	996.00 FL	*980.00 FL
31	1		*SPARE TYRE BOARD	Torn	185.00 FL	*185.00 FL
32	1		*SPARE TYRE CARPET	Not Necessary	275.00 FL	*- FL
33	1		*REAR FENDER RH	Badly Dented / Buckled	795.00 FL	*756.00 FL
34	1		*REAR FENDER LH	Repair	795.00 FL	*- FL
35	1		*REAR FENDER TRIMBOARD RH	Torn	173.00 FL	*173.00 FL
36	1		*REAR FENDER TRIMBOARD LH	Not Necessary	173.00 FL	*- FL
37	1		*REAR WHEELHOUSE PANEL RH	Repair	275.00 FL	*- FL
38	1		*REAR WHEELHOUSE PANEL LH (NPA)	Repair	0.00 FL	*- FL
39	1		*EXHAUST SILENCER CHROME	Dented	99.00 FL	*60.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*EXHAUST SILENCER	Repair	628.00 FL	*- FL
41	1		*REAR WINDSCREEN MOUDLING	Necessary	40.00 FL	*40.00 FL
42	10		*FRONT BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
43	1		*FRONT BUMPER LOWER LID	Repair	385.00 FS	*- FS
44	1		*FRONT NUMBER PLATE	Bent	35.00 FS	*20.00 FS
45	1		*FRONT NUMBER PLATE CASING	Bent	35.00 FS	*20.00 FS
46	1		*REAR NUMBER PLATE	Bent	35.00 FS	*20.00 FS
47	1		*REAR NUMBER PLATE CASING	Bent	35.00 FS	*20.00 FS
48	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
49	1		*CYCLE & CARRIAGE LOGO	Necessary	98.00 FS	*35.00 FS
50	1		*BOOT LID SPOILER	Not Necessary	350.00 FS	*- FS
51	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
52	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*50.00 FS
53	8		*REAR END PANEL GARNISH CLIP	Not Necessary	40.00 FS	*- FS
54	1		*SPARE TYRE	Not Necessary	250.00 FS	*- FS
55	1		*SPARE TYRE TOOLS (NPA)	Not Necessary	-	-
56	1		*SPARE TYRE BOARD TOP COVER	Torn	300.00 FS	*150.00 FS
57	10		*REAR FENDER TRIMBOARD CLIP	Not Necessary	50.00 FS	*- FS
58	1		*REAR FENDER WHEEL ARCH RH	Not Necessary	120.00 FS	*- FS
59	1		*REVERSE CAMERA	Not Necessary	388.00 FS	*- FS
60	1		*REAR CHASSIS RH (NPA)	Repair	0.00 FL	*- FL
61	1		*REAR AIR VENT COVER	Deformed / Twisted	49.00 FL	*49.00 FL
62	1		*FRONT BUMPER REINFORCEMENT	Bent	155.00 FL	*155.00 FL
63	1		*SAMURAI STICKER	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,537.00	8,040.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,094.60	743.50
Total Parts (S\$)	12,442.40	7,296.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	120.00	30.00
2	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	2,800.00	2,200.00
3	SPRAY PAINTING ALL AFFECTED PARTS & AREAS	New	2,000.00	1,700.00
4	TO SPRAY ANTI-RUST UNDERCOAT	New	150.00	120.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
6	TO REMOVE AND REPLACE REAR EXHAUST SILENCER	New	200.00	60.00
7	TO REMOVE AND REFIT REAR SEATS, REAR WHEELHOUSE INNER GARNISH, FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS	New	250.00	80.00
8	TO REMOVE AND INSTALL REAR WHEELHOUSE	New	300.00	0.00
Gross Labour Cost (\$\$)			5,940.00	4,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >