

22/03/2002

ASS. REC. BY:

REF:

CS3/SMD 18018250/Acd30

Special Instruction:

Surveyor

Mennen

Adnan

ASSIGNMENT (Office)

From (Person):

Gmel Leo

of

SMD

Date/Time:

8/10/18 @ 4:39pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIP 6871 K

Insured:

SKR 5172 D

at Workshop m/s

Yap Lee Motor

Tel:

6844 1555

of

1 Kaki Bukit Ave 6 # 01-26 Auto bay

Policy No:

D18MTPV01000562

Claim No:

CMTD1804366

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

5/10/18

CA / REV / REP. / REV 24 HRS

1 up

H.O.D. Endorsement:

Date/Time:

11:49am @ 9/10/18

Person Contacted:

Flurley

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

SIP 6871 K-X

SKR 5172 D-X.

Dismantle: 9/10/2018

SIN2005

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____ - _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:		
IDAC Accident Rpt:		Consistent? : Yes or No
GIA / PR Seen:		Consistent? : Yes or No
Est. Repairs:	<u>6</u> days	Res.: Yes or No
Lum Sum:	%	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

R: 185/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	06	mm	R/Bal. 06 mm
L/Bal.	06	mm	L/Bal. 06 mm
D.O.A.			D.O.I. 09/10/18

Survey held at Ysp Loe.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Soaps PRS.
	= Estimated repair range \$4,500 - \$6,000
	<i>[Signature]</i> 12/10/2018

Date/Time: File Pass to?

13

Date/Time File Return to?

2)

Report Format : PRQ .

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee: ☐ : Site Insp (\$) ____S + RS ____SI

Interview (\$) Photos

Tech. Invs (\$) Others

Weekend (\$

TOTAL

100

60

10

170

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Oct 2018		08 Oct 2018 16:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YEO SUAN SIANG , ID: S7801238B								
Main Claimant:	PHUA LAY HENG , ID: S1688330A								
Vehicle Reg. No.:	SJP6871K	Date of Loss:	05/10/2018 19:00 - :59						
Claim Type:	TP / CMTD1804366	Policy/Cover Note No.:	D18MTPV01000562 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKR5172D	Policy No. (Claimant):							
		Excess:							
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 17/10/2018]								
Adj Asg. Remarks:	- PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT - NO TP SAS SUBMITTED								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 8 October 2018 4:39 PM
To: Ruby Ong; assignments@lkkauto.com; assignments@lkkauto.com
Cc: Yap Lee Motor; Gnoh, Pau Loong; Ye, Yong Kang Melvin
Subject: CMTD1804366/GPL - SUV(LKK)/ SKR5172D / SJP6871K ACC ON 05.10.18 [YR REF. TCL.GCN.RO.50392.18.YLM]

Our Reference : CMTD1804366/GPL
Your Reference: TCL.GCN.RO. 50392.18.YLM

Without Prejudice
EMAIL ONLY

Date: 8th October 2018

Attention:
M/S HIN TAT AUGUSTINE & PARTNERS

Dear Ruby,

ACCIDENT INVOLVING SKR5172D & SJP6871K ON 05.10.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompso SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompso Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ruby Ong [mailto:ruby@htapartners.com.sg]
Sent: Monday, October 08, 2018 4:30 PM
To: Teo, Grace
Cc: Yap Lee Motor; Gnoh, Pau Loong; Ye, Yong Kang Melvin
Subject: RE: CMTD1804366/GPL - PRI/ SKR5172D / SJP6871K ACC ON 05.10.18 [YR REF. TCL.GCN.RO.50392.18.YLM]
Importance: High

Dear Sirs

WITHOUT PREJUDICE

We refer to your email of even date informing that you wish to conduct a pre-repair survey and to your List of Motor Surveyors.

TAKE NOTICE that we object to all your surveyors stated in your said List, for appointment as the Single Joint Expert.

Pursuant to Pre-Action Protocol for NIMA cases, we now propose for appointment as Single Joint Expert the following List of Motor Surveyors for your consideration:-

1. Andrew How Prominent Appraiser Services Pte Ltd
2. Alan CL Appraiser Pte Ltd

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

Venue : **Yap Lee Motor**
1 Kaki Bukit Avenue 6
#01-26 Autobay@Kaki Bukit (417883)

Contact Person : **Mrs Chua / Shirley : 6844 1555**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 278
Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Teo, Grace <grace.teo@sompo.com.sg>

Sent: Monday, October 08, 2018 3:31 PM

To: Ruby Ong <ruby@htapartners.com.sg>

Cc: Yap Lee Motor <yap_lee_motor@singnet.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1804366/GPL - PRI/ SKR5172D / SJP6871K ACC ON 05.10.18 [YR REF. TCL.GCN.RO.50392.18.YLM]

Our Reference : CMTD1804366/GPL

Your Reference: TCL.GCN.RO. 50392.18.YLM

Without Prejudice

EMAIL ONLY

Date: 8th October 2018

Attention:

M/S HIN TAT AUGUSTINE & PARTNERS

Dear Ruby,

ACCIDENT INVOLVING SKR5172D & SJP6871K ON 05.10.2018

We refer to your Notice of Accident dated 08/10/2018.

Please be informed that Mr. Gnoh Pau Loong is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

- Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ruby Ong [<mailto:ruby@htapartners.com.sg>]

Sent: Monday, October 08, 2018 2:37 PM

To: Claims - Motor Survey

Cc: Yap Lee Motor

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SJP6871K [OUR REF. TCL.GCN.RO.50392.18.YLM]

Importance: High

Your ref: SKR 5172D

Our ref: TCL.GCN.ro.50392.18.ylm

WITHOUT PREJUDICE

8 October 2018

Sompo Insurance Pte Ltd
Motor Claims Department
50 Raffles Place #05-01/06
Singapore Land Tower
Singapore 048623

By Email Only

VERY URGENT

Dear Sir,

CLAIMANT: PHUA LAY HENG

ACCIDENT INVOLVING SJP 6871K, SKR 5172D & SKH 1802Z ALONG MARYMOUNT ROAD TOWARDS THOMSON ROAD ON 5 OCTOBER 2018 @ 1900RS

We are instructed by Phua Lay Heng to notify you of a road traffic accident on 5 October 2018 at about 1900 hrs along Marymount Road towards Thomson Road involving our client's vehicle registration number **SJP 6871K** and vehicle registration number SKR 5172D driven by your insured's driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 278

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8330A
Vehicle Details	
Vehicle No.:	SJP6871K
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1ZZ3235482
Chassis No.:	JTDER12W703002507
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$18,662.00
Original Registration Date:	01 Apr 2009
First Registration Date:	01 Apr 2009
Transfer Count:	3
Actual ARF Paid:	\$8,657.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Mar 2019
PARF Rebate Amount:	\$4,328.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$831.00
COE Rebate Amount:	\$233.00
Total Rebate Amount:	\$4,561.00

The information contained herein is correct as at 12 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2018 14:30
Date Of Accident	05/10/2018 19:00
Exact Location Of Accident	MARYMOUNT ROAD TOWARDS THOMSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJP6871K
Insured/Policyholder	
Name Of Registered Owner	PHUA LAY HENG
NRIC No	S1688330A
Email Address	PHUA_LAY_HENG@NYP.EDU.SG
Mobile Phone No	(LOCAL) +65-90221855
Alternative Phone No	OFFICE-90221855

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101205891
Cover Note Number	

Driver

Name of Driver	PHUA LAY HENG
NRIC No	S1688330A
Date Of Birth	26/08/1965
Occupation	INDOOR
Date Of Driving Pass	02/07/1985
Driving Experience	33 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90221855
Fax Number	
Contact Number	OFFICE-90221855
Email Address	PHUA_LAY_HENG@NYP.EDU.SG

Address	253 ARCADIA ROAD #05-12
Postcode	289849
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE SEE ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG, SENT VIA EMAIL TO NTUC
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKR5172D
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	TO HUI YI
NRIC/Passport Number	
Contact Number	NA
Address	NA
	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKH1802Z
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	PRIVATE CAR
Name of Driver	MURUGAIAH MITHULPRANAV
NRIC/Passport Number	
Contact Number	NA
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the G-A Records Management Centre (GARC) to the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report by the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may (and permitted to) collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to an insurer(s) who have insured vehicle(s) involved in this accident (an insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to my enquiries; and
 - (iv) administering my claims including the making of correspondence, statements, disclosures, reports or notices to me, which could involve disclosure of certain personal data about me relating to the accident, as well as on the external cover of envelopes/packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may (and permitted to) collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may be disclosed by any of the insurers and/or GIA to any third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, handling or managing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (iii) for complying with requirements under any regulations, law or court orders.



Policyholder's Signature
Date & Time


Driver's Signature
If driver is not the policyholder
Date & Time


Witness (in the presence of the Policyholder's Signature)
Name
Date & Time

Individual Statement

SKETCH PLAN



A STP6871K

B SKR5172D

C SKH1202Z

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- As per customer statement -

Insured's Co. _____
Vehicle No. _____ Date of Accident _____
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input checked="" type="checkbox"/> Third Party Claim

(2) Yap Lee Maw S

DECLARATION

(We declare the following particulars are true in every respect)

Insured's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Officer/Personnel's Signature
Name
Post. ID No.

Individual Statement

Statement of Account from Mr Phua Lay Heng (Owner & Driver of SJP6871K) - Accident on 5 Oct 2018 (about 7pm) Along Marymount Road towards Thomson Road

On 5 Oct 2018 (Friday) at about 7pm, I was on my way home from office in Ang Mo Kio. I was driving my SJP6871K [White, Toyota Wish] along Marymount Rd towards the direction of Thomson Rd. Vehicle speed estimated to be between 60-70 km/h. The weather was clear. Visibility was good. Traffic was light in my direction.

Pic 1



The portion of the road nearer to the Cross-junction (pls see Pic 1) has 5 lanes. Three straight going lanes towards Thomson Rd. 1 right turn lane (to Sin Ming Ave) and 1 right turn/straight going lane.

When approaching the above Cross-junction, I was on the 2nd leftmost lane (middle of the 3 straight going lanes). A dark blue Nissan (SKR5172D) was on my right (or the 3rd leftmost lane). The vehicle SKR5172D was travelling at about half car length ahead of me at my right. When approaching the Cross-junction (with green light in our favour) I felt an impact and heard a sound coming from the right side of my car. It was followed by some vibration when I could feel the impact caused some dragging on the right side of my car. When it was over in a flash, my car was in the middle of the Cross-junction which I slowed down and kept safely to the left side of the road and stopped without causing obstruction.

I alighted and went back to the junction. The lady Chinese driver of SKR5172D apologised for knocking onto my car. She explained that another car SKH1802Z (Toyota Corolla Altis), that was on her right (the right turn/straight going lane) came into her lane. She honed and applied the brake and swerved into my lane to avoid a collision with SKH1802Z and resulted in the accident.

I went over to see the vehicle SKH1802Z, the male Indian driver of SKH1802Z too apologised for causing the accident.

After the necessary parties have taken the photos, they moved the cars forward to the side of the road near where my vehicle has stopped.


Individual Statement

All parties exchanged particulars. During the 3-party conversation, Ms To has suggested to make the necessary report and file claims from the insurers accordingly. She has initiated to create a chat group for the 3 parties and promised to upload the video footage (this did not happen). Mr Murugaiah was advised to keep his dad informed of the accident as he is not the owner of the vehicle.

All parties left the scene.

On 6 Oct 18 (Sat, 12:26am), Ms To suggested to me a private settlement through Whatsapp chat (pls see Pic 2) and willing to foot the bill for the repair of my car. I was willing to explore the option and promised to obtain a quote without making and filing a report. After much consideration on 7 Oct 18 (Sunday), Ms To finds that the repair cost was above her budget and too prohibitive to proceed with private settlement. It was then confirmed and agreed that we will file our respective reports on 8 Oct 2018. Ms To has mentioned that she will inform the other driver Mr Murugaiah of the arrangement.

Pic 2




Phua Lay Heng
Owner and Driver of Vehicle SJP6871K
90221855

Note:

Files in the Thumb Drive include:

1. Photos of:
 - Driving License of lady driver SKR5172D, Ms To Hui Yi (Tao Huiyi)
 - NRIC of driver of SKH1802Z, Mr Murugaiah M Mithulpranav
2. Photos taken on 5 Oct 2018
3. Video footage of the accident at the scene (pls view with VLC media player) – pls ignore the date/time stamp on the footage as the camcorder was not set correctly
4. Words file of this Statement

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2018		08 Oct 2018 16:38 Edit Adj Rpt	\$50.00 Edit Estimates	\$50.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	YEO SUAN SIANG , ID: S7801238B								
Main Claimant:	PHUA LAY HENG , ID: S1688330A								
Vehicle Reg. No.:	SJP6871K	Date of Loss:	05/10/2018 19:00 - :59 [114 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1804366	Policy/Cover Note No.:	D18MTPV01000562 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKR5172D	Policy No. (Claimant):							
		Excess:							
Repairer:	Yap Lee Motor (HQ) 1 Kaki Bukit Avenue 6, #01-26 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/10/2018]								
Adj Asg. Remarks:	- PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT - NO TP SAS SUBMITTED								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJP6871K (CMTD1804366)

[SKR5172D]



































TP





PHUA LAY HENG

Oct 5 2018 7:00PM

[YEO SUAN SIANG]

Yap Lee Motor

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)					Thumbnail	Print	
1	09/10/18 11:06	Accident Statement From: SC - Reg. No: SKR5172D, Claimant: YEO SUAN SIANG					 Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
2	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
3	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
4	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
5	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
6	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
7	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
8	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
9	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
10	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
11	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
12	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
13	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
14	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
15	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
16	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
17	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
18	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
19	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
20	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
21	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
22	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
23	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
24	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
25	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
26	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
27	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
28	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
29	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
30	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
31	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
32	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	
33	12/10/18 15:46	General View					 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
34	12/10/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
35	12/10/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
36	12/10/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
37	12/10/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
38	12/10/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
39	12/10/18 15:46	General View	 Load JPG	<input checked="" type="checkbox"/>
40	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	12/10/18 15:47	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	08/10/18 16:40	Pre-Repair Survey ASSIGN LKK	 Load PDF	
2	09/10/18 11:04	Third Party E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18018250/ACD3E2

Date: 17/10/2018

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01000562

Claimant Vehicle No: SJP6871K Insured Vehicle No: SKR5172D

Date of Loss: 05/10/2018 Nature of Claim: TP Claim No: CMTD1804366

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJP6871K
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3235482
 Reg. Date: 01/04/2009 (Man. Year: 2009) Chassis No: JTDER12W703002507
 Colour: White Odometer: 127245 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/55 R15 Rear Tyre Size: 195/55 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/10/2018

Date Inspected: 09/10/2018 Inspected At:

Yap Lee Motor (HQ)
 1 Kaki Bukit Avenue 6, #01-26 Autobay @
 Kaki Bukit
 Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,500.00 -\$6,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Oct 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJP6871K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >