

22/03/2002

ASS. REC. BY:

REF:

CS3/FWD18018259/Tcd30

Special Instruction:

Surveyor:
monmen

Taufik

ASSIGNMENT (Office)

From (Person):

Josey Loh

of

FWD

Date/Time:

8/10/18 @ 3.43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 1740H

Insured:

SLJ 4312D

at Workshop m/s

Ngei Hong Auto

Tel:

9677 9434

of

160 Sing Ming Drive # 06-08

Policy No:

Claim No:

12018 00012603

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/10/18

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

H.O.D. Endorsement:

Date/Time:

9.51am @ 9/10/18

Person Contacted:

Mr. Teo

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SLV 1740H - X
	SLJ 4312D - X
10/10/18-	VNI yet (Mr. Teo)

PRs: *Tay Hin*

REF: FWD

ASSIGNMENT

From: _____ Date: 12/10/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 1740H

at Workshop m/s *Ngai Hong Spray Painting*
of *160 Sh Ming Drive #06-08*

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *#5* days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *(up)*

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLV 1740H* Yr Regn: *Dec 17*

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda Vezel* C.C. *1496*

Colour: *Gold* A/C: Insured / Std / NI / NA

Sp. Reading: *36129* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *R41/229299*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *215/60R16*

R: *27*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front *6*

Rear *6*

R/Bal. _____ mm

R/Bal. _____ mm

L/Bal. *6* mm

L/Bal. *6* mm

D.O.A. _____

D.O.I. *12/10/18 24pm*

Survey held at *Ngai Hong*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>Range 3800/2 - 4500/2</i>
	<i>Repair days #5</i>
	<i>19/10/2018</i>
	<i>Tellim Lim</i>
	<i>19/10/18</i>

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *5*

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: *80*

Transportation: _____

Photos

Others

TOTAL

80

Report Format: *PRE*

Lump Sum / I.B.I: (\$ _____)

Catherine Chong (LKK Auto)

From: motorclaims.sg@fwd.com
Sent: Monday, 8 October, 2018 3:43 PM
To: assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com; admin-d@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: [SPAM] Re: our Ref: DT/mlc/SLV1740H FWD Ref: 1201800012603
Attachments: PDF - SLV1740H - PRI.PDF

Hi LKK team,

Please refer to the attached and liaise with TP repairer for PRS.

Attached is the TP GIA report.

Please create the case in Merimen.

Thank you.

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



From: Motor Claims SG - SG Common
Sent: Monday, 8 October, 2018 3:39 PM
To: gillian@advlawllc.com
Cc: Motor Claims SG - SG Common
Subject: RE: [SPAM] Re: our Ref: DT/mlc/SLV1740H FWD Ref: 1201800012603

WITHOUT PREJUDICE

Dear Gillian,

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s LKK Auto Consultants Pte Ltd, to conduct the pre-repair survey (PRS) on your client's vehicle, SLV1740H. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh

Executive, Claims


FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg



From: gillian@advlawllc.com [<mailto:gillian@advlawllc.com>]

Sent: Monday, 8 October, 2018 3:18 PM

To: Motor Claims SG - SG Common

Subject: FW: [SPAM] Re: our Ref: DT/mlc/SLV1740H FWD Ref: 1201800012603

Hi,

We refer to the above matter.

Our client are requested whether can you appointing FormTeam Consultancy Pte Ltd.

Please revert. Thank you.

Best Regards

Gillian

Advance Law LLC

63235488

From: teo yew haw [<mailto:yewhaw@ngaihongsp.com>]

Sent: Monday, 8 October, 2018 1:53 PM

To: gillian@advlawllc.com

Subject: [SPAM] Re: our Ref: DT/mlc/SLV1740H FWD Ref: 1201800012603

Hi Gillian,

please ask them, can they agree with FormTeam Consultancy Pte Ltd.
Thank you.

On Mon, 8 Oct 2018 at 12:28, <gillian@advlawllc.com> wrote:

Hi Mr Teo,

Please refer to an email from FDW for your attention.

Kindly let us have your instructions.

Best Regards

Gillian

Advance Law LLC

63235488

From: motorclaims.sg@fwd.com [mailto:motorclaims.sg@fwd.com]

Sent: Monday, 8 October, 2018 11:54 AM

To: gillian@advlawllc.com

Cc: motorclaims.sg@fwd.com

Subject: [SPAM] RE: Your Ref: DT/mlc/SLV1740H FWD Ref: 1201800012603

WITHOUT PREJUDICE

Dear Gillian,

We refer to your letter dated 08 October 2018 of the PRI Notice of your client's vehicle SLV1740H.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD
4. Appraisals Associates Pte Ltd
5. VICOM Ltd

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

****Please note that we do not accept fax. Hence, please send in any correspondences related to Motor Claims via e-mail to motorclaims.sg@fwd.com. Thank you.***

Kind Regards

Josey Loh

Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5872

E josey.loh@fwd.com

W fwd.com.sg

From: gillian@advlawllc.com [<mailto:gillian@advlawllc.com>]

Sent: Monday, 8 October, 2018 11:49 AM

To: Motor Claims SG - SG Common

Subject: RE: PRS

WITHOUT PREJUDICE

Dear Sir/Madam,

Please see attached our PRS letter for your urgent attention. Thank you.

Best Regards

Gillian

M/s Advance Law LLC

63235488

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

No virus found in this message.

Checked by AVG - www.avg.com

Version: 2016.0.8048 / Virus Database: 4793/15883 - Release Date: 08/14/18

Internal Virus Database is out of date.

Best Regards,

Teo Yew Haw | Managing Director

Ngai Hong Spray Painting & Ngai Hong Auto Services

Blk 160 Sin Ming Drive #06-08 Sin Ming AutoCity

HP: +65 96779434 | O: +65 64531712 | Fax: +65 62666402

Webpage: www.ngaihongsp.com | FB: <https://www.facebook.com/ngaihongsp/>

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.



Advocates & Solicitors
Commissioner for Oaths
Notary Public
UEN: 201310208H

430 Lorong 6 Toa Payoh
#11-01 Orangetee Building
Singapore 319402
Tel: (65) 6323 5488 (5 lines)
Fax: (65) 6258 5521
(65) 6225 7738

Business Hours: Mon to Fri
9.00am to 6.00pm

check file - 100216

Directors:
DANNY TEO KIM SOON (MD)
DAVID HK FONES

Senior Associates:
SIM HUI SHIEN, ADELINE

Associates:
TAN SHU HUA VANESSA

Consultant:
WONG CHEE MUN

Email: admin@advancelaw.com We do not accept service of Court documents by fax transmissions.
Secretary-in-charge : Ms Gillian / e-mail: gillian@advancelaw-llc.com

(Please quote our Ref. when replying)

Your Ref: To be advised
Our Ref: DT/mlc/SLV1740H (PD)

05 October 2018

FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

BY EMAIL

Attention: Motor Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING SLV1740H & SLJ4312D ALONG BUKIT BATOK EAST AVENUE 6 TO BUKIT BATOK AVENUE 1 (TOWARDS JURONG EAST) ON 02/10/2018 @ 07:30 HRS

We act for **Mr Chuah Choon Yen** in an accident above.

We are instructed by the abovenamed to notify you of a road accident on **2 OCTOBER 2018** at about 07:30 hrs **ALONG BUKIT BATOK EAST AVENUE 6 TO BUKIT BATOK AVENUE 1 (TOWARDS JURONG EAST)** involving our client's motor vehicle **SLV1740H** and motor vehicle **SLJ4312D** driven by you or your authorized driver at the material time. A copy of the GIA/Traffic Police Report is enclosed. Kindly also let us have your GIA/Traffic Police Report for our necessary.

As a result of the accident, our client's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Please note that our client's motor vehicle **SLV1740H** is now at the following workshop: -

Ngai Hong Auto Services
160 Sin Ming Drive #06-08
Sin Ming Auto City
Singapore 575722

Contact Person: Mr. Teo Yew Haw (9677 9434)

(BY FAX: 6266 6402)

Yours faithfully,



ADVANCE LAW LLC

cc: client

** Survey was conducted by:-

Name of Surveyor:

Date of Survey:

Time of Survey:

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0454E
Vehicle Details	
Vehicle No.:	SLV1740H
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X SENSING CVT ABS D/AIRBAG 2WD
Primary Colour:	Gold
Manufacturing Year:	2017
Engine No.:	L15B4429304
Chassis No.:	RU11229299
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,164.00
Original Registration Date:	22 Dec 2017
First Registration Date:	22 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$11,630.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2027
PARF Rebate Amount:	\$8,722.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,761.00
COE Rebate Amount:	\$38,314.00
Total Rebate Amount:	\$47,036.00

The information contained herein is correct as at 18 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process.
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7 By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available abroad.

ACCIDENT STATEMENT

Date Of Report 03/10/2018 08:53
Date Of Accident 02/10/2018 07:30
Exact Location Of Accident SLIP RD FM BT8 BATOK EAST AVE 6 TO BT BATOK AVE 1
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLV1740H
Insured/Policyholder
Name Of Registered Owner JUST-IN-TIME CARRIAGE
Co Reg No 53370454E
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96893787
Alternative Phone No OFFICE-96893787
Vehicle Particulars
Manufacturer HONDA
Model VEZEL-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE HIRE
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5096932496 (GLASSIC)
Cover Note Number
Driver
Name of Driver CHUAH CHOON YEN
NRIC No S7235900C
Date Of Birth 29/09/1972
Occupation INDOOR
Date Of Driving Pass 14/06/1995
Driving Experience 23 YEARS AND 3 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-96893787
Fax Number
OFFICE-96893787
NOEMAIL

Address 2 TOH YI DRIVE
 Postcode 5590002
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY
 Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name BUKIT TIMAH NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 1 TOH YI DRIVE, POSTCODE: 590001, COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-4689999 - FAX NO: 64623782
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number SU4312D
 Vehicle Make KIA
 Vehicle Type PRIVATE CAR
 Vehicle Owner TANG TECK CHUAN
 Vehicle Insurance S7638952F

NA Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	CHUAH CHOON YEN
Approximate Age	
Injuries Sustain	REFER TO POLICE REPORT
Injured person in which vehicle?	SLV1740H
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg


Policyholder's Signature
Date & Time:

 - 4 OCT 2018
Driver's Signature
(If driver is not the policyholder)
Date & Time: 3/10/18 9.00am

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

...true in every respect

OCT 2018

IDAC BUKIT BATOK (VAC)

511 Bukit Batok Street 23

Singapore 659545

Tel: 6560 3312 Fax: 6569 0722

Email: vacbu@slingshot.com

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Enquire Vehicle & Owner Information (Vehicle No. SLJ4312D As At 02 Oct 2018 / 07:30:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: SLJ4312D

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S7636952F
Owner Name: TANG TECK CHUAN (DENG DECHUAN)
Registered Address Type: HDB / HUDC
Registered Block/House No.: 291A
Registered Street Name: BUKIT BATOK STREET 24
Registered Unit No.: # 07 - 53
Registered Building Name: -
Registered Postal Code: 650291

Current Vehicle Details

Vehicle No.: SLJ4312D
Make Description/Model: KIA / CARENS 1.7(A) DIESEL SUNROOF
Insurance Company Name: FWD SINGAPORE PTE. LTD.



Thank you

Satwant Singh S/o Sarban Singh has successfully logged out.

Your last login date and time was 05 Oct 2018, 17:18:59.

To return to ONE.MOTORING, please [click here](#)

For security reasons, please CLEAR YOUR CACHE after each session.

Session Transaction History

S/No	Asset Type:	Asset ID:	Asset Owner ID:	Transaction Type:	Transaction
1	Vehicle	SLJ4312D	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49



SINGAPORE POLICE FORCE



T/20181002/2184

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

1 of 3
Report No. T/20181002/2184

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 02/10/2018 21:15		Vide Report No.:		Station Diary No.: 99	
Name of Informant: CHUAH CHOON YEN					
Address: APT BLK 2 TOH YI DRIVE #04-163 SINGAPORE 590002					
ID Type / ID No.:		Contact No.:			
NRIC-NO / S7235900C		Home/Office: Mobile: 96893787			
Nationality: SINGAPORE CITIZEN		Email:			
Sex: Female	Age: 46	Date of Birth: 29/09/1972	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: HOMEMAKER		Driving Licence Information: Class: Date of Expiry:			

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 02/10/2018 07:30	Type of Location:
Location: Junction of Road 1 and Road 2 BUKIT BATOK EAST AVENUE 6 BUKIT BATOK AVENUE 1 towards Jurong East				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Vehicle 1	Car				No Damage	0
Vehicle 2	Car				Slightly Damaged	0

Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20181002/2184

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

2 of 3

Report No. T/20181002/2184

CONTINUATION OF REPORT

Driver				
Name	TANG TECK CHUAN		ID No.	S7636952F
Related Vehicle	SLJ4312D (Car)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	CHUAH CHOON YEN		ID No.	S7235900C
Related Vehicle	SLV1740H (Car)		Contact No.	96893787
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	02/10/2018		Date Discharge	02/10/2018
No. of Days granted Medical Leave	06		Degree of Injury	NIL

Brief Details.

On 02/10/2018 at about 0730hrs, I was driving along Bukit Batok East Avenue 6 and wanted to make a left turn to Bukit Batok Avenue 1 (towards Jurong East).

When I was at the filter lane, I had stopped at the give way line to wait for the traffic to clear on the main road (Bukit Batok Avenue 1).

While waiting, I suddenly felt an impact coming from the rear. I alighted and saw that a white coloured Kia had collided into the rear of my vehicle. The driver of the Kia immediately gave me his particulars. After taking some photos, we then drove off in our own directions.

After the incident, I was feeling pain at the back of my neck and feeling nauseous. I went to NUH to seek medical attention and was given 6 days medical leave by the doctor.

There is no in-car camera installed in my vehicle.



**SINGAPORE
POLICE FORCE**



T/20181002/2184

Police Station Of Origin:
Bukit Timah NPP
1 Toh Yi Drive #01-139 SINGAPORE 591501
Tel No: 1800-4689999

3 of 3

Report No. T/20181002/2184

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 PAY ZHIQIN

Signature Of Informant:

Not a valid signature

Signature Of Informant:

Date/Time:

02/10/2018 21:15

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Oct 2018 Edit Reg		08 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	Tang Teck Chuan , ID: S7636952F			
Main Claimant:	-			
Vehicle Reg. No.:	SLV1740H	Date of Loss:	02/10/2018 00:00 - :59 [9 Months and 10 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 1201800012603	Policy/Cover Note No.:	PNPV2017-00008240 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLJ4312D	Policy No. (Claimant):		
		Excess:		
Repairer:	Ngai Hong Spray Painting (HQ) BLK 12, #01-53 SIN MING IND EST SECTOR B, 575656 Sin Ming - Tel: 64531712			
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 18/10/2018]			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

































Claim Documents

***SLV1740H (1201800012603)**
[SLJ4312D]

TP

-

Oct 2 2018 12:00AM
[Tang Teck Chuan]
Ngai Hong Spray Painting

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print
1	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
2	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
3	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
4	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
5	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
6	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
7	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
8	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
9	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
10	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
11	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
12	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
13	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
14	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
15	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
16	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
17	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
18	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
19	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
20	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
21	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
22	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
23	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
24	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
25	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
26	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
27	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
28	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
29	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
30	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
31	18/10/18 10:52	General View							Load JPG	<input checked="" type="checkbox"/>
Documentation								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)							Thumbnail	Print
1	10/10/18 18:39	Insured GIA							Load PDF	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/FWD18018259/T1CD3E2

Date: 08/11/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00008240

Claimant Vehicle No: SLV1740H Insured Vehicle No: SLJ4312D

Date of Loss: 02/10/2018 Nature of Claim: TP Claim No: 1201800012603

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV1740H	Engine No:	L15B4429304
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11229299
Reg. Date:	22/12/2017 (Man. Year: 2017)	Odometer:	36199 km
Colour:	Gold		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 08/10/2018

Date Inspected: 12/10/2018 Inspected At:

160 SIN MING DRIVE # 06-08

Repairer : Ngai Hong Spray Painting (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,800.00 -\$4,500.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV1740H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >