



Your Ref: SS/10201/1116

Date: 17th Oct 2018

Our Ref: CS1/LAW18018275/Urbe2

M/s Alan Shankar & Lim LLC

151 Chin Swee Road
#09-16 Manhattan House
Singapore 169876

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YK 324L
INSURED VEHICLE: YK 8688J
ACCIDENT DATE: 22/07/2015**

We thank you for your instruction on 02/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YK 324L from M/s Par Automotive Consultancy.
- b) Survey report by Raleigh Services with colour photographs.
- c) Singapore Accident Statement of Vehicles YK 324L and YK 8688J.
- d) Colour damaged vehicle photographs of YK 324L.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: YK 324L
Make & Model	: Nissan Cabstar
Year of Registration	: 1999
Chassis Number	: JN1SF4F23Z0001045
Engine Capacity	: 3153 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.