

ASS. REC. BY:

REF: CS3/SMO18018284/Gcd302

Special Instruction:

Surveyor:
Menimen

GO

ASSIGNMENT (Office)

From (Person): Ngo Sau Wei shawn of SMO

Date/Time: 9/10/18 @ 4:32pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJX 5526Y

Insured: SJQ 607S

at Workshop m/s: Saf Motors

Tel: 9859 9677

of 24 Defu Lane 12

Policy No: D17MTPV 01014734

Claim No: CMTD1804381

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 07/10/2018

CA / REV / REP. / REV 24 HRS ^{1up}

H.O.D. Endorsement:

Date/Time: 4:46pm @ 9/10/18

Person Contacted:

Jessie

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	SJX 5526Y - X
	SJQ 607S - X
10/10/18-	Jessie said VNI yet
	Dismanth.: 23/10/2018

REF: 5mo

C2116N

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TR / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s Sart Motor
 of _____
 Insured _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record) _____
 Make of Veh: _____

Ⓞ	
N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$17k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SIX5526Y Yr Regn: 29 Jun 2010
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Insight c.c. 1339
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: - T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZE 21168106
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/60R15
 R: 11
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 22-10-18
 Survey held at w/s 5:30pm
 Des. of Damages Frt Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>\$1500 - \$2500</u>

Date/Time, File Pass to? : Preli. Report
 : Final Report
 Date/Time, File Return to?
 Report Format : PR
 Lump Sum / I.B.I. (\$) _____

Days Of Repair: 3
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)
 Survey Fee:

100
60
10
TOTAL 170

 Transportation) S + RS \$
 Photos)
 Others)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth of	Status
Main	08 Oct 2018		09 Oct 2018 16:32 Assign				New Assignment Cancel Case

[Main](#) [Reference](#) [Claim Details](#) [Documents](#) [Show All](#)

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	LIAU SEOW HWEE (LIAO SHAOWEI), ID: S7624653Z, Tel: +6597455268, Email: lionelliau@outlook.com	
Main Claimant:	SHOWROOMCARS PTE LTD, Co. Reg. No.: 20132116N	
Vehicle Reg. No.:	SJX5526Y	Date of Loss: 07/10/2018 17:00 - :59
Claim Type:	TP / CMTD1804381	Policy/Cover Note No.: D17MTPV01014734 (Third Party Only)
Vehicle Reg. No. (Insured):	SJQ607S	Policy No. (Claimant):
		Excess:
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:	
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5217]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/10/2018]	
Driver/Custodian (Insured):	LIAU SEOW HWEE (LIAO SHAOWEI) (42 / Male), NRIC: S7624653Z, Tel: +6597455268	

ASSOCIATED MAIL RECEIVED

There are no mail for this case. [View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed By	Created On	Complete
No results.									

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 9 October 2018 4:30 PM
To: Spencer Phng; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: 'joey'; Jonathan; Sean; PAKWENG; Limdanny; Aarontan; margaretlim@satwantlaw.com.sg; Ngo, Sau Wei Shawn; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1804381/NSW - SUV(LKK)/ & SJQ607S & SJX5526Y on 07/10/18 (Yr Ref: PD/DL/1801750 (Sp))

Our Reference : CMTD1804381/NSW
Your Reference: PD/DL/1801750 (sp)

Date: 9th October 2018

Without Prejudice
EMAIL ONLY

Attention:
M/S SATWANT & ASSOCIATES

Dear Spencer,

ACCIDENT INVOLVING SJQ607S & SJX5526Y ON 07.10.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

-----Original Message-----

From: Spencer Phng [mailto:pri@satwantlaw.com]

Sent: Tuesday, October 09, 2018 4:24 PM

To: Teo, Grace

Cc: 'joey'; Jonathan; Sean; PAKWENG; Limdanny; Aarontan; margaretlim@satwantlaw.com.sg

Subject: Re: CMTD1804381/NSW - PRI/ & SJQ607S & SJX5526Y on 07/10/18 (Yr Ref: PD/DL/1801750 (Sp))

Without Prejudice

Dear Grace,

We have instructions to reject using your motor surveyor. We propose to use our motor surveyor as below:-

1. Lim Chang Liang
2. Lim Yong Tian, Sebastian

Kindly see attached our letter and the workshop details as below:- Workshop name: Sat Motors

Address: No. 24 Defu Lane 12 Singapore 539131 Contact Person: Jessie (HP: 9859 9677), Jonathan (HP: 9126 9987)

Kindly liaise with the workshop directly for the PRS on an urgent basis.

Thank you.

Regards,
Spencer

On 2018-10-09 19:10, Teo, Grace wrote:

> Our Reference : CMTD1804381/NSW

>

> Your Reference: PD/DL/1801750 (sp)

>

>

> WITHOUT PREJUDICE

>

> Date: 9th October 2018

> EMAIL ONLY

>

> ATTENTION:

>

> M/S SATWANT & ASSOCIATES

>
> Dear Spencer,
>
> ACCIDENT INVOLVING SJQ607S & SJX5526Y ON 07.10.2018
>
> We refer to your Notice of Accident dated 09/10/2018.
>
> Please be informed that Mr. Shawn Ngo is the handler of this case.
>
> We intend to conduct a pre-repair survey of the damage to your
> client's/your customer's vehicle jointly with your client/your motor
> workshop. We propose to use one of the motor surveyors named in the
> attached list to conduct the joint pre-repair survey as a single joint
> expert.
>
> PRE-REPAIR SURVEY
>
> MOTOR SURVEYOR
>
> SURVEYOR
>
> SELECTION (INDICATE AS TICK)
>
> 1
>
> Raleigh Services
>
> Andrew Ow Yong
>
> Vincent Ng
>
> 2
>
> LKK Auto Consultants
>
> Kenneth Kong (North area)
>
> Marcus Chua (East area)
>
> Mohd Rasul (West area)
>
> Mohd Taufikh (West area)
>
> 3
>
> Priority Services
>
> Jimmy Lee
>
> Lawrence Ng
>
> Jeffrey Ong
>
> 4
>
> JP Knights Adjusters & Surveyors

>
> Jason Lek
>
> 5
>
> In House surveyor
>
> Teo See Ling
>
> Please let us know within TWO (2) WORKING DAYS whether you agree to
> the appointment of any of these motor surveyors as a single joint
> expert. You may select up to two of the listed motor surveyors. We
> will bear the cost of the pre-repair survey carried out by the single
> joint expert.
>
> Best Regards
>
> GRACE TEO
>
> Claims Division
>
> D: 6329 5170 | T: 6461 6555 | F: 6221 3147
>
> SOMPO INSURANCE SINGAPORE PTE. LTD.
> 50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
> WEBSITE: www.sompo.com.sg [1] | FACEBOOK: www.facebook.com/SompoSG [2]
>
>
> QUICK & EASY CLAIMS SUBMISSION1 & PRODUCT PURCHASE2 VIA SOMPO SG
>
> DOWNLOAD NOW @ [3] OR [4]
>
> 1 For Travel, Personal Accident & Home Insurance | 2 For Travel,
> Personal Accident, Home & Private Motor Insurance
>
> DISCLAIMER: This e-mail, including attachments, is intended for the
> person(s) or company named and may contain confidential and/or legally
> privileged information. Unauthorised disclosure, copying or use of
> this information may be unlawful and is prohibited. If you are not the
> intended recipient, please delete this message.
>
> PRIVACY POLICY NOTICE: Sompo Insurance Singapore Pte. Ltd. may
> collect, use and disclose your personal data for the purposes stated
> in our Privacy Policy. This may include disclosure to holding and
> associated companies, credit bureau, parties to whom disclosure is
> permitted/required by laws, our third party service providers and
> agents (acting on our behalf). Please click here [5] for our Privacy
> Policy
>
> -----Original Message-----
> From: Spencer Phng [<mailto:pri@satwantlaw.com>]
> Sent: Tuesday, October 09, 2018 1:35 PM
> To: Claims - Motor Survey
> Cc: PAKWENG; 'joey'; Jonathan; Sean; Limdanny; Aarontan;
> margaretlim@satwantlaw.com.sg
> Subject: URGENT: Accident involving SJX5526Y & SJQ607S on 07/10/18

> (Our Ref: PD/DL/1801750 (Sp))
>
> WITHOUT PREJUDICE
>
> Dear Sir/Madam,
>
> Kindly see attached our PRS letter for your urgent attention. Thank
> you.
>
> Thank you & Best Regards
>
> Spencer Phng (Branch Office)
>
> For and on behalf of
>
> SATWANT & ASSOCIATES
>
> Advocates & Solicitors | Notary Public | Commissioner for Oaths Main
> Office: No. 3 Jalan Bingka, Singapore 588896 | tel: 6299 9470 |
>
> fax: 6299 5541
>
> Branch Office: 450 Lorong 6 Toa Payoh #02-03 Harsing Centre Singapore
>
> 319394 | tel: 6221 6114 | fax: 6266 6925
>
> Email Confidentiality Warning:
>
> This message contains information which is subject to legal
> professional
>
> privilege and/or is confidential. If you are not the intended
> recipient,
>
> you are notified that any unauthorised disclosure, copying,
> distribution
>
> or use of this information is strictly prohibited. If you have
> received
>
> this message in error, please notify us by e-mailing us at
>
> [margaretlim@satwantlaw.com.sg] and delete it from your system. Unless
>
>
> the contents of this email relate to matters within the scope of the
>
> firm's engagement, any opinions, views and other information are
>
> expressed in the sender's personal capacity. You should scan this
> email
>
> and any file attached for viruses. We take no responsibility for any
>
> loss or damage, whether caused by our own negligence or not, that
>

>.results from a computer virus or a defect in the transmission of this
>
> email or any attached file.
>
> On 2018-10-09 15:45, PAKWENG wrote:
>
>> Re-send
>
>>
>
>> Best Regards,
>
>>
>
>> Jessie Ong
>
>>
>
>> Hp : 9859 9677
>
>>
>
>> Email: pakweng@satmotors.com
>
>>
>
>> Website: www.satmotors.com [1]
>
>>
>
>> 24 Defu Lane 12 S(539131)
>
>>
>
>> TEL: +65 6748 1141
>
>>
>
>> FAX: +65 6749 1141
>
>>
>
>> Find us on Facebook today @
>
>> [Http://www.facebook.com/SATMotors.Yourcarspecialist](http://www.facebook.com/SATMotors.Yourcarspecialist) [2]
>
>>
>
>> ~~~~~YOUR CAR SPECIALIST~~~~~
>
>>
>
>> FROM: PAKWENG <pakweng@satmotors.com>
>
>> SENT: Tuesday, 9 October 2018 12:43 PM
>

>> TO: 'Margaret Lim' <MargaretLim@satwantlaw.com.sg>
>
>> CC: 'Jonathan@satmotors.com' <jonathan@satmotors.com>;
>
>> 'sean@satmotors.com' <sean@satmotors.com>; 'pri@satwantlaw.com'
>
>> <pri@satwantlaw.com>; 'sophia@satwantlaw.com'
> <sophia@satwantlaw.com>;
>
>> 'Danny Lim' <limdanny@satwantlaw.com.sg>
>
>> SUBJECT: RE: Arrangement for PRS for (SJX5526Y) with attached GIA
>
>> accident --SAT MOTORS--
>
>>
>
>> Good Day, Danny & Margaret
>
>>
>
>> Attached is the GIA report for the accident.
>
>>
>
>> Please proceed to arrange PRS for the above accident vehicle as per
>
>> our company protocols.
>
>>
>
>> Please contact me @ 9859 9677 or Jonathan @ 9126 9987.
>
>>
>
>> Thank you.
>
>>
>
>> Best Regards,
>
>>
>
>> Jessie Ong
>
>>
>
>> Hp : 9859 9677
>
>>
>
>> Email: pakweng@satmotors.com
>
>>
>
>> Website: www.satmotors.com [3]

>
>>
>
>> 24 Defu Lane 12 S(539131)
>
>>
>
>> TEL: +65 6748 1141
>
>>
>
>> FAX: +65 6749 1141
>
>>
>
>> Find us on Facebook today @
>
>> [Http://www.facebook.com/SATMotors.Yourcarspecialist](http://www.facebook.com/SATMotors.Yourcarspecialist) [4]
>
>>
>
>> ~~~~~YOUR CAR SPECIALIST~~~~~
>
>>
>
>> Links:
>
>> -----
>
>> [1] <http://www.satmotors.com/>
>
>> [2] <http://www.facebook.com/SATMotors.Yourcarspecialist>
>
>> [3] <http://www.satmotors.com>
>
>> [4] <Http://www.facebook.com/SATMotors.Yourcarspecialist>
>
> --
>
> Spencer Phng
>
> Links:
> -----
> [1] <http://www.sompo.com.sg/>
> [2] <http://www.facebook.com/SompoSG>
> [3] <https://itunes.apple.com/sg/app/sompo-sg/id1387425777>
> [4]
> <https://play.google.com/store/apps/details?id=sg.com.sompo.sompoapp>
> [5] <https://www.sompo.com.sg/Privacy/PrivacyPolicy.aspx>

--
Spencer Phng

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	2116N

Vehicle Details

Vehicle No.:	SJX5526Y
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	INSIGHT 1.3G A
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	LDA2068233
Chassis No.:	ZE21168106
Maximum Power Output:	65.0 kW (87 bhp)
Open Market Value:	\$24,280.00
Original Registration Date:	24 Jun 2010
First Registration Date:	24 Jun 2010
Transfer Count:	1
Actual ARF Paid:	\$14,568.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Jun 2020
PARF Rebate Amount:	\$8,012.00

Intended COE Rebate Details

COE Expiry Date:	23 Jun 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$31,510.00
COE Rebate Amount:	\$5,251.00
Total Rebate Amount:	\$13,263.00

The information contained herein is correct as at 23 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/10/2018 18:31
Date Of Accident	07/10/2018 18:05
Exact Location Of Accident	BLK 305 UBI AVENUE 1 (INSIDE CARPARK)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX5526Y
Insured/Policyholder	
Name Of Registered Owner	SHOWROOMCARS PTE LTD
Co Reg No	201332116N
Email Address	BATSAMORA@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91424321
Alternative Phone No	OFFICE-90277782

Vehicle Particulars

Manufacturer	HONDA
Model	INSIGHT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096518003
Cover Note Number	

Driver

Name of Driver	MUHAMMAD FADHIL HAZIQ BIN HASHIM
NRIC No	S9041883A
Date Of Birth	09/11/1990
Occupation	INDOOR
Date Of Driving Pass	03/10/2014
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91424321
Fax Number	
Contact Number	OFFICE-90277782
EMail Address	BATSAMORA@GMAIL.COM


Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MUHAMMAD FADHIL HAZIQ BIN HASHIM
Approximate Age	27
Injuries Sustain	REFER POLICE REPORT
Injured person in which vehicle?	SJX5526Y
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	APT BLK 535 CHOA CHU KANG STREET 51 #08-116 SINGAPORE
Postcode	680535

SKETCH PLAN



A : SJX5526Y
 B : SJQ607S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 7/10/2018 at about 1805hrs, I was driving in a carpark of block 305 ulu Avenue 1 going towards block 307, while I was (SJQ607S) driving, a vehicle in front of me suddenly reverse and hit onto me.

After the accident, I was not feeling well and I went to consult a doctor, and was given 5 days of MC.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

08 OCT 2018
 Policyholder's Signature
 Date & Time:

[Signature] 12.26pm, 08/10/18
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Oct 2018		09 Oct 2018 16:32 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by insurer]		
Insured:	LIAU SEOW HWEE (LIAO SHAOWEI) , ID: S7624653Z, Tel: +6597455268, Email: lionelliau@outlook.com			
Main Claimant:	SHOWROOMCARS PTE LTD , Co. Reg. No.: 20132116N			
Vehicle Reg. No.:	SJX5526Y	Date of Loss:	07/10/2018 17:00 - :59 [99 Months and 13 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / CMTD1804381	Policy/Cover Note No.:	D17MTPV01014734 (Third Party Only)	
Vehicle Reg. No. (Insured):	SJQ607S	Policy No. (Claimant):		
		Excess:		
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, S39131 Defu Lane - Tel:			
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by NGO SAU WEI SHAWN - 6329 5202]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 18/10/2018]			
Driver/Custodian (Insured):	LIAU SEOW HWEE (LIAO SHAOWEI) (42 / Male), NRIC: S7624653Z, Tel: +6597455268			
ASSOCIATED MAIL RECEIVED		View All		Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS		View All		Search Tasks
		Create New Task		Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

***SJX5526Y (CMTD1804381)**
[SJQ607S]
TP
SHOWROOMCARS PTE LTD
Oct 7 2018 5:00PM
[LIAU SEOW HWEE (LIAO SHAOWEI)]
Sat Motors

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	09/10/18 16:32	Accident Statement From: SC - Reg. No: SJQ607S, Claimant: LIAU SEOW HWEE (LIAO SHAOWEI)	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
2	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
3	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
4	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
5	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
6	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
7	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
8	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
9	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
10	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
11	23/10/18 17:36	General View	Load JPG	<input checked="" type="checkbox"/>
12	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
13	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
14	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
15	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
16	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
17	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
18	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
19	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
20	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
21	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
22	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
23	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	26/10/18 14:34	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	09/10/18 16:17	Third Party E-filed GIA report	Load PDF	<input type="checkbox"/>
2	09/10/18 16:31	Pre-Repair Survey - Sat Motors	Load PDF	<input type="checkbox"/>
3	09/10/18 16:31	Pre-Repair Survey - ASSIGN LKK	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18018284/GCD3E2

Date: 02/11/2018

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D17MTPV01014734

Claimant Vehicle No : SJX5526Y Insured Vehicle No : SJQ607S

Date of Loss: 07/10/2018 Nature of Claim: TP Claim No: CMTD1804381

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX5526Y**
 Make & Model: HONDA INSIGHT, 1.0 Engine No: LDA2068233
 Reg. Date: 24/06/2010 (Man. Year: 2009) Chassis No: ZE21168106
 Colour: Blue Odometer: 0 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 09/10/2018

Date Inspected: 22/10/2018

Inspected At: Sat Motors (HQ)
24 Defu Lane 12
Singapore 539131

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 -\$2,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2018)
Parts: 144	HONDA INSIGHT 1.0 (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX5526Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

Sketch Plan Pg. 1

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Driver's Signature
(If driver is not the policyholder)
Date & Time:

12.26pm, 08/10/18


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Address	APT BLK 535 CHOA CHU KANG STREET 51 #08-116 SINGAPORE
Postcode	680535
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJQ607S
Vehicle Make/Model/Colour	HONDA STREAM
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIAU SEOW HWEE (LIAO SHAOWEI)
NRIC/Passport Number	S7624653Z
Contact Number	97455268
Address	
Postcode	
Insurance Company Name	