

12/12/2018

ASS. REC. BY:

REF:

C1/FCI18018348/NC

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Karen Tan

of

FCI

Date/Time:

17/9/2018

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD6567B

Insured:

at Workshop m/s

Tel:

of

Policy No:

Claim No:

D18006707MESH/JY/KT

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

6/9/2018

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction ()

Estimate

SHD6567B-X

5601 8

Catherine Chong (LKK Auto)

From: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>
Sent: Monday, 17 September, 2018 10:54 AM
To: KARENTAN@MSFIRSTCAPITAL.COM.SG; assignments
Cc: Christine Tay Siew Hway; Fauzy Bin Mokhtar; Roger How Keen Meng; Tan Pei Wei; SUR
Subject: FW: URGENT NEW ASSIGNMENT - SHD6567B- FIRE ON 06/092018 - MSFCI REF: D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)
Attachments: SAS (SHD6567B).pdf

Dear Karen,
Thank you for your email.

Dear Assignment Team,
Kindly assist.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

I.LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen Tan [mailto:karentan@msfirstcapital.com.sg]
Sent: Monday, September 17, 2018 10:32 AM
To: SUR <sur@lkkauto.com>
Cc: Christine Tay Siew Hway <christine_tay@cdgtaxi.com.sg>; Fauzy Bin Mokhtar <fauzy@sparkcarcare.com>; Roger How Keen Meng <rogerhow@cdge.com.sg>; Tan Pei Wei <tanpw@cdge.com.sg>
Subject: URGENT NEW ASSIGNMENT - SHD6567B- FIRE ON 06/092018 - MSFCI REF: D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Dear Sirs/Madam,

The above taxi caught fire on 06/09/2018.

Kindly assist to investigate into the matter.

Taxi is grounded at 59 Loyang Drive.

Kindly contact Fauzy@ 62148319 (copied-in) if you need any other information.

A copy of our driver's report is attached.

Best Regards,

Karen Tan
Motor Claims Dept.

MS First Capital Insurance Ltd | 36 Robinson Road #16-01 City House Singapore 068877 | DID : 6507 3582 | Fax No. : 6507 3849 | Company Regn. No. 195000106C

A Member of **MS&AD** INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to <http://www.msfirstcapital.com.sg> for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/09/2018 08:35
Date Of Accident	06/09/2018 13:45
Exact Location Of Accident	PIE(TUAS) BENDEMEER ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHD8567B
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	TAY CHOR KWEE
NRIC No	S0103308E
Date Of Birth	16/11/1954
Occupation	OUTDOOR
Date Of Driving Pass	16/02/1973
Driving Experience	45 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97327675
Fax Number	
Contact Number	
Email Address	KWEETAY3308@GMAIL.COM

Address: BLK 574A WOODLANDS DRIVE 16 #11-730
 Postcode: 731574
 Was driver an employee of the Insured's Company: NO
 If No, Relationship of the Driver with the Insured: OTHER - TAXI DRIVER
 Vehicle Registration Number of Driver's Own Vehicle: -
 Insurance Company of Driver's Own Vehicle: -

General Information of the Accident

Type Of Accident: FIRE, EXPLOSION OR LIGHTNING
 Weather Conditions: CLEAR
 Road Surface: DRY

Other Information

Was any foreign vehicle involved in this accident?: NO
 Number of vehicles involved in the accident:
 Was any body injured in the Accident?: NO
 Was any injured conveyed to hospital by ambulance?: NO
 Was any other material or property damaged?: NO
 I have been approached by unknown person(s) soliciting/offering accident claims assistance.: NO
 Number of Passengers (Including Driver): 3
 Passenger 1:

NAME: : -
 GENDER: : FEMALE

Passenger 2:

NAME: : -
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?: YES
 If Yes, Please state which Police Station:
 POLICE STATION NAME [OTHER]: WOODLANDS EAST N.P.C
 Was notice of intended Prosecution given?: NO
 If Yes, against whom?:

Circumstances of Accident

PLS REFER TO ATTACHED / POLICE REPORT : J/20180906/2181

Attachment(s)

Are accident photos available for attachment?: YES
 Was there any video captured by Car Camera?: NO
 Was there any audio recorded?: NO

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 192203321R

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6/9/18 at about 1345 hrs while driving my vehicle suddenly caught fire. I have idea how this happened. SCDF, Police + Ambulance were at site. The screen. I was advised by reporting officer to make police report and submit immediately

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG NO. 102507351R

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/EIN No.:

GAISM SketchPlanForm_V3

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**

RECEIVED
6 7 SEP 2018

BY: *SL*



J/20180906/2181

1 of 2

POLICE REPORT (NP299)

Report No. J/20180906/2181

Police Station Of Origin
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

Date/Time Report Made 06/09/2018 21:59	Vide Report No.		Station Diary No. 158
Name Of Informant TAY CHOR KWEE	Address APT BLK 574A WOODLANDS DRIVE 16 #11-730 SINGAPORE 731574		
ID Type / ID No. NRIC NO / S0103308E	Contact No. Home/Office	Mobile 97327675	
Nationality SINGAPORE CITIZEN	Email Address		
Occupation Taxi driver	Sex Male	Age 63	Date of Birth 16/11/1954
Institution/School Name	Race Chinese		
	Language		
Date/Time Of Incident 06/09/2018 13:45	Location Of Incident PAN-ISLAND EXPRESSWAY SINGAPORE PIE just after Kallang Bahru exit, near MOM Services Centre		

Brief details.

On 06/09/2018 at about 1345hrs, I was driving my taxi (SHD6567B) along PIE (Tuas) as I was heading towards Potong Pasir with my wife and cousin. At the traffic light near Ministry of Manpower Services Centre, I stopped as the traffic light was red.

Suddenly, there is smoke coming out from the engine of my taxi. After that, my taxi suddenly caught fire.

Signature Of Officer Recording The Report: J / EISEN MAH SHI YAO <i>[Signature]</i>	Signature Of Informant: <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 06/09/2018 21:59
Officer In-Charge Of Case: J / Jurong Police Divisional Investigation Branch / Insp LIM EN TECK, SHERWIN Contact No.: 67910000	Classification Of Case:

Authentication Stamp





**SINGAPORE
POLICE FORCE**



J/20180908/2181

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. J/20180908/2181

- He stopped i car.

My wife called 995 for SCDF.

forget turn on or off
magnifying

After a short while, the SCDF arrived along with the Police and ambulance. The tow truck also came after that. SCDF managed to put out the fire, and no one was injured. My taxi was towed to Loyang.

I reported to ComfortDelGro company about the incident, and they advised me to lodge a police report so that they can do their follow-up.

- Where he from - home. front when drive at junction
- Smoke come from where? Which side of bonnet long
- Whiff inside - Centre of engine - motor - improve? smoke
- How long SCDF take to come? very long time immediate
- How long SCDF take to put out fire? - long time down the car.
- Who called tow truck? How long tow truck come? dunnoe,
- Did he follow tow truck to comfort? yes. no report handphone in car use wife phone

dunnoe
actual
timing

police call
not try out
alone

Signature Of Officer Recording The Report:

J / EISEN MAH SHI YAO

Signature Of Interpreter:
Not applicableOfficer In-Charge Of Case:
J / Jurong Police Divisional Investigation Branch /
Insp LIM EN TECK, SHERWIN
Contact No.: 67910000

Signature Of Informant:

Date/Time:
06/09/2018 21:59

Classification Of Case:

5/18

soon after drive
seaboard

Authentication Stamp


SN 130



Singapore Police Force

- when he last service?
- Got any problem with taxi? - no
- Any overheating problem? morning 4 hr. no, morning no drive

Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0030
Operating Hours : Monday to Friday, 09:00 – 17:00
UEN: S645590306 / GST Reg. No.: MA00017738

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MCD618115826 Vehicle Registration No: SHD6567B
Name (as shown in NRIC) : TAY CHOR KWEE NRIC/FIN/Passport No : S0103308E
☒ **Vehicle Driver** / Vehicle Owner (*) Please delete as appropriate
Address : BLK 574A WOODLANDS DRIVE 18 #11-730 Singapore (731574)
Contact (Tel) : _____ Mobile No. : _____
Email Address : _____
Date of Accident : 06/09/2018 Time of Accident : 13:45
Place of Accident : PIE(TUAS) BENDEMEER ROAD
Insurance Company: MS First Capital Insurance Ltd

(B) ☒ ADDITIONAL INFORMATION AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Upload Police Report : J/20180906/2181

Policyholder / Driver's Signature
Date:



Reporting Centre Personnel's Signature
Name: xiao yan
NRIC/FIN No.: _____
Date: 07.09.2018

Download

X Hide email



Date: 25.09.2018 TAXI SERVICE HISTORY
Time: 18:18:19
VT5511F
Page: 3

Serviced on: 07.03.2018 / 02:34:00 Time Out: 07.03.2018 / 02:34:00
Remarks: (RNM BATTERY-CSK)
Job Card Nos: 305122884 Type: TC Odometer Reading: 0

MATERIAL CHANGED

SN	DESCRIPTION	QTY
----	-------------	-----

1	(140)BATTERY ASSY 85D26LBH 12V80AH	1.000 EAC
---	------------------------------------	-----------

Serviced on: 29.03.2018 / 15:49:00 Time Out: 29.03.2018 / 17:04:49
Remarks: (Next PM-14/05/2018 time-14:00)
Job Card Nos: 602758960 Type: 3P Odometer Reading: 456,556

PM/PROBLEM REPORTED

HI3	HYUNDAI I-40 DOCKING 3	
INSP	PRE-VICOM INSPECTION	
15.5	Undercarriage Noisy - Front Suspension	
17.1	Wiper Blade/Washer	
HR00	Mechanic Team Repair	- Yap Yoke Hwa
QC	QC TEST BY LAT	- Hong Leong Teck

MATERIAL CHANGED

SN	DESCRIPTION	QTY
----	-------------	-----

1	(ALL)(EURO IV)*ENGINE OIL F SYN SAE 5W30	5.300 L
2	I40VC OIL FILTER	1.000 EAC
3	I40VC FILTER-AIR CLEANER	1.000 EAC
4	I40VC CABIN FILTER ASSY-AIR	1.000 EAC
5	I40VC DIESEL FUEL FILTER	1.000 EAC
6	I40VC/IONIQ WIPER BLADE 16"(PASSENGER)	1.000 EAC
7	I40VC/IONIQ WIPER BLADE 26"(DRIVER)	1.000 EAC
8	Washer, Plain, SS (M6)	1.000 EAC
9	Bolt, Hex, SS (M6x30)	1.000 EAC
10	Nut, Flange, GI (M8)	1.000 EAC
11	Washer, Spring, SS (M6)	1.000 EAC
12	(I40/E220)WESTLAKE TYRE 205/60R16 RP26	2.000 PC
13	I40VC **PULLEY-DAMPER	1.000 EAC
14	I40V2 ARM COMPLETE-FR LWR RH	1.000 EAC
15	I40V2 DRIVE SHAFT ASSY RH (LONG)	1.000 EAC

REMARKS

SN	DESCRIPTION
1	HI3 - 60,000 KM

Serviced on: 02.04.2018 / 09:17:15 Time Out: 02.04.2018 / 09:17:15
Remarks: (Tyre Damage Pay 7mm -150733)
Job Card Nos: 602792621 Type: 0G Odometer Reading: 0

Re: SHD6567B- FIRE ON 06/092018 - MSFCI
REF: D18006707MFSH/JY/KT LKK REF: TBA
(NEW MATTER)



Lam Tow Chik

Wednesday, 5-44 PM

Fauzy Bin Mokhtar: +6 more v

SHD6567B - Service His...
11.88

Download | Save to OneDrive | ComfortDelGro Corporation Limited

Hi Fauzy

Please refer to attached.

Lam Tow Chik
Supervisor
Senoko (Taxi Maintenance)
6757 8762

From: Fauzy Bin Mokhtar
Sent: Tuesday, September 25, 2018 11:59 AM
To: Lam Tow Chik
Cc: Christine Tay Siew Hway; Tan Pei Wei; Roger How Keen Meng; Juman Bin Masudin; Naz@lkkauto.com; Doris Lim Puay Noi
Subject: Re: SHD6567B- FIRE ON 06/092018 - MSFCI REF: D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Hi Lam,
Surveyor request for the last 6 months servicing records.

Best Regards,
Fauzy Mokhtar
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148319 / Fax:65468156

From: Fauzy Bin Mokhtar
Sent: Tuesday, 25 September 2018 11:53:56 AM
To: Doris Lim Puay Noi
Cc: Christine Tay Siew Hway; Tan Pei Wei; Roger How Keen Meng; Juman Bin Masudin; Naz@lkkauto.com; Lam Tow Chik
Subject: Fw: SHD6567B- FIRE ON 06/092018 - MSFCI REF: D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Hi Doris,
Please refer email below LKK surveyor requested net book value

Best Regards,
Fauzy Mokhtar
Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd
Off:62148319 / Fax:65468156

From: Naz (LKKAuto) <Naz@lkkauto.com>
Sent: Tuesday, 25 September 2018 11:33 AM
To: Fauzy Bin Mokhtar
Subject: Re: SHD6567B- FIRE ON 06/092018 - MSFCI REF: D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Download

X Hide email



H1000 Mechanic Team Repair - Yap Yoke Hua
QC QC TEST BY LAT - Hong Leong Teck

MATERIAL CHANGED

SN	DESCRIPTION
QTY	
1	(ALL)(EURO IV)*ENGINE OIL F SYN SAE 5W30
5.000 L	
2	I40VC OIL FILTER
1.000 EAC	
3	I40VC **SENSOR-LAMBDA
1.000 EAC	
4	I40VC/IDN1Q WIPER BLADE 26"(DRIVER)
1.000 EAC	

REMARKS

SN	DESCRIPTION
1	H14 - 80,000 KM

Serviced on: 27.06.2018 / 14:20:00 Time Out: 27.06.2018 / 15:03:36

Remarks: (Next PM-13/08/2018 time-16:00)
Job Card Nos: 002813865 Type: 3P Odometer Reading: 495,489

PIN/PROBLEM REPORTED

H15 HYUNDAI I-40 DOCKING S
6.4 Engine Check Light ON
10.1 Lighting - External

H1000 Mechanic Team Repair - Ng Kok Fei
QC QC TEST BY LAT - Leong Chee Keong

MATERIAL CHANGED

SN	DESCRIPTION
QTY	
1	(ALL)(EURO IV)*ENGINE OIL F SYN SAE 5W30
5.000 L	
2	I40VC OIL FILTER
1.000 EAC	
3	(I40/E220)WESTLAKE TYRE 205/60R16 RP26
2.000 PC	
4	I40V2 ARM COMPLETE-FR LWR LH
1.000 EAC	

REMARKS

SN	DESCRIPTION
2	H15 - 100,000 KM

Serviced on: 19.07.2018 / 15:10:00 Time Out: 19.07.2018 / 16:51:15

Remarks: (Engine Noisy)
Job Card Nos: 002843225 Type: 3C Odometer Reading: 504,358

PIN/PROBLEM REPORTED

8.0 Mechanical Team Repair - Ng Kok Fei
8.1 Engine Noisy

QC QC TEST BY LAT - Leong Chee Keong

MATERIAL CHANGED

SN	DESCRIPTION
QTY	
1	(ALL)(EURO IV)*ENGINE OIL F SYN SAE 5W30
5.000 L	
2	I40VC BRACKET ASSY-ENGINE MTG
1.000 EAC	
3	I40VC COVER ASSY-ROCKER
1.000 EAC	
4	HYUNDAI INJECTOR GASKET(33818-27000)
4.000 EAC	

Re: SHD6567B- FIRE ON 06/092018 - MSFCI
REF: D18006707MFSH/JY/KT LKK REF: TBA
(NEW MATTER)

LC

Lam Tow Chik

Wednesday, 11:44 PM

Fauzy Bin Mokhtar, +6 more

SHD6567B - Service His...
11 KB

Download - Save to OneDrive - ComfortDelGro Corporation Limited

Hi Fauzy

Please refer to attached.

Lam Tow Chik

Supervisor

Senoko (Taxi Maintenance)

6757 8762

From: Fauzy Bin Mokhtar

Sent: Tuesday, September 25, 2018 11:59 AM

To: Lam Tow Chik

Cc: Christine Tay Siew Hway; Tan Pei Wei; Roger How Keen Meng;

Jumani Bin Masudin; Naz@lkkauto.com; Doris Lim Puay Noi

Subject: Re: SHD6567B- FIRE ON 06/092018 - MSFCI REF:

D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Hi Lam,

Surveyor request for the last 6 months servicing records.

Best Regards,

Fauzy Mokhtar

Taxi Crash Repair / ComfortDelGro Engineering Pte Ltd

Off:62148319 / Fax:65468156

From: Fauzy Bin Mokhtar

Sent: Tuesday, 25 September 2018 11:53:56 AM

To: Doris Lim Puay Noi

Cc: Christine Tay Siew Hway; Tan Pei Wei; Roger How Keen Meng;

Jumani Bin Masudin; Naz@lkkauto.com; Lam Tow Chik

Subject: Fw: SHD6567B- FIRE ON 06/092018 - MSFCI REF:

D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Hi Doris,

Please refer email below LKK surveyor requested net book value

Best Regards,

Fauzy Mokhtar

Taxi Crash Repair / ComfortDelGro Engineering Pte Ltd

Off:62148319 / Fax:65468156

From: Naz (LKKAuto) <Naz@lkkauto.com>

Sent: Tuesday, 25 September 2018 11:33 AM

To: Fauzy Bin Mokhtar

Subject: Re: SHD6567B- FIRE ON 06/092018 - MSFCI REF:

D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Download

X Hide email



SN DESCRIPTION

3

Served on: 02.08.2018 / 10:00:00 Time Out: 02.08.2018 /

17:16:58

Remarks: (Engine Overhaul)

Job Card Nos: 602851609 Type: JC Odometer Reading:

509,986

PH/PROBLEM REPORTED

8.5 Smoky Exhaust
 8.6 Engine Overhaul
 10.1 Lighting - External
 12.1 Steering Noisy
 15.0 Mechanical Team Repair - Ng Kok Fei
 15.5 Undercarriage Noisy - Front Suspension

QC QC TEST BY LAT - Hong Leong Teck

MATERIAL CHANGED

QTY	SN	DESCRIPTION
1	I40VC	^^CAMSHAFT ASSY-LH
1.000	EAC	
2	I40VC	^GUIDE-T/CHAIN
1.000	EAC	
3	I40VC	^O RING-FUEL INJECTOR
4.000	EAC	
4	I40VC	^SQUARE RING[B]-FUEL INJECTOR
4.000	EAC	
5	HYUNDAI	INJECTOR GASKET(33818-27000)
4.000	EAC	
6	I40VC	COMPLETE ENGINE ASSY
1.000	EAC	
7	I40VC	^^CHAIN SPROCKET-CAMSHAFT
2.000	EAC	
8	I40VC	^^CHAIN SPROCKET-INJECTION PUMP
1.000	EAC	
9	I40V2	^CHAIN SPROCKET-CRANKSHAFT
1.000	EAC	
10	I40V2	^CHAIN-TIMING
1.000	EAC	
11	I40V2	^CHAIN-HIGH PRESSURE PUMP
1.000	EAC	
12	I40VC	^GUIDE-T/CHAIN
2.000	EAC	
13	I40VC	^LEVER-TIMING CHAIN
1.000	EAC	
14	I40VC	^LEVER-TIMING CHAIN
1.000	EAC	
15	I40V2	^GASKET-CYLINDER HEAD
1.000	EAC	
16	I40VC	GASKET-TIMING CHAIN CASE UPP
1.000	EAC	
17	I40VC	^ASSY-CAM FOLLOWER SHORT
16.000	EAC	
18	I40VC	ADJUSTER ASSY-ROCKER ARM LASH
16.000	EAC	
19	I40VC	^HOSE-OIL COOLER RETURN
1.000	EAC	
20	I40VC	^PIPE ASSY-E.G.R COOLER IN
1.000	EAC	
21	(I40/SONATA)^^GASKET SILICON (65-75)*	
1.000	EAC	
22	I40VC	^PUMP ASSY-COOLANT
1.000	EAC	
23	I40VC	^^INJECTOR ASSY-FUEL
4.000	EAC	
24	I40SONV2	SEAL-OIL RR/CRANKSHAFT
1.000	EAC	
25	I40VC	OIL FILTER
1.000	EAC	
26	I40VC	^O-RING-EGR COOLER
1.000	EAC	
27	I40VC	^TENSIONER ASSY
1.000	EAC	

REMARKS

SN DESCRIPTION

4

Re: SHD6567B- FIRE ON 06/092018 - MSFCI
 REF: D18006707MFSH/JY/KT LKK REF: TBA
 (NEW MATTER)

LC

Lam Tow Chik

Yesterday 6:44 PM

Fauzy Bin Mokhtar, 46 more

SHD6567B - Service His...
 11 KB

Download - Save to OneDrive - ComfortDelgro Corporation Limited

Hi Fauzy

Please refer to attached.

Lam Tow Chik

Supervisor

Senoko (Taxi Maintenance)

6757 8762

From: Fauzy Bin Mokhtar

Sent: Tuesday, September 25, 2018 11:59 AM

To: Lam Tow Chik

Cc: Christine Tay Siew Hway; Tan Pei Wei; Roger How Keen Meng;

Jumani Bin Masudin; Naz@lkkauto.com; Doris Lim Puay Noi

Subject: Re: SHD6567B- FIRE ON 06/092018 - MSFCI REF:

D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Hi Lam,

Surveyor request for the last 6 months servicing records.

Best Regards,

Fauzy Mokhtar

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Off:62148319 / Fax:65468156

From: Fauzy Bin Mokhtar

Sent: Tuesday, 25 September 2018 11:53:56 AM

To: Doris Lim Puay Noi

Cc: Christine Tay Siew Hway; Tan Pei Wei; Roger How Keen Meng;

Jumani Bin Masudin; Naz@lkkauto.com; Lam Tow Chik

Subject: Fw: SHD6567B- FIRE ON 06/092018 - MSFCI REF:

D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

Hi Doris,

Please refer email below LKK surveyor requested net book value

Best Regards,

Fauzy Mokhtar

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Off:62148319 / Fax:65468156

From: Naz (LKKAuto) <Naz@lkkauto.com>

Sent: Tuesday, 25 September 2018 11:33 AM

To: Fauzy Bin Mokhtar

Subject: Re: SHD6567B- FIRE ON 06/092018 - MSFCI REF:

D18006707MFSH/JY/KT LKK REF: TBA (NEW MATTER)

REMARKS

SN	DESCRIPTION
----	-------------

4	
---	--

Serviced on: 17.08.2018 / 14:17:00 Time Out: 17.08.2018 / 15:25:11
 Remarks: (+INSP+Next PM-27/09/2018 time-09:30)
 Job Card Nos: 602860368 Type: JP Odometer Reading: 516,559

PM/PROBLEM REPORTED

HI6	HYUNDAI I-40 DOCKING 6	
H000	Mechanic Team Repair	- Koh Nian Kha
QC	QC TEST BY LAT	- Leong Chee Keong

MATERIAL CHANGED

SN	DESCRIPTION	QTY
1	(ALL)(EURO IV)^ENGINE OIL F SYN SAE 5W30	5.300 L
2	I40VC OIL FILTER	1.000 EAC
3	I40VC FILTER-AIR CLEANER	1.000 EAC
4	I40VC CABIN FILTER ASSY-AIR	1.000 EAC
5	I40VC DIESEL FUEL FILTER	1.000 EAC
6	I40VC PAD KIT-FR DISC BRAKE	1.000 EAC
7	I40VC MOTOR-RADIATOR COOLING FAN	1.000 EAC

REMARKS

SN	DESCRIPTION
5	HI6 - 120,000 KM

Serviced on: 06.09.2018 / 13:45:00 Time Out: 00.00.0000 / 00:00:00
 Remarks: (OD 06.09.18 - FIRE CASE INVESTIGATION)
 Job Card Nos: 305209519 Type: OD Odometer Reading: 0

Serviced on: 06.09.2018 / 15:02:26 Time Out: 06.09.2018 / 16:00:17
 Remarks: (ARC TOW-FIRE CASE)
 Job Card Nos: 305209613 Type: Z1 Odometer Reading: 0

Enquire Transfer Fee

Vehicle Details

Vehicle No.	2H065678
Vehicle Type	1110 - Public Transport Tax (Motor Car)
Vehicle Attachment 1	Air-Con (Tax)
Vehicle Scheme	Taxi (Company)
Vehicle Make	HYUNDAI
Vehicle Model	140 1.7L CRDI AT XRS AIRBAG RDR
Chassis No.	KH06BA1LMEU061493
Propellant	Diesel
Engine No.	04FDE0429934
Engine Capacity	1485 cc
Maximum Power Output	100.0 kW (134 bhp)
Maximum Laden Weight	2100 kg
Unladen Weight	1501 kg
Year Of Manufacture	2014
Original Registration Date	18 Dec 2014
Warranty Expiry Date	17 Dec 2022
COE Category	A - Car up to 1600cc & 171kW (230bhp)
PGF Fee	\$51,648.00
COE Expiry Date	17 Dec 2022
Road Tax Expiry Date	17 Dec 2018
PAWF Eligibility Expiry Date	17 Dec 2022
Inspection Due Date	17 Dec 2018
Intended Transfer Date	04 Oct 2018
CO2 Emission	158.00 g/km
CEV/VES Estimate Utilised Amount	\$7,500.00

CO Emission: -
 HC Emission: -
 NOx Emission: -
 PM Emission: -
 The current road tax expiry is 17 Dec 2018. You may renew the road tax from 18 Sep 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 17 Dec 2018, late renewal fee(s) will be imposed. Please use [Engine Road Tax Payable](#) to check on the late fee(s) payable.
 Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.
 Amount Payable (From 18 Dec 2018 to 17 Jun 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee	25.00	-	25.00
Sub Total			25.00
Nett Road Tax Amount (After Offsetting Over Payment)	2,635.00	-	2,635.00
Total Amount Payable			2,660.00

Message
 Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory Warrant Of Fitness (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print